

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1247/2018/GW
Date : 5-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SLU 5522 A

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Wong Geok Chun
Address : 71 Jurong West Central 3
#10-14
Singapore 648335
Telephone : HP +65 97285342
Type of Claim : Third Party Claims
Policy No. : 5099739095
Vehicle No : **SLN 141 K**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Apr-17
Engine No : CVN 032231
Chassis No : WAUZZZF43HA121927
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Nov-18
Place of Accident : Commonwealth Ave West Infront of West Coast Court

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 141 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according if necessary.	S/N \$ 360.00	✓
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	X
3	To dismantle rear bumper. Cut out and weld rear outer and inner cross panels. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,000.00	600
4	To respray rear bumper, rear lid and end panelling. To carry out joint sealer and stone chip treatment.	\$ 2,100.00	500
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,132.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>schand</i>	\$ 1,907.00	✓
2	REAR BUMPER SPOILER <i>lit</i>	\$ 216.00	✓
3	REAR BUMPER SECURING STRIP <i>xl am</i>	\$ 191.00	x.
4	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>xl am 2</i>	\$ 38.00	x.
5	REAR BUMPER GUIDE SECTION-LH/RH <i>xl am</i>	2 \$ 75.00	x.
6	REAR SENSOR <i>xl am</i>	2 \$ 421.00	x
7	REAR SENSOR SEAL RING <i>2</i>	4 \$ 14.00	x
8	REAR BUMPER WIRING SET <i>xl am</i>	\$ 598.00	x
9	REAR BUMPER CABLE HOLDER	\$ 8.00	x
10	REAR BUMPER REAR LIGHT REFLECTOR-LH/RH <i>RTT could 2</i>	\$ 70.00	35
11	REAR BUMPER CARRIER <i>?</i>	\$ 786.00	?
12	REAR BUMPER SEAL <i>xl am</i>	2 \$ 24.00	x.
13	REAR CROSS PANEL <i>Repair xl am</i>	\$ 230.00	x
14	REAR REINFORCEMENT CROSS PANEL <i>Repair Not Neds</i>	\$ 445.00	x
15	UNDERBODYTRIM <i>xl am</i>	\$ 97.00	x
16	AUDI EMBLEM	\$ 108.00	x
17	INSCRIPTION "A4"	\$ 83.00	x
18	INSCRIPTION "TFSI" <i>HP</i>	\$ 83.00	x
19	PACKING ADHESIVE <i>Ned</i>	\$ 15.00	x
20	ACRYLIC SEALER	S/N \$ 180.00	x
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,589.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 141 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	CAVITY WAX	S/N \$ 140.00	✓
22	STONE CHIP	S/N \$ 180.00	✓
23	SUNDRIES	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 6,309.00	
TOTAL LABOUR CHARGES		: \$ 6,132.00	
GRAND TOTAL		: \$ 12,441.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 07/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant