

15/02/18

INS. CASE OWNER:

CC

/AXA1801 0036,

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

PIP

SS 4,713.99

(4 days) Reduction:

41 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 12.04.19

Confirm with: PIREP2

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 36

If NO or B 28, Ass. Lia :

Repair Cost:

WIKST

SS 5,043.97

OI LOST CONTROL AND HIT TP.

Loss of Rental (LOR):

SS -

(4 days)

Loss of Use (LOU):

SS 400.00

(\$ 100 x 4 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +350

Total:

SS 5,443.97

Global Sum SS:

FINAL PAYMENT

Date/Time: 12.04.19

Confirm with: PIREP2

Email ☒ Call ☐

Payee 1:

SS 5,443.97

Name 1:

KAH MOTOR CO. SON BND

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18020036/eb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 05-11-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 2361L	Veh. Inspected	SVJ 6845E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/10/2018	Inspection Date		
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No: M200050223
Company Ref. No.: S60FC1380G

Katherine
LKK Auto *68411972* *67411972*

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJV6845E
Chassis No : JHMRB38509C201535
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : ONG KIAN TONG
Ins Policy No. : VPA/P1028848
Date of Accident : 30/10/2018

Document No. : SQT18004713
Date : 2. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24Z21301541
Date | Time : 2. Nov 2018 2:31:04 PM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG KIAN TONG OWNER INSURER: AXA INSURANCE S'PORE PTE LTD ACC DATE: 30/10/2018@20.15PM SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SKJ2361L (VOLKSWAGEN/PASSAT/GREY)						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT <i>✗</i>	1	180.00		180.00	12.60	192.60
	Sum Ext. Service				180.00	12.60	192.60
91505-TM8-003	CLIP,BUMPER <i>me</i>	14	2.30	25	24.15	1.69	25.84
42700-S3N-J31	DISKALUMINIUM WHEEL <i>cu</i>	1	642.90 <i>977.80</i>	25	632.17 <i>733.31</i>	44.25	676.42
33101-SLE-J01	HEADLIGHTR.HID <i>cm</i>	1	796.70	25	597.52	41.83	639.35
04711-SLE-900ZZ	FACEFR.BUMPER <i>D.S</i>	1	748.50	25	561.37	39.30	600.67
71140-SLE-000	BEAMR.FR.BUMPER <i>bul</i>	1	39.90	25	29.92	2.09	32.01
71193-SLE-003	SPACERR.FR.BUMPER <i>bul</i>	1	12.50	25	9.37	0.66	10.03
71130-SLE-000ZZ	BEAMFR.BUMPER <i>11</i>	1	249.50	25	187.12	13.10	200.22
60212-SFE-300ZZ	STAY R FENDER <i>11</i>	1	13.00	25	9.75	0.68	10.43
60210-SLE-000ZZ	PANELR.FR.FENDER <i>bul</i>	1	586.40	25	439.80	30.79	470.59
74101-SLE-000	FENDERR.FR INNER <i>bul</i>	1	99.70	25	74.77	5.23	80.00
74105-SLE-000	ENCLOSURER.FR.FENDER <i>11</i>	1	20.00	25	15.00	1.05	16.05
	Sum Item				2580.94	180.67	2,761.61
BOSUN	SUNDRIES <i>me</i>	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	11 X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT	1	100.00	11 X	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	130	140.00	9.80	149.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11 X	250.00	17.50	267.50



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJV6845E
Chassis No : JHMRB38509C201535
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : ONG KIAN TONG
Ins Policy No : VPA/P1028848
Date of Accident : 30/10/2018

Document No. : SQT18004713
Date : 2. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24Z21301541
Date | Time : 2. Nov 2018 2:31:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00	560	1800.00	126.00	1926.00
BKBH12M	CUT OFF & RENEW BULKHEAD FR R WHEELHOUSE. 2 pc	1	2800.00	900	2800.00	196.00	2996.00
Sum Labor					5290.00	370.30	5660.30

Survey By

Date & Time

Excess

Status

Signature

Marcus Hal
26/11/18 @ 10.15am
Not Authorized
to be part of the repair.
4 dy.

Total Amount 8,050.94 563.57 8,614.51

Total (Inclusive of GST) 8,614.51

8605.864

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price will be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/11/2018 2:48:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S1666804D / ONG KIAN TONG
Chassis No: JHMRB38509C201535
License No: SJV6845E
Mileage: 240168
Engine No: K24Z21301541

Document No: SVO18070368
Printed By: ARYCHUA
Order Date: 26. November 2018
Order Time: 12:13:46 PM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 71692) OWNER: ONG KIAN TONG OWNER INSURER: AXA INSURANCE S'PORE PTE LTD ACC DATE: 30/10/2018@20.15PM SURVEYED BY: MARCUS CHUA (LKKAUTO)26/11/2018@10.15 REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SKJ2361L (VOLKSWAGEN/PASSAT/GREY) SUPPLIMENTARY ITEM PARTS & LABOR						
51210-SLE-000	KNUCKLER FR <i>bul</i>	1	324.30	25	243.22	17.03	260.25 ✓
44300-SDA-A52	BEARING FR HUB <i>bul</i>	1	126.00	25	94.50	6.62	101.12 ✓
53540-SLE-013	END COMPR TIE ROD <i>bul</i>	1	79.90	25	59.92	4.19	64.11 ✓
53610-SLE-013	END COMPRACK <i>bul</i>	1	74.80	25	56.10	3.93	60.03 ✓
	SUM PARTS:				453.74	31.77	485.51
	TOTAL SGD				453.74	31.77	485.51

Total Payable (SGD) 485.51

GST Amount is calculated from individual line(s)

(A) WHEEL ALIGNMENT X4

180 ✓



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRB38509C201535
 License No: SJV6845E
 Mileage: 240168
 Engine No: K24Z21301541

Document No: SVO18070368
 Printed By: ARYCHUA
 Order Date: 26. November 2018
 Order Time: 12:13:46 PM
 Service Advisor: ARY CHUA WAI NGEN

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71692) OWNER: ONG KIAN TONG OWNER INSURER: AXA INSURANCE S'PORE PTE LTD ACC DATE: 30/10/2018@20.15PM SURVEYED BY: MARCUS CHUA (LKKAUTO)26/11/2018@10.15 REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SKJ2361L (VOLKSWAGEN/PASSAT/GREY)						
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84
42700-SEF-E91	DISKALUMINIUM WHEEL	1	977.80	25	733.35	51.33	784.68
33101-SLE-J01	HEADLIGHTR.HID	1	796.70	25	597.52	41.83	639.35
04711-SLE-900ZZ	FACEFR.BUMPER	1	748.50	25	561.37	39.30	600.67
71140-SLE-000	BEAMR.FR.BUMPER	1	39.90	25	29.92	2.09	32.01
71193-SLE-003	SPACERR.FR.BUMPER	1	12.50	25	9.37	0.66	10.03
60210-SLE-000ZZ	PANELR.FR.FENDER	1	586.40	25	439.80	30.79	470.59
74101-SLE-000	FENDERR.FR INNER	1	99.70	25	74.77	5.23	80.00
51210-SLE-000	KNUCKLER FR	1	324.30	25	243.22	17.03	260.25
44300-SDA-A52	BEARING FR HUB	1	126.00	25	94.50	6.62	101.12
53540-SLE-013	END COMPR TIE ROD	1	79.90	25	59.92	4.19	64.11
53610-SLE-013	END COMPRACK	1	74.80	25	56.10	3.93	60.03
	SUM PARTS:				2,923.99	204.69	3,128.68
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML01I	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	130.00		130.00	9.10	139.10
BKBH12S	EXT-YJ STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20
BP02R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(2P)	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				1,610.00	112.70	1,722.70
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				4,713.99	329.99	5,043.98

Total Payable (SGD)

5,043.98

GST Amount is calculated from individual line(s)

Customer

Hi Marcus
 SJV 6845E

Vehicle Ident no.

Repair order no.

R001526

Technician

Date

28.11.18

License plate no.

SJV6845E

First reg. date

Model

HONDA ODYSSEY 2009>

Odometer reading: km/miles

240170

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-1°00' +/-0°45'	-2°04'
		right			-2°16'
		cross		0°00'	0°12'
	Toe	left		0°05' +0°05' -0°03'	0°23'
		right			-0°01'
		total		0°09' +0°09' -0°05'	0°22'
Geometrical driving axis			0°00'	0°12'	
Front axle	Camber	left		-0°05' +/-0°45'	-0°26'
		right			0°20' 0.20
		cross		0°00'	-0°45'
	Caster	left		4°30' +/-0°45'	4°24'
		right			4°51'
		cross		0°00'	-0°27'
	SAI	left			8°48'
		right			8°47'
		cross		0°00'	0°02'
	Track differential angle	left			
		right			
	Toe	left		0°00' +/-0°05'	-0°13'
		right			2°35' 2.35
		total		0°00' +/-0°09'	2°22'
	Setback			0°00'	
Max steering lock	left steer	left			
		right			
	right steer	left			
		right			

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Katherine
LKK Auto 68411972 68411972

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Registration No : SJV6845E
 Chassis No : JHMRB38509C201535
 Model : ODYSSEY 2.4 EXV AUTO
 Owner's Name : ONG KIAN TONG
 Ins Policy No. : VPA/P1028848
 Date of Accident : 30/10/2018

Document No. : SQT18004713 Page 1
 Date : 2. Nov 2018
 Customer No. : WZA006
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : K24Z21301541
 Date | Time : 2. Nov 2018 2:31:04 PM
 Surveyor Name : DID : +65 6846 5673
 Survey Date : HP : +65 8100 6306
 Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG KIAN TONG OWNER INSURER: AXA INSURANCE S'PORE PTE LTD ACC DATE: 30/10/2018@20.15PM SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SKJ2361L (VOLKSWAGEN/PASSAT/GREY)						

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60

91505-TM8-003	CLIP,BUMPER <i>mer</i>	14	2.30	25	24.15	1.69	25.84
42700-S3N-J31	DISKALUMINIUM WHEEL <i>47</i>	1	842.90	25	632.17	44.25	676.42
33101-SLE-J01	HEADLIGHTR.HID <i>cm</i>	1	796.70	25	597.52	41.83	639.35
04711-SLE-900ZZ	FACEFR.BUMPER <i>D.S</i>	1	748.50	25	561.37	39.30	600.67
71140-SLE-000	BEAMR.FR.BUMPER <i>sel</i>	1	39.90	25	29.92	2.09	32.01
71193-SLE-003	SPACERR.FR.BUMPER <i>sel</i>	1	12.50	25	9.37	0.66	10.03
71130-SLE-000ZZ	BEAMFR.BUMPER <i>11</i>	1	249.50	25	187.12	13.10	200.22
60212-SFE-300ZZ	STAY R FENDER	1	13.00	25	9.75	0.68	10.43
60210-SLE-000ZZ	PANELR.FR.FENDER <i>buc</i>	1	586.40	25	439.80	30.79	470.59
74101-SLE-000	FENDERR.FR INNER <i>bin</i>	1	99.70	25	74.77	5.23	80.00
74105-SLE-000	ENCLOSURER.FR.FENDER	1	20.00	25	15.00	1.05	16.05
			Sum Item		2580.94	180.67	2,761.61

BOSUN	SUNDRIES <i>mer</i>	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	11 X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	mx	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	130	140.00	9.80	149.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11 X	250.00	17.50	267.50



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJV6845E
Chassis No : JHMRB38509C201535
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : ONG KIAN TONG
Ins Policy No. : VPA/P1028848
Date of Accident : 30/10/2018

Document No. : SQT18004713 **Page** 2
Date : 2. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24Z21301541
Date | Time : 2. Nov 2018 2:31:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00	560	1800.00	126.00	1926.00
BKBH12M	CUT OFF & RENEW BULKHEAD FR R WHEELHOUSE. 2 pc	1	2800.00	900	2800.00	196.00	2996.00
Sum Labor					5290.00	370.30	5,660.30

Survey By

Date & Time

Excess

Status

Signature

Total Amount 8,050.94 563.57 8,614.51

Total (Inclusive of GST) 8,614.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/11/2018 2:48:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

◀ Service Request Details

Claim

S8M011DC

Reference

None ✎

Loss Date

October 30, 2018

Request Date

November 2, 2018

Due Date

November 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

0211.2018 C 437pm
Any veh not in
6846 5673 or 81006306

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJV6845E

Make

TPVD HONDA

Model

ODYSSEY-2.4 ABSOLUTE (RB3) (A)

Service Address

Primary Contact/Insured

KIM SONG SIMON CHUA
BLK 132 EDGEDALE PLAINS, #09-28, 820132, Singapore
98248308
SIMONJK39@GMAIL.COM

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



MANDATE IA (S8M011DC)

Type

🔔 Question

Message

Liability: Insured lost control and hit third party parked vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$5,043.97 (w/GST) Loss of Use: \$400.00 (4days x \$100) Total: \$5,443.97 Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (07/03/2019)

Reply



Re:RE: Re:RE: MANDATE IA (S8M011DC)

Type

🔗 Question

Message

MANDATE APPROVED

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKJ 2361L (Insd veh)	Model:	HONDA ODYSSEY (A)
	SJV 6845E (TP veh)		
Date of Accident:	30/10/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,208.27
Final Repair Cost	:	\$	5,043.97
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	5,443.97

Is Third Party Workshop GIA Registered?		☒ YES	☐ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____ _____				

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO. SDN. BHD.	:	\$ 5,443.97

NUR SHAQILAH BTE ABDOL
WAHAB

14/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18020036/Ueb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 14-05-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 2361L	Veh. Inspected	SJV 6845E
Policy No.		Coverage (\$)	0.00
Claim No.	S8M011DC	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	05/11/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMRB38509C201535	Colour	BLACK
Odometer	240168	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R17	YOKOHAMA	3 mm
L/H Front Tyre	215/55R17	YOKOHAMA	3 mm
R/H Rear Tyre	215/55R17	YOKOHAMA	5 mm
L/H Rear Tyre	215/55R17	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2018	Inspection Date	26/11/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 6845E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	20.00
14	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	24.15	24.15
1	DISKALUMINIUM WHEEL (SN) (CONSISTENT)	CUT	733.35	733.35
1	HEADLIGHTR.HID (SN) (CONSISTENT)	CRACKED	597.52	597.52
1	FACEFR.BUMPER (SN) (CONSISTENT)	DISTORTED	561.37	561.37
1	BEAM.FR.BUMPER (SN) (CONSISTENT)	BENT	29.92	29.92
1	SPACERR.FR.BUMPER (SN) (CONSISTENT)	BENT	9.37	9.37
1	BEAMFR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	187.12	-
1	STAY R FENDER (SN) (CONSISTENT)	NOT NECESSARY	9.75	-
1	PANELR.FR.FENDER (SN) (CONSISTENT)	BUCKLED	439.80	439.80
1	FENDERR.FR.INNER (SN) (CONSISTENT)	TORN	74.77	74.77
1	ENCLOSURER.FR.FENDER (SN) (CONSISTENT)	NOT NECESSARY	15.00	-
1	KNUCKLER FR (SN) (CONSISTENT) (ADDITIONAL)	BENT	243.22	243.22
1	BEARING FR HUB (SN) (CONSISTENT) (ADDITIONAL)	BENT	94.50	94.50
1	END COMPR TIE ROD (SN) (CONSISTENT) (ADDITIONAL)	BENT	59.92	59.92
1	END COMPRACK (SN) (CONSISTENT) (ADDITIONAL)	BENT	56.10	56.10
			3,235.86	2,943.99
LABOUR				
	BODY UNDERSIDE COATING.	NOT NECESSARY	100.00	-
	BODY JOINT SEALANT.	NOT NECESSARY	100.00	-
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		140.00	130.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,800.00	560.00
	CUT OFF & RENEW BULKHEAD FR R WHEELHOUSE.		2,800.00	900.00
	WHEEL ALIGNMENT.		180.00	180.00
			-	-
			-	-
			-	-
			5,370.00	1,770.00
GRAND TOTAL			8,605.86	4,713.99

Report Ref No. CC4/ASM18020036/Ueb3s2



RECOMMENDED COST OF REPAIRS			4,713.99
-----------------------------	--	--	----------

Report Ref No. CC4/ASM18020036/Ueb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.