



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

*Katherine
LKK Auto 68411972 68411972*

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJV6845E
Chassis No : JHMRB38509C201535
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : ONG KIAN TONG
Ins Policy No. : VPA/P1028848
Date of Accident : 30/10/2018

Document No. : SQT18004713
Date : 2. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24Z21301541
Date | Time : 2. Nov 2018 2:31:04 PM
Surveyor Name : DID : +65 6846 5673
Survey Date : HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG KIAN TONG OWNER INSURER: AXA INSURANCE S'PORE PTE LTD ACC DATE: 30/10/2018@20.15PM SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SKJ2361L (VOLKSWAGEN/PASSAT/GREY)						
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
			Sum Ext. Service		180.00	12.60	192.60
91505-TM8-003	CLIP,BUMPER <i>me</i>	14	2.30	25	24.15	1.69	25.84
42700-S3N-J31	DISKALUMINIUM WHEEL <i>cu</i>	1	842.90	25	632.17	44.25	676.42
33101-SLE-J01	HEADLIGHTR.HID <i>me</i>	1	796.70	25	597.52	41.83	639.35
04711-SLE-900ZZ	FACEFR.BUMPER <i>D.S</i>	1	748.50	25	561.37	39.30	600.67
71140-SLE-000	BEAMR.FR.BUMPER <i>Sel</i>	1	39.90	25	29.92	2.09	32.01
71193-SLE-003	SPACERR.FR.BUMPER <i>Sel</i>	1	12.50	25	9.37	0.66	10.03
71130-SLE-000ZZ	BEAMFR.BUMPER <i>11</i>	1	249.50	25	187.12	13.10	200.22
60212-SFE-300ZZ	STAY R FENDER	1	13.00	25	9.75	0.68	10.43
60210-SLE-000ZZ	PANELR.FR.FENDER <i>SUC</i>	1	586.40	25	439.80	30.79	470.59
74101-SLE-000	FENDERR.FR.INNER <i>win</i>	1	99.70	25	74.77	5.23	80.00
74105-SLE-000	ENCLOSURER.FR.FENDER	1	20.00	25	15.00	1.05	16.05
			Sum Item		2580.94	180.67	2,761.61
BOSUN	SUNDRIES <i>me</i>	1	100.00	20	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	11X	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	meX	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	140.00	130	140.00	9.80	149.80
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	11X	250.00	17.50	267.50



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SJV6845E
Chassis No : JHMRB38509C201535
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : ONG KIAN TONG
Ins Policy No. : VPA/P1028848
Date of Accident : 30/10/2018

Document No. : SQT18004713
Date : 2. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24Z21301541
Date | Time : 2. Nov 2018 2:31:04 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00	500	1800.00	126.00	1926.00
BKBH12M	CUT OFF & RENEW BULKHEAD FR R WHEELHOUSE. 2pc	1	2800.00	900	2800.00	196.00	2996.00
Sum Labor					5290.00	370.30	5,660.30

Survey By

Date & Time

Excess

Status

Signature

Marcus Hal
26/11/18 @ 10.15am
Not Authorized
to be paid before per. story
4 dy.

Total Amount 8,050.94 563.57 8,614.51

Total (Inclusive of GST) 8,614.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/11/2018 2:48:50 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)