22/03/2002 ASS_REC.BY:	REF: C9/CTU8020	0045 /TIVbez Special Instruction:
Surveyor:	ASSIGNMEN	NT (Office)
From (Person)	ong Onin Klut of	CTL Date/Time: (5112016 1/25pm
Estimated Cos	st:	Bill to:
OD/TP/WS	STTP RES / OD RES / EVA / INV / MV / CS	
To Inspect Ve	hicle No: SLN 2859K	Insured: GBB 83 3K
at Workshop i	n/s <u>Perfumana</u>	Tel: 6319014
of	303 Alexandra Rd	
Policy No:	1081(4) FCOE M2YOMB	Claim No: SNM18DU5 JUUCUZ
Sum Insured:		Excess:
Make of Veh:		D.O.A. 01.11.7018
CA / REV	REP. / REV 24 HRS 'WPI	H.O.D. Endorsement:
Date/Time:	05-11-2018 5-111pm Person Contacted:	Caroline Vehicle IN/OUT
Date/Time	Action/Instruction (/) Estimate	-
	SIN 385K - K	E.
	GBB 8313K - K	
3/1/18	Final fig \$ 13,371.70	Confirmed by email (Red 4568.15, 25

...CLAIM SUBFOLDER...(New Assignment)

ALPHA MEDIA PTE LTD, Co. Reg. No.: 199404690E Main Claimant: TNG WEE KIAT, ID: S7835556E /ehicle Reg. No.: SLN2859K Date of Loss: TP / SNM18D05200C02 Policy/Cover Note No.: Claim Type: /ehicle Reg. No. (Insured): GBB8313K Policy No. (Claimant): Excess: S\$0.00 Repairer: Alexandra - Tel: 63190172/63190174 Alexandra - Tel: 63190172/63190174 Alexandra - Tel: 6256-3561 [Final Rpt due 15/11/2018] DIACK SNOCIATED MAIL RECEIVED There are no mail for this case.	Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
CLAIM SUBFOLDER DETAILS Insured: ALPHA MEDIA PTE LTD, Co. Reg. No.: 199404690E Main Claimant: TNG WEE KIAT, ID: \$7835556E Vehicle Reg. No.: SLN2859K Date of Loss: [18 Months and 4 Day: Reg Date (Man Yr)] DMCVSN3027421801 (Comprehensive) Coverage: 22/04/2018 21/04/2019 Vehicle Reg. No. (Insured): GBB8313K Policy No. (Claimant): Excess: S\$0.00 Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M ASSOCIATED MAIL RECEIVED There are no mail for this case.	Main	05 Nov 2018		16:25				New Assignment		
ALPHA MEDIA PTE LTD, Co. Reg. No.: 199404690E Main Claimant: TNG WEE KIAT, ID: S7835556E Vehicle Reg. No.: SLN2859K Date of Loss: TP / SNM18D05200C02 Policy/Cover Note No.: Claim Type: TP / SNM18D05200C02 Policy/Cover Note No.: TP / SNM18D05200C02 Policy/Cover Note No.: Comprehensive) Coverage: 22/04/2018 21/04/2019 Vehicle Reg. No. (Insured): Excess: S\$0.00 Repairer: Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 15/11/2018] Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M View All Compose There are no mail for this case.		Main		Reference		laim Details	Doc	uments	Show All	
Insured: Main Claimant: TNG WEE KIAT, ID: S7835556E Vehicle Reg. No.: SLN2859K Date of Loss: TP / SNM18D05200C02 Policy/Cover Note No.: TP / SNM18D05200C02 Policy/Cover Note No.: Claim Type: TP / SNM18D05200C02 Policy/Cover Note No.: TP / SNM18D05200C02 Policy/Cover Note No.: Excess: S\$0.00 Repairer: Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M Pigg Date (Man Yr)] DMCVSN3027421801 (Comprehensive) Coverage: 22/04/2018 21/04/2019 S\$0.00 Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Alexandra - Tel: 63190172/63190174 Alexandra - Tel: 6256-3561 [Final Rpt due 15/11/2018] Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M View All Compose There are no mall for this case.	CLAIM S	UBFOLDER DE	TAILS		with the same of t		ı	Created by ins	urerl	
Main Claimant: TNG WEE KIAT, ID: \$7835556E Vehicle Reg. No.: SLN2859K Date of Loss: [18 Months and 4 Day: Reg Date (Man Yr.)] DMCVSN3027421801 (Comprehensive) Coverage: 22/04/2018 21/04/2019 Vehicle Reg. No. (Insured): Fixes: S\$0.00 Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M View All Compose There are no mall for this case.	Insured:		ALPI	A MEDIA PTE LT	D. Co. Reg. N	o.: 199404690E				
Vehicle Reg. No.: SLN2859K Date of Loss: [18 Months and 4 Day: Reg Date (Man Yr)] DMCVSN3027421801 (Comprehensive) Coverage: 22/04/2018 21/04/2019 Vehicle Reg. No. (Insured): GBB8313K Policy No. (Claimant): Excess: S\$0.00 Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M ASSOCIATED MAIL RECEIVED There are no mail for this case.	Main Clair	nant:	THE PERSON NAMED IN COLUMN 1							
Claim Type: TP / SNM18D05200C02 Policy/Cover Note No.: (Comprehensive) Coverage: 22/04/2018 21/04/2019 Vehicle Reg. No. (Insured): Excess: S\$0.00 Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong Ch Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M ASSOCIATED MAIL RECEIVED There are no mall for this case.	Vehicle Re	eg. No.:	SLN	2859K	ı	Date of Loss:		01/11/2018 16:00 - :59 [18 Months and 4 Days Reg Date (Man Yr)]		
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance (Singapore) Pte. Ltd.	Claim Typ	e:	TP /	SNM18D05200	C02	Policy/Cover Note No.	: ((Comprehensive) Coverage: 22/04/2018 -		
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance) LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 15/11/2018] Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M View All Compose There are no mall for this case.	Vehicle Re	g. No. (Insured)	: GBB	3313K		Policy No. (Claimant):				
Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Ong China Taiping Insurance] LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 15/11/2018] Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M View All Compose There are no mall for this case.					E	excess:	5	\$0.00		
Adjuster: Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M Wiew All Compose There are no mail for this case.	Repairer:					andra) 303 Alexandra	Road, Sime Dar	by Performance C	entre, 159941	
Driver/Custodian (Insured): MUNIYASAMY VENKATESAN (28 / Male), NRIC: G2374459M ASSOCIATED MAIL RECEIVED There are no mail for this case.	Handling 1	Insurer:	Chin	a Taiping Insurar	nce (Singapor	e) Pte. Ltd. (HQ) - T	el: 6389 6111	[Handled by Ong	Chin Kiat]	
ASSOCIATED MAIL RECEIVED There are no mail for this case.	the state of the s				Committee of the Commit		* N. A. C.	2 15/11/2018]		
There are no mall for this case.	Driver/Cu	stodian (Insured)	: MUN	YASAMY VENKATE	SAN (28 / Male), NRIC: G2374459	М			
T	ASSOCIA	TED MAIL REC	EIVED				Vic	ew All Com	pose Case Mail	
T	There are	no mall for this	case.							
ALL ASSOCIATED TASKS View All Search Tasks Create New Task	B						-			
	ALL ASS	OCIATED TASK	cs			View All S	earch Tasks	Create New Task	Complete	
Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created Or	Due Da	te Priority	Type Task	Group Subje	ect Handle	r Assigned By	Completed	On Create	d On Done?	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT	
02/11/2018 08:48	
01/11/2018 15:55	
MANDAI ROAD	
SINGAPORE	
DETAILS OF OWN VEHICLE	
	02/11/2018 08:48 01/11/2018 15:55 MANDAI ROAD SINGAPORE

Vehicle Registration Number

SLN2859K

Insured/Policyholder

Name Of Registered Owner

TNG WEE KIAT

NRIC No

S7835556E

Email Address

KLEINXTRE@YAHOO.COM

Mobile Phone No

(LOCAL) +65-81011005

Alternative Phone No

OTHERS-81011005

Vehicle Particulars

Manufacturer

BMW

Model

216AT

Exact Purpose for which vehicle was being used at

time of accident

NORMAL USAGE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

LIBERTY INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

SD17V05803/VPC2/R00

Cover Note Number

Driver

Name of Driver TNG WEE KIAT NRIC No S7835556E

Date Of Birth 04/12/1978 Occupation **INDOOR**

Date Of Driving Pass 25/08/2000

Driving Experience 18 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-81011005

Fax Number

Contact Number OTHERS-81011005

EMail Address KLEINXTRE@YAHOO.COM Address

BLK 23 PUNGGOL FIELD WALK #12-20

Postcode

828750

2000 Men

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

ii ivo, ivelationship of the

.

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

2

NO

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

Passenger 1

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance

NO

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2 NAME:

: ANAND KUMAR

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBB8313K

Vehicle Make/Model/Colour

KIA LORRY WHITE

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

MVNIYASAMY VENKATESAN

NRIC/Passport Number

G2374459M

Contact Number

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 20

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudlate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

oliegholder's signature

100 00

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 151 Nov 2018 at about 3.55pm, a white KIA Long (4BB 8318K) Knocked into ntie
back of my vehicle (SLN 2859K). I was during along Manda Read and at
a traffic punction as the traffic light turned truber I came to a
complete buttoned stop. Shortly after the stop, there my an impact from
my the rear of the relide and the KIA long (GBB \$313K) had taxeted
into my versele. The impact was gutte big as I hit my head against the save
sent.
I was with a pastonger. Mr Amand during the accident is Both of
us algebred the car and spoke to the diver. He was fine with in injuries
The vehicle is owned by ALPHA MEDIA PTE LTD.
j

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: \$1/16/18

6 bus

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

19/11 @ 10 apr

SIN2859K

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303. Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

LKK Auto Consultants hence notify the Repairer of the following:

· To resurvey before/after spray painting

To display damaged wart(s) during resurvey

315, Alexand a asis prices are subject to confirmation
Sime Damby Suriness Centre
Singapore 159900 pany survey is on a "Without Prejudice" basis

Fax. 64796603 Supple Motor Fad (s) must be resurveyed and 64796624 Supple Motor Fad (s) must be resurveyed and is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081 vledged Xv Repairer

Signature:

0.5 NOV 2018

ESTIMAT Edute:

Page No. : 1 of 5

Estimate No.

: b1 48977

Date Estimated Prepared By

: 02/11/2018

: Han Kwan Yong

- ESTIMATE REPAIR FOR -

Tng Wee Kiat

23 Punggol Field Walk

#12-20

ACCOUNT -40000

Cash Sales - Service

Singapore

Singapore 828750

REGN. NO.

CHASSIS NO.

REGN. DATE

MODET.

MILEAGE

SLN2859K

V925792

28/04/2017

216d CAT

0

DESCRIPTION

To replace rear bumper & attac hments, boot lid including to knock out tail panel and dente d caused by the accident

885 1038 ~

To respray rear bumper, boot lid, tail panel, rear left

fender and rear right fender

To carry out body cavity preservation.

(Per panel).

To remove and install rear windscreen glass to transfer

from old to new boot lid

To conduct water leak tests.

To replace bootlid smart opener top and

bottom sensor lines including program and conduct checks for

proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking

system for proper function.

To remove and install boot compartment carpet and garnish

to facilitate repairs.

To check electrical wiring systems and lightings at the

rear section for proper function.

To supply front emboss number plate.

Sundries.

VALUE 3825 2975 4,675.00

39924,436.00

100 118.00

574 516. 574.00

> 75 63. 75.00

NU X 5617 661.00

45 531.00

2 50 271.00

83.00

150.00

Total Labour 1:

PRIC

11,751.00

DESCRIPTION

QTY

VALUE

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

BMV Dealer '

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated Prepared By	: b1 4897 : 02/11/2018 : Han Kwan Y				Page N	0. :	2 of 5	
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL				MILEAGE	
SLN2859K	V925792	28/04/2017	216d CA	r			0	J
DES	CRIPTION			QTY	PRIC		VALUE	1
The state of the s	LIP FOR PLASTIC NUT			10	1.00		Mer 10.00	
	INK LID			1	1,204.35		1,204.35	
	R BUMPER PANEL PRIM	MED (PDC)		1	990.40		de 990.40	
	BUMPER LH SIDE GUIDE			1	49.05		7 49.05	-
	BUMPER RH SIDE GUID			1	49.05		7 49.05	
	R BUMPER CARRIER			1	434.40		7 434.40	
	PORT			1	45.30		de 3 45.30	V
RR I	BUMPER LH INNER SIDE	GUIDE		1	60.05		de 2 60.05	v
RR I	BUMPER RH INNER SID	E GUIDE		1	60.05		de 60.05	
GRO	OMMET			2	0.75		nec 1.50	-
PLA	QUE 74MM			1	71.25		M 71.25	b
BUM	MP STOP			10	3.35		my 33.50	3
COV	ER WINDSCREEN TOP			1	33.10		nex 33.10	
LHI	ORIP MOULDING			1	64.20		ne 1 64.20	
RHI	DRIP MOULDING			1	64.20		MX 64.20	
REA	R FLAP TOWING EYE P	RIMED		1	42.85		de x 42.85	1
CLA	MP			4	2.80		ner 11.20	1
(S/L)	SOUND INSULATION A	PRON L1367M		1	84.35		84.35	
PLU	G BLACK D=5MM			10	0.90		ur 9.00	
SEN	ISOR WIRE FOR SMART	OPENER TOP		1	43.15		M1 2 43.15	
SEN	ISOR WIRE FOR SMART	OPENER BOTTOM		1	41.50		41.50	2
EXP	ANDING NUT 10 (1)	(S)		10	0.55	2	ML 7 5.50	
# LH	GUTTER STRIP			1	49.45		49.45	
	H GUTTER STRIP			1	49.45		2 49.45	
	LH LIGHT IN THE TRUNK			1	245.80		7 245.80	
	RH LIGHT IN THE TRUN			1	245.80		cut 245.80	
	R LH LIGHT IN THE SIDE			1	351.20		351.20	
	RH LIGHT IN THE SIDE F		de ?	1	351.20		m 351.20	
	COUPING RING PDC TOP		Varia /	2	5.05		10.10	
	RASONIC SENSOR GLA	CIERSILBER(WA8	1 XII	2	368.80		? 737.60	
) CLEANER R1 (100ML)			1	26.15		26.15	
(DG	SL) W/SCREEN SEALAI	NT (COLD 1 HOUR)		c~ 2	131.55		263.10	
Claims (SLI GLASS PRIMER 30	AL (VP206) losses / Direct Settlemen	1/ //	0 1	27.85		27.85	١
			30	Tot	al Parts		5,765.65	1
Regn No.	14 11 150 170	Claim No	201	100	ar raits		5,765.65	-
Date&Time	THU ICE ILOS	Excess S\$						-
Surveyor's	Name Taugh	Sign				17	939.85	1
	974949					(1)	(21.02	_
Surveyor's	le Trait	Authorised Tes / No	T.	abour 1	1		11,751.00	7
Authorised	Date	Time	190	arts .			5,765.65	
DESLIBVE	Y PARTS PHOTO BY SURVEYO	R(Ye)/No PML Yes/No					0.00	- 1
-	laubh.	Manforon.		abour 2	4	:		- 1
Surveyor's	E-mail Troydin	7 - And - Pr	14	xcess		8	0.00	- 1
No. of Wor	king Days Recommend	tous -or	T C	otal GS	ST @ 7%	:	1,226.17	
			U G	rand To	otal	:	18,742.82	

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admir 63190111 (AfterSales) Pax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944

Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1** 48977 Page No. : **3 of 5**

Date Estimated : 02/11/2018
Prepared By : Han Kwan Yong

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SLN2859K V925792 28/04/2017 216d CAT 0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- 2. The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- 4. The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- 5. The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- 6. PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- 7. Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- 8. Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- 9. The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- 10. If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- 11. If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- 12. PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- 13. These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- 14. If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941


Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

BMW Dealer

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

(Motorrad Fax. 64796601 64796624 (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48977 Page No. : 4 of 5

Date Estimated : 02/11/2018

Prepared By : Han Kwan Yong

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SLN2859K V925792 28/04/2017 216d CAT 0

- 15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
- 16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
- 17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
 - The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
 - (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore
 - 17.2 The Vendor shall also disclose the Customer's personal data:
 - (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides:
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
 - The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any 17.3 contractual arrangements or under any applicable law, whichever is later.
 - 17.4 If the Vendor amends any provision in this clause17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
 - 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
 - The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
 - (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



BMW Dealer 9 4

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSa: 63190533/530 (Motorra

Fax. 64796601 64796624

(AfterSales) (Motorrad) (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 48977

: 02/11/2018

Prepared By

Date Estimated

: Han Kwan Yong

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SLN2859K

V925792

28/04/2017

216d CAT

0

Page No. : 5 of 5

- The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
 - (a) put his request in writing:
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.

The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.

- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
 - (a) put his request in writing by way of an email sent to the Vendor,
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer Performance Motors Limited

Address Sime Darby Performance Centre 303 Alexandra Road Singapore 159941

Email address: dataprotection@pml.com.sg

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No.

b1 48977

Date Estimated

02/11/2018

Prepared By

Han Kwan Yong

REPAIR FOR -

- ACCOUNT -

135 China Taiping Insurance (S) Pte Ltd

Page No. :

Tng Wee Kiat

23 Punggol Field Walk

3 Anson Road

#12-20

#16-00 Springleaf Tower

Singapore 079909

Singapore 828750

REGN NO

CHASSIS NO

REGN DATE

MODEL

M LEAGE

216d CAT

V925792 28/04/2017 SLN2859K ORIGINAL PRICE DISC. % NETT DESCRIPTION 3825.00 3,825.00 To replace rear bumper and attachments, trunk lid and attachments, rear LH/RH light in side panels include making good the tail end panel, rear LH/RH fenders and knocking out dents caused by the accident To respray rear bumper, trunk lid, tail end panel, rear LH 3992.00 3,992.00 fender and rear RH fender 100.00 100.00 To carry out body cavity preservation. (Per panel). 574.00 * To remove and install rear windscreen glass to 574.00 facilitate repairs 75.00 * To conduct water leak tests 75.00 To transfer lock mechanism from old to new trunk lid 451.00 451.00 include conducting checks on new trunk lid central locking system for proper function 230.00 230.00 To remove and install boot compartment carpet and garnish to facilitate repairs 150.00 To check electrical wiring systems and lightings at the 150.00 rear section for proper function. 150.00 150.00 Sundries.

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
C CLIP FOR PLASTIC NUT	1.00	10.00		10.00
# BLIND RIVET NUT M6 *	2.55	1.00		2.55
# BLIND RIVET NUT M6 *	2.55	2.00		5.10
TRUNK LID	1,204.35	1.00		1,204.35
REAR BUMPER PANEL PRIMED (PDC)	990.40	1.00		990.40
EXPANDING NUT	1.00	2.00		2.00
SUPPORT	45.30	1.00		45.30
RR BUMPER LH INNER SIDE GUIDE	60.05	1.00		60.05

A member of the Sime Darby Group Co, Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

RR BUMPER RH INNER SIDE GUIDE	60.05	1.00	60.05
GROMMET	0.75	2.00	1.50
PLAQUE 74MM	71.25	1.00	71.25
# BOOT LID/TAILGATE PUSH BOTTON ICAM *	48.40	1.00	48.40
# REAR VIEW CAMERA COVER (ICAM) *	15.95	1.00	15.95
BUMP STOP	3.35	10.00	33.50
PLUG BLACK D=5MM	0.90	10.00	9.00
RR RH LIGHT IN THE TRUNK LID	245.80	1.00	245.80
RR LH LIGHT IN THE SIDE PANEL *	351.20	1.00	351.20
RR RH LIGHT IN THE SIDE PANEL	351.20	1.00	351.20
(DG) CLEANER R1 (100ML)	26.15	1.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	9,547.00
Total Parts:	3,824.70
Total Labour & Parts :	13,371.70
Deduction for Excess:	0.00
Total Repair Costs less Excess:	13,371.70
GST @7%:	936.02
Grand Total:	14,307.72

A member of the Sime Darby Group Co, Reg. No. 197401559W, GST Reg. No. M2-0020081-X

5



SUPPLEMENTARY

Estimate No.

ы 48977

Dat e Est i mat ed : 02/11/2018

Prepared By : Han Kwan Yong

REPAIR FOR -

- ACCOUNT -

135

Page No. :

Tng Wee Kiat

23 Punggol Field Walk

#12-20

China Taiping Insurance (S) Pte Ltd 3 Anson Road

ORIGINAL PRICE

#16-00 Springleaf Tower Singapore 079909

Singapore 828750

REGN NO

CHASSIS NO

REGN DATE

MODEL

M LEAŒ

SLN2859K

DESCRIPTION

V925792

28/04/2017

216d CAT

DISC. %

NETT

423.20

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2,55	1.00		2.55 ML
# BLIND RIVET NUT M6 *	2.55	2.00		5.10 mes
# BOOT LID/TAILGATE PUSH BOTTON ICAM *	48.40	1.00		48,40 de/
* REAR VIEW CAMERA COVER (ICAM) *	15.95	1.00		15.95 de
RR LH LIGHT IN THE SIDE PANEL *	351.20	1.00		351.20 Repeated

Total Labour: 423.20 Total Parts: Total Labour & Parts:

Finalised by: Caroline DID: 63190174 Fax: 64794601

Veron Chen (IKKAuto)

From: Sent: To: Cc: Subject:	Veron Chen (LKKAuto) Thursday, 3 January 2019 11:29 'PBSP'; Keith Leo Chi Yung; Share SUR; Toh Jing Xuan RE: FINAL REPORT / SLN2859K		
Dear Caroline,			
WITHOUT PREJUDIC	Œ		
Confirmed \$13,371.70	before GST @ 7 working days.		
Best Regards,			
Veron Chen Case Handler			
LKK Auto Consultants Pte Lt	td		
Phone: 6256-3561 email :s	sur@lkkauto.com fax: 6256-4315		
Blk 51, Paya Ubi Industrial P	ark, Ubi Avenue 1, #02-25 S(408933)		
<sharon.heng.leekun@sir< th=""><td>nber 2018 4:05 PM eith.leo.chiyung@simedarby.com.sg>; Sl medarby.com.sg>; Han Kwan Yong <han. m>; Toh Jing Xuan <toh.jing.xuan@simeo m></toh.jing.xuan@simeo </han. </td><td>kwan.yong@simedarby.com.sg></td><td></td></sharon.heng.leekun@sir<>	nber 2018 4:05 PM eith.leo.chiyung@simedarby.com.sg>; Sl medarby.com.sg>; Han Kwan Yong <han. m>; Toh Jing Xuan <toh.jing.xuan@simeo m></toh.jing.xuan@simeo </han. 	kwan.yong@simedarby.com.sg>	
Dear All			
Please assist to send be	efore paint photographs ASAP.		
Thank you.			
Regards, Caroline			

Sent: Wednesday, 26 December 2018 10:29:26 AM

To: PBSP; Keith Leo Chi Yung

Cc: SUR

Subject: RE: FINAL REPORT / SLN2859K

Dear Keith,

Please assist to forward us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 18 December 2018 1:45 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com >; Keith Leo Chi Yung < keith.leo.chiyung@simedarby.com.sg >

Cc: SUR <sur@lkkauto.com>

Subject: Re: FINAL REPORT / SLN2859K

Dear Keith

Please assist to forward before paint to surveyor soonest.

Thank you.

Regards, Caroline

From: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Sent: Monday, 17 December 2018 10:38:46 AM

To: Keith Leo Chi Yung; PBSP

Cc: SUR

Subject: FW: FINAL REPORT / SLN2859K

Dear Caroline/Keith,

Kindly forward us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 13 December 2018 4:22 PM

To: PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: FW: FINAL REPORT / SLN2859K

Dear Caroline/Keith,

Kindly forward us before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg> Sent: Thursday, 13 December 2018 1:21 PM

To: Taufikh (LKKAuto) < Taufikh@lkkauto.com >; SUR < sur@lkkauto.com >

Subject: FINAL REPORT / SLN2859K

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 9,547.00 Total Parts : 3,824.70

Total Labour & Parts: 13,371.70

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	9	itatus	
Main	05 Nov 2018		05 Nov 2018 16:25 Edit Adj Rpt	S\$13,371.70 Edit Estimates	11 11 11 11	3,371.70 ew Rpt			Pending for Report Cancel Case	4
	Main	R	eference	Claim De	tails		Docume	nts	٦.	Show All
CLAIM SUI	BFOLDER DE	TAILS	- State of the little of the l			[Created b	oy insurer]			
Insured:	ALPHA M	EDIA PTE LTD,	Co. Reg. No.: 19940	4690E						
Main Claimant:	TNG WEE	KIAT, ID: S78	35556E							
Vehicle Reg. No.:	SLN285	9К		Date of	Loss:		16:00 - :59 and 4 Days Fr	om LTA	Reg Date (M	lan Yr)]
Claim Type:	TP / SNN	118D05200C02		Policy/C Note No			27421801 (Cor 22/04/2018 - 2			
Vehicle Reg. No. (Insured):	GBB8313	ĸ		Policy N (Claima						
				Excess:		S\$0.00				
Repairer:	Performa 63190172	nce Motors Limit 63190174	ted (Alexandra) 30	3 Alexandra Road,	Sime I	Darby Perforn	nance Centre,	159941	Alexandra -	Tel:
Handling Insurer:	China Tai	ping Insurance ((Singapore) Pte. L	td. (HQ) - Tel: 638	9 6111	1 [Handled	by Ong Chin	Kiat]		
Adjuster:	15/11/20		Ltd (HQ) - Tel: 62	56-3561 [Handle	d by M	OHD TAUFI	KH BIN HAM	ID] [I	Final Rpt	due
Driver/Custo dian (Insured):		MY VENKATESAN	(28 / Male), NRIC	: G2374459M						
ASSOCIAT	ED MAIL RE	CEIVED			130		1	View All	Compos	Case Mail
There are no	mail for this	case.					_			
ALL ASSO	CIATED TAS	ks⊟			1	View All S	earch Tasks	Create	New Task	Complete
Due Date	Priority	Type Task	Group Subjec	t Handler /	Assign	ned By	Completed O	n (Created On	Done

Claim Documents

*SLN2859K (SNM18D05200C02)

[GBB8313K]

TP

TNG WEE KIAT

Nov 1 2018 4:00PM

[ALPHA MEDIA PTE LTD]

Performance Motors Limited

Uţ	pload Documents U	oload Photos Compose New Letter	View	View in Brow	ser 🗸
Pho	otos/Images		3 per p	page 🔻	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/01/19 11:42	General View	0	Load PDF	
Doc	cumentation		1 per p	page 🔻	V
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/11/18 11:44	ESTIMATE	0	Load PDF	
2	05/11/18 11:44	TP REPORT	0	Load PDF	
3	05/11/18 11:44	INSD REPORT	0	Load PDF	
4	05/11/18 16:25	email from PML to check liability & arrange SJE survey	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/01/19 11:30	Supplementary	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer			

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18020045/T1VBE2

Date:

07/01/2019

Claim

No:

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN3027421801

Claimant Vehicle No:

SLN2859K

Insured Vehicle No:

Nature of Claim: TP

GBB8313K

Date of Loss:

01/11/2018

SNM18D05200C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLN2859K

Make & Model:

BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A) Engine No:

Chassis No:

34569888B37C15A

Reg. Date: Colour:

Silver

28/04/2017 (Man. Year: 2017) Odometer:

WBA2B32010V925792 29713 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

No

205/60 R16

Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,421.85	3,974.70	2,447.15	38.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,518.00	9,397.00	2,121.00	18.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,939.85	13,371.70	4,568.15	25.46
+ GST 7.00/7.00% (S\$)	1,255.79	936.02	319.77	25.46
Nett Amount (S\$)	19,195.64	14,307.72	4,887.92	25.46

INSPECTION

Date of Assignment:

05/11/2018

Date Inspected:

19/11/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

7.0 days

Adjuster Report Page 2 of 5

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2019)

Parts: M1-MPV BMW 216D 1.5 D Active Tourer (F45) D/AB LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN2859K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Not Necessary	83.00 FS	*- FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	10		*C CLIP FOR PLASTIC NUT	Necessary	10.00 FS	*10.00 FS
4	1		*TRUNK LID	Bent	1,204.35 FS	*1,204.35 FS
5	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	990.40 FS	*990.40 FS
6	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	49.05 FS	*- FS
7	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	49.05 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	434.40 FS	*-FS
9	1		*SUPPORT	Deformed	45.30 FS	*45.30 FS
10	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	60.05 FS	*60.05 FS
11	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	60.05 FS	*60.05 FS
12	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
13	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
14	10		*BUMP STOP	Necessary	33.50 FS	*33.50 FS
15	1		*COVER WINDSCREEN TOP	Not Necessary	33.10 FS	*- FS
16	1		*LH DRIP MOULDING	Not Necessary	64.20 FS	*- FS
17	1		*RH DRIP MOULDING	Not Necessary	64.20 FS	*- FS
18	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	42.85 FS	*- FS
19	4		*CLAMP	Not Necessary	11.20 FS	*- FS
20	1		*(S/L) SOUND INSULATION APRON L1367M	Not Necessary	84.35 FS	*- FS
21	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
22	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	43.15 FS	*- FS
23	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	41.50 FS	*- FS
24	1		*#LH GUTTER STRIP	Not Necessary	49.45 FS	*-FS
25	1		*RR LH LIGHT IN THE TRUNK LID	Not Necessary	245.80 FS	*- FS
26	1		*RR RH LIGHT IN THE TRUNK LID	Cut	245.80 FS	*245.80 FS
27	1		*#RR LH LIGHT IN THE SIDE PANE	Cut	351.20 FS	*351.20 FS
28	1		*RR RH LIGHT IN THE SIDE PANEL	Cut	351.20 FS	*351.20 FS
29	2		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	10.10 FS	*-FS
30	2		*ULTRASONIC SENSOR GLACIERSILBER (WA8	Not Necessary	737.60 FS	*-FS
31	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
32	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
33	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
34	1		*BLIND RIVET NUT M6	Necessary	2.55 FS	*2.55 FS
35	2		*BLIND RIVET NUT M6	Necessary	5.10 FS	*5.10 FS
36	1		*BOOT LID / TAILGATE PUSH BOTTON ICAM	Deformed	48.40 FS	*48.40 FS
37	1		*REAR VIEW CAMERA COVER (ICAM)	Deformed	15.95 FS	*15.95 FS
38	1		*RR LH LIGHT IN THE SIDE PANEL	Repeated	351.20 FS	*-FS
39	1		*EXPANDING NUT (10PCS)	Necessary-2PCS	5.50 FS	*2.00 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40 1 *#RH GUTTER STRIP F=Franchise part. S=SpcNett.		*#RH GUTTER STRIP	Not Necessary	49.45 FS	*- FS
		part. S=SpcNett.	Total Parts (S\$) 6,421.85		3,974.70
		Report was unsubmi	tted during this print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED CAUSED BY THE ACCIDENT	New	4,675.00	3,825.00
2	TO RESPRAY REAR BUMPER, BOOT LID, TAIL PANEL, REAR LEFT FENDER AND REAR RIGHT FENDER	New	4,436.00	3,992.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	0.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
8	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
9	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labou	Cost (S\$)	11,518.00	9,397.00
	Report was unsubmitted during	his print-out.		

< END OF ESTIMATES >