

ASS. REC. BY:

REF: CS/CT18020046/Ksbnz2

Special Instruction:

Surveyor

Kinneth

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CT1

Date/Time:

05/11/2018 4:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 9825D

Insured:

YP 788JC

at Workshop m/s

Cheng Hoe

Tel:

6755 6142

of

Blk TORI Yishun Ind Park A # 01-37H

Policy No:

PMCVSN F 3868 1801

Claim No:

SNM18005219002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/12/2018

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

05.11.2018 5:58pm

Person Contacted:

June

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJT 9825D - NS/TNC16007719/H11602

QA: 240416

YP 788JC - X

11/3 1 Day 818000 Car from E Road

ASS. REC. BY:

REF:

C721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STT 9825D

Yr Regn:

01, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Allion

c.c

1.896

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

110750

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NET 260 303 6395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

2/1/18

D.O.I.

3/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

0/1/18

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/11

File pass to Catherine

(\$495.00

Red. 22%)

RECEIVED 11 MAR 2019

Date/Time, File Pass to?

11/03/19

☐

: Prel. Report

1)

Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

220

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

1,800 - H.S.)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Nov 2018 Sendback Est	05 Nov 2018 10:59 S\$2,295.00	05 Nov 2018 16:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: AES FACADE PL, Co. Reg. No.: -									
Main Claimant: LIM JEE CHWEN,ALEX, ID: S8216717Z									
Vehicle Reg. No.:	SJT9825D	Date of Loss:	02/11/2018 10:00 - :59 [117 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05219C02	Policy/Cover Note No.:	DMCVSN1738681801						
Vehicle Reg. No. (Insured):	YP2882C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/11/2018]								
Driver/Custodian (Insured):	SATHANAM MURUGESAN (/ Male), Tel: +6597153668								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SGCARMART.COM

Login Sign up

New Cars Used Cars Sell My Car Directory Products Insurance Articles Forum Resources



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Toyota Allion

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Allion 1.5A

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



X

Toyota Allion 1.5A

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$16,888	
Depreciation	\$12,190 /yr	View models with similar depreciation
Reg Date	18-Jun-2009	(7mths 15days COE left)
Manufactured	2008	
Mileage	188,988 km (20.1k /yr)	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	
Power	81.0 kW (108 bhp)	View specs of the Toyota Allion (2007-2012)
Curb Weight	1,200 kg	
Features	CVT Auto Transmission, Auto Climatic Aircon Control, Keyless Entry.	
Accessories	Leather Seats, Reverse Sensors Ad Camera, 2 DIN Pioneer DVD Player And Polaroid Dashboard Camera.	
Description	Excellent Condition. Just Serviced Oil Change, Oil Filter, Air Filter, Spark Plugs, Aircon Air Filter, Etc.	
COE	\$8,501	
OMV	\$18,607	
ARF	\$18,607	
Dereg Value	\$9,832 as of today (change)	
No. of Owners	3	
Type of Veh	Mid-Sized Sedan	
Category	PARF Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 20-Oct-2018 | Last Updated on: 27-Oct-2018

Tags: Toyota Allion, toyota allion, 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, allion, Used Toyota



Seller Information

Contact Person(s) Abdul Rahim

Contact No. 98194869

Enquiry ☐ Contact Seller

USEFUL FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$5,066 (change)	Maximum 70% Loan
1st Instalment	\$1,718	
Total Upfront Payment	\$6,809 (excluding insurance)	

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Toyota Allion

» View All



Compare

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6717Z
Vehicle Details	
Vehicle No.:	SJT9825D
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZD269330
Chassis No.:	NZT2603036395
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$17,394.00
Original Registration Date:	12 Jan 2009
First Registration Date:	12 Jan 2009
Transfer Count:	3
Actual ARF Paid:	\$17,394.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2019
PARF Rebate Amount:	\$8,697.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$5,001.00
COE Rebate Amount:	\$95.00
Total Rebate Amount:	\$8,792.00

The information contained herein is correct as at 02 Nov 2018

OK

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
AES FACADE PL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	T/CHINA
Policy No:		Date of Loss:	02/11/2018
Vehicle Reg. No.:	SJT9825D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	SATHANAM MURUGESAN		
Make/Model:	TOYOTA ALLION, 1.5 (A)	Vehicle Reg. Date:	12/01/2009
Vehicle Colour:	WHITE		
Engine No:	1N2D269330	Chassis No:	NZT2603036395
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not Authorised
 1/11/18 @?
 Recovery After Repair
 4 days*

COST OF CLAIMS	Amount
Parts	1,245.00
Miscellaneous Items	0.00
Labour	1,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,295.00
+ GST 7.00% (S\$)	160.65
Nett Amount (S\$)	2,455.65

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SJT9825D

TP/china

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts: 143 TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SJT9825D/05/11/2018 10:59
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*185.00 F ✓
2	1		*FRONT BUMPER CLIPS	0.00	0.00	*12.00 F ✓
3	1		*RH HEADLAMP	0.00	0.00	*290.00 F ✓
4	1		*FRONT GRILLE	0.00	0.00	*205.00 F ✓
5	1		*FRONT GRILLE CLIPS	0.00	0.00	*8.00 F ✓
6	1		*FRONT RH FENDER	0.00	0.00	*230.00 F ✓
7	1		*FRONT WIPER TANK	0.00	0.00	*35.00 F X
8	1		*AIRCON CONDENSOR	0.00	0.00	*280.00 F ✓

F=Franchise part.

Total Parts (\$\$)

1,245.00

Cheng Hoe Motor Pte Ltd/SJT9825D/05/11/2018 10:59. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE AND REFIT FRONT BUMPER ASSY, GRILLE, FOGLAMPS, FRONT RH FENDER AND REALIGN THE SAME. REPAIR HEADLAMP WIRE HARNESS.	New	400.00 360 ✓
2	REMOVE AND REFIT AIRCON, CHECK, VACUUM AND REFILL AIRCON GAS	New	50.00 ✓
3	PUTTY AND RESPRAY ON BONNET, FRONT RH FENDER AND FRONT BUMPER.	New	600.00 ✓
④ Towing - \$50 ✓			
Gross Labour Cost (\$\$)			1,050.00

Cheng Hoe Motor Pte Ltd/SJT9825D/05/11/2018 10:59. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

<END OF ESTIMATES>

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



24 Hours Towing Services

Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 21663

CASH SALE / JOB ORDER

Date: 2/11/18

Messrs: Cash
车牌 SJT9825D 车型 Toyota
Vehicle No. SJT9825D Model No: Toyota
时间 (日/夜) 2/11/18 联络号码 85115775
Time (day/night): 2/11/18 Contact No: 85115775
由 Northlink 03-43
Location: Northlink 03-43
到 Yeshun
To: Yeshun
银额 501 其他 Others:
Cash \$ 501
经手人 Authorised By:
Authorised By: Driver Name:

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18020046/KSBN2

Date: 11/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1738681801
Claimant Vehicle No :	SJT9825D	Insured Vehicle No :	YP2882C
Date of Loss:	02/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05219C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9825D	Engine No:	1NZD269330
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603036395
Reg. Date:	12/01/2009 (Man. Year: 2008)	Odometer:	110750 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R16	Rear Tyre Size:	195/65R16
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,245.00	1,210.00	35.00	2.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	1,060.00	-10.00	-0.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,295.00	2,270.00	25.00	1.09
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	2,295.00	1,800.00	495.00	21.57
+ GST 7.00/7.00% (\$\$)	160.65	126.00	34.65	21.57
Nett Amount (\$\$)	2,455.65	1,926.00	529.65	21.57

INSPECTION

Date of Assignment:	05/11/2018 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	05/11/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun Industrial Park A
		Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2019)
Parts: 143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT9825D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	185.00 F	*185.00 F
2	1		*FRONT BUMPER CLIPS	Necessary	12.00 F	*12.00 F
3	1		*RH HEADLAMP	Broken	290.00 F	*290.00 F
4	1		*FRONT GRILLE	Cracked	205.00 F	*205.00 F
5	1		*FRONT GRILLE CLIPS	Necessary	8.00 F	*8.00 F
6	1		*FRONT RH FENDER	Bent	230.00 F	*230.00 F
7	1		*FRONT WIPER TANK	Serviceable	35.00 F	*- F
8	1		*AIRCON CONDENSOR	Punctured	280.00 F	*280.00 F
Total Parts (S\$)					1,245.00	1,210.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT FRONT BUMPER ASSY, GRILLE, FOGLAMPS, FRONT RH FENDER AND REALIGN THE SAME. REPAIR HEADLAMP WIRE HARNESS.	New	400.00	360.00
2	REMOVE AND REFIT AIRCON, CHECK, VACUUM AND REFILL AIRCON GAS	New	50.00	50.00
3	PUTTY AND RESPRAY ON BONNET, FRONT RH FENDER AND FRONT BUMPER.	New	600.00	600.00
4	TOWING	New	-	50.00
Gross Labour Cost (\$\$)			1,050.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >