

INSURANCE

INS. CASE OWNER:

JACHIN

CC 3

/AIG18020047

TI 1/339

LKC

IDAC

Surveyor:

THUMKHA

DOI:

ASSIGNMENT

09/11/18

Date / Time:

5/11/18

Registered in Merimen:

5/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

EE 1623K

Name of Insured:

PRINCE PRINCE WEE MYE

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A:

20/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

910562576556

Policy No.:

2100756804

Make / Model:

LAND ROVER

Place of Accident:

BET HARTOR WEST AVE 8

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

5/11/18



INSRS:
WSP:
Tel:
Liability:
RMKS:

Minimum



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
9/11/18	Non-Reporting 1st (1st)	
	Non-Reporting 1st (2nd)	
	Non-Reporting 1st (Final)	
	Notification 1st (if non-pickup)	
	Call OI	13/11/18 - 26/10/18 - vic
	After call 1st to OI	
13-11-18	Documentation Check List: Handler	Typist
	Notification 1st (if non-pickup)	
	After call 1st to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	
PRELIMINARY ADVICE	Date/Time:	Sent By:
	26/10/18	CONFIRMED MANDATE TO LOB
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: L19	\$S 10,000.00	7 days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	% 100	(Assessed / Assessed) BOLA S/N No. : 24
Repair Cost (w/ass)	\$S 10,700.00	
Loss of Rental (LOR):	\$S	(days)
Loss of Use (LOU):	\$S 800.00	100 x 8 days)
Loss of Income (LOI):	\$S	(5 x days)
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	(Tick only one)
GIA/TA Search	\$S 2.00	
Medical:	\$S	
Disbursement:	\$S	(e.g. Tow/Independent)
Legal Cost	\$S	
Total:	\$S 11,502.00	Global Sum \$S: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S 10,702.00	Name 1: PREMIUM AUTOCARE CENTRE
Payee 2: (Strike if N.A.)	\$S 800.00	Name 2: LONG JACK
Payee 3: (Strike if N.A.)	\$S	Name 3: -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18020047/jb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-11-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EE 1623K	Veh. Inspected	SLU 7341S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/11/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/10/2018	Inspection Date	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0051/2018/GW
Date : 8-Nov-18

Vehicle IN workshop . Kindly arrange for survey.

Your insured vehicle number : EE 1623 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6841 0055 - Fax 6256 4315

Owner's Name : Mr. Lyons Jack
Address : 53 Grange Road
01-04 Sprine Grove
Singapore 249566
Telephone : (HP) 96423660
Type of Claim : Third Party Claims
Policy No. : 5099580823
Vehicle No : **SLU 7341 S**
Model Code : Audi A4 2.0 TFSI Qu
Model / Year : Jul-11
Engine No : CDN 194037
Chassis No : WAUZZZ8K5BA154561
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Oct-18
Place of Accident : Bukit Batok Rd West B , West Crest

Tayfun 9795749
WP
9/11/18 E1015
Resurvey before print
sure 11khand.com
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SLU 7341 S

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlights washer assy.	\$ 120.00 ^{60.}
2	To remove and renew aircon condenser, coolant with oil cooler. To carry out vacuum/ regas and to pressurise cooling system.	\$ 250.00 ^{✓ ?}
3	To dismantle and renew front bumper, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,000.00 ^{700. 1650.}
4	To respray front bumper and bonnet.	\$ 600.00 ⁵⁰⁰
5	To carry out diagnostic check.	S/N \$ 100.00 [✓]
TOTAL LABOUR CHARGES		: <u>\$ 3,070.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	FRONT BUMPER	\$	2,394.00 <i>ok</i>
2	FRONT VENT GRILLE <i>for grille RH</i>	\$	118.00 <i>mis</i>
3	RADIATOR GRILLE	\$	595.00 <i>can</i>
4	FRONT BUMPER SUPPORT-LH/RH	2 \$	48.00 ?
5	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$	74.00 X
6	FRONT BUMPER COVER	\$	109.00 ?
7	SIGN 'CAUTION'	\$	12.00 ?
8	FOAM FILLER PIECE	\$	107.00 ?
9	FRONT BUMPER SIDE REINFORCEMENT	\$	770.00 ?
10	FRONT BUMPER TRIM	\$	84.00 <i>can</i>
11	HEADLIGHT-LH/RH	2 \$	3,836.00 ? <i>LH Xun, RH can</i>
12	HEADLIGHT MOUTING-LH/RH	2 \$	206.00 X <i>un</i>
13	HEADLIGHT BRACKET-LH/RH	2 \$	136.00 X <i>un</i>
14	BONNET	\$	1,654.00 <i>bl</i>
15	BONNET ATTACHMENT PARTS	\$	144.00 ?
16	BONNET LID HINGE-LH/RH	\$	130.00 ?
17	BONNET CATCH HOOK	\$	122.00 ?
18	BONNET GAS FILLED STRUT	\$	105.00 ?
19	BONNET EDGE PROTECTION	2 \$	48.00 ?
20	BONNET LID LOCK WITH MICRO SWITCH	\$	188.00 ?
SUB- TOTAL SPARE PARTS CHARGES			\$ 10,880.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S.

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>		<u>S/Nett</u>
21	BONNET LID LOCK CABLLE	\$	43.00 ? X un
22	STICKER FOR AIR CONDITIONER	\$	17.00 ? X un
23	LOCK CARRIER WITH COOLANT RADIATOR MOUNTING	\$	891.00 ? OK ✓
24	AIR GUIDE-LH/RH	2 \$	46.00 ? X un
25	A/C CONDENSOR	\$	651.00 ? b1 ✓
26	A/C SCHRADER VALVE	\$	46.00 ? X un
27	PRESSURE SENDER	\$	165.00 ? X un
28	COOLANT RADIATOR WITH OIL COOLER	\$	1,206.00 ? b1 ✓
29	RADIATOR UPPER BUSH	2 \$	12.00 ? un ✓
30	RADIATOR LOWER BUSH	2 \$	6.00 ? un ✓
31	READY-MIX COOLANT - 1.5 LTR	4 \$	82.00 ? un ✓
32	INSCRIPTION "S-LINE"	2 \$	215.00 ? X un
33	CAMSHAFT ADJUSTER MAGNET	\$	161.00 ? X un
34	FLAT CONTACT HOUSING	\$	9.00 ? X un
35	FRONT NO. PLATE	S/N \$	25.00 ? net ✓
36	SUNDRIES	\$	100.00 ? 53.80 net ✓
TOTAL SPARE PARTS CHARGES		:	\$ 14,555.00
TOTAL LABOUR CHARGES		:	\$ 3,070.00
GRAND TOTAL		:	\$ 17,625.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

18,097.00
+ SUPP

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PAC/TP/0051/2018/GW 16-Nov-18 Kee Siang 1 of 1 SLU 7341 S Audi A4 2.0 TFSI Qu
Quantity	Description	Unit Price	Amount
Parts			
1	Outside Temperature Sensor Bracket	\$ 16.00	\$ 16.00
2	Headlight Mounting Bracket	\$ 103.00	\$ 103.00
3	Radiator Holder	\$ 45.00	\$ 45.00
4	Front bumper Top cover	\$ 109.00	\$ 109.00
5	Bonnet Edge protection	\$ 48.00	
6	Catch Hook	\$ 122.00	\$ 122.00
7	"Caution" Sign Sticker	\$ 12.00	\$ 12.00
8	Air cond Sticker	\$ 17.00	\$ 17.00
TOTAL		\$ 472.00	\$ 424.00

For Premium Automobiles Pte Ltd

Authorised Signature



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

audi a4 2.0

Price Range

Depreciation

2011

Vehicle Type

\$

Home » Used Cars » Direct Owners » Audi A4 2.0A TFSI Quattro S-tronic S-Line

Audi A4 2.0A TFSI Quattro S-tronic S-Line

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$48,500		
Depreciation ⓘ	\$13,180 /yr View models with similar depre	Reg Date	29-Apr-2011 (2yrs 18days COE left)
Mileage	150,000 km (18.9k /yr)	Manufactured ⓘ	2011
Road Tax ⓘ	\$1,194 /yr	Transmission	Auto
Dereg Value ⓘ	\$37,038 as of today (change)	OMV ⓘ	\$42,919
COE ⓘ	\$55,001	ARF ⓘ	\$42,919
Engine Cap	1,984 cc	Power	155.0 kW (207 bhp)
Curb Weight ⓘ	1,565 kg	No. of Owners ⓘ	2
Type of Vehicle	Luxury Sedan		



Features

A4 2.0 TFSI Quattro S-Line. Power154kW (207 Bhp). Torque 350 Nm. S-tronic. Dynamic Sports Mode Full Service Records. From Premium Auto. [View specs of the Audi A4 \(2005-2007\)](#)

Accessories

S-LINE Bodykit. 18 Inch Rims. Blackvue Cam. Full Upgrade Dealer Options. New Brake Discs/pads. Recently Replaced Tires. Very Well Maintained Unit.

Description

Sports Sedan That Offers An Involving Drive Experience In Dynamic Mode. Suitable For Family And Yet Not A Boring Drive. All Necessary Maintenance Done.

Category

PARF Car, Direct Owner Sale

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Foreign Identification Number

Owner ID: 1980L

Vehicle Details

Vehicle No.: SLU7341S

Vehicle to be Exported: No

Intended Deregistration Date: 10 Apr 2019

Vehicle Make: AUDI

Vehicle Model: A4 2.0 TFSI QU S-TRONIC

Primary Colour: Brown

Manufacturing Year: 2011

Engine No.: CDN194037

Chassis No.: WAUZZZ8K5BA154561

Maximum Power Output: 155.0 kW (207 bhp)

Open Market Value: \$42,881.00

Original Registration Date: 28 Jul 2011

First Registration Date: 28 Jul 2011

Transfer Count: 2

Actual ARF Paid: \$42,881.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Jul 2021

PARF Rebate Amount: \$25,728.00

Intended COE Rebate Details

COE Expiry Date: 27 Jul 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$68,811.00

COE Rebate Amount: \$15,725.00

Total Rebate Amount: \$41,453.00

The information contained herein is correct as at 10 Apr 2019

OK



Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Bodyshop Repair Manager

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0051/2018/GW
Date : 8-Nov-18

Vehicle IN workshop . Kindly arrange for survey.

Your insured vehicle number : EE 1623 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Taufikh, Your rec 4 days

Additional lock carrier.

Total 7 days

Attn: Motor Claims Dept

Tel: 6841 0055 - Fax 6256 4315

Owner's Name : Mr. Lyons Jack
Address : 53 Grange Road
01-04 Sprine Grove
Singapore 249566
Telephone : (HP) 96423660
Type of Claim : Third Party Claims
Policy No. : 5099580823
Vehicle No : **SLU 7341 S**
Model Code : Audi A4 2.0 TFSI Qu
Model / Year : Jul-11
Engine No : CDN 194037
Chassis No : WAUZZZ8K5BA154561
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Oct-18
Place of Accident : Bukit Batok Rd West 8 , West Crest

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SLU 7341 S

S/n	Nature of Jobs	Estimated Charges	REMARK
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlights washer assy.	\$ 120.00	\$ 60.00
2	To remove and renew aircon condenser, coolant with oil cooler. To carry out vacuum/ regas and to pressurise cooling system.	\$ 250.00	\$ 250.00
3	To dismantle and renew front bumper, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,000.00	\$ 1,650.00
4	To respray front bumper and bonnet.	\$ 600.00	\$ 500.00
5	To carry out diagnostic check.	S/N \$ 100.00	\$ 100.00
TOTAL LABOUR CHARGES		: \$ 3,070.00	\$ 2,560.00

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER	\$ 2,394.00	\$ 2,394.00
2	FRONT VENT GRILLE	\$ 118.00	\$ 118.00
3	RADIATOR GRILLE	\$ 595.00	\$ 595.00
4	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	
5	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$ 74.00	
6	FRONT BUMPER COVER	\$ 109.00	
7	SIGN ' CAUTION '	\$ 12.00	
8	FOAM FILLER PIECE	\$ 107.00	
9	FRONT BUMPER SIDE REINFORCEMENT	\$ 770.00	
10	FRONT BUMPER TRIM	\$ 84.00	\$ 84.00
11	HEADLIGHT-LH/RH	2 \$ 3,836.00	\$ 1,918.00
12	HEADLIGHT MOUNTING-LH/RH	2 \$ 206.00	
13	HEADLIGHT BRACKET-LH/RH	2 \$ 136.00	
14	BONNET	\$ 1,654.00	\$ 1,654.00
15	BONNET ATTACHMENT PARTS	\$ 144.00	
16	BONNET LID HINGE-LH/RH	\$ 130.00	
17	BONNET CATCH HOOK	\$ 122.00	
18	BONNET GAS FILLED STRUT	\$ 105.00	
19	BONNET EDGE PROTECTION	2 \$ 48.00	
20	BONNET LID LOCK WITH MICRO SWITCH	\$ 188.00	
SUB- TOTAL SPARE PARTS CHARGES		\$ 10,880.00	\$ 6,763.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARK
21	BONNET LID LOCK CABLE	\$ 43.00	
22	STICKER FOR AIR CONDITIONER	\$ 17.00	
23	LOCK CARRIER WITH COOLANT RADIATOR MOUNTING	\$ 891.00	\$ 891.00
24	AIR GUIDE-LH/RH	2 \$ 46.00	
25	A/C CONDENSOR	\$ 651.00	\$ 651.00
26	A/C SCHRADER VALVE	\$ 46.00	
27	PRESSURE SENDER	\$ 165.00	
28	COOLANT RADIATOR WITH OIL COOLER	\$ 1,206.00	\$ 1,206.00
29	RADIATOR UPPER BUSH	2 \$ 12.00	\$ 12.00
30	RADIATOR LOWER BUSH	2 \$ 6.00	\$ 6.00
31	READY-MIX COOLANT - 1.5 LTR	4 \$ 82.00	\$ 82.00
32	INSCRIPTION "S-LINE"	2 \$ 215.00	
33	CAMSHAFT ADJUSTER MAGNET	\$ 161.00	
34	FLAT CONTACT HOUSING	\$ 9.00	
35	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
36	SUNDRIES	\$ 100.00	\$ 53.80
	SUPPLEMENTARY		\$ 424.00
	TOTAL SPARE PARTS CHARGES	\$ 14,555.00	\$ 10,113.80
	TOTAL LABOUR CHARGES	\$ 3,070.00	\$ 2,560.00
	GRAND TOTAL	\$ 17,625.00	\$ 12,673.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

4/5/10,000

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PAC/TP/0051/2018/GW 16-Nov-18 Kee Siang 1 of 1 SLU 7341 S Audi A4 2.0 TFSI Qu
Quantity	Description	Unit Price	Amount
Parts			
1	Outside Temperature Sensor Bracket	\$ 16.00	\$ 16.00
2	Headlight Mounting Bracket	\$ 103.00	\$ 103.00
3	Radiator Holder	\$ 45.00	\$ 45.00
4	Front bumper Top cover	\$ 109.00	\$ 109.00
5	Bonnet Edge protection	\$ 48.00	
6	Catch Hook	\$ 122.00	\$ 122.00
7	"Caution" Sign Sticker	\$ 12.00	\$ 12.00
8	Air cond Sticker	\$ 17.00	\$ 17.00
TOTAL		\$ 472.00	\$ 424.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel: 6474 3323 Fax: 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Bodyshop Repair Manager

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiuautocare.com.sg / claims@premiuautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0051/2018/GW
Date : 8-Nov-18

Vehicle IN workshop . Kindly arrange for survey.

Your insured vehicle number : EE 1623 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Taufikh, Your rec 4 days
Additional lock carrier.
Total 7 days

Attn: Motor Claims Dept
Tel: 6841 0055 - Fax 6256 4315

Owner's Name : Mr. Lyons Jack
Address : 53 Grange Road
01-04 Sprine Grove
Singapore 249566
Telephone : (HP) 96423660
Type of Claim : Third Party Claims
Policy No. : 5099580823
Vehicle No : **SLU 7341 S**
Model Code : Audi A4 2.0 TFSI Qu
Model / Year : Jul-11
Engine No : CDN 194037
Chassis No : WAUZZZ8K5BA154561
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Oct-18
Place of Accident : Bukit Batok Rd West 8 , West Crest

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>			
		S/Nett			
1	FRONT BUMPER	\$	2,394.00	\$	2,394.00
2	FRONT VENT GRILLE	\$	118.00	\$	118.00
3	RADIATOR GRILLE	\$	595.00	\$	595.00
4	FRONT BUMPER SUPPORT-LH/RH	2 \$	48.00		
5	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$	74.00		
6	FRONT BUMPER COVER	\$	109.00		
7	SIGN ' CAUTION '	\$	12.00		
8	FOAM FILLER PIECE	\$	107.00		
9	FRONT BUMPER SIDE REINFORCEMENT	\$	770.00		
10	FRONT BUMPER TRIM	\$	84.00	\$	84.00
11	HEADLIGHT-LH/RH	2 \$	3,836.00	\$	1,918.00 LH-RH
12	HEADLIGHT MOUTING-LH/RH	2 \$	206.00		
13	HEADLIGHT BRACKET-LH/RH	2 \$	136.00		
14	BONNET	\$	1,654.00	\$	1,654.00
15	BONNET ATTACHMENT PARTS	\$	144.00		
16	BONNET LID HINGE-LH/RH	\$	130.00		
17	BONNET CATCH HOOK	\$	122.00		
18	BONNET GAS FILLED STRUT	\$	105.00		
19	BONNET EDGE PROTECTION	2 \$	48.00		
20	BONNET LID LOCK WITH MICRO SWITCH	\$	188.00		
SUB- TOTAL SPARE PARTS CHARGES		:	\$ 10,880.00	\$	6,763.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	FRONT BUMPER	S	2,394.00 <i>de</i>
2	FRONT VENT GRILLE <i>for grille RH</i>	S	118.00 <i>mis</i>
3	RADIATOR GRILLE	S	595.00 <i>con</i>
4	FRONT BUMPER SUPPORT-LH/RH	2 S	48.00 ?
5	FRONT BUMPER GUIDE SECTION-LH/RH	2 S	74.00 X
6	FRONT BUMPER COVER	S	109.00 ?
7	SIGN "CAUTION"	S	12.00 ?
8	FOAM FILLER PIECE	S	107.00 ?
9	FRONT BUMPER SIDE REINFORCEMENT	S	770.00 ?
10	FRONT BUMPER TRIM	S	84.00 <i>con</i>
11	HEADLIGHT-LH/RH	2 S	3,836.00 ? <i>LH-RH, RH-AT</i>
12	HEADLIGHT MOUNTING-LH/RH	2 S	206.00 ? X <i>un</i>
13	HEADLIGHT BRACKET-LH/RH	2 S	136.00 ? X <i>un</i>
14	BONNET	S	1,654.00 <i>bl</i>
15	BONNET ATTACHMENT PARTS	S	144.00 ?
16	BONNET LID HINGE-LH/RH	S	130.00 ?
17	BONNET CATCH HOOK	S	122.00 ?
18	BONNET GAS FILLED STRUT	S	105.00 ?
19	BONNET EDGE PROTECTION	2 S	48.00 ?
20	BONNET LID LOCK WITH MICRO SWITCH	S	188.00 ?
SUB- TOTAL SPARE PARTS CHARGES			<u>\$ 10,880.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S.

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	
21	BONNET LID LOCK CABLE	S	43.00
22	STICKER FOR AIR CONDITIONER	S	17.00
23	LOCK CARRIER WITH COOLANT RADIATOR MOUNTING	S	891.00
24	AIR GUIDE-LH/RH	2 S	46.00
25	A/C CONDENSOR	S	651.00
26	A/C SCHRADER VALVE	S	46.00
27	PRESSURE SENDER	S	165.00
28	COOLANT RADIATOR WITH OIL COOLER	S	1,206.00
29	RADIATOR UPPER BUSH	2 S	12.00
30	RADIATOR LOWER BUSH	2 S	6.00
31	READY-MIX COOLANT - 1.5 LTR	4 S	82.00
32	INSCRIPTION "S-LINE"	2 S	215.00
33	CAMSHAFT ADJUSTER MAGNET	S	161.00
34	FLAT CONTACT HOUSING	S	9.00
35	FRONT NO. PLATE	S/N S	25.00
36	SUNDRIES	S	100.00
TOTAL SPARE PARTS CHARGES		:	\$ 14,555.00
TOTAL LABOUR CHARGES		:	\$ 3,070.00
GRAND TOTAL		:	\$ 17,625.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Print Received Message

This mail is associated with :

***SLU7341S (9105629265SG)**
[EE1623K]

TP

LYONS JACK

Oct 30 2018 5:00PM

[BERNICE FRANCK WEE AYE]

Premium Autocare Centre

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on 27/06/2019 10:24 AM.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$11502.00) - SLU7341S - Claim Handler: Kesaval, Jaclyn-M**

Approved:11502.00.

Premium Autocare Centre

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18020047/JB3

Chang Chee Sing
6474 3323
6264 6786
claims@premiumautocare.com.sg
Body & Paint Dept
PAC/TP/0051/2018/GW

20 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir/Mdm,

1

total pages

RE: INSURANCE CLAIM FOR SLU 7341 S, AUDI A4 2.0 TFSI QU

Premium Autocare Centre
24 Benoi Sector
Singapore 629857
Telephone (65) 6474 3323
Telefax (65) 6264 6786

With reference to the above-mentioned vehicle: **SLU 7341 S**

Claimant: **Mr. Jyons Jack**

Please find the related document as per attached.

1. A copy of the Original invoice no. 15000327 – S\$ 10,700.00
2. A copy of the Discharge Voucher duly signed by client
3. A copy of the Letter of Authorisation duly signed by client
4. A copy of the Breakdown of Payment
5. Loss of Use – S\$800.00 (14/11/18 – 21/11/18 = S\$100.00 X 8 days)
Surveyor recommendation 7 working days + 1 Sunday
6. Third Party Search via Merimen – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6474 3323.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Manager

Encls

AIG ASIA PACIFIC INSURANCE PTE LTD – SLU 7341 S

BREAKDOWN OF PAYMENT

Vehicle No: SLU7341S

Accident on 30/10/2018 at Bukit Botak Rd West 8, West. Cres

Involving vehicle/s EE 1623 K

1) Repair cost \$ 10,700.00 Payable to: Premium Autocare Centre

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Autocare Centre

3) Loss of Use or Rental Car \$ 800.00 Payable to: Lyons Jack

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

26 JUNE 2019

**BERNICE FRANCK WEE AYE
11A JALAN KAMPONG CHANTEK
SINGAPORE 588596**

Dear Sir/Madam,

**OUR REF : CC3/AIG18020047/T1hb3
YOUR REF : EE 1623K
ACCIDENT INVOLVING EE 1623K AND SLU 7341S ALONG BUKIT BATOK WEST
AVENUE 8 ON 30.10.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLU 7341S against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLU 7341S. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, LYONS JACK (the third party claimant) of 53 GRANGE ROAD
01-04 SPRING GROVE SC249566 (address), owner of SLU 7341S (vehicle no.)
hereby authorize Premium Autocare Centre ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLU 7341S that was damaged pursuant to the accident which occurred on 30/10/2018
(date) along BUKIT RATOK RD WEST & WEST CREST (location) involving vehicle no/s
EE 1623K ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 20 (day) of June (month) 2019 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Autocare Centre ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 10,740.00 (Repair Cost), S\$ 810.00 (Loss of ~~rental~~ use), S\$ 2,000 (Disbursement), for vehicle no. SLU7341S that was damaged pursuant to the accident which occurred on 30/10/2018 (date) along Bukit Batok Rd West 2, West Cres (location) involving vehicle no/s EE1623K. This is pursuant to the inspection conducted on 9/11/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Lyons Jack ("the third party claimant") of vehicle no. SLU7341S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLU7341S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 03 (day) of July (month) 2019 (year).


Signed by appointed surveyor


Signed by "the workshop" (with chop)

Premium Autocare Centre

34 Sims Street,
Singapore 639857
Telephone: (65) 6474 3333
Page 1
Telex: (65) 6284 6786

INS TAX INVOICE

Company Reg No. 201009676M

GST Reg. No. 201009676M

Invoice: 15000327	Account : A0003 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT. 78 SHENTON WAY #08-16 SINGAPORE 079120	Date: 27/04/2019 Order: SLU7341S Term: 30
	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT. 78 SHENTON WAY #08-16 SINGAPORE 079120

Regn No: SLU7341S Regn Date: 28/07/2011 Mileage: 124174 WIP NO. : 10309

Model: AUDI A4 2.0 TFSI QU Chassis: WAUZZZ8K5BA154561 Engine: CDN194037 Dept: W

VSF No:

You have been assisted by:- Chang Chee Sing (11)

		Details	Qty	Unit Price	Amount
S	BODYWORK	To carry out contractual repair as agreed for material and labour.	10000.00	1.00	10000.00

Parts 0.00
Labour 0.00
Sublet 10000.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,000.00

7% GST 700.00

Grand Total 10,700.00



Received by

For & on behalf of
Premium Autocare Centre

Customer



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-169608

Date of Request: 01/11/2018

Your Ref No:

Online Purchase

Premium Autocare Centre
24 Benoi Sector
Singapore 629857

Dear Sir/Madam,

Enquiry Date 01/11/2018
Enquiry By Wong Khong Seng, George
TP Vehicle No. EE1623K
Accident Date 30/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
EE1623K	AIG Asia Pacific Insurance Pte. Ltd.	18/11/2017-17/11/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-169608

Date of Request: 01/11/2018

Your Ref No: Online Purchase

Premium Autocare Centre
24 Benoi Sector
Singapore 629857

Dear Sir/Madam,

Enquiry Date 01/11/2018
Enquiry By Wong Khong Seng, George
TP Vehicle No. EE1623K
Accident Date 30/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING











Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2018 Edit Reg		09 Nov 2018 00:00 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BERNICE FRANCK WEE AYE , ID: S6985969									
Main Claimant: LYONS JACK , ID: G5671980L									
Vehicle Reg. No.: SLU7341S		Date of Loss: 30/10/2018 17:00 - :59 [87 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9105629265SG		Policy/Cover Note No.: 2100356864 (Comprehensive)							
Vehicle Reg. No. (Insured): EE1623K		Policy No. (Claimant): 5099580823							
		Excess:							
Repairer: Premium Autocare Centre (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 64743323/67689827									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (27/06/2019): Alert - Adj Mandate Approved (S\$11502.00) - SLU7341S - Claim Handler: Kesaval, J...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU7341S (9105629265SG)
[EE1623K]
TP
LYONS JACK
Oct 30 2018 5:00PM
[BERNICE FRANCK WEE AYE]
Premium Autocare Centre

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<div></div>	<div></div>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												<div></div>	Edit				
Photos/Images															3 per page		<div></div>	<div></div>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
2	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
3	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
4	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
5	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
6	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
7	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
8	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
9	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
10	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
11	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
12	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
13	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
14	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
15	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
16	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
17	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
18	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
19	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
20	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
21	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
22	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
23	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
24	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
25	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
26	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
27	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
28	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
29	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
30	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
31	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
32	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
33	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			
34	14/06/19 13:27		General View												<div></div>	Load JPG	<div></div>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/06/19 13:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	14/06/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/11/18 18:08	TP GIA REPORT	 Load PDF	
2	14/11/18 08:45	TP ESTIMATE- MARKED	 Load PDF	
3	26/06/19 17:05	AUTHORIZATION LETTER	 Load PDF	
4	26/06/19 17:05	REPAIR INVOICE	 Load PDF	
5	26/06/19 17:05	GIA SEARCH FEE	 Load PDF	
6	26/06/19 17:14	LETTER TO OI	 Load PDF	
7	11/07/19 10:35	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 12:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
<div>^</div> <div>v</div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EE1623K (Insd veh)	Model:	AUDI A4 2.0 TFSI QU
	SLU7341S (TP veh)		S-TRONIC (A)
Date of Accident:	30/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	19,363.79
Final Repair Cost	:	\$	10,700.00
Loss of Use	:	\$	800.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	11,502.00

8.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 24

BOLA Liability: _____100____(%) Assessed Liability (*): _____(%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Autocare Centre	:	\$ 10,702.00
2)	Lyons Jack	:	\$ 800.00
3)		:	\$

JOANNE LEE KHANG MIN

11 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18020047/T1HB3Q2

Date: 11/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100356864
 Claimant Vehicle No: SLU7341S Insured Vehicle No: EE1623K
 Date of Loss: 30/10/2018 Nature of Claim: TP Claim No: 9105629265SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU7341S
 Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: CDN194037
 Reg. Date: 28/07/2011 (Man. Year: 2011) Chassis No: WAUZZZ8K5BA154561
 Colour: Bronze Odometer: 124174 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,027.00	10,113.80	4,913.20	32.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	2,560.00	510.00	16.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,097.00	12,673.80	5,423.20	29.97
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	18,097.00	10,000.00	8,097.00	44.74
+ GST 7.00/7.00% (S\$)	1,266.79	700.00	566.79	44.74
Nett Amount (S\$)	19,363.79	10,700.00	8,663.79	44.74
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,502.00		

INSPECTION

Date of Assignment: 09/11/2018
 Date Inspected: 09/11/2018 Inspected At: Premium Autocare Centre (Benoi)
 24 Benoi Sector
 Singapore 629857

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,394.00 FS	*2,394.00 FS
2	1		*FRONT VENT GRILLE	Missing	118.00 FS	*118.00 FS
3	1		*RADIATOR GRILLE	Cracked	595.00 FS	*595.00 FS
4	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	48.00 FS	*- FS
5	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	74.00 FS	*- FS
6	1		*FRONT BUMPER COVER	Not Necessary	109.00 FS	*- FS
7	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
8	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	770.00 FS	*- FS
10	1		*FRONT BUMPER TRIM	Cracked	84.00 FS	*84.00 FS
11	1		*HEADLIGHT -LH/RH	N/S Not Necessary /O/S Cracked	3,836.00 FS	*1,918.00 FS
12	2		*HEADLIGHT MOUNTING-LH/RH	Not Necessary	206.00 FS	*- FS
13	2		*HEADLIGHT BRACKET-LH/RH	Not Necessary	136.00 FS	*- FS
14	1		*BONNET	Bent	1,654.00 FS	*1,654.00 FS
15	1		*BONNET ATTACHMENT PARTS	Not Necessary	144.00 FS	*- FS
16	2		*BONNET LID HINGE -LH/RH	Not Necessary	130.00 FS	*- FS
17	1		*BONNET CATCH HOOK	Not Necessary	122.00 FS	*- FS
18	1		*BONNET GAS FILLER STRUT	Not Necessary	105.00 FS	*- FS
19	2		*BONNET EDGE PROTECTION	Not Necessary	48.00 FS	*- FS
20	1		*BONNET LID LOCK WITH MICRO SWITCH	Not Necessary	188.00 FS	*- FS
21	1		*BONNET LID LOCK CABLE	Not Necessary	43.00 FS	*- FS
22	1		*STICKER FOR AIR CONDITIONER	Not Necessary	17.00 FS	*- FS
23	1		*LOCK CARRIER WITH COOLER RADIATOR MOUNTING	Cracked	891.00 FS	*891.00 FS
24	2		*AIR GUIDE -LH/RH	Not Necessary	46.00 FS	*- FS
25	1		*A/C CONDENSOR	Bent	651.00 FS	*651.00 FS
26	1		*A/C SCHRADER VALVE	Not Necessary	46.00 FS	*- FS
27	1		*PRESSURE SENDER	Not Necessary	165.00 FS	*- FS
28	1		*COOLANT RADIATOR WITH OIL COOLER	Bent	1,206.00 FS	*1,206.00 FS
29	2		*RADIATOR UPPER BUSH	Necessary	12.00 FS	*12.00 FS
30	2		*RADIATOR LOWER BUSH	Necessary	6.00 FS	*6.00 FS
31	4		*READY -MIX COOLANT -1.5LTR	Necessary	82.00 FS	*82.00 FS
32	2		*INSCRIPTION S-LINE	Not Necessary	215.00 FS	*- FS
33	1		*CAMSHAFT ADJUSTER MAGNET	Not Necessary	161.00 FS	*- FS
34	1		*FLAT CONTACT HOUSING	Not Necessary	9.00 FS	*- FS
35	1		*FRONT NO. PLATE	Necessary	25.00 FS	*25.00 FS
36	1		*SUNDRIES	Necessary	100.00 FS	*53.80 FS
37	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Missing	16.00 FS	*16.00 FS
38	1		*HEADLIGHT MOUNTING BRACKET	Deformed	103.00 FS	*103.00 FS
39	1		*RADIATOR HOLDER	Distorted	45.00 FS	*45.00 FS
40	1		*FRONT BUMPER TOP COVER	Deformed	109.00 FS	*109.00 FS
41	1		*BONNET EDGE PROTECTION	Not Necessary	48.00 FS	*- FS
42	1		*CATCH HOOK	Bent	122.00 FS	*122.00 FS
43	1		*CAUTION SIGN STICKER	Necessary	12.00 FS	*12.00 FS
44	1		*AIR COND STICKER	Necessary	17.00 FS	*17.00 FS

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					15,027.00	10,113.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHTS WASHER ASSY	New	120.00	60.00
2	TO REMOVE AND RENEW AIRCON CONDENSER ,COOLANT WITH OIL COOLER .TO CARRY OUT VACUUM /REGAS AND TO PRESSURIES COOLING SYSTEM	New	250.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND BOTH HEADLIGHTS .RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,000.00	1,650.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	600.00	500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	100.00	100.00
Gross Labour Cost (\$\$)			3,070.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >