

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0051/2018/GW
Date : 8-Nov-18

Vehicle IN workshop . Kindly arrange for survey.

Your insured vehicle number : EE 1623 K

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept
Tel: 6841 0055 - Fax 6256 4315

Owner's Name : Mr. Lyons Jack
Address : 53 Grange Road
01-04 Sprine Grove
Singapore 249566
Telephone : (HP) 96423660
Type of Claim : Third Party Claims
Policy No. : 5099580823
Vehicle No : **SLU 7341 S**
Model Code : Audi A4 2.0 TFSI Qu
Model / Year : Jul-11
Engine No : CDN 194037
Chassis No : WAUZZZ8K5BA154561
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Oct-18
Place of Accident : Bukit Batok Rd West 8 , West Crest

Tanpin 9795749
WP
9/11/18 1015
Resurvey before paint.
sure 11kms.wm.
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SLU 7341 S

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlights washer assy.	\$ 120.00 ^{60.}
2	To remove and renew aircon condenser, coolant with oil cooler. To carry out vacuum/ regas and to pressurise cooling system.	\$ 250.00 [?]
3	To dismantle and renew front bumper, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,000.00 ^{700.}
4	To respray front bumper and bonnet.	\$ 600.00 ⁵⁰⁰
5	To carry out diagnostic check.	S/N \$ 100.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 3,070.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT BUMPER	\$	2,394.00 <i>de</i>
2	FRONT VENT GRILLE <i>for grille LH</i>	\$	118.00 <i>miss</i>
3	RADIATOR GRILLE	\$	595.00 <i>cur</i>
4	FRONT BUMPER SUPPORT-LH/RH	2 \$	48.00 ?
5	FRONT BUMPER GUIDE SECTION-LH/RH	2 \$	74.00 X
6	FRONT BUMPER COVER	\$	109.00 ?
7	SIGN ' CAUTION '	\$	12.00 ?
8	FOAM FILLER PIECE	\$	107.00 ?
9	FRONT BUMPER SIDE REINFORCEMENT	\$	770.00 ?
10	FRONT BUMPER TRIM	\$	84.00 <i>eng</i>
11	HEADLIGHT-LH/RH	2 \$	3,836.00 ?
12	HEADLIGHT MOUTING-LH/RH	2 \$	206.00 ?
13	HEADLIGHT BRACKET-LH/RH	2 \$	136.00 ?
14	BONNET	\$	1,654.00 <i>bt</i>
15	BONNET ATTACHMENT PARTS	\$	144.00 ?
16	BONNET LID HINGE-LH/RH	\$	130.00 ?
17	BONNET CATCH HOOK	\$	122.00 ?
18	BONNET GAS FILLED STRUT	\$	105.00 ?
19	BONNET EDGE PROTECTION	2 \$	48.00 ?
20	BONNET LID LOCK WITH MICRO SWITCH	\$	188.00 ?
SUB- TOTAL SPARE PARTS CHARGES		:	\$ 10,880.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLU 7341 S.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
21	BONNET LID LOCK CABLLE	\$	43.00 ?
22	STICKER FOR AIR CONDITIONER	\$	17.00 ?
23	LOCK CARRIER WITH COOLANT RADIATOR MOUNTING	\$	891.00 ?
24	AIR GUIDE-LH/RH	2 \$	46.00 ?
25	A/C CONDENSOR	\$	651.00 ?
26	A/C SCHRADER VALVE	\$	46.00 ?
27	PRESSURE SENDER	\$	165.00 ?
28	COOLANT RADIATOR WITH OIL COOLER	\$	1,206.00 ?
29	RADIATOR UPPER BUSH	2 \$	12.00 ?
30	RADIATOR LOWER BUSH	2 \$	6.00 ?
31	READY-MIX COOLANT - 1.5 LTR	4 \$	82.00 ?
32	INSCRIPTION "S-LINE"	2 \$	215.00 ?
33	CAMSHAFT ADJUSTER MAGNET	\$	161.00 ?
34	FLAT CONTACT HOUSING	\$	9.00 ?
35	FRONT NO. PLATE	S/N \$	25.00 ?
36	SUNDRIES	\$	100.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 14,555.00
TOTAL LABOUR CHARGES		:	\$ 3,070.00
GRAND TOTAL		:	\$ 17,625.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre



Allan Wu
Bodyshop Repair Manager