

22/03/2002

ASS. REC. BY:

REF: CS/MS(18020088 / Gtber

Special Instruction:

SURVEYOR
Men'men

EQ

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSLH

Date/Time:

07-11-2018 9:44am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 7617Z

Insured:

SUM 9817R

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 Ubi Rd 4

Policy No:

A29069766MKF

Claim No:

573039

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12.10.2018

CA / REV / REP. / REV 24 HRS w/p

10am

H.O.D. Endorsement:

Date/Time:

07-11-2018 9:50am

Person Contacted:

Any

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLP 7617Z - x

SUM 9817R - x

THI -

Revised via men'men preli advise.

Part by Part \$536.85. 5 days (Red: 7975.05!, 60%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Filed	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2018		07 Nov 2018 09:44 Assign				New Assignment Cancel Case

Name	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	LIU YONG WEE (LIU YONGWEI), ID: S7438289D								
Vehicle Reg. No.:	SLP7617Z	Date of Loss:	12/10/2018 10:00 - :59 [15 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 573039	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLM9817R	Policy No. (Claimant):	Excess:						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/11/2018]								
Driver/Custodian (Insured):	HIDAYATULLAH BIN AHMAD ALI (), NRIC: S7041049D, Tel: +6596423045								
Adj Asg. Remarks:	Survey appointment on 07/11/2018, 10am, owner waiting. Liability down. Contact Person: Ary Chua Wai Ngee / 6846 5673 / 8100 6306								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 5 December 2018 3:57 PM
To: 'Ary Chua'; Guo Qiang (LKKAuto); Admin A; Admin-D (LKKAuto)
Cc: Liew Thye Wui; Faeaz
Subject: RE: SECOND REMINDER: Finalise TPDS: SLP7617Z (TM) & SLM9817R (MSIG) DOA: 12/10/2018@10.50am

Dear Ary,

Confirm final figure at \$5136.85,5days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>
Sent: Wednesday, 5 December 2018 3:29 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: SECOND REMINDER: Finalise TPDS: SLP7617Z (TM) & SLM9817R (MSIG) DOA: 12/10/2018@10.50am

Hi Guo Qiang,
Second Reminder: Kindly Finalise TPDS: SLP7617Z (TM) & SLM9817R (MSIG) DOA: 12/10/2018@10.50am

Final Repair Costs (include GST)	\$5,136.85 + (\$359.58) = \$5,496.43
Repair Period* (Working Day)	05

Please examine the above information carefully. If no discrepancy is reported within 7 days (*Exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor **Kah Motor Co.Sdn.Bhd.** Address:15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

From: Ary Chua
Sent: Thursday, 15 November, 2018 6:53 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: Finalise TPDS: SLP7617Z (TM) & SLM9817R (MSIG) DOA: 12/10/2018@10.50am

Hi Guo Qiang,
Kindly Finalise TPDS: SLP7617Z (TM) & SLM9817R (MSIG) DOA: 12/10/2018@10.50am

Final Repair Costs (include GST)	\$5,136.85 + (\$359.58) = \$5,496.43
Repair Period* (Working Day)	05

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8289D
Vehicle Details	
Vehicle No.:	SLP7617Z
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B31191047
Chassis No.:	JHMGK5850HX201432
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$17,910.00
Original Registration Date:	16 Jun 2017
First Registration Date:	16 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$12,910.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2027
PARF Rebate Amount:	\$9,682.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$44,734.00
Total Rebate Amount:	\$54,416.00

The information contained herein is correct as at 08 Nov 2018

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 09 Nov 2018

Preliminary Advice

Insured Vehicle No	: SLM9817R	Accident Date	: 12/10/2018
TP Vehicle No	: SLP7617Z	Assignment Date	: 07/11/2018
Make	: HONDA JAZZ	Est. Duration of Repair	: 5.00
Date of Inspection	: 07/11/2018		
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,111.90
Revised Amount	:S\$	5,462.50
Check Items (Estimated)	:S\$	431.40
Total	:S\$	5,893.90
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/10/2018 16:17
Date Of Accident	12/10/2018 10:50
Exact Location Of Accident	KAKI BKT AVE2 JUNCTION RIGHT TURN TO KAKI BKT RD1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP7617Z
Insured/Policyholder	
Name Of Registered Owner	LIU YONG WEE (LIU YONGWEI)
NRIC No	S7438289D
Email Address	LIUYONGWEE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-88181792
Alternative Phone No	OFFICE-88181792

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 RS (GK5) (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MU007122-R00
Cover Note Number	

Driver

Name of Driver	LIU YONG WEE (LIU YONGWEI)
NRIC No	S7438289D
Date Of Birth	03/12/1974
Occupation	INDOOR
Date Of Driving Pass	12/06/1997
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88181792
Fax Number	
Contact Number	OFFICE-88181792
EMail Address	LIUYONGWEE@GMAIL.COM

Address	BLK 666 JALAN DAMAI #09-93
Postcode	S410666
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KEK CHERN NEE (WIFE) GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

NOBODY INJURY DURING THE ACCIDENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM9817R
Vehicle Make/Model/Colour	TOYOTA/VIOS/SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HIDAYATULLAH BIN AHMAD ALI
NRIC/Passport Number	S7041049D
Contact Number	96423045
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle No SLP 7617Z

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

fi 12/10/18 @ 13:10hrs


13:13pm
12 OCT 2018
ARY CHUA

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No SLP 7617Z

Annex E

Describe Circumstances of the Accident

I was driving SLP 7617Z along Kalit Bukit Ave 2, queuing to turn right into Kalit Bukit Rd. 1. There was a 2-plate vehicle SKR 29334 ahead of me. Both myself and SKR 29334 were stationary when SLP 9817R hit me from rear.

Immediately, I approached the driver - HIDAYATULLAH BIN AHMAD ALZ who admitted his fault and suggested to claim insurance for settlement.

There were 3 passengers on-board his Arab Rental, SCM 9817R (Silver Vios, E-toyota)

Detail of the driver, ~~see~~ photo of incident, rider's postcard

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

12/10/18 @ 13:10hrs

Driver's Signature (If driver is not the policyholder) / Date & Time

13:13pm

12 OCT 2018

Witnessed by Reporting Centre Personnel


ARY CHUA



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

Survey & Repair & Perm. Co.
07 NOV 2018 @ 10:00 am
MSIG Arrange for Survey
Critical 65942535

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT18004369	Page	1
Registration No	: SLP7617Z	Date	: 12. Oct 2018	Customer No.	: WZI001
Chassis No	: JHMGK5850HX201432	Svc Advisor	: ARY CHUA WAI NGEE	Engine No	: L15B31191047
Model	: JAZZ 1.5VTIR CVT 17YM	Date Time	: 12. Oct 2018 4:50:45 PM	Surveyor Name	:
Owner's Name	: LIU YONG WEE	Survey Date	:	Authorisation Date	:
Ins Policy No.	: 17-MU007122-R00				
Date of Accident	: 12/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LIU YONG WEE (LIU YONGWEI) OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 12/10/2018@10.50AM SURVEYED BY: REF NO: TP INSURER: MSIG INSURANCE (SINGAPORE) PTE LTD TP VEH: SLM9817R (TOYOTA/VIOS/SILVER)							
BO-WS-SEALANT	WINDSCREEN SEALANT (N) - <i>me</i>	1	60.00		60.00	4.20	64.20	
34150-T5A-J01	LIGHT ASSY.R.LID X	1	79.30		79.30	5.55	84.85	
34155-T5A-J01	LIGHT ASSY.L.LID X	1	79.30		79.30	5.55	84.85	
33500-T5A-J02	TAILLIGHT ASSY.R. X	1	235.10		235.10	16.46	251.56	
33550-T5A-J02	TAILLIGHT ASSY.L. X	1	235.10		235.10	16.46	251.56	
74890-T5B-911	GARNISH ASSY.RR.LICENSE X	1	194.70		194.70	13.63	208.33	
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20		11.20	0.78	11.98	
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30		12.60	0.88	13.48	
73226-SZW-000	DAMPERSTD 5X5	1	8.30		8.30	0.58	8.88	
75701-T5A-000	EMBLEMH X	1	10.70		10.70	0.75	11.45	
90301-ST0-003	NUTPUSH 3MM X	2	1.90		3.80	0.27	4.07	
75722-T5L-T01	EMBLEMRR. - <i>me</i>	1	10.50		10.50	0.74	11.24	
04715-T5B-000ZZ	FACERR.BUMPER - <i>re</i>	1	492.60		492.60	34.48	527.08	
71593-T5A-000	SPACERR.RR.BUMPER - <i>me</i>	1	11.50		11.50	0.81	12.31	
71598-T5A-000	SPACERL.RR.BUMPER - <i>me</i>	1	11.50		11.50	0.81	12.31	
68100-TAS-Z50ZZ	TAILGATE COMP - <i>me</i>	1	716.30		716.30	50.14	766.44	
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30		59.30	4.15	63.45	
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	58.10		58.10	4.07	62.17	
66100-TAR-T10ZZ	PANEL COMPRR. ?	1	314.00		314.00	21.98	335.98	
91505-TM8-003	CLIPBUMPER - <i>me</i>	14	2.00		28.00	1.96	29.96	
					Sum Item	2631.90	184.25	2,816.15



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	WZI001 / MSIG INSURANCE	Document No:	SVO18065125
Chassis No:	JHMGK5850HX201432	Printed By:	ARYCHUA
License No:	SLP7617Z	Order Date:	7. November 2018
Mileage:	33253	Order Time:	4:50:45 PM
Engine No:	L15B31191047	Service Advisor:	ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71538) OWNER: LIU YONG WEE (LIU YONGWEI) OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 12/10/2018@10.50AM SURVEYED BY: GUAQIANG(LKKAUTO)07/11/2018@11.11AM REF NO: TP INSURER: MSIG INSURANCE (SINGAPORE) PTE LTD TP VEH: SLM9817R (TOYOTAVIOS/SILVER)						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66
75722-T5L-T01	EMBLEMRR.	1	10.50	25	7.87	0.55	8.42
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60	25	369.45	25.86	395.31
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30	25	537.22	37.61	574.83
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
	SUM PARTS:				1,036.85	72.58	1,109.43
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ REMOVE & INSTALL REVERSE CAMERA & CALIBRATION(N)	1	300.00		300.00	21.00	321.00
BOMISC1	EXT-YJ RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM(N)	1	300.00		300.00	21.00	321.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00		450.00	31.50	481.50
BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00		1,350.00	94.50	1,444.50
	SUM LABOUR:				4,100.00	287.00	4,387.00
	TOTAL SGD				5,136.85	359.58	5,496.43
	Total Payable (SGD)						5,496.43

WD=5

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2018		07 Nov 2018 09:44 Edit Adj Rpt	S\$5,136.85 Edit Estimates	S\$5,136.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Main Claimant:	LIU YONG WEE (LIU YONGWEI) , ID: S7438289D								
Vehicle Reg. No.:	SLP7617Z	Date of Loss:	12/10/2018 10:00 - :59 [15 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 573039	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLM9817R	Policy No. (Claimant):							
		Excess:							
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/12/2018]								
Driver/Custodian (Insured):	HIDAYATULLAH BIN AHMAD ALI (), NRIC: S7041049D, Tel: +6596423045								
Adj Asg. Remarks:	Survey appointment on 07/11/2018, 10am, owner waiting. Liability down. Contact Person: Ary Chua Wai Ngee / 6846 5673 / 8100 6306								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP7617Z (573039)
[SLM9817R]
TP
LIU YONG WEE (LIU YONGWEI)
Oct 12 2018 10:00AM
[GRAB RENTALS PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	15/10/18 12:28	Accident Statement From: SC - Reg. No: SLM9817R, Claimant: GRAB RENTALS PTE LTD					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	09/11/18 14:58	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
2	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
3	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
4	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
5	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
6	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
7	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
8	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
9	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
10	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
11	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
12	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
13	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
14	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
15	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
16	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
17	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
18	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
19	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
20	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
21	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
22	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
23	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
24	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
25	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
26	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
27	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
28	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
29	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
30	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	
31	05/12/18 16:22	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singa0ore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/10/18 12:28	SLP7617Z GIA Rpt From:SC - Reg. No: SLM9817R, Claimant: GRAB RENTALS PTE LTD	 Load PDF	
2	15/10/18 12:29	Email - PRI	 Load PDF	
3	15/10/18 12:32	Estimate	 Load PDF	
4	15/10/18 18:46	Valid Vocational Driving licence	 Load PDF	
5	07/11/18 09:46	Email frm TP on PRI assignment date & time. Owner waiting	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18020088/GTBE2

Date: 12/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No: SLP7617Z	Insured Vehicle No:	SLM9817R
Date of Loss: 12/10/2018	Nature of Claim:	TP
		Claim No: 573039

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP7617Z	Engine No: L15B31191047
Make & Model: HONDA JAZZ, 1.5 VTIR CVT (A)	Chassis No: JHMGK5850HX201432
Reg. Date: 16/06/2017 (Man. Year: 2016)	Odometer: 32923 km
Colour: Red	
Engine Capacity: 1498 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,691.90	1,056.85	1,635.05	60.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,420.00	4,080.00	6,340.00	60.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,111.90	5,136.85	7,975.05	60.82
+ GST 7.00/7.00% (S\$)	917.83	359.58	558.25	60.82
Nett Amount (S\$)	14,029.73	5,496.43	8,533.30	60.82

INSPECTION

Date of Assignment:	07/11/2018	Inspected At:	Kah Motor Co Sdn Bhd (Ubi)
Date Inspected:	07/11/2018		15 Ubi Road 4
			Singapore 408610
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2018)
Parts: 144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP7617Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
2	1		*LIGHT ASSYR.LID	Not Necessary	79.30 FS	*- FS
3	1		*LIGHT ASSYL.LID	Not Necessary	79.30 FS	*- FS
4	1		*TAILLIGHT ASSY,R.	Not Necessary	235.10 FS	*- FS
5	1		*TAILLIGHT ASSYL	Not Necessary	235.10 FS	*- FS
6	1		*GARNISH ASSYRR.LICENSE	Not Necessary	194.70 FS	*- FS
7	1		*RUBBER CWINDSHIELD DAMPER	Necessary	11.20 FS	*8.40 FS
8	1		*RUBBERWINDSHIELD DAMPER (2PCS)	Necessary	12.60 FS	*9.45 FS
9	1		*DAMPER STD 5X5	Necessary	8.30 FS	*6.22 FS
10	1		*EMBLEMH	Not Necessary	10.70 FS	*- FS
11	2		*NUTPUSH 3MM	Not Necessary	3.80 FS	*- FS
12	1		*EMBLEMRR.	Necessary	10.50 FS	*7.87 FS
13	1		*FACERR.BUMPER	Deformed	492.60 FS	*369.45 FS
14	1		*SPACERR.RR.BUMPER	Necessary	11.50 FS	*8.62 FS
15	1		*SPACERL.RR.BUMPER	Necessary	11.50 FS	*8.62 FS
16	1		*TAILGATE COMP	Buckled	716.30 FS	*537.22 FS
17	1		*BUZZER ASSYSMART	Not Necessary	59.30 FS	*- FS
18	1		*ANTENNA COMPRR.	Not Necessary	58.10 FS	*- FS
19	1		*PANEL COMPRR	Not Necessary	314.00 FS	*- FS
20	14		*CLIPBUMPER	Necessary	28.00 FS	*21.00 FS
21	1		*SUNDRIES	Necessary	60.00 FS	*20.00 FS
Total Parts (S\$)					2,691.90	1,056.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY UNDERSIDE COATING	New	100.00	0.00
2	BODY JOINT SEALANT	New	100.00	0.00
3	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	140.00	120.00
4	REMOVE & RENEW REVERSE SENSORS-4PCS	New	180.00	140.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	0.00
6	REMOVE & INSTALL RR.WINDSCREEN	New	350.00	300.00
7	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	New	350.00	300.00
8	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	New	350.00	300.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	0.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	550.00	450.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	2,800.00	1,350.00
12	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	4,800.00	1,120.00
Gross Labour Cost (S\$)			10,420.00	4,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >