CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 3457X (Supplementary)

MAKE

MODEL : HYUNDAI i40

DATE: 7.11.2018

TEL : 6542 5119

FAX: 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender Side Garnish (LH)			\$ 150.00
			_	
	SUB TOTAL			\$ 150.00
	LESS 20%			\$ 30.00
	DISCOUNTED TOTAL			\$ 120.00
	2			
	- Man		ę	
			45	
	JKK Auto			
	SEE YOU)
			12.1	
				}
	2			
				*
			*	
			1	~
		× 1		
	This is an initial estimate based on a visual inspection of t			

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.