

ASS. REC. BY:

REF:

CS/TC118020098/THbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Cws Eileen Lee of FCLDate/Time: 07-11-2018 10:45am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 1076

Insured:

SHC 3888A

at Workshop m/s

Charm's Customcraft

Tel:

6272 5421

of

806 1010 Bukit Merah Lane 3 #01-105

Policy No:

Claim No:

D18007872MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

07-11-2018 @ 11am - 2pm

H.O.D. Endorsement:

Date/Time:

07-11-2018 10:50am

Person Contacted:

Sharon

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SMC 1076 - X</u>
	<u>SHC 3888A - (C3) 111610011605 / Kaila</u>
<u>13/11@3:41pm</u>	<u>Revised via email</u>
	<u>Confirm final figure @ \$278674 , 3 days</u>
	<u>(Red: 280, 99%)</u>

DIA: 12062410

REPORT

Tuppi

REF:

FCI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 1079

Yr Regn:

2017 Aug

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volvo V40

G.C

1498

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

YVIMV2840J2450253

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim/or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

9/11/18 @ 120 pm

Survey held at

Chen's Customcraft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 15 JAN 2019

15/1/2019

Date/Time. File Pass to?

1) 15/1 Tuppi

Date/Time. File Return to?

2)

Report Format :

TP

Lump Sum / I/B: (\$) 2786.74

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

) \$ + RS (\$))

) Photos

) Other

)

TOTAL

130

50

50

22

252



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007872MFSH

Date: 13/11/2018

Our Ref: CS/FCI18020098/T1tb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMC 107G

Please be informed that we had conducted the inspection of the abovementioned vehicle 9/11/2018 at the premises of M/s Charm's Custom craft have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,281.41</u>
Revised Estimate Amount	: S\$ <u>2,786.74</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	01-11-2018	Our Ref No. D18007872MFSH
Accident Date	30-10-2018	Claim Type. Third Party
Insured Vehicle	SHC3888A	Third Party Vehicle. SMC107G
Survey Location	BLK 1010 BUKIT MERAH LANE 3 #01-105	
Contact Person.	SHARON LEE	
Contact No.	62725429/ 0	Fax No. 62736676
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHARN'S CUSTOMCRAFT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 13 November 2018 3:41 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007872MFSH/1
Attachments: PRELI ADVISED SMC 107G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMC 107G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 7 November 2018 10:52 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007872MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 7 November, 2018 10:45 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007872MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 15 January 2019 11:32 AM
To: 'Charn's Customcraft'
Subject: RE: check vehicle status

Dear Sharon,

Confirm total: \$2786.74 (b4 GST), 3days.

Please submit all relevant documents to first capital insurance.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Monday, 14 January 2019 4:02 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: check vehicle status
Importance: High

Hi Denis

Kindly refer to the attached for finalization.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Monday, 14 January, 2019 3:58 PM
To: Charn's Customcraft
Subject: check vehicle status

Dear All,

Can check for me for the following vehicle:

SJU 2810L – DOA: 14/11/2018 FIRST CAPITAL
SMC 107G – DOA: 30/12/2018 FIRST CAPITAL

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5102972471

Cover : drive PREMIUM

- | | |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SMC107G |
| Chassis Number | : YV1MV28H0J2450253 |
| 2. Name of Policyholder | : TAN CHEE FUI |
| 3. Effective Date of Insurance | : 28 Aug 2018 |
| 4. Expiry Date of Insurance | : 27 Aug 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: NO
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: YES
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TAN CHEE FUI
NAMED DRIVER (1)	: KWAN KAH YIN
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: MAYBANK
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE LESS RESIDUAL COE/PART VALUE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : TIMES INS BROKERS (MOTOR BUSINESS) (00000690643)
Date of Issue : 08 Aug 2018 18:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



**TIMES INSURANCE
BROKERS PTE LTD**
时代保险经纪公司有限公司

81c 2 Balestier Road #03-659 to 663
Balestier Hill Shopping Centre S (320002)
T 6252 8888 F 6253 3230 / 6250 9133
W timesinsurance.com.sg

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1195221F**

Name: **KWAN KAH YIN**

Birth Date: **27 Oct 1956**

Issue Date: **21 Aug 2003**

000763340A




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1195221F



Name

KWAN KAH YIN

关 家 贤

Race

CHINESE

Date of birth

27-10-1956

Country/Place of birth

SINGAPORE

Sex

M

S1195221F


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

22 Oct 1998

Licence No: S1195221F

NP 428A



6026469



NRIC No. S1195221F



Date of issue

19-09-2018

Address

**APT BLK 111B DEPOT ROAD
 #16-107
 SINGAPORE 102111**

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4634J

Vehicle Details

Vehicle No.: SMC107G
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Nov 2018
Vehicle Make: VOLVO
Vehicle Model: V40 T2 (A)
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: B4154T52119181
Chassis No.: YV1MV28H0J2450253
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$23,535.00
Original Registration Date: 28 Aug 2017
First Registration Date: 28 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$19,949.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Aug 2027
PARF Rebate Amount: \$14,961.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,900.00
COE Rebate Amount: \$34,320.00
Total Rebate Amount: \$49,281.00

The information contained herein is correct as at 02 Nov 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3533G

Vehicle Details

Vehicle No.: SKZ3089H
Vehicle to be Exported: Yes
Intended Deregistration Date: 30 Nov 2018
Vehicle Make: MAZDA
Vehicle Model: MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR LED
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: PY20705085
Chassis No.: JM6GJ1032G0229286
Maximum Power Output: 141.0 kW (189 bhp)
Open Market Value: \$23,566.00
Original Registration Date: 18 Jan 2016
First Registration Date: 18 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$24,993.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jan 2026
PARF Rebate Amount: \$18,744.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$60,003.00
COE Rebate Amount: \$42,774.00
Total Rebate Amount: \$61,518.00

The information contained herein is correct as at 05 Nov 2018

OK



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

NTUC/FC(SHC3888A)

DOA: 30/10/2018@1930

MS FIRST CAPITAL INSURANCE PTE LTD

05/11/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SMC 107 G - VOLVO V40 T2 (A)

CHASSIS NO: YV1MV28H0J2450253

1 pc	Rear bumper	\$ 1,566.30 <i>de</i>
1 pc	rear bumper reflector LH	\$ 102.50 <i>ant</i>
1 pc	Rear bumper lower garnish	\$ 522.60 <i>de</i>
1 pc	Rear bumper lower garnish sensor LH	\$ 215.70 <i>ds</i>
		<hr/>
		\$ 2,407.10
		<hr/>
		\$ 120.36
		<hr/>
		\$ 2,286.74

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel and rear bumper.

\$ 380.00 *250*

Putty and respray rear inner panel, rear end panel and rear bumper.

\$ 400.00 *250*

ADD 7% GST

\$	3,066.74
\$	214.67
\$	<u>3,281.41</u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental system must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Kah 97495749
wp
9/11/18 12:00pm
Resurvey before paint
sur@lkkauto.com
03 days.



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

NTUC/FC(SHC3888A)

DOA: 30/10/2018@1930

MS FIRST CAPITAL INSURANCE PTE LTD

05/11/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SMC 107 G - VOLVO V40 T2 (A)

CHASSIS NO: YV1MV28H0J2450253

1 pc	Rear bumper	\$ 1,566.30 <i>den</i>
1 pc	rear bumper reflector LH	\$ 102.50 <i>ant</i>
1 pc	Rear bumper lower garnish	\$ 522.60 <i>de</i>
1 pc	Rear bumper lower garnish sensor LH	\$ 215.70 <i>dis</i>
		<hr/>
		\$ 2,407.10
	LESS 5%	\$ 120.36
		<hr/>
		\$ 2,286.74

Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel and rear bumper.

\$ 380.00 *250*

Putty and respray rear inner panel, rear end panel and rear bumper.

\$ 400.00 *250*

\$ 3,066.74
\$ 214.67

\$ 3,281.41

ADD 7% GST

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Parts - 2286.74
Lab - 500.00

2786.74

Tanfer 97495799
wp
9/11/18 1200pm
Respray before paint
sur@khanh.com
03 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020098/T1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3888A	Veh. Inspected	SMC 107G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007872MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	07/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO V40	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YV1MV28H0J2450253	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2018	Inspection Date	09/11/2018	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 107G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	1,566.30	1,566.30
1	REAR BUMPER REFLECTOR LH	CUT	102.50	102.50
1	REAR BUMPER LOWER GARNISH	DEFORMED	522.60	522.60
1	REAR BUMPER LOWER GARNISH SENSOR LH	DISTORTED	215.70	215.70
	LESS 5% DISCOUNT		-120.36	-120.36
			2,286.74	2,286.74
	LABOUR			
	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR AND STRAIGHTEN REAR INNER PANEL,REAR END PANEL AND REAR BUMPER.		380.00	250.00
	PUTTY AND RESPRAY REAR INNER PANEL,REAR END PANEL AND REAR BUMPER.		400.00	250.00
			780.00	500.00
	GRAND TOTAL		3,066.74	2,786.74
	RECOMMENDED COST OF REPAIRS			2,786.74

Report Ref No. CS/FCI18020098/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.