

ASS. REC. BY: Sebastian REF: CS3 / MSG 17017 808 / B 6-17
 From (Person): Monica Chung ASSIGNMENT (Office): MSG Date/Time: 07.11.2018
 Estimated Cost: _____
 OD / ☒ WS / TR RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SLK 9706 M Insured: SLC 7808 D
 at Workshop to: World Auto Tel: 975 88 347
 at: No 1, Kranji Leep, 73 9535
 Policy No: MSD/VPCP/17-001233-00 Claim No: MSC/v/17-001419
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ DOA: 11/9/17
 (Client's Record): _____

CA / REV / REP. / REV 24 HRS 'wp' R.O.D. Estimate: _____
 Date/Time: 15/9/17 9:33am Person Contacted: Mr. Sim Vehicle: ☒ ENLDT

Date/Time	Action/Instruction (✓) Estimate
	SLK 9706 M - X
	SLC 7808 D - X
	Dismantle Part: 2709 2017
	After repair: 02.10.2017

14/10/17 3:30pm Email to Monica Chung thru meimen.

09/11/18 Submit I/P \$7063.68, 12 days
 (Red \$ 2923.28, 12%)


 8/11/2018.

Repair days 12

RECEIVED 09 NOV 2018

Team Hui
 8/11/18

PRS

REF: MS/G

ASSIGNMENT

From _____ Date 15/9/17

Estimated Cost _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No SLK 9706Mat Workshop n/a World Autoof No. 1 Kranji Loop, 739535

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value _____

IDAC Accident Report _____ Consistent? Yes or No

G/A PR Seen _____ Consistent? Yes or No

Est Repairs 14 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date _____

Person Contacted _____

Vehicle IN / OUT

Date Time Action Instruction

Veh No SLK 9706M yr Reg 9/2/14Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make Honda Verza cc 1496Colour black AC Insured / Std / NI / NA

Sp Reading _____ T Radio Insured / Std / NI / NA

Eng No. _____

C No. KH 51214758

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: ☒ N / S Rim / STD A Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal 6 mmR/Bal 6 mmL/Bal 6 mmL/Bal 6 mmD.O.A. 11/9/2017D.O.I. 15/9/2017 @ 11:18amSurvey held at World AutoDes. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

\$22,000 (Shirley Hweo 09/04/18)
12K-15K with 14 days 8m

RECEIVED 15 APR 2018

Date/Time File Pass to?

☐

: Prel. Report

Days Of Repair: 14

1.

☐

: Final Report

Resurvey No. of Trip: 3

Date/Time File Return to?

2.

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: PRG

Lump Sum / I.B.I. (\$

Survey Fee

Transportation

1. S + P = \$

2. Photo

3. Other

4.

TOTAL

120

50

10

180

Catherine Chong (LKK Auto)

From: Monica Chung <Monica_Chung@sg.msig-asia.com>
Sent: Wednesday, 7 November, 2018 11:12 AM
To: assignments@lkkauto.com
Subject: RE: FW: 3rd party survey for SLK 9706M

Dear Catherine,

We have sent back case for paper adjustment.

Thanks.

Regards,

Monica Chung
Executive, Claims Services (Motor)
D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, September 15, 2017 9:38 AM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>; assignments@lkkauto.com; sur@lkkauto.com
Subject: RE: FW: 3rd party survey for SLK 9706M

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rashitha Binte Shahuthuman [mailto:rashitha_shahuthuman@sg.msig-asia.com]
Sent: Thursday, 14 September, 2017 5:06 PM
To: 'Sim'; 'Ashley Chong (LKK Auto)'
Cc: Monica Chung; Rashitha Binte Shahuthuman
Subject: RE: FW: 3rd party survey for SLK 9706M

Dear LKK,

Please survey SLK9706M @ World Auto Pte Ltd. Thank you .

Rashitha





Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msiga-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msiga.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Sim [<mailto:sim@worldauto.com.sg>]

Sent: Thursday, 14 September, 2017 4:53 PM

To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msiga-asia.com>

Subject: Re: FW: 3rd party survey for SLK 9706M

Dear sir

We would like to engage LKK for this survey

Regards

S.T.Sim

Claims Manager

97588347

World Auto Pte Ltd

No 1 Kranji Loop

Singapore 739535

-----Original Message-----

From: "Rashitha Binte Shahuthuman" <rashitha_shahuthuman@sg.msiga-asia.com>

To: "sim@worldauto.com.sg" <sim@worldauto.com.sg>

Cc: "Monica Chung" <Monica_Chung@sg.msiga-asia.com>, "Rashitha Binte Shahuthuman" <rashitha_shahuthuman@sg.msiga-asia.com>

Date: 14-09-2017 16:29

Subject: FW: 3rd party survey for SLK 9706M

OUR REF - MSC/V/17-001419

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd

3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Sim [<mailto:sim@worldauto.com.sg>]

Sent: 14 September 2017 11:23

To: Claims <claims@sg.msig-asia.com>

Subject: Re: 3rd party survey for SLK 9706M

Dear sir

Please arrange a 3rd party surveyor to survey the following car

Our client: SLK 9706M

Your Insured: SLC 7408D

Date of accident: 11/09/17

Regards

S.T.Sim

Claims Manager

97588347

World Auto Pte Ltd

No 1 Kranji Loop

Singapore 739535

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2017		15 Sep 2017 14:15 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLK9706M	Date of Loss:	11/09/2017 12:00 - :59 [7 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/17-001419	Policy/Cover Note No.:	MSD/VPCP/17-001233-00 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018						
Vehicle Reg. No. (Insured):	SLC7408D	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 09/11/2018]								
Driver/Custodian (Insured):	NEO KEE TECK (), NRIC: S1414132D, Tel: +6581331515								
Adj Asg. Remarks:	pri								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> MSIG_SG (07/11/2018): Report Send Back Alerts - SLK9706M (TP) 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



17-1419
PT

WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03
HALCYON 2
SINGAPORE 577200



28/08/2018

Your Ref :

Our Ref : TP/1428/2017

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01 SGX CENTRE 2
SINGAPORE 068807

Attn : Motor Claim Dept – Third Party

Dear Sirs,

ACCIDENT INVOLVING VEH.NO. SLK9706M / SLC7408D ON 11/09/2017

Reference is made to the aforesaid matter (on behalf of our client M/S LCRF PL)

Enclosed herewith are the following documents for your information and necessary actions only :-

a) Our Final Repair Bill

Please assist in our claims of :

Final Bill	\$ 23986.96
GST 7%	\$ 1679.09
Search Fee	\$ 2.00
Surveyor report	\$ 805.00
Pre-repair Inspection (\$60x 2 days)	\$ 120.00
Loss of Use (\$60 x 13 days)	\$ 780.00
Amount	<u>\$ 27373.05</u>

YQ,
-upload - ⑦
-ML 1.
- PPS to K22000.
Monica Chung 0430
Executive
Claims Services
2/10/18

Kindly let us have your reply and payment as soon as possible.

Thank you for your kind attention and much appreciated assistance.

Yours faithfully,

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SGX CENTRE 2
 S'PORE 068807

Attention : Motor Claim Department
 Contact : 68277888 Fax No. : 68277809

Tax Invoice : F188735

Date : 28/08/2018
 Vehicle Num. : SLK 9706M
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/09/2017
 Claim No. : TP/1428/2017
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BONNET		795.00
2.	1	BONNET HINGES		170.00
3.	1	BONNET LOCK		160.00
4.	1	FRONT BUMPER		495.00
5.	1	FRONT BUMPER LOWER		295.00
6.	1	FRONT BUMPER REINFORCEMENT		445.00
7.	1	FRONT BUMPER SIDE RETAINER O/S		75.00
8.	1	FRONT BUMPER LOWER GRILLE		118.00
9.	2	HEADLAMP ASSY LH/RH	1,580.00	3,160.00
10.	2	HEADLAMP TOP BRACKET	68.00	136.00
11.	2	HEADLAMP LOWER BRACKET	78.00	156.00
12.	1	FRONT GRILLE BASE		380.00
13.	1	FRONT GRILLE MOULDING		368.00
14.	1	GRILLE CENTRE BRACKET		98.00
15.	1	FOG LAMP COVER		45.00
16.	1	SUPPORT PANEL		672.80
17.	1	SUPPORT PANEL TOP GARNISH		94.00
18.	1	RADIATOR		1,311.90
19.	1	A/C CONDENSER		1,160.00
20.	1	FRONT FENDER O/S		499.60
21.	1	FRONT FENDER WHEEL ARCH GARNISHES O/S		144.60
22.	1	FRONT FENDER UNDERDUST COVER O/S		152.80
23.	1	FRONT WHEELHOUSE INNER PANEL O/S		198.00
24.	1	FRONT WHEELHOUSE OUTER PANEL O/S		186.00
25.	1	FRONT WHEELHOUSE EXTENSION INNER PANEL O/S		98.00
26.	1	FRONT WHEELHOUSE EXTENSION OUTER PANEL O/S		88.00
27.	1	WIPER WASHER TANK		125.00
28.	1	AIR RESONATOR		122.00
29.	1	AIR INTAKE AIR DUCT		60.00
30.	1	DASHBOARD		1,045.80
31.	1	DRIVER AIRBAG		1,345.80
32.	1	FRONT PASSENGER AIRBAG		2,340.10
33.	1	STEERING WHEEL AIRBAG SPIRAL CABLE		366.90
34.	1	STEERING ANGLE SENSOR		398.60
35.	2	FRONT IMPACT SENSOR	243.80	487.60
36.	2	FRONT SEAT BELTS	1,298.00	2,596.00
37.	2	FRONT SEAT BELT BUCKLES	328.00	656.00

CONTINUE / ...

WORLD AUTO PTE LTD
 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
 S'PORE 577200
 Tel No. : 64513933 Fax No. : 64557576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

Page 2 / 3

MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SOX CENTRE 2
 S'PORE 068807

Attention : Motor Claim Department
 Contact : 68277888 Fax No. : 68277809

Tax Invoice : F188735

Date : 28/08/2018
 Vehicle Num. : SLK 9706M
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 11/09/2017
 Claim No. : TP/1428/2017
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
38.	1	AIRBAG CONTROL MODULE		936.20
39.	1	RADIATOR FAN COWLING		186.00
40.	1	RADIATOR FAN BLADE		80.00
41.	1	RADIATOR FAN MOTOR		320.00
42.	1	A/C CONDENSER FAN COWLING		110.00
43.	1	A/C CONDENSER FAN BLADE		75.00
44.	1	A/C CONDENSER FAN MOTOR		320.00
45.	1	AIRCON RECEIVER PIPE		158.00
46.	1	A/C DISCHARGE HOSE		223.00
47.	1	SUCTION PIPE		160.00
48.	2	RADIATOR AIR GUIDE	60.00	120.00
49.	1	ENGINE UNDERCOVER O/S		75.00
List Total S\$:				23,808.70
20.00% Discount S\$:				4,761.74
				19,046.96
SPECIAL NETT ITEMS :				
1.	1 SET	BONNET INSULATOR CLIPS		30.00
2.	1 SET	FRONT BUMPER CLIPS		30.00
3.	1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS		20.00
4.	1 SET	FRONT FENDER UNDERDUST COVER CLIPS		20.00
5.	1	RADIATOR COOLANT		60.00
Special Nett Total S\$:				160.00
LABOUR :				
TO REPLACE DAMAGED LAMPS,CHECK WIRES AND CONNECTIONS FOCUS HEADLAMPS,INCLUDING REMOVE AND REFIT BATTERY, RELAYS AND SUPPORT PANEL HARNESS WIRES AND ETC.				150.00
* TO REMOVE AND REPLACE THE ABOVE LISTED PARTS,KNOCK OUT,STRAIGHTEN AND RESHAPE,CUT/WELD BODY PANEL PARTS WHERE NECESSARY,RE-POSITION AND RE-ALIGN,REPLACEMENT PARTS TO ORIGINAL POSITION INCLUDING ADJUSTMENT,USING OF REQUIRED EQUIPMENTS AND TOOLS IF NECESSARY				1,750.00
* TO PUTTY,SANDING,SPRAY PAINT AND POLISH REPAIRED AND				1,600.00

CONTINUE / ...

WORLD AUTO PTE LTD
47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG
S'PORE 577200
Tel No. : 64513933 Fax No. : 64557576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765H Buss. Reg. No. : 200006765H

Page 3 / 3

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01 SGX CENTRE 2
S'PORE 068807

Attention : Motor Claim Department
Contact : 68277888 Fax No. : 68277809

Tax Invoice : F188735

Date : 28/08/2018
Vehicle Num. : SLK 9706M
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 11/09/2017
Claim No. : TP/1428/2017
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REPLACE BODY PANELS INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE,SAND,PAPERS,PRIMER,POLISHING COMPUND		
		TO REMOVE AND REPLACE AIRBAGS,SET BELTS,DASHBOARD, STEERING WHEEL AND OTHERS,ANCILLARIES PARTS AND ETC.		350.00
		TO RESET FAULT CODES BY USING DIAGNOSTIC EQUIPMENTS AND SAFETY CHECK ETC		250.00
		TO REPLACE RADIATOR,CHECK PIPES AND HOSES INCLUDING WATER PRESSURE TEST AND ETC		120.00
		TO REPLACE AIRCON CONDENSER PIPES,HOSES CHECK LEAK AND REFILL GAS		150.00
		TO REMOVE AND REFIT ENGINE TO FACILITATE OF REPAIR BOTH FRONT CHASSIS FRAMES AND REPLACE WHEELHOUSING,INNER AND OUTER PANELS AND ETC		350.00
		TOWING CHARGE		60.00
		Labour Total S\$:		4,780.00

Total S\$: 23,986.96
GST 7% S\$: 1,679.09
Amount Due S\$: 25,666.05
=====


WORLD AUTO PTE LTD

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-136620

Date of Request: 13/09/2017

Your Ref No:

Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date 13/09/2017
Enquiry By FOO MEI LING
TP Vehicle No. SLC7408D
Accident Date 11/09/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLC7408D	MSIG Insurance (Singapore) Pte. Ltd.	01/06/2017-31/05/2018	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-136620

Date of Request: 13/09/2017

Your Ref No:

Online Purchase

World Auto Pte Ltd
47 Jln Pemimpin
#01-02/03 Halcyon 2
Singapore 577200

Dear Sir/Madam,

Enquiry Date 13/09/2017
Enquiry By FOO MEI LING
TP Vehicle No. SLC7408D
Accident Date 11/09/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

ROG ASSOCIATES

Bedok Central Post Office P.O.Box 577

(Business Regn. No. 272691/00C)

Automobile Licensed Appraisers/Assessors

& Loss Adjusters

AUTOMOBILE & MECHANICAL ENGINEERS

Mr Kang Eng Kiang

C/o World Auto Pte Ltd

47 Jalan Pemimpin #01-02/03

Halcyon 2 Building

Singapore 577200

Bill No. : 184080

Your Ref : Third Party

Our Ref : **184080.Ps**

Date : 30 May 2018

PARTICULARS	AMOUNT S\$
-------------	---------------

Vehicle No : **SLK9706M**

Model : Honda Vezel HB 1.5 (A)

Date of Accd: 11 Sep 2017

Policy No. : -

Claim No : -

Insured : -

To our Professional charges in connection with the below matters:-


- | | |
|--|--------|
| 1) To peruse accident reports, repair estimation, analysis vehicle accident damaged portion, to submit survey reports (2sets) and attached with photographs and etc. | 780.00 |
| 2) To supply of colour inks, provide photography service and print out/submit (25) colour photographs. | 25.00 |

Total: **\$805.00**

(SDLS: EIGHT HUNDRED AND FIVE ONLY)

Please quote our Bill No. or return a copy Bill with your remittance. Cheque should be made payable to ROG ASSOCIATES

ROG ASSOCIATES



Authorised Signature

E.&O.E



ROG ASSOCIATES

Business Regn. No. 272691/00C
Bedok Central Post Office P.O. Box 577
Singapore 460218
Tel:67495955/96423855 Fax:62433728
Email: rogassociates@gmail.com

- Acc. Reconstructionists
- Integrated Consultants
- Mechanical Engineers
- Automobile Engineers
- Diagnostic Engineers
- Adjusters/Appraisers
- Valuers/Assessors
- Expert witnesses
- Arbitration
- Mediation

Date: 30 May 2018

Our Ref: 184080.Ps

Your Ref: Assessment cost of repair

Mr. Kang Eng Kiang
C/o World Auto Pte Ltd
47 Jalan Pemimpin #01-02/03
Halcyon 2 Building
Singapore 577200

Dear Sir,

**ASSESSEMNT COST OF REPAIR FOR VEHICLE SLK9706M (FEB/2017)
ACCIDENT ON 11 SEP 2017 WITH VEHICLE SLC7408D**

REFERENCE

We refer to your instruction dated 12 May 2018.

DOCUMENTS

Basing on the below documents received;

1. Colour photographs of your vehicle SLK9706M, herein after ("the vehicle");
2. Accident report of the vehicle; and
3. An estimation cost of repair of M/s World Auto Pte Ltd.

FINDINGS AND ASSESSEMNT COST OF REPAIR

The vehicle has sustained a severe impact on the frontal in direction more towards offside (o/s) portion. As a result, both front chassis frames bent, airbags activated and the entire front quarter portion shifted to nearside (n/s) and etc. We herewith render our professional assessment cost of repair on the attachment appendix (A). In our opinion, it is fair and reasonable.

ROG ASSOCIATES

Our Ref: 184080.Ps

Your Ref: Assessment cost of repair

Veh No. SLK9706M

Mr. Kang Eng Kiang

The entire repair require about (13) days to complete.

We attached herewith (25) colour photographs showing the vehicle damaged portion as well as the vehicle before painting.

Without Prejudice of the foregoing, we trust that this report provided by us will be of assistance to you in dealing with the matter.

Kindly notify us within (14) days of this report, if there is any discrepancy.

Yours faithfully,



ROGER S S GAN (P.Eng. UK)
MITAI, MSOAR, FIDiagE, MSIArb

APPENDIX A

ROG ASSOCIATES

Our Ref : 184080.Ps
Date : 30 May 2018

Survey held at: M/s World Auto Pte Ltd
1 Kranji Loop
Singapore 739535

Veh. No: SLK9706M Model : Honda Vezel HB 1.5 (A)

Qty	Description	Condition	Repairer's Estimation	Our Revised Recommendation
			S\$	S\$
	Parts Supply			
	LIST ITEMS			
1	Front bonnet	Buckled	795.00	795.00 DD✓
2	Front bonnet hinges	Twisted	170.00	170.00 BT✓
1	Front bonnet insulator	Intact	160.00	0.00 xnn
1	Bonnet lock	Bent	160.00	60.00 160.00 BT✓
1	Front bumper	Distorted	495.00	495.00 BR✓
1	Front bumper lower	Distorted	295.00	295.00 BR✓
1	Front bumper reinforcement	Bent	445.00	445.00 BT✓
1	Front bumper o/s retainer	Bent	75.00	75.00 NEC✓
1	Front bumper lower grille	Cracked	118.00	118.00 CRA✓
2	Headlamps	Cracked	3,160.00	3,160.00 CRA✓
2	Headlamp top brackets	Bent	136.00	60.00 136.00 BT✓
2	Headlamp lower brackets	Bent	156.00	70.00 156.00 BT✓
1	Front grille base	Cracked	380.00	380.00 CRA✓
1	Front grille moulding	Cracked	368.00	368.00 CRA✓
1	Grille centre lock bracket	Twisted	98.00	98.00 BT✓
1	Fog lamp o/s cover	Cracked	45.00	45.00 CRA✓
1	Support panel	Distorted	672.80	672.80 DD✓
1	Support panel top granish	Cracked	94.00	94.00 CRA✓
1	Radiator	Bent	1,311.90	1,311.90 BT✓
1	Condensor	Bent	1,160.00	1,160.00 BT✓
2	Front fenders (o/s) only	Buckled	999.20	499.60 DD✓
2	Fender wheel arch garnishes (o/s) only	Missing	289.20	144.60 MIS✓
1	Fender o/s under dust cover	Cracked	152.80	152.80 CRA✓
1	Front o/s wheel housing inner panel	Buckled	198.00	198.00 DIS✓
1	Front o/s wheel housing outer panel	Buckled	186.00	186.00 DD✓
1	O/s wheel house extension panel inner	Bent	98.00	98.00 BT✓
1	O/s wheel house extension panel outer	Bent	88.00	88.00 BT✓
1	Wiper washer tank	Dented	125.00	125.00 DD✓
1	Radiator sub-tank	Intact	68.00	0.00 } xnn
1	Water pump	Intact	680.00	0.00 }
1	Air resonator	Cracked	122.00	122.00 CRA✓
1	Air intake air duct	Cracked	60.00	60.00 CRA✓
1	Thermostat w/cover	Intact	90.00	0.00 }
1	EGR valve	Intact	450.00	0.00 }
			13,900.90	11,808.70

APPENDIX A

ROG ASSOCIATES

Cont's sheet ...2/-
Our Ref : 184080.Ps
Date : 30 May 2018

Veh. No: SLK9706M		Model : Honda Vezel HB 1.5 (A)		
Qty	Description	Condition	Repairer's Estimation	Our Revised Re commendation
		C/F	\$ 13,900.90	\$ 11,808.70
1	Dashboard	Cracked	1,045.80	1,045.80 CRA ✓
1	Driver Airbag	Activated	1,345.80	1,345.80 NEC ✓
1	Front n/s passenger airbag	Activated	2,340.10	2,340.10 NEC ✓
1	Steering wheel airbg spiral cable	Necessary	366.90	366.90 NEC ✓
1	Steering Angle sensor	Necessary	398.60	398.60 NH ✓
2	Impact airbag sensors	Activated	487.60	487.60 NEC ✓
2	Front seat belts	Activated	2,596.00	2,596.00
2	Front seat belts buckles	Activated	656.00	656.00 XNN ✓
1	Airbag control module	Activated	936.20	936.20 NEC ✓
1	Radiator fan cowling	Cracked	186.00	186.00 CRA ✓
1	Radiator fan blade	Twisted	80.00	80.00 CRA ✓
1	Radiator fan motor	Dented	320.00	320.00 DD ✓
1	Aircon-condensor fan cowling	Cracked	110.00	110.00 CRA ✓
1	con-condensor fan balde	Bent	75.00	75.00 BT ✓
1	Air-con condensor fan motor	Jammed	320.00	320.00 DD ✓
1	Aircon receiver pipe	Kinked	158.00	158.00
1	Discharge hose	Kinked	223.00	223.00 BT ✓
1	Suction pipe	Kinked	160.00	160.00
2	Radiator air guides	Cracked	120.00	120.00 CRA ✓
1	Wiper washer tank motor	Intact	96.00	0.00 XNN ✓
1	Engine o/s under cover	Cracked	75.00	75.00 CRA ✓
			25,996.90	23,808.70
Less 20%			5199.52	4761.74
			20,797.52	19,046.96
Special Nett				
1	Front bonnet insulator clips (set)	Necessary	30.00	30.00
1	Front bumper clips (set)	Necessary	30.00	30.00
1	Support panel top garnish clips (set)	Necessary	20.00	20.00
1	Fender under cover clips (set)	Necessary	20.00	20.00
1	Radiator coolant	Necessary	80.00	40.00 60.00
			21,037.52	19,206.96

..3/-

APPENDIX A

ROG ASSOCIATES

Cont's sheet ..3/-
Our Ref : 184080.Ps
Date : 30 May 2018

Veh. No:	SLK9706M	Model :	Honda Vezel HB 1.5 (A)	
Qty	Description	Condition	Repairer's Estimation	Our Revised Re commendation
		C/F	\$ 21,037.52	\$ 19,206.96

Labour Charges

1	To replace damaged lamps, check wires and connections focus head lamps, including remove and refit battery, relays and support panel harness wires and etc.	180.00	150.00	50.00
2	To remove and replace the above listed parts, knock out, straighten and reshape, cut and weld body panel parts where necessary, re-position and re-align, replacement parts to the original position including adjustment, using of required equipments and tools if necessary.	1,800.00	1,750.00	1,200.00
3	To putty, sanding, spray paint and polish repaired and replaced body panels including supply of paint materials such as masking tape, sand papers, primer, polishing compound	1,800.00	1,600.00	1,000.00
4	To remove and replace airbags, seat belts, dashboard, steering wheel and others, ancillaries parts and etc.	480.00	350.00	150.00
5	To reset fault codes by using diagnostic equipments and safety check etc.	280.00	250.00	100.00
6	To replace radiator, check pipes and hoses, including water pressure test and etc.	250.00	120.00	50.00
7	To replace aircon-condensor pipes, hoses check leak and refill gas.	250.00	150.00	120.00
8	To remove and refit engine to facilitate of repair both front chassis frames and replace wheel housing, inner and outer panels and etc.	480.00	350.00	200.00
9	To tow vehicle charge.	60.00	60.00	
		\$26,557.52	\$23,736.96	11,236.96



ROGER S. GAN
P.Eng (UK), MITAI, MSOAR, FIDiagE, MSIArb.

Repair days 12

TG Gan

8/11/18

Motor Claims Discharge Voucher

Insured / Owner : LCRF Pte Ltd Vehicle No : SLK 9706M
Policy No. : _____ NRIC : 201624597K
Address : _____
Tel : _____ H/P : _____

I am / We are the registered owners(s) of the above motor vehicle involved in the above captioned accident.

My / Our authorized repairs **WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 S'pore 577200** Will be forwarding to you all the relevant documents. I / We undertake to pay all the legal costs incurred thereof.

I / We have authorized **WORLD AUTO PTE LTD** to represent me / us in all aspects of my claim against the driver of the other vehicle and you may take full instructions from them.

In the event, I am / We are successful in my / our claim againsts the other driver who was involved in the above accident. I / We hereby irrevocable instruct and authorize you to deduct from the proceeds recovered your legal costs and incidentals and thereafter to forward the balance to **M/S WORLD AUTO PTE LTD**.

I / We authorize **M/S WORLD AUTO PTE LTD** to sign all discharge voucher / indemnity forms and all necessary documents in connection with and arising out of the above claim.

I / We undertake to indemnify you and keep you indemnified in respect of any claim or action that may rise as a result of your complying with my / our request.

I confirm that I have taken delivery of vehicle registration no. SLK 9706M from the requires, **M/S WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 s'pore 577200** and that all repairs necessary as a result of an accident in which the said vehicle was involves on or about the 11/09/2017 have been completed to my satisfaction and that i have no further claims whatsoever against the said repairs in respect hereof.

I hereby assign all monies arising from my claims, due under insurance policy to **M/S WORLD AUTO PTE LTD** of **47 Jalan Pemimpin #01 - 02/03, Halcyon 2 S'pore 577200**.

Kindly effect payment of all monies to **M/S WORLD AUTO PTE LTD** and only payment to them will constitute a good effective discharge of the debt.

Date : 16/10/2017

Signature of Insured / Owner : _____



...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2017		15 Sep 2017 14:15 Edit Adj Rpt	S\$21,063.68 Edit Estimates	S\$21,063.68 View Rpt		Pending for Survey Report Cancel Case








































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLK9706M	Date of Loss:	11/09/2017 12:00 - :59 [7 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/17-001419	Policy/Cover Note No.:	MSD/VPCP/17-001233-00 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018						
Vehicle Reg. No. (Insured):	SLC7408D	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 09/11/2018]								
Driver/Custodian (Insured):	NEO KEE TECK (), NRIC: S1414132D, Tel: +6581331515								
Adj Asg. Remarks:	pri								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (07/11/2018): Report Send Back Alerts - SLK9706M (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK9706M (MSC/V/17-001419)
[SLC7408D]
TP
LCRF PTE LTD
Sep 11 2017 12:00PM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
World Auto Pte Ltd - Kranji

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	18/09/17 08:38	Video - Accident From:DO - Reg. No: SLC7408D, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD							Load AVI	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	15/09/17 14:16	Accident Statement From:DO - Reg. No: SLC7408D, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD							Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	14/10/17 13:36	General View							Load JPG	
2	14/10/17 13:36	General View							Load JPG	
3	14/10/17 13:36	General View							Load JPG	
4	14/10/17 13:36	General View							Load JPG	
5	14/10/17 13:36	General View							Load JPG	
6	14/10/17 13:36	General View							Load JPG	
7	14/10/17 13:36	General View							Load JPG	
8	14/10/17 13:36	General View							Load JPG	
9	14/10/17 13:36	General View							Load JPG	
10	14/10/17 13:36	General View							Load JPG	
11	14/10/17 13:36	General View							Load JPG	
12	14/10/17 13:36	General View							Load JPG	
13	14/10/17 13:36	General View							Load JPG	
14	14/10/17 13:36	General View							Load JPG	
15	14/10/17 13:36	General View							Load JPG	
16	14/10/17 13:36	General View							Load JPG	
17	14/10/17 13:36	General View							Load JPG	
18	14/10/17 13:36	General View							Load JPG	
19	14/10/17 13:36	General View							Load JPG	
20	14/10/17 13:36	General View							Load JPG	
21	14/10/17 13:36	General View							Load JPG	
22	14/10/17 13:36	General View							Load JPG	
23	14/10/17 13:36	General View							Load JPG	
24	14/10/17 13:36	General View							Load JPG	
25	14/10/17 13:36	General View							Load JPG	
26	14/10/17 13:36	General View							Load JPG	
27	14/10/17 13:36	General View							Load JPG	
28	14/10/17 13:36	General View							Load JPG	
29	14/10/17 13:36	General View							Load JPG	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
30	14/10/17 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/10/17 13:36	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
58	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
59	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
60	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
61	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
62	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
63	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
64	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
65	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
66	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
67	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
68	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
69	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
70	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
71	14/10/17 13:37	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
72	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
73	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
74	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
75	14/10/17 13:37	General View	 Load JPG	<input checked="" type="checkbox"/>
76	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	14/10/17 13:37	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	14/10/17 13:37	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/09/17 14:16	TP GIA REPORT	 Load PDF	
2	15/09/17 14:16	WORLD AUTO NOMINATE LKK	 Load PDF	
3	04/10/18 17:53	LOD, TAX INVOICE, GIA SEARCH, SURVEY REPORT, DV,	 Load PDF	
4	04/10/18 17:53	COLOURED IMAGES	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 15:41	PRS Invoice	 Load PDF	
2	13/11/18 15:42	Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17017808/BQBE2-1

Date: 13/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001233-00
Claimant Vehicle No:	SLK9706M	Insured Vehicle No:	SLC7408D
Date of Loss:	11/09/2017	Nature of Claim:	TP
		Claim No:	MSCN/17-001419

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9706M	Engine No:	LEB5914768
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31214758
Reg. Date:	09/02/2017 (Man. Year: 2016)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,977.52	18,133.68	2,843.84	13.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	2,930.00	2,650.00	47.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,557.52	21,063.68	5,493.84	20.69
+ GST 7.00/7.00% (S\$)	1,859.03	1,474.46	384.57	20.69
Nett Amount (S\$)	28,416.55	22,538.14	5,878.41	20.69

INSPECTION

Date of Assignment:	15/09/2017		
Date Inspected:	15/09/2017	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535
Estimated Period of Repair:	12.0 days		

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK9706M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	795.00 FL	*795.00 FL
2	2		*FRONT BONNET HINGES	Bent	170.00 FL	*170.00 FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	160.00 FL	*- FL
4	1		*BONNET LOCK	Bent	160.00 FL	*60.00 FL
5	1		*FRONT BUMPER	Broken	495.00 FL	*495.00 FL
6	1		*FRONT BUMPER LOWER	Broken	295.00 FL	*295.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	445.00 FL	*445.00 FL
8	1		*FRONT BUMPER O/S RETAINER	Necessary	75.00 FL	*75.00 FL
9	1		*FRONT BUMPER LOWER GRILLE	Cracked	118.00 FL	*118.00 FL
10	2		*HEADLAMPS	Cracked	3,160.00 FL	*3,160.00 FL
11	2		*HEADLAMP TOP BRACKETS	Bent	136.00 FL	*60.00 FL
12	2		*HEADLAMP LOWER BRACKETS	Bent	156.00 FL	*70.00 FL
13	1		*FRONT GRILLE BASE	Cracked	380.00 FL	*380.00 FL
14	1		*FRONT GRILLE MOULDING	Cracked	368.00 FL	*368.00 FL
15	1		*GRILLE CENTRE LOCK BRACKET	Bent	98.00 FL	*98.00 FL
16	1		*FOG LAMP O/S COVER	Cracked	45.00 FL	*45.00 FL
17	1		*SUPPORT PANEL	Dented	672.80 FL	*672.80 FL
18	1		*SUPPORT PANEL TOP GARNISH	Cracked	94.00 FL	*94.00 FL
19	1		*RADIATOR	Bent	1,311.90 FL	*1,311.90 FL
20	1		*CONDENSOR	Bent	1,160.00 FL	*1,160.00 FL
21	1		*FRONT FENDER	O/S Dented	999.20 FL	*499.60 FL
22	1		*FENDER WHEEL ARCH GARNISHES	O/S Missing	289.20 FL	*144.60 FL
23	1		*FENDER O/S UNDER DUST COVER	Cracked	152.80 FL	*152.80 FL
24	1		*FRONT O/S WHEEL HOUSING INNER PANEL	Distorted	198.00 FL	*198.00 FL
25	1		*FRONT O/S WHEEL HOUSING OUTER PANEL	Dented	186.00 FL	*186.00 FL
26	1		*O/S WHEEL HOUSE EXTENSION PANEL INNER	Bent	98.00 FL	*98.00 FL
27	1		*O/S WHEEL HOUSE EXTENSION PANEL OUTER	Bent	88.00 FL	*88.00 FL
28	1		*WIPER WASHER TANK	Dented	125.00 FL	*125.00 FL
29	1		*RADIATOR SUB-TANK	Not Necessary	68.00 FL	*- FL
30	1		*WATER PUMP	Not Necessary	680.00 FL	*- FL
31	1		*AIR RESONATOR	Cracked	122.00 FL	*122.00 FL
32	1		*AIR INTAKE AIR DUCT	Cracked	60.00 FL	*60.00 FL
33	1		*THERMOSTAT W/COVER	Not Necessary	90.00 FL	*- FL
34	1		*EGR VALVE	Not Necessary	450.00 FL	*- FL
35	1		*DASHBOARD	Cracked	1,045.80 FL	*1,045.80 FL
36	1		*DRIVER AIRBAG	Necessary	1,345.80 FL	*1,345.80 FL
37	1		*FRONT N/S PASSENGER AIRBAG	Necessary	2,340.10 FL	*2,340.10 FL
38	1		*STEERING WHEEL AIRBG SPIRAL CABLE	Necessary	366.90 FL	*366.90 FL
39	1		*STEERING ANGLE SENSOR	Not Necessary	398.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*IMPACT AIDBAG SENSORS	Necessary	487.60 FL	*487.60 FL
41	2		*FRONT SEAT BELTS	Activated	2,596.00 FL	*2,596.00 FL
42	2		*FRONT SEAT BELTS BUCKLES	Not Necessary	656.00 FL	*- FL
43	1		*AIRBAG CONTROL MODULE	Necessary	936.20 FL	*936.20 FL
44	1		*RADIATOR FAN COWLING	Cracked	186.00 FL	*186.00 FL
45	1		*RADIATOR FAN BLADE	Cracked	80.00 FL	*80.00 FL
46	1		*RADIATOR FAN MOTOR	Dented	320.00 FL	*320.00 FL
47	1		*AIRCON-CONDENSOR FAN COWLING	Cracked	110.00 FL	*110.00 FL
48	1		*AIR-CON CONDENSOR FAN MOTOR	Dented	320.00 FL	*320.00 FL
49	1		*AIRCON RECEIVER PIPE	Bent	158.00 FL	*158.00 FL
50	1		*DISCHARGE HOSE	Bent	223.00 FL	*223.00 FL
51	1		*SUCTION PIPE	Bent	160.00 FL	*160.00 FL
52	2		*RADIATOR AIR GUIDES	Cracked	120.00 FL	*120.00 FL
53	1		*WIPER WASHER TANK MOTOR	Not Necessary	96.00 FL	*- FL
54	1		*ENGINE O/S UNDER COVER	Cracked	75.00 FL	*75.00 FL
55	1		*SET FRONT BONNET INSULATOR CLIPS	Necessary	30.00 FS	*30.00 FS
56	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
57	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
58	1		*SET FENDER UNDER COVER CLIPS	Necessary	20.00 FS	*20.00 FS
59	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
60	1		*CON-CONDENSOR FAN BALDE	Bent	75.00 FL	*75.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,176.90	22,632.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,199.38	4,498.42
Total Parts (\$\$)	20,977.52	18,133.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE DAMAGED LAMPS, CHECK WIRES AND CONNECTIONS FOCUS HEAD LAMPS, INCLUDING REMOVE AND REFIT BATTERY, RELAYS AND SUPPORT PANEL HARNESS WIRES AND ETC	New	180.00	50.00
2	TO REMOVE AND REPLACE THE ABOVE LISTED PARTS, KNOCK OUT, STRAIGHTEN AND RESHAPE, CUT AND WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION AND RE-ALIGN, REPLACEMENT PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT, USING OF REQUIRED EQUIPMENTS AND TOOLS IF NECESSARY	New	1,800.00	1,200.00
3	TO PUTTY, SANDING, SPRAY PAINT AND POLISH REPAIRED AND REPLACED BODY PANELS INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND	New	1,800.00	1,000.00
4	TO REMOVE AND REPLACE AIRBAGS, SEAT BELTS, DASHBOARD, STEERING WHEEL AND OTHERS, ANCILLARIES PARTS AND ETC	New	480.00	150.00
5	TO REPLACE RADIATOR, CHECK PIPES AND HOSES, INCLUDING WATER PRESSURE TEST AND ETC	New	250.00	50.00
6	TO REPLACE AIRCON-CONDENSOR PIPES, HOSES CHECK LEAK AND REFILL GAS	New	250.00	120.00
7	TO REMOVE AND REFIT ENGINE TO FACILITATE OF REPAIR BOTH FRONT CHASSIS FRAMES AND REPLACE WHEEL HOUSING, INNER AND OUTER PANELS AND ETC	New	480.00	200.00
8	TO TOW VEHICLE CHARGE	New	60.00	60.00
9	TO RESET FAULT CODES BY USING DIAGNOSTIC EQUIPMENTS AND SAFETY CHECK ETC	New	280.00	100.00
Gross Labour Cost (S\$)			5,580.00	2,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >