REF: N	1516 / CC3/ms(18020109/UVbn2
710.4503.5	IGNATENT .
From: Date:	Veh No. 5Jw 27876 Yr Regn: 3110
Estimated Cost:	Type: M.Cart M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or (4/
To Inspect Vehicle No: . SJW 2787G	Make: Topte con/bAttesco 1518
at Workshop m/s	Colour S./ A/C: Insured / Std / NI / NA
of A Common of	Sp.Reading / X F A/ 2 T/Radio: Insured / Std / NI / NA
Insured: 1/M 6 3681)	Eng/No:
Policy No. 29090793 mKF	C/No: MROS3 ZEE 106169102
Claims No. 574963	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder I Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Mil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65-25
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA /MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 4 W.	Front Rear
/DAC Accident Rport: // Consistent? : Yes or No	R/Bal. 6 mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6, mm L/Bal. 6, mm
Est. Repairs: 1 2 days Res.: Yes or No	D.O.A. 1/11/18 D.O.I. 7/11/18
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS LA 11994	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure, affected due to collision.
Date / Time Action / Instruction Lyrs Jally Hus Dep 11 h. Mety 10 asky lole. Redictor X	
8/11/18 Email police report to ti	Qion 14/11/2018 14 Aly (Red 24, 950.74, 718)
19/11/18 Confirmed 2/5 \$ 10,000 u	14 1944. (red 34, 950.74, 711)
19/11/18 Send preti revised via me	RECEIVED 2 D NOV 2018
Date/Time: File Pass to? - : Preli. Report	Days Of Repair: 12
: Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time. File Return to?	Transportation: 250
2) 20/11 - typist Add Fe	
	: Interview (\$) Photos
Report Format: Merimen	Tech. lovs (\$) Others
Lump Sum / I.B.I: (\$ 10,000/2	: Weakend (\$)
	TOTAL 260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd MSIG Insurance (Singapore) Pte. Ltd. To: 51 Ubi Ave 1 #01-25 4 Shenton Way Paya Ubi Industrial Park #21-01 SGX Centre 2 Singapore 408933 Singapore 068807 Date: 19 Nov 2018 Elaine Ngu Siau Mei Attn: **Preliminary Advice** : YM6968D Insured Vehicle No : 01/11/2018 Accident Date : SJW2797G TP Vehicle No : 09/11/2018 : TOYOTA COROLLA Assignment Date Make Est. Duration of Repair : 12.00 Date of Inspection: 07/11/2018 : FASTECH AUTO PTE LTD (HQ) Inspection At 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883 Point of Impact / General Description of Damages The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident. 34,950.74 Repairer's Estimate (Gross) :S\$ 10,000.00 (Lump Sum) :S\$ Revised Amount 0.00 :S\$ Check Items (Estimated) 10.000.00 :S\$ Total :S\$ Lump Sum Repair **Total Loss Consideration** :S\$ New for Old Value :S\$ Pre-Accident Value :\$\$ COE / PARF Rebate :SS Salvage Value :S\$ Margin for Repair Remarks The vehicle is economical/not economical for repair. (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

	OLDER TRA	Est Submitted	Adi Assigned	Adi Rot	Adi Su	omitted	Ins Auth'ed	Status	17.00
	02 Nov 2018	Est/Submitted	09 Nov 2018 09:38 Edit Adj Rpt	They right				Pending for Report Cancel Cas	
N	fain	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SU	BFOLDER DE		AL STATE OF THE ST			[Creat	ted by insurer]		
Insured:	GOLDBEL	L LEASING PTE I	TD, Co. Reg. N	lo.: 199001	196N				
Main Claimant:	SALIM BI	N KHANALI, II	: S1326619J				2040 15:00 :50		
Vehicle Reg. No.:	SJW279	7G			Date of Loss	[103 N	2018 15:00 - :59 Nonths and 16 Day	AND DESCRIPTION OF THE PARTY OF	Date (Man Yr)
Claim Type:	TP / 574	1963			Policy/Cove Note No.:	er 29090793MKF (Third Party Only) Coverage: 01/09/2018 - 31/08/2019			
Vehicle Reg. No. (Insured):	YM6968E	•			Policy No. (Claimant):				
(Insurco).					Excess:				
Repairer:	Fastech A	Auto Pte Ltd (HQ) 1 Kaki Bukit Av	ve 6, #01-46	5/48/50 Autoba	y, 417883	Kaki Bukit - Tel: 6	7465405	
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	HQ) - Tel: +	65 6827 7888	[Handle	ed by Elaine Ngu S	Siau Mei - 659	4 2540]
Adjuster:	LKK Auto	Consultants Pto	Ltd (HQ) - Tel:	6256-3561	[Handled b	MARCUS	S CHUA] [Imn	n.Advice du	e 10/11/2010
Driver/Cust dian (Insured):		TAR BIN YADI (),	NRIC: \$16767	71I, Tel: +	6591991532				
Adj Asg. Remarks:	DIRECT S	URVEY BY LKK DO	NE ON 07.11.20	18					
ASSOCIAT	TED MAIL RI	ECEIVED						View All C	ompose Case M
There are n	no mail for this	s case.							
ALL ASSO	CIATED TA	sks⊟				View			
Due Dat	e Priority	Type Task	Group Sub	ject Ha	ndler Assi	gned By	Completed (On Creat	ed On Don
No results.									

Veron Chen (LKKAuto)

From:

Low Yi Qian <yiqian_low@sg.msig-asia.com>

Sent:

Friday, 9 November 2018 9:40 AM

To:

Veron Chen (LKKAuto)

Cc:

SUR; KKLau; Accounts (LKKAuto); Elaine Ngu

Subject:

RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/11/2018, SJW 2797G (TP VEHICLE), YM 6968D (OI VEHICLE) Claim Ref: 574963

Hi Veron

Thank you for your email.

Claim Reference: 574963 for your action.

Thank you and have a great day ahead!

Best Regards Low Yi Qian Administrative Officer Claims Services Department Direct line +65 6594 2525 | Direct fax +65 6225 7402 | yiqian_low@sg.msig-asia.com





MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on @MSIG_SG

A member of MS&AD INSURANCE GROUP

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, 8 November, 2018 2:05 PM

To: Low Yi Qian <yiqian_low@sg.msig-asia.com>; Low Yi Qian <yiqian_low@sg.msig-asia.com>

Cc: SUR <sur@lkkauto.com>; KKLau <kklau@lkkauto.com>; Accounts (LKKAuto) <account@lkkauto.com>

Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/11/2018, SJW 2797G (TP

VEHICLE), YM 6968D (OI VEHICLE)

Dear Yi Qian,

Please be informed that we had inspected the vehicle SJW 2797G at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 7/11/2018

Enclosed herewith a copy of police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 8 November 2018 2:05 PM

To:

Low Yi Qian; Low Yi Qian

Cc:

SUR; KKLau; Accounts (LKKAuto)

Subject:

DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:

1/11/2018, SJW 2797G (TP VEHICLE), YM 6968D (OI VEHICLE)

Attachments:

POLICE REPORT.pdf

Dear Yi Qian,

Please be informed that we had inspected the vehicle SJW 2797G at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 7/11/2018

Enclosed herewith a copy of police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products


Insurance

Articles

Forum

Resources

D X



SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CAR NUMBER PLATES FOR SALE!

Find the unique car number plate that represents you!

tovota corolla altis

Price Range

✓ Depreciation ✓

2010

Vehicle Type

Submit (

Advanced

Home » Used Cars » Karz Automobile » Toyota Corolla Altis 1.6A

Resources Car Buying Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing



Toyota Corolla Altis 1.6A

Financial Overview

Accessories

Similar

Research

Photos

Мар

utomobile Pte

Add to Shortlist

Add to Compare

Add a Note

Report Error

0

0

0

0

0

Ð

0

0

More Actions

Share

Car Details \$22,388 Price Depreciation \$11,320 /yr

16-Jan-2010

(1yr 2mths 8days COE left)

Manufactured 2009

Mileage

Reg Date

140,115 km (15.9k /yr)

View models with similar depreciation

Transmission

1,598 cc

Auto

Engine Cap Road Tax

\$742 /yr

Power

80.0 kW (107 bhp)

View specs of the Toyota Corolla Altis (2008-2013)

Curb Weight

Features

1,195 kg

Airbags, ABS, Reliable And Fuel Efficient 1.6L VVTI Engine, Climatic Aircon Control, Multi Function

Steering, Reverse Camera.

Accessories

Leather Seats, Sports Rims, Touch Screen Audio Player.

Description

Full And Regular Service At Borneo Motors! Well Maintenance By Previous Teacher Owner! Original Paint Work With No Accidents Records, Drive Away With No Repair Needed. Contact Us For Test Drive Now!

\$18,502

COE OMV

\$17,853

ARF

\$17,853

Dereg Value

\$12,019 as of today (change)

No. of Owners

Mid-Sized Sedan

Type of Veh

PARE CHE

Category Availability

Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 08-Oct-2018 | Last Updated on: 17-Oct-2018

Compare













Seller Information

Company

Karz Automobile » dealer's pricelist

» 15 vehs sold | 21 vehs available

Address

31 West Coast Highway #01-04/05 Search cars nearby this location

Location

West Coast Car Mart

Office No

62882454 Contact Person(s) Anthony Yeo

90088400

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	6619J
Vehicle No.:	SJW2797G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	3ZZ4980288
Chassis No.:	MR053ZEE106169102
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	16 Mar 2010
First Registration Date:	16 Mar 2010
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$16,716.00 PSF
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Mar 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	15 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$2,801.00
Total Rebate Amount:	\$11,994.00

The information contained herein is correct as at 07 Nov 2018

ОК

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	ou nervely consent to the arenating of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	02/11/2018 10:43
Date Of Accident	01/11/2018 15:45
Exact Location Of Accident	BKE TWRDS WOODLANDS BEFORE BT PANJANG/CCK EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJW2797G
Insured/Policyholder	
Name Of Registered Owner	SALIM BIN KHANALI
NRIC No	S1326619J
Email Address	NOEMAIL

Mobile Phone No (LOCAL) +65-98217259 Alternative Phone No OTHERS-98217259

Vehicle Particulars

Manufacturer TOYOTA

Model COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy NO

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

PVT USE

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5103128619 Cover Note Number 20/8/18-15/9/19

Driver

Name of Driver SALIM BIN KHANALI

NRIC No S1326619J Date Of Birth 15/10/1958 Occupation INDOOR Date Of Driving Pass 01/10/2007

Driving Experience 11 YEARS AND 1 MONTH

Gender

Mobile Number (LOCAL) +65-98217259

Fax Number

Contact Number OTHERS-98217259

EMail Address NOEMAIL Address

BLK 415 YISHUN AVE 11 #08-309

Postcode

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

DRIZZLING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

BNF5587 (PRIVATE CAR)

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 31 YISHUN CENTRAL, POSTCODE: 768827, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-8529999 - FAX NO: 68522299

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER POLICE REPORT: T/20181102/2013

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

SD CARD WITH TRAFFIC POLICE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YM6968D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ABDUL PATAR BIN YADI

NRIC/Passport Number

S1676771I

Contact Number

91991532

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

BNF5587

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

SITI AISHAH BINTI ABDUL

NRIC/Passport Number

Contact Number

81424614

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LIM SEE BAK (TONY)

NRIC/Passport Number

F0181666R

Contact Number

82838840

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN
VEHICLE NO.: \$7 W27976
INSURER: NTW C

IMPORTANT NOTICE DATE & TIME:

15 46 hrs

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance
 Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that;

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed;
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

[ii] for complying with requirements under any regulations, laws or court orders-

Policyholder's Signature Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Effic. (YS


2-11-18

CHARNIC Match and only VI

Date & Time:

Sketch Plan #2

	- Resev-SI	cetin Attnct	red -		
			11-4-4-4		
44-4-4-4	4				
			1411		
			111111		
CRIBE CIRCUMSTANCE	ES OF THE ACCIDEN		4 1 4 4 4 1	14 19-4	2
			13.55		
Kefer to pe	olice report	, T/20/8/102	1013		
		The State of the S	1		
					· · · · · · · · · · · · · · · · · · ·
		and Adding Time Con			Name of China
under your own c		ave 14days Time Francy. Please check with			
under your own co	omprehensive polic	cy. Please check with			
under your own co	omprehensive polic	cy. Please check with			
under your own co	omprehensive polic	cy. Please check with			on.
under your own co	omprehensive polic rticulars are true in evi	cy. Please check with ery respect.	your policy for me	ore information	2·11·18
under your own co	omprehensive police rticulars are true in eve Driver's Sign	cy. Please check with ery respect.	your policy for me	Centre Person	2·11·18
lote : Please note that y under your own co CLARATION The declaration foregoing particles of the foregoing particles of the foregoing foregoing particles of the foregoing particles of	omprehensive police rticulars are true in eve Driver's Sign	ery respect. ature of the policyholder)	your policy for me	Centre Person	2·11·18







Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

1 of 4 Report No. T/20181102/2013

A TRAFFIC ACCIDENT

REPORT OF	A IKAFFIC	ACCIDENT		Station Diary No.		
Date/Time 02/11/20	e Report M 18 09:22	lade:	Vide Report No.: F/20181101/0163	42		
Informar	nt's Particu	ılars				
Name of	informant: IN KHANA	4	Address: APT BLK 415 YISHUN AVEI 760415	NUE 11 #08-309 SINGAPORE		
ID Type / ID No.: NRIC NO / S1326619J			Contact No.: Home/Office:	Mobile: 98217259		
Nationali			Email:			
Sex: Male	Age: 60	Date of Birth: 15/10/1958	Type of Informant: Driver			
Race: Indian Occupation: GRAB DRIVER		*	Language: Institution / School Nam English			
			Driving Licence Information: Class: 3 Date of Expiry:			

Type of Accident:	Non-Injury Foreign Vehicle	Drink Date/Time of		Type of Location Straight Road	
	I EXPRESSWAY Ilands bef Bukit Panjang/			D. I Consid Limits	
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:	
Traffic Flow: Traffic Control: One Way Not Controlled				Traffic Volume: Heavy	
Type of Collis	sion: ving Vehicles - Head To f	Rear		Anyone conveyed by ambulance: No	

Details of Ve	Blood Street, Street, St. St. St.	Make	Model	Color	Condition	No of Passenge
Vehicle No. BNF5587	Type	Ividito			Seriously Damaged	0
SJW2797G	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Seriously Damaged	0
YM6968D	Lorry		AOTO		Slightly Damaged	0





2 of 4

Report No. T/20181102/2013

Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999

CONTINUATION OF REPORT

Details of V	ehicle Insurance	L. Control of the Con	Fre War	Funiar Date
Vahicle No	Insurance Company	Insurance No	Effective	Expiry Date
		5103128619	20/08/2018	15/09/2019
SJW2797G	NTUC Income Insurance Co-Operative Limited	3100120010		

Details of Perso	n Involved	MARKET AND STREET	E ARREST ESPONSE	AL REI IS	9.44	ENGLES (SEE) AND SEE
Any Pedestrian Ir	volved: No				•	
No. of Pedestrians Injured: NIL Use			Use of Pe	destrian	Cross	ing: NA
Driver		A SHAPE	100 PHENONE			CARLES AND RESIDENCE
Name	SALIM BIN KHANALI		ID No		S1326619J	
Related Vehicle	SJW2797G (Car)			Contact No.		98217259
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL Date Dis					
	ted Medical Leave	NIL	Degree of	finjury	NIL	

Brief Details.

On the 01/11/2018 at about 1545hrs, I was driving my vehicle (V3) bearing registration number SJW2797G (White, Toyota Altis) along BKE heading towards Woodlands and was travelling on the middle of the 3 lane road. I was driving just before the exit of Bukit Panjang and Choa Chu Kang when there was a Large impact from the rear left of my vehicle, Causing my vehicle to surge forward and hit head onto the rear of V2 which was travelling ahead of me. V2 then surged forward and hit onto V1 which was travelling ahead. After the collision I came to a stop and the driver of V4, approached me and informed me that he had hit onto the rear of my vehicle causing the chain collision.

The driver of V4 also informed me that he was trying to avoid the bus ahead of him and swerved right to the middle lane and hit onto the rear left of my vehicle as he was unable to stop in time. All parties had exchanged contact details. Due to the chaotic incident I had overlooked to obtain the vehicle number of V1. Traffic police had attended to us and advised me to make a police report. Traffic police also obtained the memory card from my vehicles car camera for investigation purposes.

V1 - (Unknown Number plate, Tony, Hp; 82838840)

V2 - (BNF5587 - Aisha, Hp: 81424614)

V4 - (YM6968D - Petar HP: 91991532)

Both the lorries (V1 and V4) suffered minor damages. However both my vehicle and the Malaysian vehicle (V2 & V3) suffered extensive damages. My vehicle had the rear and front bumper dented in and dislodged badly and the rear left tail lights were damaged. My front bonnet and right side bumper and fenders were also damaged due to the accident. I have yet to get a workshop evaluation of the damages.





Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999 4 of 4 Report No. T/20181102/2013


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Re	eport: Signature Of Informant:
Sgt 2 SARVANN	
Signature Of Interpreter: Not applicable	Date/Time: 02/11/2018 09:22
Officer In Charge Of Case: TP / AEIT /	Classification Of Case:
SSI 2 SITIMARSITA BINTE BOHARI	
Contact No.: 65476219	SN 085
Authentication	X.
Signature:	5
Singapore Police For	ce



FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 SINGAPORE 417883

2 PCS

1 PCS

Acknowledged by Repairer Signature: VEHICLE NO: SJW 2797G Date: QTY PARTICULAR 1 PCS BOOTLID 1 PCS **BOOTLID REAR LOGO** 1 PCS BOOTLID '1.6' EMBLEM 1 PCS BOOTLID 'COROLLA' EMBLEM 1 PCS BOOTLID 'ALTIS' EMBLEM BOOTLID REFLECTORS @\$288.10 186.10 2 PCS 1 PCS BOOTLID OUTER CHROME GARNISH 1 PCS BOOTLID INNER LOCK 1 PCS BOOTLID WEATHERSTRIP 2 PCS BOOTLID HINGES @\$99.10 1 PCS BOOTLID INNER TRIM 1 SET BOOTLID INNER TRIM CLIPS 1 PCS REAR BUMPER 2 PCS REAR BUMPER REFLECTORS @\$35.00 2 PCS REAR BUMPER BRACKETS @\$65.50 1 PCS REAR BUMPER INNER SPONGE 2 PCS REAR BUMPER SIDE RETAINERS @\$66.10 1 SET REAR BUMPER CLIPS 1 PCS REAR END PANEL 1 PCS REAR END PANEL TOP GARNISH 2 PCS TAILLAMPS @\$385.10 TAILLAMP HOUSING PANELS @\$245.50 2 PCS 1 PCS REAR WINDSCREEN MOULDING 2 PCS REAR FENDERS @\$917.40 2 PCS REAR FENDER INNER TRIMS @\$315.13 229./0 1 PCS REAR EXHAUST 2 PCS REAR EXHAUST MOUNTINGS @\$35.00 1 PCS REAR FLOOR PANEL 1 PCS REAR FLOOR PANEL TOP BOARD 1 PCS BONNET 1 PCS BONNET INNER LOCK 1 PCS BONNET RUBBER 1 PCS BONNET INSULATOR 1 SET **BONNET INSULATOR CLIPS** 2 PCS BONNET HIN ES @\$78.10 1 PCS FRONT BUMPER 1 PCS FRONT BUMPER REINFORCEMENT

FRONT BUMPER SIDE HOLDERS @\$65.10

FRONT BUMPER CENTRE GRILLE

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before latter spray painting

To display damaged part(s) during resurvey

Parts onces are subject to confirmation

Third party survey is on a "Without Prejudice" basis

is subject to final approval from Insurance Company

Supplementary item(s) must be resurveyed and

No illegal modification(s) is allowed

2/5 410,000 7/11/18

Buc \$845.10 nu \$48.00 ne \$31.00 ner \$38.50 ner \$36.50 AlsAN \$576.20 126 Buffere \$266.10_ \$105.00 \$188.10 NISSEY \$198.20 IPC 11 \$311.20 \(\times \) 11 \$50.00 210 \$566.01-NISTAL \$70.00 17 6 SU SIN \$131.00 (2) \$248.10 \$132.20 120 \$50.00 ner \$619.10 \$238.10 x NISBRO \$770.20 176 \$491.00 17 6 \$88.10 N/S D/BUC \$1,834.80 (20 NISTORA \$630.26 11 \$826.55 × 17 \$70.00 × 1 \$945.10 × 1001 \$305.10 DP/Ju (\$1,425.10. twi \$105.00 \$31.00 nu \$288.10 0 11 11 \$50.00 Suf \$156.20 \$566.10 \$395.10 / \$130.20 \$102.30

13958.62

		W
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$45.00	NISMIS \$90.00 12C
1 PCS	FRONT BUMPER LOGO	MIS \$48.10 -
1 PCS	FRONT BUMPER TOP RUBBER	nn \$65.10
1 PCS	FRONT GRILLE	\$10 \$385.32
1 PCS	FRONT GRILLE CHROME MOULDING TOP	47 \$65.50 X
1 PCS	FRONT GRILLE CHROME MOULDING LOWER	\$68.75
1 PCS	FRONT SUPPORT PANEL	1 006.75
1 PCS	FRONT BRACE PANEL	
2 PCS	HEADLAMPS @\$850.10 680.10x2 1360.20	\$104.80
1 PCS	AIR CON CONDENSER	\$1,700.20
1 PCS	RADIATOR	17 \$2,101.10
1 SET	RADIATOR FAN COWLING	\$223.45 ¢
1 PCS	RADIATOR FAN MOTOR	19225.45 q
1 PCS	RADIATOR FAN BLADE	\$96.10
2 PCS	FRONT FENDERS @\$845.10 645-10x2	
2 PCS	FRONT FENDER INNERSHIELDS @\$199.10	\$1,690.20
1 SET	FRONT FENDER IINNERSHIELD CLIPS	4000.20
2 PCS	FRONT FENDER VVTI EMBLEMS @\$48.50	400.00
2 PCS	FRONT DOORS @\$1005.10	\$97.00
		\$2,010.20 🕮
	S.NETT	\$25,820.74
1 SET	REAR BUMPER REVERSE SENSOR	Shortel \$280,00 200
1 PCS	REAR END PANEL SEALANT	
1 PCS	REAR WINDSCREEN SEALANT	M \$50.00 -
1 SET		nu \$50.00 40
1 PCS	REAR LICENCE PLATE W/HOLDER	17 \$380.00 X
1 PCS	REAR REVERSE CARMERA REAR LICENCE PLATE W/HOLDER FRONT LICENCE PLATE W/HOLDER	344 \$50.00 Go
		Sent \$50.00 40
	LABOUR CHRAGES:	
	TO CHECK WIRING	2.0
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 30
	TO TRANSFER BOOTLID MECHANISM	\$80.00 50
		\$80.00 60
	TO DISMANTLE & REPLY REAR WINDSCREEN	\$150.00 / 20
	TO DISMANTLE & REPEIX REAR EXHAUST	17 \$100.00 X
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00 80
	TO DISMANTLE & REFIX PETROL TANK	\$100,00 60
	TO SPRAY RUST PROOFING	\$200.00 /20
	TO REFILL AIR CON GAS	\$150.00 100
	TO MOUNT VEHICLE ON CAR O-LINER	∧^ \$380.00 ×
	LABOUR FOR PANEL BEATING, & REPLACING PARTS	\$4,000.00 /800
	TO PUTTY & SPRAY PAINTING	
		\$2,800.00 /800
		TOTAL \$34,950.74

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/MSG18020109/UVBN2

Date:

27/11/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29090793MKF

Claimant Vehicle No :

SJW2797G

Insured Vehicle No:

YM6968D

Date of Loss:

01/11/2018

Nature of Claim:

TP

Claim No: 574963

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJW2797G

Make & Model:

TOYOTA COROLLA, 1.6 (A)

Engine No: Chassis No: Odometer: 3ZZ4980288 MR053ZEE106169102

145812 km

Reg. Date: Colour: 16/03/2010 (Man. Year: 2010) Silver

Engine Capacity: Market Value/New Car 1598 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): No Pre-accident Condition: Yes

Handbrake (Serviceable): CONDITION OF TYRES Yes Engine Modification:

2.

195/65 R15

Front Tyre Size: Front Left Side: 195/65 R15 Michelin 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm
The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
26,680.74	9,938.82	16,741.92	62.75
0.00	0.00	0.00	
8,270.00	4,220.00	4,050.00	48.97
0.00	0.00	0.00	
0.00	0.00	0.00	
34,950.74	14,158.82	20,791.92	59.49
	10,000.00		
34,950.74	10,000.00	24,950.74	71.39
2,446.55	700.00	1,746.55	71.39
37,397.29	10,700.00	26,697.29	71.39
	26,680.74 0.00 8,270.00 0.00 0.00 34,950.74 34,950.74 2,446.55	26,680.74 9,938.82 0.00 0.00 8,270.00 4,220.00 0.00 0.00 0.00 0.00 34,950.74 14,158.82 10,000.00 34,950.74 10,000.00 2,446.55 700.00	26,680.74 9,938.82 16,741.92 0.00 0.00 0.00 8,270.00 4,220.00 4,050.00 0.00 0.00 0.00 0.00 0.00 0.00 34,950.74 14,158.82 20,791.92 10,000.00 34,950.74 10,000.00 24,950.74 2,446.55 700.00 1,746.55

INSPECTION

Date of Assignment:

09/11/2018

Date Inspected:

07/11/2018 Inspected At:

Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Estimated Period of Repair:

12.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 27 Nov 2018) Part Source: MRM-SG

TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SJW2797G)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	com	mended	Parts
No.	Qtv	Part No. Par	ticulars

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Buckled	845.10 F	*845.10 FL
2	1	*BOOTLID REAR LOGO	Necessary	48.00 F	*48.00 FL
3	1	*BOOTLID 1.6 EMBLEM	Necessary	31.00 F	*31.00 FL
4	1	*BOOTLID COROLLA EMBLEM	Necessary	38.50 F	*38.50 FL
5	1	*BOOTLID ALTIS EMBLEM	Necessary	36.50 F	*36.50 FL
6	1	*BOOTLID REFLECTORS	N/s Broken	576.20 F	*186.10 FL
7	1	*BOOTLID OUTER CHROME GARNISH	Bent/Cracked	266.10 F	*266.10 FL
8	1	*BOOTLID INNER LOCK	Twisted	105.00 F	*105.00 FL
9	1	*BOOTLID WEATHERSTRIP	Twisted	188.10 F	*188.10 FL
10	1	*BOOTLID HINGES	N/s Bent	198.20 F	*99.10 FL
11	1	*BOOTLID INNER TRIM	Not Necessary	311.20 F	*- FL
12	1	*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
13	1	*REAR BUMPER	Distorted	566.01 F	*566.01 FL
14	1	*REAR BUMPER REFLECTORS	N/s Cracked	70.00 F	*35.00 FL
15	1	*REAR BUMPER BRACKETS	N/s Dented	131.00 F	*65.50 FL
16	1	*REAR BUMPER INNER SPONGE	Torn	248.10 F	*248.10 FL
17	1	*REAR BUMPER SIDE RETAINERS	N/s Cracked	132.20 F	*66.10 FL
18	1	*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1	*REAR END PANEL	Badly Dented	619.10 F	*619.10 FL
20	1	*REAR END PANEL TOP GARNISH	Not Necessary	238.10 F	*- FL
21	1	*TAILLAMPS	N/s Broken	770.20 F	*385.10 FL
22	1	*TAILLAMP HOUSING PANELS	N/s Dented	491.00 F	*245.50 FL
23	1	*REAR WINDSCREEN MOULDING	Necessary	88.10 F	*88.10 FL
24	1	*REAR FENDERS	N/s Dented/Buckled	1,834.80 F	*917.40 FL
25	1	*REAR FENDER INNER TRIMS	N/s Torn	630.26 F	*289.10 FL
26	1	*REAR EXHAUST	Not Necessary	826.55 F	*-FL
27	2	*REAR EXHAUST MOUNTINGS	Not Necessary	70.00 F	*-FL
28	1	*REAR FLOOR PANEL	Repair	945.10 F	*-FL
29	1	*REAR FLOOR PANEL TOP BOARD	Torn	305.10 F	*305.10 FL
30	1	*BONNET	Dented/Buckled	1,425.10 F	*1,425.10 FL
31	1	*BONNET INNER LOCK	Twisted	105.00 F	*105.00 FL
32	1	*BONNET RUBBER	Necessary	31.00 F	*31.00 FL
33	1	*BONNET INSULATOR	Not Necessary	288.10 F	*-FL
34	1	*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*-FL
35	2	*BONNET HINGES	Bent	156.20 F	*156.20 FL
36	1	*FRONT BUMPER	Distorted	566.10 F	*566.10 FL
37	1	*FRONT BUMPER REINFORCEMENT	Dented	395.10 F	*395.10 FL
38	2	*FRONT BUMPER SIDE HOLDERS	Bent	130.20 F	*130.20 FL
39	1	*FRONT BUMPER CENTRE GRILLE	Torn	102.30 F	*102.30 FL
40	1	*FRONT BUMPER FOG LAMP COVERS	N/s Missing	90.00 F	*45.00 FL
41	1	*FRONT BUMPER LOGO	Missing	48.10 F	*48.10 FL
42	1	*FRONT BUMPER TOP RUBBER	Necessary	65.10 F	*65.10 FL
43	1	*FRONT GRILLE	Broken	385.32 F	*385.32 FL
44	1	*FRONT GRILLE CHROME MOULDING TOP	Not Necessary	65,50 F	*- FL

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
45	1		*FRONT GRILLE CHROME MOULDING LOWER	Not Necessary	68.75 F	*-FL
46	1		*FRONT SUPPORT PANEL	Bent/Buckled	728.10 F	*728.10FL
47	1		*FRONT BRACE PANEL	Twisted	104.80 F	*104.80 FL
48	2		*HEADLAMPS	Cracked	1,700.20 F	*1,360.20 FL
49 50	1		*AIR CON CONDENSER *RADIATOR	Serviceable Not Necessary	1,388.10 F 2,101.10 F	*-FL *-FL
51	1		*SET RADIATOR FAN COWLING	Not Necessary	223.45 F	*-FL
52	1		*RADIATOR FAN MOTOR	Not Necessary	541.90 F	*-FL
53	1		*RADIATOR FAN BLADE	Not Necessary	96.10 F	*-FL
54	2		*FRONT FENDERS	Buckled	1,690.20 F	*1,290.20 FL
55	2		*FRONT FENDER INNERSHIELDS	Not Necessary	398.20 F	*-FL
56	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	60.00 F	*-FL
57	2		*FRONT FENDER VVTI EMBLEMS	Necessary	97.00 F	*97.00 FL
58	2		*FRONT DOORS	Repair	2,010.20 F	*-FL
59	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	
60	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	
61	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	
62	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	
63	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	
64	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
F=Fr	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	26,680.74	13,128.43
			- List Item Discount on L Ite	ems 0.00/25.00% (S\$)	0.00	3,189.61
				Total Parts (S\$)	26,680.74	9,938.82
			Report was unsubmitted during t	his print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
Reconniciaed	Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	-
6	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	New	150.00	80.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
8	TO SPRAY RUST PROOFING	New	200.00	120.00
9	TO REFILL AIR CON GAS	New	150.00	100.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	4,000.00	1,800.00
11	TO PUTTY & SPRAY PAINTING	New	2,800.00	1,800.00
12	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
	Gross Labo	ur Cost (S\$)	8,270.00	4,220.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >