

ASS. REC. BY:

REF:

CS/FCL18020110/Utb2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

WS Lawrence Jena

of

FCL

Date/Time:

03-11-2018 931am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 2514S

Insured:

SHB 2304E

at Workshop m/s

Strong Hui

Tel:

6565 7272

of

Blk 1 Kaki Bukit Ave 6 #02-03

Policy No:

Claim No:

D18007953MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Huet

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLG 2514S - X

SHB 2304E - CS / FCL18007417 / GZ4632

DA: 150418

Glu@4:05pm sent email pending estimate.

REF:

Signature (M/M)

FCI/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG25145

Yr Regn:

9/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Naza 3

C.C.

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

115-946

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BM-42A860342663

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Comperon

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/11/18

D.O.I.

7/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have vide... LTA 50283
no undercarriage headlight

10/12/18 4/5 \$7300 confirmed with AM Insur.
cred: 11379.28! 60%)

RECEIVED 12 DEC 2018

Date/Time. File Pass to?

1) 12/12 Typist

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$7300)

TP

☐

Preli. Report

☒

Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) S + PS. \$

) Photos

) Others

TOTAL

8x15 = 120

170 + 120

50

50

85

475

MOTOR SURVEY ASSIGNMENT

Date	07-11-2018	Our Ref No. D18007953MFSH
Accident Date	02-11-2018	Claim Type. Third Party
Insured Vehicle	SHB2304E	Third Party Vehicle. SLG2514S
Survey Location	1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY	
Contact Person.	MR AH HUAT	
Contact No.	65557272/ 65557272	Fax No. 63383536
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG HAI MOTOR & TRADING	Attention. NIL
Cc : TP Solicitor	HIN TAT AUGUSTINE & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 8 November 2018 4:05 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007953MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLG 2514S on 7/11/2018.
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 8 November 2018 9:37 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007953MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 November, 2018 9:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007953MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 7424G

Vehicle Details

Vehicle No.: SLG2514S

Vehicle to be Exported: No

Intended Deregistration Date: 10 Nov 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: P520368216

Chassis No.: JM6BM42A8G0342663

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$17,128.00

Original Registration Date: 26 Sep 2016

First Registration Date: 26 Sep 2016

Transfer Count: 2

Actual ARF Paid: \$12,128.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Sep 2026

PARF Rebate Amount: \$9,096.00

Intended COE Rebate Details

COE Expiry Date: 25 Sep 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,002.00

COE Rebate Amount: \$41,187.00

Total Rebate Amount: \$50,283.00

The information contained herein is correct as at 07 Nov 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- Confusing Signals
- LTA buys electric buses from China
- Singapore to Fail without PAP?

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Vios M At Incredible Price For What You Get!



Power! Tuned With JUN Camis &
Aftermarket Extractor, Lowered!
Best Manual Vios!
SG Cash N Cars StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997

[view our cars](#)

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

25 vehicles

Mazda 3

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mazda 3		Any	Any	2016	Any	Any	Any	Available
	Mazda 3	1.5A Sunroof	\$63,588	\$7,590 /yr	24-Jun-2016	1,496 cc	38,500 km	Sedan	Available
Monthly \$605 Only! 1 Owner, Low Mileage Done! Full Agent Maintained! Superb Condition, As Good As New! 100% Accident Free! Fuel Consumption Friendly! Bank Loan/In-House Loan Available, Low Down-Paymen...									
Posted: 06-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	HB 1.5A	\$73,300	\$8,270 /yr	12-Dec-2016	1,496 cc	38,000 km	Hatchback	Available
Graded A by STP									
20% Deposit, Enjoy Promotion Rate From 1.99%, Under Warranty And Free Servicing With Agent, Superb Condition, Buy With A Peace Of Mind, Easy Loan / Trade In Available.									
Posted: 06-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A Sunroof	\$70,800	\$7,990 /yr	27-Dec-2016	1,496 cc	18,000 km	Sedan	Available
Almost New! Agent Unit! Come With 3 Years Agent Warranty! Lowest Depreciation, High Loan Available. 90% Loan! Flexible Repayment With In House Financing, \$6000 Drive Away Possible. Trade In Available....									
Tay Motor & Credit Pte Ltd									
Posted: 06-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A Sunroof	\$61,800	\$7,620 /yr	30-Mar-2016	1,496 cc	44,000 km	Sedan	Available
1 Owner With Low Mileage Done. Fully Agent Serviced And Just Done On 20/8/18. Still Under Agent Warranty. Still In Original Paintwork And Condition! Peace Of Mind! 100% Accident Free! Call Us Now For ...									
Posted: 05-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$64,500	\$7,840 /yr	26-May-2016	1,496 cc	48,900 km	Sedan	Available
Elegant White, With Sunroof, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.									
Prime Motor & Leasing									
Posted: 04-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									
	Mazda 3	1.5A	\$67,800	\$7,860 /yr	09-Sep-2016	1,496 cc	23,500 km	Sedan	Available
Almost New! Agent Unit! Come With 3 Years Agent Warranty! Lowest Depreciation, High Loan Available. 90% Loan! Flexible Repayment With In House Financing, \$6000 Drive Away Possible. Trade In Available....									
Tay Motor & Credit Pte Ltd									
Posted: 04-Nov-2018 Tags: 2016 Mazda 3, 2016 mazda 3, Mazda 3, mazda 3, Mazda, 3, Used Mazda									

Compare

SIONG HAI MOTOR AND TRADING

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 65557272

Fax: 67411019

H/P: 93365311 (Ah Huat)

Vehicle No: SLG25145

Model: MAZDA 3

Not Authorised
2/5 27300/1
7/11/18
Take photos of everyone
5 day.

QTY	List Items	Price \$
1	Front bumper <i>cut 7/20-1</i>	1339.50
1	Front bumper L/H retainer <i>sent</i>	42.50
1	Front L/H fender <i>10/30-1</i>	333.90
1	Front L/H fender inner shields <i>20/30-1</i>	129.50
1	Front L/H headlamp <i>one</i>	1889.00
1	Front support panel <i>11</i>	569.00
1	Front L/H door <i>20/30-1</i>	1143.00
1	Front L/H door innerboard <i>11</i>	850.00
2	Front L/H door hinges (1) 85.30 <i>11</i>	170.60
1	Front L/H door mirror <i>cut 650</i>	787.00
1	Front L/H door outer handle assy <i>11</i>	128.00
1	Front L/H door inner lock <i>11</i>	362.50
1	Front L/H door glass outer chrome <i>11</i>	76.00
1	Front L/H door glass outer top moulding <i>11</i>	75.00
1	Front L/H door glass outer rear moulding <i>11</i>	78.00
1	Front L/H door weatherstrip <i>11</i>	106.00
1	Rear L/H door <i>20/30-1 1024.30</i>	1075.00
1	Rear L/H door inner board <i>11</i>	805.00
1	Rear L/H door weatherstrip <i>11</i>	106.00
1	Rear L/H door outer handle assy <i>11</i>	128.00
1	Rear L/H door inner lock <i>11</i>	321.50
1	Rear L/H door glass outer chrome <i>11</i>	70.00
1	Rear L/H door glass outer top moulding <i>11</i>	70.00
1	Rear L/H door glass outer front moulding <i>11</i>	78.00
1	Rear L/H door 1/4 glass rubber <i>11</i>	87.00
1	Rear L/H fender <i>10/30-1</i>	891.90
1	Rear L/H fender inner shield <i>11</i>	68.60
1	Rear L/H windscreen glass outer moulding <i>11</i>	89.00
1	Rear L/H taillamp <i>11</i>	1078.60
1	Rear bumper <i>11</i>	1160.00
1	Rear L/H shock absorber <i>11</i>	228.00
1	Rear L/H lower arm <i>11</i>	258.00
1	Rear L/H shock absorber <i>11</i>	320.00
1	Front L/H lower arm <i>11</i>	260.00

Total

\$15,174.10

Less 20%

\$3,034.82

\$12,139.28

7436.8
202
5949.44
9169.44

Special Nett Items

1set	Rear windscreen sealant	nn	80.00	40
1set	Front bumper clip	nn	45.00	✓
1set	Front fender shield clip	nn	45.00	✓
1set	Front door board clip	nn	45.00	X
1set	Rear door board clip	nn	45.00	X
1set	Rear fender shield clip	nn	45.00	X
1set	Rear bumper clip	nn	45.00	X
2	Front and rear sport rim (1) 800	nn	1600.00	800
2	Front and rear tyre (1) 250	nn	500	X
			\$2,450.00	<u>830</u>

Labour Charges

Towing charges	nn	100.00	X
To check wheel alignment		150.00	60
To remove,refix rear windscreen glass		180.00	120
To apply undercoating on accident parts		250.00	90
To transfer door mechanism front and rear		240.00	120
To remove,refix cushion seat,roof, carpets and interior trims to assist repair		250.00	80
To check centre locking and electrical wiring		120.00	20
Panel beating,cut,weld,remove and replacing above parts		1500.00	800
To respray painting and ETC		1300.00	1000

2290

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$18,679.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18020110/Utn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2304E	Veh. Inspected	SLG 2514S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007953MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	03/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0342663	Colour	BLUE	
Odometer	115946	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CAMPEON	6 mm	
L/H Front Tyre	205/60 R16	CAMPEON	6 mm	
R/H Rear Tyre	205/60 R16	CAMPEON	6 mm	
L/H Rear Tyre	205/60 R16	CAMPEON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2018	Inspection Date	07/11/2018	
Survey held at	SIONG HAI MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6 # 02-03 AUTOBAY SINGAPORE 417883.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 2514S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT / TORN	1,339.50	1,031.70
1	FRONT BUMPER L/H RETAINER	BENT	42.50	42.50
1	FRONT L/H FENDER	DENTED / BENT	333.90	333.90
1	FRONT L/H FENDER INNER SHIELDS	DEFORMED / TORN	129.50	129.50
1	FRONT L/H HEADLAMP	CRACKED	1,889.00	1,889.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	569.00	-
1	FRONT L/H DOOR	DENTED / BENT	1,143.00	1,143.00
1	FRONT L/H DOOR INNERBOARD	NOT NECESSARY	850.00	-
2	FRONT L/H DOOR HINGES @\$85.30	NOT NECESSARY	170.60	-
1	FRONT L/H DOOR MIRROR	CUT	787.00	650.00
1	FRONT L/H DOOR OUTER HANDLE ASSY	NOT NECESSARY	128.00	-
1	FRONT L/H DOOR INNER LOCK	NOT NECESSARY	362.50	-
1	FRONT L/H DOOR GLASS OUTER CHROME	NOT NECESSARY	76.00	-
1	FRONT L/H DOOR GLASS OUTER TOP MOULDING	NOT NECESSARY	75.00	-
1	FRONT L/H DOOR GLASS OUTER REAR MOULDING	NOT NECESSARY	78.00	-
1	FRONT L/H DOOR WEATHERSTRIP	NECESSARY	106.00	106.00
1	REAR L/H DOOR	DENTED / BENT	1,075.00	1,024.30
1	REAR L/H DOOR INNER BOARD	NOT NECESSARY	805.00	-
1	REAR L/H DOOR WEATHERSTRIP	NECESSARY	106.00	106.00
1	REAR L/H DOOR OUTER HANDLE ASSY	NOT NECESSARY	128.00	-
1	REAR L/H DOOR INNER LOCK	NOT NECESSARY	321.50	-
1	REAR L/H DOOR GLASS OUTER CHROME	NOT NECESSARY	70.00	-
1	REAR L/H DOOR GLASS OUTER TOP MOULDING	NOT NECESSARY	70.00	-
1	REAR L/H DOOR GLASS OUTER FRONT MOULDING	NOT NECESSARY	78.00	-
1	REAR L/H DOOR 1/4 GLASS RUBBER	NOT NECESSARY	87.00	-
1	REAR L/H FENDER	DENTED / BENT	891.90	891.90
1	REAR L/H FENDER INNER SHIELD	NOT NECESSARY	68.60	-
1	REAR WINDSCREEN GLASS OUTER MOULDING	NECESSARY	89.00	89.00
1	REAR L/H TAILLAMP	NOT NECESSARY	1,078.60	-
1	REAR BUMPER	NOT NECESSARY	1,160.00	-
1	REAR L/H SHOCK ABSORBER	NOT NECESSARY	228.00	-

Report Ref No. CS/FCI18020110/Utnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR L/H LOWER ARM	NOT NECESSARY	258.00	-
1	REAR L/H SHOCK ABSORBER	NOT NECESSARY	320.00	-
1	FRONT L/H LOWER ARM	NOT NECESSARY	260.00	-
	LESS 20% DISCOUNT		-3,034.82	-1,487.36
			12,139.28	5,949.44
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET FRONT FENDER SHIELD CLIP (SN)	NECESSARY	45.00	45.00
1	SET FRONT DOOR BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET REAR DOOR BOARD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET REAR FENDER SHIELD CLIP (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	45.00	-
2	FRONT AND REAR SPORT RIM @\$800.00 (SN)	CUT	1,600.00	800.00
2	FRONT AND REAR TYRE @\$250.00 (SN)	NOT NECESSARY	500.00	-
			2,450.00	930.00
	<u>LABOUR</u>			
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	TO CHECK WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE,REFIX REAR WINDSCREEN GLASS.		180.00	120.00
	TO APPLY UNDERCOATING ON ACCIDENT PARTS.		250.00	90.00
	TO TRANSFER DOOR MECHANISM FRONT AND REAR.		240.00	120.00
	TO REMOVE,REFIX CUSHION SEAT,ROOF,CARPETS AND INTERIOR TRIMS TO ASSIST REPAIR.		250.00	80.00
	TO CHECK CENTRE LOCKING AND ELECTRICAL WIRING.		120.00	20.00
	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS.		1,500.00	800.00
	TO RESPRAY PAINTING AND ETC.		1,300.00	1,000.00
			4,090.00	2,290.00
	GRAND TOTAL		18,679.28	9,169.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,300.00



Report Ref No. CS/FCI18020110/Utbn2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.