

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLK 8296 K

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N	\$	360.00	\$ 360.00
2	To remove and reinstall rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N	\$	480.00	\$ 480.00
3	To renew rear windscreen.	S/N	\$	480.00	\$ 480.00
4	To dismantle and renew rear bumper assy and rear lid. To repair lhs rear fender. Re-organize crash management components. Reinstall all parts removed.		\$	2,800.00	\$ 1,200.00
5	To respray rear top bumper, rear lower bumper, rear lid, lhs rear fender and both wheel arch covers, rear lid hinges.		\$	4,400.00	\$ 1,900.00
6	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	<u>8,712.00</u>	\$ <u>4,612.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 8296 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,648.00	\$ 2,118.40
2	REAR BUMPER FIXNG PARTS	\$ 178.00	
3	REAR BUMPER SPOILER BARCELONETA SILVER	\$ 1,095.00	\$ 876.00
4	REAR BUMPER SPOILER SATIN BLACK	\$ 92.00	
5	REAR BOOT LID CONTROL UNIT	\$ 334.00	
6	REAR SENSOR	2 \$ 421.00	
7	REAR SENSOR SEAL RING	4 \$ 14.00	
8	REAR BUMPER CARRIER	\$ 1,189.00	
9	REAR BUMPER HOLDING STRAP	\$ 156.00	
10	REAR BUMPER GUIDE SECTION-LH	\$ 54.00	
11	REAR BUMPER GUIDE SECTION- CENTRE	\$ 121.00	
12	REAR LID	\$ 4,295.00	\$ 3,436.00
13	REAR LID ATTACHMENT PARTS	\$ 133.00	
14	REAR LID HINGE-LH/RH	2 \$ 270.00	
15	REAR LID CHAFE GUARD	\$ 5.00	
16	REAR LID LOCK	\$ 224.00	
17	REAR LID COVER CAP FOR FLAP	\$ 10.00	
18	REAR LID LOCK STRIKER	\$ 75.00	
19	REAR LID PUSH BUTTON	\$ 1,181.00	
20	REAR BUMPER PACKING ADHESIVE	\$ 15.00	
SUB TOTAL PARTS CHARGES		\$ 12,510.00	\$ 6,430.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 8296 K

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT		
				\$	6,430.40
20	REAR LID AUDI EMBLEM		\$ 108.00	\$	86.00
21	REAR LID INSCRIPTION 'Q7'		\$ 83.00	\$	66.16
22	REAR LID INSCRIPTION 'TFSI'		\$ 83.00	\$	66.16
23	REAR LID INSCRIPTION 'QUATTRO'		\$ 83.00	\$	66.16
24	REAR SPOILER FIXING PARTS		\$ 53.00	\$	42.32
25	REAR WINDOW		\$ 847.00	\$	677.60
26	PRIMER	2	\$ 37.00	\$	29.12
27	REAR BUMPER TAIL LIGHT-LH		\$ 313.00	\$	250.40
28	REAR EXHAUST TAIL PIPE TRIM-LH		\$ 288.00		
29	REAR WHEEL COVER-LH/RH	2	\$ 662.00	\$	528.80
30	REAR NO. PLATE	S/N	\$ 25.00		
31	REAR W/S SEALANT	S/N	\$ 200.00	\$	200.00
32	Added parts - see attached		\$ 401.00	\$	320.80
33	SUNDRIES		\$ 500.00	\$	3.36
	TOTAL PARTS CHARGES	:	\$ 16,193.00	\$	8,767.28
	TOTAL LABOUR CHARGES	:	\$ 8,712.00	\$	4,612.00
	GRAND TOTAL	:	\$ 24,905.00	\$	13,379.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1242/2018/GW
21-Nov-18
JB
ONE
SLK 8296 K
Q7 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear windscreen moulding lhs/rhs (Nec) <i>Nec</i>	\$ 401.00	\$ 320.80
		<u>\$ 401.00</u>	<u>\$ 320.80</u>
<u>LABORS</u>			
	TOTAL	\$ 401.00	\$ 320.80

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLK 8296 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1242/2018/MAS

23 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLK 8296 K, Audi Q7 2.0 TFSI Qu

With reference to the above-mentioned vehicle, no. **SLK 8296 K**, claimant,
Mr. Devonald Andrew James, please find the related document per attached.

1. A copy of the Original invoice no. 85013454 – S\$13,245.83
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLK 8296 K

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408609
Telephone 6399 1343

Customer Service
Service Appointment 6365 2323
24 Hour Breakdown Service 9829 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 13:23

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013454
Date : 15/02/2019
Order : SLK8296K
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLK8296K (V 31441) Regn Date: 26/01/2017 Mileage: 20375 WIP No.: 30777
Model: Q7 2.0 TFSI DU (252 bhp) 4MB01 Chassis: WAUZZZ4M6HD009432 Engine: CYR 019471 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM,WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	480.00	1.00	480.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER ASSY AND REAR LID.TO REPAIR LHS REAR FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1200.00	1.00	1,200.00
S	BODYWORK	M: TO RESPRAY REAR TOP BUMPER,REAR LOWER BUMPER,	1900.00	1.00	1,900.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408600
Telephone: 6388 2323

Customer Service

Service Appointment: 6366 2323
24-hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

Page 2 13:23

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013454

Date: 15/02/2019

Order: SLK8296K

Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLK8296K (V 31441)

Regn Date: 26/01/2017

Mileage: 20375

WIP No.: 30777

Model: Q7 2.0 TFSI QU (252 bhp) 4M001

Chassis: WAUZZZ4M6HD009432

Engine: CYR 019471

Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REAR LID AND BOTH WHEEL ARCH COVER. M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	200.00	1.00	200.00
X	A4M0827025D	LID	1.00	4295.00	3,436.00
X	A4M0945095	(SK) TAILLIGHT	1.00	313.00	250.40
X	A4M0807511 GRU	(A) (SK) COVER (12/11/1)	1.00	1061.00	848.80
X	A4M0807434E KAB	(A) (SK) SPOILER (12/11)	1.00	1095.00	876.00
X	A4M0845501B NVB	REAR WINDOW	1.00	847.00	677.60
X	A4M0807067B GRU	COVER	1.00	1587.00	1,269.60
X	A4H0853737D 2ZZ	INSCRIPTION 'TFSI'	1.00	82.70	66.16
X	A4M0853737 2ZZ	INSCRIPTION "QUATTRO"	1.00	82.70	66.16
X	A4M0853741 2ZZ	INSCRIPTION "Q7"	1.00	82.70	66.16
X	A4M0853742 2ZZ	AUDI SIGN	1.00	107.50	86.00
X	A4G0827310	CLIP	2.00	2.10	3.36
X	A4M0898941	(A) (SK) PARTS KIT (19/	1.00	52.90	42.32
X	AD 00920002	PRIMER (D6)	2.00	18.20	29.12
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408629
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6566 2323
9826 1233

Page 3 13:23

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013454 Date: 15/02/2019 Order: SLK8296K Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SLK8296K (V 31441) Regn Date: 26/01/2017 Mileage: 20375 WIP No.: 30777
Model: Q7 2.0 TFSI QU (252 bhp) 4MB01 Chassis: WAUZZZ4M6HD009432 Engine: CYR 019471 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	A4M0854872A 5FQ	SPOILER	1.00	200.50	160.40
X	A4M0854871A 5FQ	SPOILER	1.00	200.50	160.40
X	A4M0853818A GRU	(A) (SK) COVER (12/11/1)	1.00	330.50	264.40
X	A4M0853817A GRU	(A) (SK) COVER (12/11/1)	1.00	330.50	264.40

Parts	8,567.28	Sub-Total	12,379.28
Labour	0.00	7% GST	866.55
Sublet	4,812.00	Grand Total	13,245.83
Menus	0.00		
Lubricant	0.00		

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLK 8296 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1242/2018/JW
22 November 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q7 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ4M6HD009432
Vehicle Regn No. : **SLK 8296 K**
Vehicle Mileage : 18276 km
Vehicle Owner : Mr Devonald Andrew James
Certificate No : 2100499565-01
Own Damage Excess : S\$ 1,070.00 (inclusive of 7% GST)
Accident Date : 30/10/2018
Place : At Tanglin Mall Carpark
Repair Cost : \$ 13,245.83
WIP No. : 30777
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


6pm
26/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	05 Nov 2018		07 Nov 2018 13:44 Edit Adj Rpt	S\$13,379.28 Edit Estimates	S\$13,379.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **DEVONALD ANDREW JAMES**, ID: G5963530T, Tel: +6581611158, Email: ANDREW.DENONALD@GMAIL.COM

Vehicle Reg. No.: **SLK8296K** Date of Loss: 30/10/2018 19:00 - :59
[21 Months and 4 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 3084753722SG** Policy/Cover Note No.: (Comprehensive)

Excess: S\$1,000.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**]
Norsazani.Zawaye@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [Final Rpt due 16/11/2018]

Driver/Custodian: **DEVONALD ANDREW JAMES (52 / Male)**, NRIC: G5963530T, Tel: +6581611158 Email: ANDREW.DENONALD@GMAIL.COM

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (09/11/2018): Alert - Adj Mandate Approved (S\$15119.00) - SLK8296K - Claim Handler: Mohd Zaway...
- AIG_SG (09/11/2018): SLK8296K / OD / 30/10/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLK8296K (3084753722SG)**
OD
Oct 30 2018 7:00PM
[DEVONALD ANDREW JAMES]
Premium Automobiles Pte Ltd

Upload Documents
Upload Photos
Compose New Letter
Upload Video
Upload Audio

View View in Browser

1 per page

Thumbnail Print

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 14:12	Adjuster Immediate Advice	1 Load HTM	

3 per page

Thumbnail Print

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 13:51	General View	1 Load JPG	
2	08/11/18 13:51	Chassis Number	1 Load JPG	
3	08/11/18 13:51	General View	1 Load JPG	
4	08/11/18 13:51	General View	1 Load JPG	
5	08/11/18 13:51	General View	1 Load JPG	
6	08/11/18 13:51	General View	1 Load JPG	
7	08/11/18 13:51	General View	1 Load JPG	
8	08/11/18 13:51	General View	1 Load JPG	
9	08/11/18 13:51	General View	1 Load JPG	
10	08/11/18 13:51	General View	1 Load JPG	
11	08/11/18 13:51	General View	1 Load JPG	
12	08/11/18 13:51	General View	1 Load JPG	
13	08/11/18 13:51	General View	1 Load JPG	
14	08/11/18 13:51	General View	1 Load JPG	
15	08/11/18 13:51	General View	1 Load JPG	

1 per page

Thumbnail Print

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 13:50	Singapore Accident Statement	1 Load PDF	
2	08/11/18 13:50	Certificate of Insurance	1 Load PDF	
3	08/11/18 13:50	Driver's Driving License	1 Load PDF	
4	08/11/18 13:50	ESTIMATE	1 Load PDF	
5	01/02/19 16:50	SUPPLEMENTARY LIST	1 Load PDF	
6	04/03/19 09:00	DISCHARGE VOUCHER	1 Load PDF	
7	04/03/19 09:00	SUPPLEMENTARY	1 Load PDF	
8	04/03/19 09:00	WORKSHOP INVOICE	1 Load PDF	

Linked Accident Report Documents

View View in Browser

1 per page

Thumbnail Print

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	31/10/18 19:06	Accident Statement	1 Load HTM	

3 per page

Thumbnail Print

No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
----	--------------	-----------------------------------	-----------	-------

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18020111/AQBS2

Date: 04/03/2019

REFERENCE

Insured/Claimant: DEVONALD ANDREW JAMES
Date of Loss: 30/10/2018

Policy No:
Nature of Claim: OD Claim No: 3084753722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK8296K**
Make & Model: AUDI Q7, 2.0 TFSI QU (A)
Reg. Date: 26/01/2017 (Man. Year: 2016)
Colour: Grey
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$220,000.00
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: CYR019471
Chassis No: WAUZZZ4M6HD009432
Odometer: 17754 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,112.80	8,767.28	7,345.52	45.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,712.00	4,612.00	4,100.00	47.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,824.80	13,379.28	11,445.52	46.11
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	23,824.80	12,379.28	11,445.52	48.04
+ GST 7.00/7.00% (S\$)	1,667.74	866.55	801.19	48.04
Nett Amount (S\$)	25,492.54	13,245.83	12,246.71	48.04

INSPECTION

Date of Assignment: 07/11/2018

Date Inspected: 07/11/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,648.00 FS	*2,118.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	178.00 FS	*- FS
3	1		*REAR BUMPER SPOILER BARCELONETA SILVER	Torn	1,095.00 FS	*876.00 FS
4	1		*REAR BUMPER SPOILER SATIN BLACK	Not Necessary	92.00 FS	*- FS
5	1		*REAR BOOT LID CONTROL UNIT	Not Necessary	334.00 FS	*- FS
6	2		*REAR SENSOR	Not Necessary	421.00 FS	*- FS
7	4		*REAR SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
8	1		*REAR BUMPER CARRIER	Not Necessary	1,189.00 FS	*- FS
9	1		*REAR BUMPER HOLDING STRAP	Not Necessary	156.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	54.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION - CENTRE	Not Necessary	121.00 FS	*- FS
12	1		*REAR LID	Dented	4,295.00 FS	*3,436.00 FS
13	1		*REAR LID ATTACHMENT PARTS	Not Necessary	133.00 FS	*- FS
14	2		*REAR LID HINGE - LH/RH	Not Necessary	270.00 FS	*- FS
15	1		*REAR LID CHAFE GUARD	Not Necessary	5.00 FS	*- FS
16	1		*REAR LID LOCK	Not Necessary	224.00 FS	*- FS
17	1		*REAR LID COVER CAP FOR FLAP	Not Necessary	10.00 FS	*- FS
18	1		*REAR LID LOCK STRIKER	Not Necessary	75.00 FS	*- FS
19	1		*REAR LID PUSH BUTTON	Not Necessary	1,181.00 FS	*- FS
20	1		*REAR BUMPER PACKING ADHESIVE	Not Necessary	15.00 FS	*- FS
21	1		*REAR LID AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
22	1		*REAR LID INSCRIPTION Q7	Necessary	83.00 FS	*66.16 FS
23	1		*REAR LID INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
24	1		*REAR LID INSCRIPTION QUATTRO	Necessary	83.00 FS	*66.16 FS
25	1		*REAR SPOILER FIXING PARTS	Necessary	53.00 FS	*42.32 FS
26	1		*REAR WINDOW	Necessary	847.00 FS	*677.60 FS
27	2		*PRIMER	Necessary	37.00 FS	*29.12 FS
28	1		*REAR BUMPER TAIL LIGHT - LH	Cracked	313.00 FS	*250.40 FS
29	1		*REAR EXHAUST TAIL PIPE TRIM - LH	Not Necessary	288.00 FS	*- FS
30	2		*REAR WHEEL COVER - LH/RH	Necessary	662.00 FS	*528.80 FS
31	1		*REAR NO. PLATE	Not Necessary	25.00 FS	*- FS
32	1		*REAR W/S SEALANT	Necessary	200.00 FS	*200.00 FS
33	1		*SUNDRIES	Necessary	500.00 FS	*3.36 FS
34	1		*REAR WINDSCREEN MOULDING LHS/RHS	Necessary	320.80 FS	*320.80 FS
Total Parts (\$\$)					16,112.80	8,767.28

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
2	TO REMOVE AND REINSTALL REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN.	New	480.00	480.00
4	TO DISMANTLE AND RENEW REAR BUMPER ASSY AND REAR LID. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,800.00	1,200.00
5	TO RESPRAY REAR TOP BUMPER, REAR LOWER BUMPER, REAR LID, LHS REAR FENDER AND BOTH WHEEL ARCH COVERS, REAR LID HINGES.	New	4,400.00	1,900.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			8,712.00	4,612.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >