

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1268/2018/GW
Date	:	08-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Cao FengGang
Address	:	Blk 685 A Choa Chu Kang Crescent #10-284 Singapore 681685
Telephone	:	HP +65 98562915
Type of Claim	:	Own Damage Claim
Policy No.	:	2100491686-01
Vehicle No	:	SLJ 908 L
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Nov-16
Engine No	:	CVN 017706
Chassis No	:	WAUZZZF46HA025404
Mileage	:	
Date In	:	
Liability	:	
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	02-Nov-18
Place of Accident	:	B2 Carpark of Triling Condo S(128801)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 908 L

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To renew rear windscreen and lhs 1/4 glass for fener renewal.	S/N \$ 600.00 ✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓
4	To remove and reinsall rear seat, back rest, hat tray, abcd pillar trims, luggage conmpartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓
SUB-TOTAL LABOUR CHARGES		: \$ 3,760.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 908 L

S/N	Nature of Jobs	Estimated Charges
5	To dismantle rear bumper and rear lid. Cut out and reweld lhs rear fender. Renew rear bumper. Re-organize crash management components. Reinstall all parts removed. <i>550 ✓ 550 ✓ 275</i>	\$ 4,800.00 3000 .
6 550	To respray rear bumper , lhs rear fender, lhs sill panel, door entrances, roof channel, drain channel end panelling. To carry out joint sealant work and stone chip treatment.	\$ 3,900.00 1925
7	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 X
8	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>12,932.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 908 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>reborned</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS	\$ 63.00	x
3	REAR BUMPER SECURING PLATE	4 \$ 56.00	✓
4	REAR BUMPER SECURING STRIP	\$ 191.00	x
5	REAR BUMPER SPOILER	\$ 216.00	x
6	REAR LIGHT REFLECTOR RIGHT-LH <i>Not Nec</i>	\$ 35.00	x
7	REAR BUMPER GUIDE SECTION	\$ 37.00	?
8	REAR BUMPER UPPER GUIDE SECTION-LH	\$ 19.00	?
9	REAR SENSOR SEAL RING <i>Not Nec</i>	4 \$ 14.00	x
10	REAR SECTIONAL PART-LH <i>Distorted</i>	\$ 2,347.00	✓
11	REAR WINDOW	\$ 1,014.00	✓
12	PRIMER	2 \$ 37.00	✓
13	REAR SIDE WINDOW	\$ 541.00	✓
14	REAR SIDE WINDOW TRIM STRIPS-LH	\$ 426.00	↑
16	REAR WHEEL HOUSING LINER-LH	\$ 215.00	x
17	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 78.00	x
18	REAR ALUMINIUM RIM-LH	\$ 563.00	x
19	RUBBER VALVE	4 \$ 12.00	x
20	ACRYLIC SEALANT <i>Nec</i>	S/N \$ 180.00	✓
SUB-TOTAL SPARE PARTS		\$ 7,951.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 908 L

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	CAVITY WAX	S/N \$ 140.00 ✓	
22	STONE CHIP	S/N \$ 180.00 ✓	
23	METAL FILLER POWDER	S/N \$ 280.00 ✓	
24	REAR W/S SEALANT	S/N \$ 200.00 ✓	
25	1/4 GLASS SEALNT	S/N \$ 100.00 ✓	
26	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS		: \$ 9,351.00	
TOTAL LABOUR CHARGES		: \$ 12,932.00	
GRAND TOTAL		: \$ 22,283.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *07/11/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 12 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant