

KAY MOTOR  
BLOCK 9 SIN MING INDUSTRIAL ESTATE  
#01-46  
SINGAPORE 575644  
TEL: 6458 2283 FAX: 6459 8863  
Email : kayautosg@yahoo.com

Tan Say Heng

7 Nov 2018

*Not Withstand  
1/1/18 @?  
Running After Repair  
5 days*

Estimate To Repair Honda HRV – SLN 2198J

1pc	o/s front door
1pc	o/s rear door
1pc	o/s rocker panel garnish
1pc	o/s rear arch protector

By	\$ 950.00	✓
By	930.60	✓
Sur	337.70	x
Nett	160.00	✓

2378.30

475.66

1902.64

To remove & refit o/s front & rear door glass & mechanism.

120.00 ✓

To repair & panelbeat o/s rear fender, o/s door pillar,  
dismantle & fit the above parts.

580.00 500

To putty & spray painting

700.00 650

Total: \$ 3,302.64

(Dollars Three Thousand Three Hundred & Two & Cents Sixty Four only)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: