

ASS. REC. BY:

REF:

CS/EGU8020118 / Asbnz

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGU

Date/Time:

07-11-2018 2:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 5863E

Insured:

GBG 4923A

at Workshop m/s

LC Automotive

Tel:

9271 2214

of

Blk 1 Kaki Bukit Ave 6 #01-107

Policy No:

Claim No:

GBG4923A / SL/PI

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

07-11-2018 2:01pm

Person Contacted:

Chris

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 5863E - NA / ALH 15012885 / d1
	GBG 4923A - X
08/11/18	@ 16:36 p.m. revert pending estimate from repairer to Pei Li via email.

Adrian

## ASSIGNMENT

29/06/09.

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJRS863E Yr Regn: 2009, JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Insight- C.C. 1339.Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZE 21127611Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/65R15R: 185/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 07/01/18Survey held at LCDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Ecco.
13/2/13	Confirmed HS \$6,500/- @ 12 days with Adrian ( \$17,892.90 Red - 73% ) MV : 14.51K PV : 7.91K Nett: 6.61K.
	RECEIVED 14 DEC 2010
	Resurvey No. of Trip : 1
	6920K.

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:
1) <u>14/2/13</u>	2) _____	IN	OUT	Basic & Add.	
3) <u>Typst</u>	4) _____			___ S + RS, ___ SI	
5) _____	6) _____			Photos	
Prel. Report:				Others	
Final Report: <u>\$6,500/- HS</u>				TOTAL	<u>350</u>

**Catherine Chong (LKK Auto)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Wednesday, 7 November, 2018 2:03 PM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** SUR (sur@lkkauto.com)  
**Subject:** OI: GBG4923A / TP : SJR5863E/LKK / DOA : 07/11/2018  
**Attachments:** SJR5863E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LC AUTOMOTIVE**,

ADDRESS : 1 KAKI BUKIT AVENUE 6  
#01-107 AUTOBAY @ KB

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID : +65 6829 9194  
Tel. : +65 6829 9199  
Fax : +65 6829 9247

**ERGO**

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 07.11.2018  
Our Reference: GBG 4923A/SL/pl  
Your Reference: SJR 5863E  
  
To: LC AUTOMOTIVE

Sent via Fax   
or  
Email chris\_chanbebe@hotmail.com

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJR 5863E  
Insured's Vehicle: GBG 4923A  
Date Of Accident: 07.11.2018


We acknowledge receipt of your request for PRS on: 07.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

✓	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
✓	Your request for inspection does not have your client's GIa report, kindly forward a copy.
	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
✓	Our Insured's driver has not reported the accident to us todate.
✓	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6920K
Vehicle Details	
Vehicle No.:	SJR5863E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	INSIGHT 1.3G A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	LDA2027646
Chassis No.:	ZE21127611
Maximum Power Output:	65.0 kW (87 bhp)
Open Market Value:	\$23,629.00
Original Registration Date:	29 Jun 2009
First Registration Date:	29 Jun 2009
Transfer Count:	1
Actual ARF Paid:	\$14,178.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2019
PARF Rebate Amount:	\$7,089.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$824.00
<b>Total Rebate Amount:</b>	<b>\$7,913.00</b>

The information contained herein is correct as at 08 Nov 2018

OK


**500+ dealers competed to buy my car!**



- Sell ur Car for More Cash
- Highest Price or Get \$100 Free
- Get Paid Now, Handover Later

**SELL YOUR CAR**






**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

**New 5 Years Coe Renewal Honda Stream 1.8A**




2.88%P.A Lowest Interest@GV  
Cars Financing \$2000  
Downpayment Monthly From \$638  
GV Credit Pte Ltd StarAd




**PRIME MOTOR & LEASING**

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.



Browse by Category  Save Search  Print Sort by Date Posted 20 results/page

8 vehicles **Search** Insight  Advanced Search  Search  View All

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Insight	Any	Any	Any	Any	Any	Any	Available




☐ **Honda Insight Hybrid 1.3A** **\$40,500** **\$8,950 /yr** **18-Jul-2012** **1,339 cc** **76,000 km** **Hatchback** **Available**

**Fuel Type:** Petrol-Electric

700/mth! 2.28%! Fast Deal! Low Drive Away! Your Best Choice Selection With Us! Only 10% Down Payment, Lowest Interest Rate, 100% Accident Free, Best Quality Purchase From Us, Buy With A Peace Of Mind ...

GD Motoring

★ Posted: 06-Nov-2018 Tags: 2012 Honda Insight, 2012 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda



☐ **Honda Insight Hybrid 1.3A** **\$47,366** **\$9,140 /yr** **21-May-2013** **1,339 cc** **79,286 km** **Hatchback** **Available**

**Fuel Type:** Petrol-Electric

High Loan Available! Most Efficient And Reliable Honda Hybrid Hatchback! Outstanding Fuel Efficiency And Engine Performance! Excellent Condition, Low Maintenance Cost! High Trade In, Minimum Down Paym...

Creative Auto

★ Posted: 11-Oct-2018 Tags: 2013 Honda Insight, 2013 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda




☐ **Honda Insight Hybrid 1.3A** **\$44,800** **\$9,130 /yr** **28-Jun-2013** **1,339 cc** **48,421 km** **Hatchback** **Available**

**Fuel Type:** Petrol-Electric

Low Down Payment! Owned By 1 Careful Owner, Regular Servicing And Maintenance Done With Wear And Tear Replaced, Vehicle Park Under Shelter Most Of The Time, Healthy Hybrid Battery, Engine And Gearbox,...

Starise Automobile

★ Posted: 04-Nov-2018 Tags: 2013 Honda Insight, 2013 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda




☐ **Honda Insight Hybrid 1.3A** **\$52,888** **\$9,160 /yr** **22-Nov-2013** **1,339 cc** **63,000 km** **Hatchback** **Available**

Enjoy 1.98% Interest Rate! 5% Driveaway! Most Efficient And Reliable Honda Hybrid! Outstanding Fuel Efficiency And Engine Performance! Excellent Condition, Low Maintenance Cost! High Trade In, Minimum...

Euro Performance Asia Pte Ltd


★ Posted: 06-Nov-2018 Tags: 2013 Honda Insight, 2013 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda



**Mitja Borkert talks about Lamborghini Urus**

Mitja Borkert, Head of Design, Centro Stile at Lamborghini provides insights into the extraordinary design of the new Lamborghini Urus.

[Read this article](#)



☐ **Honda Insight Hybrid 1.3A** **\$49,800** **\$8,550 /yr** **21-May-2014** **1,339 cc** **51,000 km** **Hatchback** **Available**

**Fuel Type:** Petrol-Electric

In House Finance Available, Low Monthly Installment Available With 10% Down Payment! Still Under Agent Warranty! Very Low Mileage Done, Showroom Condition, 4 Pcs Almost New Sport Rims & Tyres, Fully A...

Speedo Motoring

★ Posted: 02-Nov-2018 Tags: 2014 Honda Insight, 2014 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda



☐ **Honda Insight Hybrid 1.3A** **\$54,000** **\$8,840 /yr** **04-Sep-2014** **1,339 cc** **48,400 km** **Hatchback** **Available**

**Fuel Type:** Petrol-Electric

An Outstanding Honda's ECO Petrol Saver Hatch! Up To 90% Loan Available! \$5.9k Down Payment, \$860 Monthly Installment. Consignment Unit. Call To Book Viewing Appointment!

Prem Roy Motoring

★ Posted: 06-Oct-2018 Tags: 2014 Honda Insight, 2014 honda insight, Honda Insight, honda insight, Honda, Insight, insight, Used Honda



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 8 November 2018 4:36 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR; Admin-D (LKKAuto)  
**Subject:** RE: GBG4923A / TP : SJR5863E/LKK / DOA : 07/11/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SJR 5863E on 07/11/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]  
**Sent:** Wednesday, 7 November 2018 2:03 PM  
**To:** 'admin-d@lkkauto.com' <admin-d@lkkauto.com>  
**Cc:** SUR (sur@lkkauto.com) <sur@lkkauto.com>  
**Subject:** OI : GBG4923A / TP : SJR5863E/LKK / DOA : 07/11/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **LC AUTOMOTIVE**,

ADDRESS : 1 KAKI BUKIT AVENUE 6  
#01-107 AUTOBAY @ KB

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

**Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.**

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

**ERGO Insurance Pte. Ltd.**

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Sheet1

# LC AUTOMOTIVE

BLOCK 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB Singapore 417800

Tel : (65) 67022915 HP: 92712214 Fax: (65) 69664526

Email : [chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)

07<sup>th</sup> Nov 2018

ROYAL LIMO

Bk 25 Kaki Bukit Rd 4

# 05-26 SYNERGY @KB

Singapore 417800

TPEgo ZE21127611  
Shirley.

Accident date: 07<sup>th</sup> November 2018

Estimated repair cost for vehicle no: SJR5863E Honda Insight 1.3A '09

S/n	Qty	Items	U/price	Amount	
1	1	Front bonnet Distorted		<del>\$1,350.20</del>	685
2	1	Front bonnet inner lock Dented		\$225.30	107.30
3	1	Front bonnet inner rubber x2 new		\$105.40	x
4	2	Front head lamp LH cracked	\$1,250.00	<del>\$2,500.00</del>	845
5	2	Front head lamp lower bracket New	\$258.40	\$516.80	x
6	1	Front bumper Deformed		<del>\$1,050.20</del>	756
7	2	Front bumper side bracket new	\$135.20	\$270.40	48
8	8	Front bumper clips new	\$5.00	\$40.00	✓
9	2	Front bumper number plate garnish Deformed	\$125.20	<del>\$250.40</del>	45
10	1	Front bumper number plate Bent		\$50.00	✓
11	2	Front bumper fog lamp Not New	\$250.40	\$500.80	x
13	1	Front bumper reinforcement Bent		<del>\$500.80</del>	280
14	1	Front grille Cracked		<del>\$485.20</del>	225
15	1	Front grille emble logo new		\$66.00	45
16	1	Front support panel 2115		\$885.60	x
17	2	Front fender LH Buckled	\$985.00	<del>\$1,970.00</del>	530
18	1	Rear Boot Lid Dented		<del>\$1,395.00</del>	1092
19	1	Rear boot lid emble logo		\$65.00	✓
20	1	Rear boot lid insight logo New		\$38.10	✓
21		rear boot lid hybrid logo		\$38.10	✓
22	1	rear Boot Lid top glass Shattered		\$1,050.00	✓
23	1	Rear boot lid inner rubber 1st		\$237.00	✓
24	1	Rear Boot Lid Inner Lock Dented		\$284.20	✓
25	1	Rear Boot Lid Number Plate New		\$50.00	+
26	1	rear Boot Lid number Plate top garnish Cracked		\$110.00	✓
27	2	Rear Boot Lid Number Plate Lamp x2 new	\$61.10	\$122.20	x

28	1	Rear Boot Lid center moulding	Reputed		\$320.80	X
29	10	Rear Boot Lid Inner Trim board clips	new	\$5.00	\$50.00	30
30	1	Rear Boot Lid Inner Trim board	crushed		\$554.00	320
31	2	Rear tail lamp	crushed	\$880.00	\$1,760.00	1260
32	1	Rear end panel	Distorted		\$620.00	
33	1	Rear End Panel Top Garnish	Distorted		\$268.00	
34	1	Rear Bumper	Distorted		\$1,150.00	680
35	2	Rear Bumper Side Bracket	new	\$118.20	\$236.40	84
36	1	Rear Bumper reverse sensor	new		\$350.00	200(SW)
37	8	Rear bumper clips	new	\$5.00	\$40.00	30
38	1	Rear windscreen moulding	new		\$158.00	X

9862.70 SW: 200  
7890.16

Subtotal :- \$19,812.90

### Labour charges

To Remove & refix cushion	\$120.00	80
to remove & Refix rear windscreen	\$120.00	100
gum ✓ new	\$50.00	✓
to remove & Refix boot lid top glass	\$120.00	80
Gum ✓ new	\$50.00	30
to remove & Refix rear reverse sensor	\$120.00	50
To check wheel alignment computer	\$120.00	X
Tuff kote	\$120.00	50
To Check Wiring System	\$60.00	30
Towing charges	\$100.00	60
Panel beating	\$1,800.00	1700
Spray painting	\$1,800.00	1400

Subtotal :- \$4,580.00

Total:- \$24,392.90

total: 11720.16  
a/s: 6.5k  
1200

KKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allow.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18020118/Asbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 18-12-2018	
			Code : EGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 4923A	Veh. Inspected	SJR 5863E	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBG4923A/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	07/11/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA INSIGHT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	ZE21127611	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/11/2018	Inspection Date	07/11/2018	
Survey held at	1 KAKI BUKIT AVE 6 #01-107			
Repairer	LC AUTOMOTIVE			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5863E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	DISTORTED	1,350.20	685.00
1	FRONT BONNET INNER LOCK	DAMAGED	225.30	107.30
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	105.40	-
2	FRONT HEAD LAMP @\$1250.00	N/S CRACKED	2,500.00	845.00
2	FRONT HEAD LAMP LOWER BRACKET @\$258.40	NOT NECESSARY	516.80	-
1	FRONT BUMPER	DEFORMED	1,050.20	756.00
2	FRONT BUMPER SIDE BRACKET @\$135.20	NECESSARY	270.40	48.00
8	FRONT BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
2	FRONT BUMPER NUMBER PLATE GARNISH @\$125.20	DEFORMED	250.40	45.00
1	FRONT BUMPER NUMBER PLATE	BENT	50.00	50.00
2	FRONT BUMPER FOG LAMP @\$250.40	NOT NECESSARY	500.80	-
1	FRONT BUMPER REINFORCEMENT	BENT	650.80	280.00
1	FRONT GRILLE	CRACKED	485.20	225.00
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	65.00	45.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	885.60	-
2	FRONT FENDER @\$985.00	N/S BUCKLED	1,970.00	530.00
1	REAR BOOT LID	DENTED	1,395.00	1,092.00
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	65.00	65.00
1	REAR BOOT LID INSIGHT LOGO	NECESSARY	38.10	38.10
1	REAR BOOT LID HYBRID LOGO	NECESSARY	38.10	38.10
1	REAR BOOT LID TOP GLASS	SHATTERED	1,050.00	1,050.00
1	REAR BOOT LID INNER RUBBER	CUT	237.00	237.00
1	REAR BOOT LID INNER LOCK	DAMAGED	284.20	284.20
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE TOP GARNISH	CRACKED	110.00	110.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$61.10	NOT NECESSARY	122.20	-
1	REAR BOOT LID CENTER MOULDING	REPEATED	320.80	-
10	REAR BOOT LID INNER TRIM BOARD CLIPS @\$5.00	NECESSARY	50.00	30.00
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	554.00	320.00
2	REAR TAIL LAMP @\$880.00	CRACKED	1,760.00	1,260.00

Report Ref No. CS/EGI18020118/Asbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DISTORTED	620.00	620.00
1	REAR END PANEL TOP GARNISH	DEFORMED	268.00	268.00
1	REAR BUMPER	DISTORTED	1,150.00	680.00
2	REAR BUMPER SIDE BRACKET @\$118.20	NECESSARY	236.40	84.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	30.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	158.00	-
	LESS 20% DISCOUNT		-	-1,972.54
			19,462.90	7,890.16
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	GUM (SN)	NECESSARY	100.00	80.00
			450.00	280.00
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIX CUSHION.		120.00	80.00
	TO REMOVE & REFIX REAR WINDSCREEN.		120.00	100.00
	TO REMOVE & REFIX BOOT LID TOP GLASS.		120.00	80.00
	TO REMOVE & REFIX REAR REVERSE SENSOR.		120.00	50.00
	TO CHECK WHEEL ALIGNMENT COMPUTER.	NOT NECESSARY	120.00	-
	TUFF KOTE.		120.00	50.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TOWING CHARGES.		100.00	60.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,800.00	1,700.00
	SPRAY PAINTING.		1,800.00	1,400.00
			4,480.00	3,550.00
	<b>GRAND TOTAL</b>		<b>24,392.90</b>	<b>11,720.16</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,500.00</b>

Report Ref No. CS/EGI18020118/Asbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.