

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: HAN CHEUNG YONG BERNARD

Date: 15 Nov 2018

Preliminary Advice

Insured Vehicle No	:	GBD6456J			
TP Vehicle No	:	SDB1003C	Accident Date	:	16/10/2018
Make	:	PORSCHE 911 CARRERA	Assignment Date	:	07/11/2018
Date of Inspection	:	13/11/2018	Est. Duration of Repair	:	4 days
Inspection At	:	Stuttgart Auto Pte Ltd 27A Tanjong Penjuru Singapore 609042			

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 18,215.96
Revised Amount	:	S\$ 6,330.54
Check Items (Estimated)	:	S\$ 5,565.87
Total	:	S\$ 11,896.41
Lump Sum Repair		:

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP