

汽車(私人)有限公司 シーエ

C L AUTO PTI

(ACRA No. 198800292M) 8 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
1 Guan Road East, #02-125 Enterprise H Hub
Website: www.clauto.com.sg E-mail: vince
Tel: +65 6795 6125 Fax: +65 67

C L Auto Pte Ltd

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO: 198800292M

M/S : LIM GUAN SOON
BLK 311 #06-331
JURONG EAST STREET 32
SINGAPORE 600311

ATTN: MR.LIM GUAN SOON

Your Ref No: SME7421S
Claim Type: Third Party
Accident Date: 02/11/2018

Estimate No: EST1800162
Date: 03 Nov 2018
Policy No:
Veh Reg No: SME7421S
Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS AT (AMS)
Chassis No: KMHD841CMJU739789
Engine No: G4FGJU248963
Reg. Date: 15/10/2018

Estimate Repair Cost to Vehicle No :SME7421S

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price:			
1 REAR BUMPER BEAM REINFORCEMENT ?	1 PC	330.00	
2 REAR BUMPER COVER UPPER cut ✓	1 PC	580.00	
3 REAR BUMPER COVER LOWER sc ✓	1 PC	250.10	
4 REAR BUMPER CLIP new ✓	1 SET	30.00	
		1,190.10	1,190.10
Labour Charges:			
5 TO REMOVE & FIXING REAR BUMPER & REPLACE REAR BUMPER	1 JOB	420.00 300	
6 TO RESPRAY PAINT REAR BUMPER & POLISH	1 JOB	450.00 300	
7 TO UNDER COAT	1 JOB	180.00 X	
8 TO REMOVE & FIXING REAR REVERSE SENSOR & CHECK WIRING	1 PC	180.00 60	
		1,230.00	1,230.00
Total			S\$ 2,420.10

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED TWENTY AND CENTS TEN ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

3 days
p/p

13/11/18 @ 1410

Resurvey by paint