

JIN AUTO SERVICES PTE LTD

Blk 14 #01-412 Defu Lane 10
Singapore 539195
Tel:62898126 Fax :62870590

not allowed
hbr
Take photo before repair
2-3h.
4/12/18
P/P &

Your ref :
Our Ref :

Date:

4/12/2018

DEAR SIR/MADAM

ESTIMATED REPAIR COST FOR SMC1755D

1	1 PC	REAR BUMPER	2e	\$	630.50	✓
2	10 pcs	REAR BUMPER CLIPS	neu	\$	38.00	✓
3	1 PC	REAR BUMPOER LOWER (BLACK)	Dis	\$	360.20	✓
4	1 PC	REAR BUMPER LH RED REFLECCTOR	1ne	\$	63.90	✓
5	1 PC	REAR BUMPER LH RED REFLECCTOR BLACK COVER	2e	\$	98.70	✓
6	1 PC	REAR BUMPER REINFORCEMENT	1u	\$	316.70	X
				\$	1,508.00	
				LESS 25%	\$	(377.00)
					\$	1,131.00
7	1set	REVERSE SENSOR	11	\$	250.00	X
8		CHECK WIRING (REAR)		\$	35.00	20
9		TO REMOVE AND RENEW SENSOR		\$	80.00	50
10		TUFF KOTE	11	\$	80.00	X
11		REMOVE AND RENEW PARTS (REPAIR END PANEL)		\$	580.00	250
12		To putty & spray painting		\$	680.00	300
				\$	2,836.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: