



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLS 8807 U

|                         |                               |    |                 |
|-------------------------|-------------------------------|----|-----------------|
| Parts                   | (a) Cost / List Price Items   | \$ | 2,014.22        |
|                         | Plus/Less 25%                 | \$ | 503.56          |
|                         | <b>Total of Cost / List</b>   | \$ | <b>1,510.67</b> |
|                         | (b) Nett Price Items          |    |                 |
|                         | Less                          |    |                 |
|                         | <b>Total of Nett Item</b>     |    |                 |
|                         | (c) <b>Special Nett Items</b> |    |                 |
| <b>Total Parts Cost</b> |                               |    |                 |
| Labour                  |                               | \$ | 1,480.00        |
| <b>Total</b>            |                               | \$ | <b>2,990.67</b> |

Not Authorized  
Resurvey Repair



The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 12/11/18 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : De Date: 12/11/18



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLS 8807 U**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU403571911**

Submit By : **Carmen Lim**  
Year Manufacture : **2017**  
Engine No. :

### Cost / List

| S/No. | Part Description                           | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|--|-----|------------|-------|-------------------------|
| 1     | Front bumper <i>Bu</i>                     | 1   | \$450.80   |       | ✓                       |
| 2     | Front bumper clip <i>Mc</i>                | 10  | \$40.00    |       | ✓                       |
| 3     | Front bumper side retainer LH <i>Dis</i>   | 1   | \$107.20   |       | ✓                       |
| 4     | Front bumper emblem <i>Mc</i>              | 1   | \$87.10    |       | ✓                       |
| 5     | LH front fender <i>Bz</i>                  | 1   | \$868.70   |       | ✓                       |
| 6     | LH front fender undershield <i>Sn</i>      | 1   | \$195.60   |       | ✓                       |
| 7     | LH front fender undershield clip <i>in</i> | 10  | \$25.00    |       | X                       |
| 8     | LHF fender wording "HYBRID" <i>Mc</i>      | 1   | \$44.17    |       | ✓                       |
| 9     | LH rear hub cap <i>Ref</i>                 | 1   | \$195.65   |       | ✓                       |
| 10    |  |     |            |       |                         |
| 11    |  |     |            |       |                         |
| 12    |  |     |            |       |                         |
| 13    |  |     |            |       |                         |
| 14    |  |     |            |       |                         |
| 15    |  |     |            |       |                         |
| 16    |  |     |            |       |                         |
| 17    |  |     |            |       |                         |
| 18    |  |     |            |       |                         |
| 19    |  |     |            |       |                         |
| 20    |  |     |            |       |                         |
| 21    |  |     |            |       |                         |
| 22    |  |     |            |       |                         |
| 23    |  |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



|                |                          |                       |                          |
|----------------|--------------------------|-----------------------|--------------------------|
| Vehicle No. :  | <u><b>SLS 8807 U</b></u> | Submit By :           | <u><b>Carmen Lim</b></u> |
| Make & Model : | <u>TOYOTA PRIUS</u>      | Year of Manufacture : | <u>2017</u>              |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*