

YM9301H. 2008 Sept.

Isuzu NHR85 2999 cc

JAA NHR85E87100174

Parts. Hydraulic Cylinder ^{KHP} _{new} 3800 (SN) x

Hydraulic Fluid ^{new 800 (SN) ✓}

Rear Towing Structure ^{Repair} 2500 (SN)

labour. To dismantle and re-align rear towing structure ~~2500~~ 1600

Spray Painting - ~~1000~~ 550.

Wiring. ~~100~~ 50

S.N: 300

labour: 2200

total: 2500 (P/P).

OH Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: