

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5005M**AAD1810-309**

Not Authorised
Resurvey by pain 86201

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 5005M
 VF1ABL15AUC283485
 RENAULT
 LATITUDE
 30.10.18
AIG

PART		LIST	
1	BUMPER COVER FRT	\$	R 1,259.42
1	BUMPER SPOILER FRT	\$	Sm 181.75
1	BUMPER ABSORBER FRT	\$	Sm 394.68
1	BUMPER RETAINER FRT LH	\$	Sm 151.41
1	BUMPER SUPPORT FRT	\$	Sm 123.88
1	BUMPER UNDERTRAY FRT	\$	Sm 472.83
1	BUMPER GRILLE LOWER FRT	\$	Sm 266.80
1	BUMPER FOG LAMP GRILLE LH	\$	Sm 207.21
1	BUMPER BEAM FRT	\$	R 914.08
1	HEADLAMP LH	\$	Sm 1,184.43
1	HEADLAMP PANEL FRT LH	\$	R 152.15
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	Sm 278.84
1	FENDER BRACKET LOWER LH	\$	Sm 15.79
1	FENDER INSULATOR LH	\$	Sm 130.84
1	AIR CLEANER BOX	\$	Sm 464.20
1	AIR CLEANER HOSE	\$	Sm 175.85
1	DOOR PANEL FRT LH	\$	R 2,844.66
1	DOOR MIRROR ASSY LH	\$	Sm 1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	Sm 466.51
1	ROCKER PANEL INNER LH	\$	Sm 1,024.79
1	ROCKER PANEL CENTER LH	\$	R 990.25
1	ROCKER PANEL OUTER LH	\$	R 1,184.99
TOTAL		\$	15,152.60
10%		\$	1,515.26
		\$	13,637.34

Special Nett

1SET	BUMPER CLIP FRT	\$	nn 66.00 X
1	BUMPER BRACKET CLIP FRT LH	\$	nn 12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50 X

Trans-cab Auto Services Pte Ltd**AAD1810-309**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5005M

1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	} X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	} X
1	FRONT LEFT TYRE	\$	nn	300.00	
1	FRONT LEFT TYRE RIM	\$	nn	380.00	
TOTAL		\$		988.00	

TOTAL PARTS \$ 14,625.34**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	100d	3,000.00	X
Putty and spray painting of the affected portion.	\$	480d	3,000.00	X
To rust-proofing of the affected areas.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	60d	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	20d	170.00	X
To Check Electrical Lighting Concerned.	\$	nn	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn	380.00	X

TOTAL \$ 7,490.00**Over All Total \$ 22,115.34**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PART BY PART (REPAIR DAY)**10 DAYS**

1 1/2 days