

ASS. REC. BY:

REF: CS/FCL18020152/Klgbr2

Special Instruction:

Surveyor:

K/lin

ASSIGNMENT (Office)

From (Person):

WS Joanne Yong

of

FCL

Date/Time:

07/11/2018 4:19pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHD 1612 L

Insured:

SHA 1617P

at Workshop m/s

Premier

Tel:

of

23 Changi South Ave 2 # 01-02

Policy No:

Claim No:

D18007939MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 09/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

07/11/2018 4:33pm

Person Contacted:

Gary

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate:

SHD 1612 L - CS/FCL18020257/Fgbc2

DCA: 29/11/15

SHA 1617P - NS/DIC16074647/Hrvbm2

DUA: 23/12/16

07/11/18 @ 3:03pm revised to Joanne Yong by email.

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD1612L Yr Regn: 4 Oct, 2014Type: M. Car / M. Cycle / Bus / Van / Lorry / T~~o~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai I30 c.c. 1500Colour: Silver A/C: Ins~~ured~~ / Std / NI / NASp. Reading: 773698 T/Radio: Ins~~ured~~ / Std / NI / NA

Eng/No: _____

C/No: 1KM4PC815LC413479Gen. Cond: Good / F~~air~~ / Poor / BurntSteering: Inord~~er~~ / Jammed / Leaked / Burnt orBrake: Inord~~er~~ / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ~~or~~ Rim orTyre Size: F: 185 / 60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 5/11/18 D.O.I. 8/11/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/11/18	Chassis 45 \$1650 / 3 Rpt. (Red to 2424.64, 60%) FCI
	45

RECEIVED 21 NOV 2018

Date/Time, File Pass to?

☐

: Preli. Report

11/21/11 TP☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I.: (\$ 1650)

135

50

50

30

265



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007939MFSH

Date: 09 November 2018

Our Ref: CS/FCI18020152/K1qb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1612L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2018 at the premises of M/s PREMIER AUTOMOTIVE. and have the following to report:-

Workshop Estimate Amount	: S\$ 4,074.64 .
Revised Estimate Amount	: S\$ 2,117.76 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s body.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-11-2018	Our Ref No. D18007939MFSH
Accident Date	05-11-2018	Claim Type. Third Party
Insured Vehicle	SHA1617P	Third Party Vehicle. SHD1612L
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 November 2018 3:03 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007939MFSH/1
Attachments: CSFCI18020152K1qb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHD 1612L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 7 November 2018 4:30 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007939MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 7 November, 2018 4:19 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007939MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	SHD1612L ✓	Vehicle Scheme:	Taxi (Company)
Vehicle Type:	H11 - Public Transport Taxi (Station Wagon)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	HYUNDAI	Vehicle Model:	FD I30CW 1.6 MT 5DR TURBO 2WD
Chassis No.:	KMHDC81SLCU134179 ✓	Engine No.:	D4FBBU005270 ✓
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Diesel	Passenger Capacity:	4
Engine Capacity:	1582 cc	Power Rating:	-
Unladen Weight:	1334 kg	Maximum Laden Weight:	1860 kg
Primary Colour:	Silver	Secondary Colour:	-
First Registration Date:	04 Oct 2011 ✓	Original Registration Date:	04 Oct 2011
Manufacturing Year:	2011	Open Market Value:	\$11,075.00 ✓
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$6,645.00
No. of Transfers:	0		

Owner Particulars

Owner Name:	PREMIER TAXIS PTE. LTD.
Owner ID Type:	Company
Owner ID:	200304975H ✓
Registered Address Type:	Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:	11
Registered Street Name:	KUNG CHONG ROAD
Registered Unit No.:	-
Registered Building Name:	ALEXANDRA INDUSTRIAL ESTATE
Registered Postal Code:	159147
COE No. / Expiry Date:	2011090101000239M / 03 Oct 2019
COE Bid Category:	A - Car (1600cc & below) & Taxi
QP Paid:	\$39,041.00 ✓

Transaction Details

Business Transaction Ref. No.:	20111004090417796607
Business Transaction Date:	04 Oct 2011
Business Transaction Time:	09:04:17

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Nov-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 REGN NO: SHD 1612 L

1 pc	Front n/s door @ \$1197.20	✓ <i>Ad</i>	\$ 1,197.20
2 pcs	Front n/s door hinges @ \$42.40	X <i>re</i>	\$ 84.80
1 pc	Rear n/s door @ \$1228.30	X <i>re</i>	\$ 1,228.30
2 pcs	Rear n/s door hinges @ \$41.50	X <i>re</i>	\$ 83.00
			\$ 2,593.30
Less 20%			\$ 518.66
			\$ 2,074.64

S/NETT

1 set	n/s door sticker	✓ <i>re</i>	\$ 100.00
-------	------------------	-------------	-----------

Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~50.00~~ *20*
\$ ~~180.00~~ *X 1.1*

To remove / refit front n/s & rear n/s door components onto new shell door

\$ ~~300.00~~ *50*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of n/s rocker panel garnish, etc

\$ ~~400~~
~~650.00~~

To putty and spray painting on front n/s door, rear n/s door, n/s rocker panel garnish

\$ ~~540~~
~~600.00~~

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ *50*

\$ 4,074.64

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kahin (11/11/18)
8/11/18 1025 hrs.
3 Pys
4/5
After Rep'r photo.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modifications allowed
- Supplementary (extra) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18020152/K1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 30-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1617P	Veh. Inspected	SHD 1612L
Policy No.		Coverage (\$)	0.00
Claim No.	D18007939MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	07/11/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KMHDC81SLCU134179	Colour	SILVER
Odometer	773698	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	MAXXIS	7 mm
L/H Front Tyre	185/65 R15	MAXXIS	7 mm
R/H Rear Tyre	185/65 R15	MAXXIS	7 mm
L/H Rear Tyre	185/65 R15	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/11/2018	Inspection Date	08/11/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1612L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT N/S DOOR	DENTED	1,197.20	1,197.20
2	FRONT N/S DOOR HINGES @\$42.40	SERVICEABLE	84.80	-
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	1,228.30	-
2	REAR N/S DOOR HINGES @\$41.50	SERVICEABLE	83.00	-
	LESS 20% DISCOUNT		-518.66	-239.44
			2,074.64	957.76
SPECIAL NETT ITEMS				
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
LABOUR				
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO REMOVE / REFIT FRONT N/S & REAR N/S DOOR COMPONENTS ONTO NEW SHELL DOOR.		300.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF N/S ROCKER PANEL GARNISH, ETC. INCLUSIVE OF THE REPAIR OF REAR N/S DOOR.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT N/S DOOR, REAR N/S DOOR, N/S ROCKER PANEL GARNISH.		600.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	50.00
	-		-	-
	-		-	-
	-		-	-
			1,850.00	1,040.00
GRAND TOTAL			4,074.64	2,117.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/FC118020152/K1qbn2



Report Ref No. CS/FCI18020152/K1qbn2

A handwritten signature in black ink, appearing to be 'W' followed by a stylized 'A'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'A.L.P.' in a stylized cursive font.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.