



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Reg No : 196700086Z
ST Reg No : MR-8500000-9

8/11 3:00pm

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM <i>LKK Cotharivan 6741834</i>	S1000020 / TPCLAIM	Mr Kua Seng Teck 361 Choa Chu Kang Avenue 3 #15-23 Singapore 689884 Mobile: 94239787
	Document No	
	0	
	Document Date	
	05/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
------	------	-------	----------	------------	------------	--------	------------------

13 JEXGBT H2 AVV50R 20/05/2013 SCA8828K 0 37338 :5DS/SCA8828K/03111:

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
------------	-----------	--------	-------	------------------	------------	--------------

MR053CK5004010630 2ARU022641 60 Francis Cher T S ---/---/---- 0.00 ---/---/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>lompac</i> T/P VEH. : GBF2637U ACC DATE : 03.11.18 BY :				<i>50</i> 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				169.50
4	B	BP-LAB DRILL HOLE TO INSTALL REVERSE SENSOR.				169.50
5	L	BP-LPO SUPPLY REGN PLATE (PO#) (REAR WITH CASING)				X 68.00
6	B	BP-LAB REMOVE REAR BOOT COMPONENTS TO TRANSFER ONTO NEW DOOR.				339.00
7	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, REAR BOOT, TAIL-LAMP PANEL AFFECTED PORTION OF CAR.				<i>1356</i> 2712.00
8	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				<i>1112</i> 2224.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

3828341

PLEASE TEAR ALONG PERFORATED LINE

3828341

TO SECURITY GUARD
PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/11/2018
TIME 09:17

VEHICLE NO SCA8828K

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Reg No : 196700086Z
T Reg No : MR-8500000-9

ESTIMATE

in Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail THIRD PARTY CLAIM	Account No	Customer Detail Mr Kua Seng Teck 361 Choa Chu Kang Avenue 3 #15-23 Singapore 689884 Mobile: 94239787
	S1000020 / TPCLAIM	
	Document No	
	Document Date	05/11/2018

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
3	JEXGBT H2	AVV50R	20/05/2013	SCA8828K	0	37338	5DS/SCA8828K/03111:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
R053CK5004010630	2ARU022641	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	1	S52159-06974 COVER, RR BUMPER <i>DC</i>	1.00	646.40		646.40
10	2	S52023-06081 REAR BPR REINFORCEMENT	1.00	391.60		391.60
11	3	S52575-06131 RETAINER, RR BUMPER R <i>DC</i>	1.00	108.30		108.30
12	4	S52161-OKO40 PIECE, RR BUMPER <i>DC</i>	4.00	4.00		16.00
13	5	S64401-06820 PANEL, LUGGAGE DR <i>BI</i>	1.00	1121.60		1121.60
14	6	S75443-06830 PLATE, LUGGAGE COMPT <i>DC</i>	1.00	44.80		44.80
15	7	S75442-06230 PALTE, LUGGAGE <i>DC</i>	1.00	44.80		44.80
16	8	T75441-33151 PLATE, BACK DOOR <i>DC</i>	1.00	64.50		64.50
17	9	T89341-33210 B1 ULTRASONIC SENSOR	1.00	390.50		390.50

Rasul
4p 900000
5 days
08/11/18 @ 1500hrs
Resurvey by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Signature: For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	8,710.50
	Please acknowledge receipt of vehicle	Parts		
		Labour	2,828.50	GST 7.00%
		Materials	5,814.00	Less
		Lubrication/Fluid	68.00	
		Others	0.00	
		0.00	Amount Due	9,320.24

3828342

PLEASE TEAR ALONG PERFORATED LINE

3828342

TO SECURITY GUARD
PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/11/2018
TIME 09:17

VEHICLE NO SCA8828K

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor