

Thiam Heng Huat Pte Ltd

Block 176 Sin Ming Drive #05-14, Sin Ming Autocare

Singapore 575721

Hp: 82636295 (Steven)

Fax: 62662881

Estimate repair cost

GY3622X

Nissan Cabstar

Qty Parts

List price

1	Tailgate	bt ✓	\$	1,688.40	1639 ✓
1	Tailgate "Nissan" sticker	neu ✓	\$	175.30	80 ✓
1	Tailgate lower panel	bt ✓	\$	686.50	✓
1	Tailgate lower panel RH side bracket	bt ✓	\$	165.00	116 ✓
1	Tailgate lower panel RH side bracket rubber stopper	neu ✓	\$	38.00	✓
3	Tailgate hinges	X svt	\$	104.00	X
1	Tailgate RH side lock	bt ✓	\$	183.60	154 ✓
1	RH side gate	bt ✓	\$	2,935.00	2750 ✓
1	RH side gate lower panel	repair	\$	898.60	R
1	RH side gate RH side stopper	neu ✓	\$	38.00	✓
1	RH taillamp	CR ✓	\$	196.20	✓
1	Rear chassis frame centre crossmember	bt ✓	\$	393.60	343 ✓
1	RH rear wheel mudguard (front)	X svt	\$	305.40	X
1	RH rear wheel mudguard (Rear)	bt ✓	\$	305.40	301 ✓
1	RH rear wheel mudflap	wt ✓	\$	87.20	✓
1	RH front door	bt ✓	\$	933.00	630 ✓
1	RH front door "Cabstar" sticker	neu ✓	\$	55.00	35 ✓
1	RH front step panel garnish	svt ✓	\$	76.50	✓
1	RH front wheel arch panel	bt ✓	\$	489.20	✓
1	RH front side mirror arm	X svt	\$	318.20	X
1	RH front side mirror	X svt	\$	116.00	X
1	Front bumper	svt ✓	\$	743.00	675 ✓
1	Front RH side lamp	bro ✓	\$	160.60	139 ✓
1	RH headlamp	CR ✓	\$	354.50	✓
1	Front grille	X svt	\$	578.10	X
1	Front grille emblem	X svt	\$	45.80	X
1set	Front grille clips	X svt	\$	50.00	X
1	RH front wheel bearing	neu ✓	\$	288.10	78 ✓
1	RH front lower arm	X svt	\$	434.50	X
1	RH front upper arm ball joint	X svt	\$	93.00	X
1	RH front upper arm	X svt	\$	450.20	X

- 1 RH front shock absorber Xsu
- 1 RH front knuckle arm BA

9067.10

30%

6346.97

\$
\$

202.80 X
538.00 255

30% -10%

\$
\$
\$

14,126.70
1,412.67
12,714.03

Special Nett

- 1 Tailgate "70km/h" sticker nu -
- 1 Rear underrun bumper BA
- 1 Rear underrun bumper RH bracket Xsu
- 1 RH side gate wooden guide Xsu
- 1 RH front wheel su
- 1 RH front tyre Xsu
- 1 RH front door ROC sticker nu -

\$
\$
\$
\$
\$
\$
\$

815

22.00 10
850.00 500
180.00 X
800.00 X
280.00 -
220.00 X
25.00 -

Labour charges on affected areas

Putty and respray affected areas

Check wiring and lighting system

Apply rust proofing on replaced and repaired panels

Remove and replace RH front undercarriage parts

Conduct and adjust wheel alignment system

Check wiring and lighting system. To focus and adjust headlamps

Remove and refix RH front door inner trims, garnish and seats

\$
\$
\$
\$
\$
\$
\$
\$

2090

1,500.00 1000
1,200.00 800
70.00 30 Xsu
100.00 60
250.00 80
100.00 60
80.00 30
280.00 60

Rasul

HP 90010068

18,671.03

8 days

4/3

09/11/18 @ 1515

Resurvey after repair

Repair limit 3K

6346.97

815.00

2090.00

9,251.97

20%

7401.57

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: