

15/5/2010

INS. CASE OWNER:

CC 3/11/18 AIG1802

LKK:

IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

Date / Time:

31/11/18

Registered in Merimen:

31/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUT 8274B

Name of Insured:

LCC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

06/11/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

L20 NUT HUB KM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

461078895289

Policy No.:

A1111111111111111

Make / Model:

Mazda

Place of Accident:

Aishan ST 14 15 15

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

Premium

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

31/11/18
224SUT 8274B - CONTACTED MERIMEN (461078895289) 16/11/18
4700000000000000

16-11-18

EMAILED PREMIUM NV @
\$48K

13/11/18 FILE PASS TO TYPE MANDATE

2/12/18 FILE PASS TO USP TO WORK

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

30728-11-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 2/12/18

Confirm with Nadia

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

5

If NO or B 28, Ass. Lia:

Repair Cost: (w/loss)

SS 51360.00

Loss of Rental (LOR):

SS 3300.00

(33 days) x \$100

Loss of Use (LOU):

SS 600.00

(S 60 x 10 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☒LOR + LOU ☐

[Tick only one]

GIA/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 55260.00

Global Sum SS:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS 55260.00

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 33.88 Consistent? : Yes or NoEst. Repairs: 18.88 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDU887A-Yr Regn: 2017 2018 AprilType: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan c.c. 1395Colour: Black A/C: Insured / Std / NI / NASp. Reading: 32803 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF42GAH1365 WAUZZZF42GAH1365
24843Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/11/18Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP A16.
	R/S - \$48000.00 (Red \$52280.08 / 52%)
	MV: 1151C
	PV: 63.7K
	Nett: 51.3K.
	16-11-18 emailed TP NV @ \$48K

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1)	2)	IN	Basic & Add.	
3)	4)	OUT	___ S + RS, ___ SI	
5)	6)		Photos	
Preli. Report:			Others	
Final Report:			TOTAL	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/LCR18020167/jb3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120			Date : 07-11-2018	
Code : LCR				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 8274B	Veh. Inspected	SDU 887A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	07/11/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/11/2018	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1267/2018/GW
Date : 8/11/2018

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLT 8274 B**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loh Boon Yiong
Address : 87 Jurong West Central 3
#11-48
Singapore 648343
Telephone : (HP) 96962615
Type of Claim : Third Party Claims
Policy No. : 2100507389-01
Vehicle No : **SDU 887 A**
Model Code : Audi A4 Sedan 1.41 TFSI S
Model / Year : Apr-18
Engine No : CVN 032575
Chassis No : WAUZZZF42GA111565
Mileage : 32803 KM
Date In : 4-Nov-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Nov-18
Place of Accident : Junction of Bishan St 14 and Bishan St 15

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N WAIVED
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00
3	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00
4	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,000.00
5	To remove and reinstall center console and dashboard assy for A- pillar renewal. Inspect for damages.	S/N \$ 3,200.00
6	To dislodge and reinstall rhs A-pillar, rhs front door harness, rhs rear door harness, multi-lock system and power window devices. Inspect for damages.	S?N \$ 1,400.00 560.
7	To suspend engine assy. To dismantle front suspension assy. To inspect damages and renew accordingly.	S/N \$ 2,800.00
SUB-TOTAL LABOUR CHARGES - FRONT		: \$ <u>9,560.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid an rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To renew rear windscreen and rhs 1/4 glass for fender renewal.	S/N \$ 600.00 ✕
3	To dislodge and reinstall rear wire harness for lights, better manager, fuse and relay trays, elcectrical and audio equiment.	S/N \$ 1,400.00 ✕.
4	To remove and reinstall rhd front seat, rhs rear seat, back rest, hat tray , abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,800.00 ✕.
5	To dismantle rear bumper and rear lid. Cut out and reweld RHS rear fender. Re-organize crash management components. Reinstall all parts removed.	\$ 4,800.00 1000.
6	To respray rear bumper, RHS rear fender, door entrances, roof channel, drain channel and end panelling. To carry out joint sealent work and stone chip treatment,	\$ 3,300.00 1100.
7	To carry out diagnostic checks.	S/N \$ 394.00 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 12,654.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
8	To setup vehicle on car-o-liner for repair.	S/N \$ 2,400.00 ✓
9	To dismantle and renew front bumper, bonnet, rhs headlight. Rhs front fender, rhs front door and rhs rear door. Cut out and reweld rhs front fender top support, A-pillar and rhs sill panel. To renew front lock carrier and align to position. Re-organise crash management components. reinstall all parts removed.	\$ 10,500.00 ✓ 5000 2000 6x \$500
10	To respray front bumper, bonnet, bonnet hinges, rhs front fender, rhs front fender top support, rhs front door, rhs rear door, rhs A-pillar. rhs sill panel, door handles, door hinges and wing mirror cover. To carry out joint sealant works and stone chip treatment.	\$ 7,100.00 ✓ 24400 2850
11	To renew rhs front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00 ✓
TOTAL LABOUR CHARGES - FRONT		: \$ 29,840.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	\$ 1,849.00	✓ 1479.20
2	FRONT BUMPER FIXING PARTS <i>not nec</i>	\$ 245.00	X
3	FRONT BUMPER SECURING STRIP <i>not nec</i>	\$ 30.00	X
4	FRONT BUMPER GRILLE-CENTER <i>not nec</i>	\$ 171.00	X
5	FRONT BUMPER CLOSING ELEMENT <i>not nec</i>	\$ 180.00	X
6	FRONT BUMPER AIR GUIDE-RH <i>Engd</i>	\$ 73.00	✓ 57.84
7	RADIATOR <i>not nec</i>	\$ 1,524.00	X
8	FRONT BUMPER AIR GUIDE GRILLE-RH <i>missing</i>	\$ 319.00	✓ 255.20
9	FRONT BUMPER GUIDE SECTION-RH <i>Engd</i>	\$ 32.00	✓ 25.36
10	FOAM FILLER PIECE <i>not nec</i>	\$ 107.00	X
11	FRONT BUMPER CARRIER <i>not nec</i>	\$ 702.00	X
12	FRONT BUMPER COVER <i>not nec</i>	\$ 109.00	X
13	SIGN " CAUTION "	\$ 12.00	X
14	AIR CODITIONER STICKER <i>not nec</i>	\$ 7.00	X
15	FRONT FENDER-RH <i>Distorted</i>	\$ 665.00	✓ 532.00
16	FRONT FENDER ATTACHEMENT PARTS-RH <i>not nec</i>	\$ 45.00	X
17	FRONT FENDER CLOSING ELEMENT-RH <i>not nec</i>	\$ 44.00	X
18	FRONT FENDER BRACKET-RH <i>Best</i>	\$ 31.00	✓ 24.16
19	FRONT FENDER FOR DEFORMATION ELEMT-RH <i>not nec</i>	\$ 43.00	✓ 34.16
20	FRONT FENDER RETAINING BRACKET-RH <i>Engd</i>	\$ 27.00	✓ 21.60
SUB- SPARE PARTS CHARGES - FRONT		\$ 6,215.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER UPPER BRACKET-RH <i>Bent</i>	\$ 15.00	✓ 11.76
22	FRONT FENDER BRACE-RH <i>Bent</i>	\$ 103.00	✓ 82.40
23	FRONT FENDER CLOSING LEMENT-RH <i>Damaged</i>	\$ 29.00	✓ 22.72
24	FRONT WHEEL HOUSING LINER-RH <i>torn</i>	\$ 209.00	✓ 167.20
25	WHEEL HOUSING ATTACHEMENT PARTS <i>Not nec</i>	\$ 78.00	X
26	FRONT WHEEL SPOILER-RH <i>torn</i>	\$ 63.00	✓ 52.32
27	FRONT END PLATE-RH <i>Damaged</i>	\$ 31.00	✓ 24.32
28	FRONT STONE CHIP GUARD-RH <i>nec</i>	\$ 44.00	✓ 34.56
29	FRONT FENDER LEDGE COVER-RH <i>3 nec</i>	\$ 27.00	✓ 21.04
30	FRONT FENDER LEDGE TOP COVER-RH	\$ 20.00	✓ 15.36
31	BONNET <i>Distorted.</i>	\$ 2,163.00	✓ 1730.40
32	BONNET ATTACHEMENT PARTS <i>Not nec</i>	\$ 105.00	X
33	BONNET LID HINGE-LH/RH <i>Not nec</i>	2 \$ 532.00	X
34	BONNET STOP BUFFER <i>nec</i>	\$ 9.00	X
35	BONNET IMPACT EDGE PROTECTION-CENTER <i>3 nec</i>	\$ 24.00	✓ 18.88
36	BONNET IMPACT EDGE PROTECTION-LH/RH	2 \$ 48.00	✓ 37.76
37	BONNET GAS FILLED STRUT <i>2</i>	2 \$ 209.00	X
38	BONNET STRIKER-LH/RH <i>Not nec</i>	2 \$ 88.00	X
39	BONNET LID LOCK	2 \$ 376.00	X
40	BONNET BOWDEN CABLE-CENTER	\$ 50.00	X
SUB- SPARE PARTS CHARGES - FRONT		\$ 4,223.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A .

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
41	BONNET RELEASE LEVER <i>Not Nec</i>	\$	12.00 +
42	PLENUM CHAMBER COVER <i>Not Nec</i>	\$	85.00 +
43	LOCK CARRIER BRACKET <i>Not Nec</i>	\$	118.00 +
44	FRONT BUMPER SUPPORT-LH/RH <i>Not Nec</i>	2 \$	48.00 +
45	FANFARE - LOW TONE <i>Not Nec</i>	\$	254.00 +
46	SPRING SHACKLE-RH <i>Not Nec</i>	\$	25.00 +
47	LOCK CARRIER WITH MOUNTING <i>Not Nec</i>	\$	891.00 +
48	COOLANT CONCENTRATE 1.5 LTR <i>Not Nec</i>	4 \$	133.00 +
49	LED HEADLIGHT-RH <i>Smashed</i>	\$	6,973.00 + 5578.40
50	LED HEADLIGHT POWER MODULE-RH <i>Not Nec</i>	\$	695.00 +
51	LED HEADLIGHT CONTROL UNIT-RH <i>Not Nec</i>	\$	657.00 +
52	COMPENSATING PIECE <i>Not Nec</i>	2 \$	73.00 +
53	LED HEADLIGHT LIFT CYLINDER-RH <i>Not Nec</i>	\$	184.00 +
54	WASH WATER RESERVOIR <i>Rehnd</i>	\$	128.00 + 102.40
55	CONNECTION PLATE-RH <i>Not Nec</i>	\$	189.00 +
56	FRONT WHEEL HOUSING-RH <i>Not Nec</i>	\$	52.00 +
57	FRONT FENDER FILLER PANEL-RH <i>Not Nec</i>	\$	219.00 +
58	FRONT DOOR-RH <i>Distorted</i>	\$	2,048.00 + 1638.40
59	FRONT OUTER DOOR SEAL-RH <i>rec</i>	\$	176.00 + 140.40
60	BONDNG AGENT <i>Not</i>	\$	43.00 + 34.16
SUB- SPARE PARTS CHARGES - FRONT		:	\$ 13,003.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	CLEANING SOLUTION <i>N/M</i>	\$ 64.00	<i>✓</i>
62	APPLICATOR <i>N/M</i>	\$ 7.00	<i>✓</i>
63	DOOR ATTACHMENT PARTS <i>N/M</i>	\$ 462.00	<i>✓</i>
64	FRONT DOOR CATCH-RH <i>Not Rec</i>	\$ 92.00	<i>✓</i>
65	FRONT DOOR CATCH COVER-RH <i>N/M</i>	\$ 13.00	<i>✓</i>
66	FRONT DOOR HINGE HALF-RH UPPER <i>Bent</i>	\$ 40.00	<i>✓</i> 31.68
67	FRONT DOOR HINGE HALF-RH LOWER <i>Bent</i>	\$ 39.00	<i>✓</i> 30.80
68	FRONT WINDOW REGULATOR WITHOUT MOTOR-RH <i>Not Rec</i>	\$ 242.00	<i>✓</i>
69	FRONT WINDOW REGULATOR MOTOR-RH <i>Not Rec</i>	\$ 228.00	<i>✓</i>
70	FRONT DOOR CONTROL UNIT-RH	\$ 653.00	<i>✓</i>
71	DATE PLATE FOR TYR PRESSURE <i>Not Rec</i>	\$ 33.00	<i>✓</i> 27.36
72	CHASSIC DATA TAG <i>Not Rec</i>	\$ 406.00	<i>✓</i>
73	FRONT ALUMINIUM RIM-RH <i>Not Rec</i>	\$ 563.00	<i>✓</i> 450.00
74	RUBBER VALVE <i>Not Rec</i>	4 \$ 12.00	<i>✓</i> 9.92
75	ASSEMBLY CARRIER <i>Bent</i>	\$ 1,657.00	<i>✓</i> 1328.60
76	FRONT WISHBONE LINK-RH <i>Bent</i>	\$ 476.00	<i>✓</i> 380.40
77	FRONT SUSPENSION GUIDE-RH <i>Bent</i>	\$ 834.00	<i>✓</i> 667.20
78	FRONT GUIDE-RH UPPER <i>Bent</i>	\$ 452.00	<i>✓</i> 361.20
79	FRONT GUIDE-RH REAR UPPER <i>Bent</i>	\$ 452.00	<i>✓</i> 361.20
80	FRONT WHEEL BEARING-RH <i>Not Rec</i>	\$ 848.00	<i>✓</i> 678.40
SUB SPARE PARTS CHARGES - FRONT		\$ 7,573.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
81	FRONT SWIVEL JOINT-RH <i>Bent</i>	\$ 165.00	☒ 132.00
82	FRONT WHEEL HUB-RH <i>Drumged</i>	\$ 433.00	☒ 346.00
83	FRONT WHEEL BEARING WITH ASSEMBLY-RH <i>Drumged</i>	\$ 283.00	☒ 226.00
84	FRONT SUSPENSION FORKS-RH <i>Here</i>	\$ 225.00	☒
85	FRONT DOOR CATCH COVER-RH <i>Here</i>	\$ 13.00	☒
86	FRONT COUPLING ROD-RH <i>Bent</i>	\$ 124.00	☒ 98.80
87	FRONT GAS SHOCK ABSORBER-RH <i>Here</i>	\$ 260.00	☒
88	FRONT DRIVE SHAFT WITH CONSTANT-RH <i>Not in</i>	\$ 2,363.00	☒
89	FRONT STRUT MOUNTING-RH <i>Here</i>	\$ 80.00	☒
90	FRONT STEERING GEAR <i>Drumged</i>	\$ 5,761.00	☒ 4608.80
91	FRONT TRACK ROD-RH <i>Bent</i>	\$ 87.00	☒ 68.88
92	STEERING GEAR GREASE <i>Here</i>	\$ 39.00	☒
93	FRONT TIE ROD END <i>Bent</i>	\$ 169.00	☒ 135.20
TOTAL SPARE PARTS CHARGES - FRONT :		\$ 41,016.00	
TOTAL LABOUR CHARGES - FRONT		\$ 29,840.00	
GRAND TOTAL - FRONT		\$ 70,856.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR DOOR-RH <i>Distorted</i>	\$ 1,928.00	✓ 1542.40
2	REAR DOOR OUTER DOOR SEAL-RH <i>new</i>	\$ 176.00	✓ 140.40
3	BONDING AGENT <i>NE new</i>	\$ 43.00	X
4	CLEANING SOLUTION <i>NE new</i>	\$ 64.00	X
5	APPLICATOR <i>NE new</i>	\$ 7.00	X
6	SEALING STRIP <i>NE new</i>	\$ 14.00	X
7	REAR DOOR CATCH -RH	\$ 105.00	X
8	REAR DOOR CATCH COVER-RH <i>NE new</i>	\$ 12.00	X
9	REAR DOOR ATTACHMENT PARTS <i>NE new</i>	\$ 488.00	X
10	REAR SIDE PANEL TRIM-RH <i>Regin</i>	\$ 2,787.00	X
11	REAR WINDOW <i>NE new</i>	\$ 1,014.00	X
11	PRIMER	2 \$ 37.00	X
12	REAR SIDE WINDOW-RH <i>NE new</i>	\$ 541.00	X
13	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>NE new</i>	\$ 265.00	X
14	REAR WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>NE new</i>	\$ 317.00	X
15	REAR TRIM STRIPS FOR SIDE WINDOW <i>new</i>	\$ 426.00	X
16	REAR FENDER LEDGE COVER-RH <i>new</i>	\$ 53.00	X
17	REAR DOOR SEAL INNER-RH <i>new</i>	\$ 176.00	X
18	ACRYLIC SEALNT <i>NE new</i>	S/N \$ 180.00	✓
19	CAVITY WAX <i>NE new</i>	S/N \$ 140.00	✓
20	STONE CHIP <i>NE new</i>	S/N \$ 180.00	✓
SUB-TOTAL SPARE PARTS - frt/rear		\$ 8,953.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	METAL FILLER POWDER <i>nee</i>	S/N \$ 280.00	✓
22	REAR W/S SEALANT	S/N \$ 200.00	x
23	1/4 GLASS SEALNT	S/N \$ 100.00	x
24	FRONT NO. PLATE	S/N \$ 25.00	x
25	SUNDRIES <i>nee</i>	\$ 1,000.00	20136
TOTAL SPARE PARTS CHARGES - FR/RR		\$ 51,574.00	
TOTAL LABOUR CHARGES - FR/RR		\$ 42,494.00	
GRAND TOTAL - FF/RR		\$ 94,068.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

100280.08*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lij

Surveyed Date

: 12/11/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 18 Days. Inclusive of undercarriage.
Not Inclusive of Lock carrier.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1267/2018/GW 20-Nov-18 Jeffery Tan 1 SDU 887 A Audi A4 Sedan 1.41 TFSI S
Quantity	Description	Unit Price	Amount
Labour			
1	To remove main wire harness and all installations on firewall to facilitate wheel house repairs. (Special nett)	\$ 1,100.00	✓
2	To cut and reweld firewall to facilitate wheel house panel repairs.	\$ 3,000.00	1500
3	To insulate and respray firewall and wheel house.	\$ 800.00	550
		\$ 4,900.00	
TOTAL		\$ 4,900.00	

For Premium Automobiles Pte Ltd

Adrian Ling
S.P.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1267/2018/GW
Date : 8/11/2018

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLT 8274 B**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 50 days - jb 2 Feb 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loh Boon Yiong
Address : 87 Jurong West Central 3
#11-48
Singapore 648343
Telephone : (HP) 96962615
Type of Claim : Third Party Claims
Policy No. : 2100507389-01
Vehicle No : **SDU 887 A**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Apr-18
Engine No : CVN 032575
Chassis No : WAUZZZF42GA111565
Mileage : 32803 KM
Date In : 4-Nov-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Nov-18
Place of Accident : Junction of Bishan St 14 and Bishan St 15

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges			
1	To tow and recover vehicle from scene of accident.	S/N	WAIVED		
2	To carry out first measurement test on car o-liner.	S/N	\$ 800.00	nil	
3	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
4	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N	\$ 1,000.00	nil	
5	To remove and reinstall center console and dashboard assy for A- pillar renewal. Inspect for damages.	S/N	\$ 3,200.00	\$	3,200.00
6	To dislodge and reinstall rhs A-pillar, rhs front door harness, rhs rear door harness, multi-lock system and power window devices. Inspect for damages.	S?N	\$ 1,400.00	\$	560.00
7	To suspend engine assy. To dismantle front suspension assy. To inspect damages and renew accordingly .	S/N	\$ 2,800.00	\$	2,800.00
SUB-TOTAL LABOUR CHARGES - FRONT		:	\$ 9,560.00	\$	6,920.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
	<i>c/f</i>	
8	To setup vehicle on car-o-liner for repair.	S/N \$ 2,400.00
9	To dismantle and renew front bumper, bonnet, rhs headlight . Rhs front fender, rhs front door and rhs rear door. Cut out and reweld rhs front fender top support, A-pillar an rhs sill panel. To renew front lock carrier and align to position. Re-organise crash management components. reinstall all parts removed. (<i>'A' Pillar sill panel replaced</i>)	\$ 10,500.00
10	To respray front bumper, bonnet, bonnet hinges, rhs front fender, rhs front fender top support, rhs front door, rhs rear door, rhs A-pillar. rhs sill panel, door handles, door hinges and wing mirror cover. To carry out joint sealant works and stone chip treatment. (<i>Added \$550/- for A pillar</i>)	\$ 7,100.00
11	To renew rhs front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00
TOTAL LABOUR CHARGES - FRONT		: \$ 29,840.00