

Dear Sirs/Madam,

ACCIDENT INVOLVING SLT 8274B(OI) AND SDU 887A(TP) ON 04/11/2018

We refer to the above matter.

Insured was making a right turn. Liability is not in our driver's favour.

We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, "**PREMIUM AUTOMOBILES PTE LTD**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 107,299.69	\$ 51,360.00
2. Loss of Rental (33days x \$100)	\$ 3,300.00	\$ 3,300.00 (33days x \$100)
3. Loss of Use (27days x \$60)	\$ 1,620.00	\$ -
Total	\$ 112,219.69	\$ 54,660.00

**33days recommendation for repair.

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SDU887A (4610778952SG)**
[SLT8274B]

TP
LOH BOON YIONG
Nov 4 2018 9:00PM
[LCRF PTE LTD]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 26/11/2019 16:47 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$54660.00) - SDU887A - Claim Handler: Gan, Angie-GL

Approved:54660.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SDU887A (4610778952SG)**
[SLT8274B]

TP
LOH BOON YIONG
Nov 4 2018 9:00PM
[LCRF PTE LTD]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 28/11/2019 13:57 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$55260.00) - SDU887A - Claim Handler: Gan, Angie-GL

Approved:55260.00.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Nov 2018 Edit Reg		12 Nov 2018 00:00 Edit Adj Rpt	S\$48,000.00 Edit Estimates	S\$48,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	LOH BOON YIONG, ID: S7206237Z		
Vehicle Reg. No.:	SDU887A	Date of Loss:	04/11/2018 21:00 - :59 [18 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4610778952SG	Policy/Cover Note No.:	0999994782 (Comprehensive)
Vehicle Reg. No. (Insured):	SLT8274B	Policy No. (Claimant):	2100507389-01
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (28/11/2019): Alert - Adj Mandate Approved (S\$55260.00) - SDU887A - Claim Handler: Gan, Angie-...
- AIG_SG_EXPRESS (26/11/2019): Alert - Adj Mandate Approved (S\$54660.00) - SDU887A - Claim Handler: Gan, Angie-...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDU887A (4610778952SG)**
[SLT8274B]
TP
LOH BOON YIONG
Nov 4 2018 9:00PM
[LCRF PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
No Finalized On LKK Auto Consultants Pte Ltd (HQ)			1 per page ▼ ☒	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Thumbnail Edit Print
Photos/Images				
No Relabel/Reorder LKK Auto Consultants Pte Ltd (HQ)			3 per page ▼ ☒	
1	04/06/19 12:02	General View		Load JPG ☒
2	04/06/19 12:02	General View		Load JPG ☒
3	04/06/19 12:02	General View		Load JPG ☒
4	04/06/19 12:02	General View		Load JPG ☒
5	04/06/19 12:02	General View		Load JPG ☒
6	04/06/19 12:02	General View		Load JPG ☒
7	04/06/19 12:02	General View		Load JPG ☒
8	04/06/19 12:02	General View		Load JPG ☒
9	04/06/19 12:02	General View		Load JPG ☒
10	04/06/19 12:02	General View		Load JPG ☒
11	04/06/19 12:02	General View		Load JPG ☒
12	04/06/19 12:02	General View		Load JPG ☒
13	04/06/19 12:02	General View		Load JPG ☒
14	04/06/19 12:02	General View		Load JPG ☒
15	04/06/19 12:02	General View		Load JPG ☒
16	04/06/19 12:02	General View		Load JPG ☒
17	04/06/19 12:02	General View		Load JPG ☒
18	04/06/19 12:02	General View		Load JPG ☒
19	04/06/19 12:02	General View		Load JPG ☒
20	04/06/19 12:02	General View		Load JPG ☒
21	04/06/19 12:02	General View		Load JPG ☒
22	04/06/19 12:02	General View		Load JPG ☒
23	04/06/19 12:02	General View		Load JPG ☒
24	04/06/19 12:02	General View		Load JPG ☒
25	04/06/19 12:02	General View		Load JPG ☒
26	04/06/19 12:02	General View		Load JPG ☒
27	04/06/19 12:02	General View		Load JPG ☒
28	04/06/19 12:02	General View		Load JPG ☒
29	04/06/19 12:02	General View		Load JPG ☒
30	04/06/19 12:02	General View		Load JPG ☒
31	04/06/19 12:02	General View		Load JPG ☒
32	04/06/19 12:02	General View		Load JPG ☒
33	04/06/19 12:02	General View		Load JPG ☒
34	04/06/19 12:02	General View		Load JPG ☒
35	04/06/19 12:02	General View		Load JPG ☒
36	04/06/19 12:02	General View		Load JPG ☒
37	04/06/19 12:02	General View		Load JPG ☒

Letters/Correspondences			1 per page ▾	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/06/19 12:02	General View	 Load JPG	✓
39	04/06/19 12:02	General View	 Load JPG	✓
40	04/06/19 12:02	General View	 Load JPG	✓
41	04/06/19 12:02	General View	 Load JPG	✓
42	04/06/19 12:02	General View	 Load JPG	✓
43	04/06/19 12:02	General View	 Load JPG	✓
44	04/06/19 12:02	General View	 Load JPG	✓
45	04/06/19 12:02	General View	 Load JPG	✓
46	04/06/19 12:02	General View	 Load JPG	✓
47	04/06/19 12:02	General View	 Load JPG	✓
48	04/06/19 12:02	General View	 Load JPG	✓
49	04/06/19 12:02	General View	 Load JPG	✓
50	04/06/19 12:02	General View	 Load JPG	✓
51	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
52	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
53	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
54	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
55	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
56	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
57	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
58	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
59	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
60	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
61	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
62	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
63	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
64	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
65	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
66	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
67	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
68	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
69	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
70	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
71	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
72	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
73	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
74	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
75	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
76	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
77	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
78	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
79	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
80	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
81	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
82	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
83	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
84	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
85	04/06/19 12:02	Reinspection Photo	Load JPG	✓
86	04/06/19 12:02	Reinspection Photo	Load JPG	✓
87	04/06/19 12:02	Reinspection Photo	Load JPG	✓
88	04/06/19 12:02	Reinspection Photo	Load JPG	✓
89	04/06/19 12:02	Reinspection Photo	Load JPG	✓
90	04/06/19 12:02	Reinspection Photo	Load JPG	✓

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
92	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
93	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
94	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
95	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
96	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
97	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
98	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
99	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
100	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
101	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
102	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
103	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
104	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
105	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
106	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
107	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
108	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
109	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
110	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
111	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
112	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
113	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
114	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
115	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
116	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
117	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
118	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
119	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
120	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
121	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
122	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
123	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
124	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
125	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
126	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
127	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
128	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
129	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
130	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
131	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
132	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
133	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
134	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
135	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
136	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
137	04/06/19 12:02	Reinspection Photo	 Load JPG	✓
138	04/06/19 12:02	Reinspection Photo	Load JPG	✓
139	04/06/19 12:02	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 17:36	TP GIA REPORT	 Load PDF	
2	12/11/18 16:50	TP ESTIMATE- MARKED	 Load PDF	

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	26/11/19 11:18	LETTER TO OI.	 Load PDF	
4	26/11/19 11:18	LOD	 Load PDF	
5	26/11/19 11:18	RENTAL RECEIPT	 Load PDF	
6	03/12/19 14:44	AUTHORISATION TO ACT	 Load PDF	
7	03/12/19 14:44	RELEASE VOUCHER	 Load PDF	
8	03/12/19 14:44	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	08/11/18 09:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT8274B (Insd veh)	Model:	AUDI A4 1.4 TFSI S TRONIC (A)
	SDU887A (TP veh)		
Date of Accident:	04/11/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$	107,299.69	
Final Repair Cost	:	\$	51,360.00	
Loss of Use	:	\$	600.00	10.00 days at \$60.00 per day
Rental (if any)	:	\$	3,300.00	33 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$	55,260.00	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>5</u>		
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 55,260.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

03 Dec
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18020167/ADB3S2

Date: 03/12/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994782
Claimant Vehicle No :	SDU887A	Insured Vehicle No :	SLT8274B
Date of Loss:	04/11/2018	Nature of Claim:	TP
		Claim No:	4610778952SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDU887A	Engine No:	CVN032575
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF41HA124843
Reg. Date:	18/04/2017 (Man. Year: 2017)	Odometer:	32803 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,876.08	27,047.68	26,828.40	49.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	46,404.00	22,604.00	23,800.00	51.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	100,280.08	49,651.68	50,628.40	50.49
Approved Total (Overridden) (S\$)		48,000.00		
(S\$)	100,280.08	48,000.00	52,280.08	52.13
+ GST 7.00/7.00% (S\$)	7,019.61	3,360.00	3,659.61	52.13
Nett Amount (S\$)	107,299.69	51,360.00	55,939.69	52.13
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Car Rental (33.0 x S\$100.00/day) (S\$)		3,300.00		
Nett Liability (S\$)		55,260.00		

INSPECTION

Date of Assignment:	12/11/2018		
Date Inspected:	12/11/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	33.0 days		

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	30.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Damaged	73.00 FS	*57.84 FS
7	1		*RADIATOR	Not Necessary	1,524.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	319.00 FS	*255.20 FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	32.00 FS	*25.36 FS
10	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Not Necessary	109.00 FS	*- FS
13	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
14	1		*AIR CONDITIONER STRIKER	Not Necessary	7.00 FS	*- FS
15	1		*FRONT FENDER - RH	Distorted	665.00 FS	*532.00 FS
16	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	45.00 FS	*- FS
17	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	44.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - RH	Bent	31.00 FS	*24.16 FS
19	1		*FRONT FENDER FOR DEFORMATION ELEMNT - RH	Necessary	43.00 FS	*34.16 FS
20	1		*FRONT FENDER RETAINING BRACKET - RH	Damaged	27.00 FS	*21.60 FS
21	1		*FRONT FENDER UPPER BRACKET - RH	Bent	15.00 FS	*11.76 FS
22	1		*FRONT FENDER BRACE - RH	Bent	103.00 FS	*82.40 FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Damaged	29.00 FS	*22.72 FS
24	1		*FRONT WHEEL HOUSING LINER - RH	Torn	209.00 FS	*167.20 FS
25	1		*WHEEL HOUSING ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
26	1		*FRONT WHEEL SPOILER - RH	Torn	63.00 FS	*52.32 FS
27	1		*FRONT END PLATE - RH	Damaged	31.00 FS	*24.32 FS
28	1		*FRONT STONE CHIP GUARD - RH	Necessary	44.00 FS	*34.56 FS
29	1		*FRONT FENDER LEDGE COVER - RH	Necessary	27.00 FS	*21.04 FS
30	1		*FRONT FENDER LEDGE TOP COVER - RH	Necessary	20.00 FS	*15.36 FS
31	1		*BONNET	Distorted	2,163.00 FS	*1,730.40 FS
32	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
33	2		*BONNET LID HINGE - LH/RH	Not Necessary	532.00 FS	*- FS
34	1		*BONNET STOPPER BUFFER	Not Necessary	9.00 FS	*- FS
35	1		*BONNET IMPACT EDGE PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
36	2		*BONNET IMPACT EDGE PROTECTION - LH/RH	Necessary	48.00 FS	*37.76 FS
37	2		*BONNET GAS FILLED STRUT	Not Necessary	209.00 FS	*- FS
38	2		*BONNET STRIKER - LH/RH	Not Necessary	88.00 FS	*- FS
39	2		*BONNET LID LOCK	Not Necessary	376.00 FS	*- FS
40	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	50.00 FS	*- FS
41	1		*BONNET RELEASE LEVER	Not Necessary	12.00 FS	*- FS
42	1		*PLENUM CHAMBER COVER	Not Necessary	85.00 FS	*- FS
43	1		*LOCK CARRIER BRACKET	Not Necessary	118.00 FS	*- FS
44	2		*FRONT BUMPER SUPPORT - LH/RH	Not Necessary	48.00 FS	*- FS
45	1		*FANFARE - LOW TONE	Not Necessary	254.00 FS	*- FS
46	1		*SPRING SHACKLE - RH	Not Necessary	25.00 FS	*- FS
47	1		*LOCK CARRIER WITH MOUNTING	Not Necessary	891.00 FS	*- FS
48	4		*COOLANT CONCENTRATE 1.5 LTR	Not Necessary	133.00 FS	*- FS
49	1		*LED HEADLIGHT - RH	Smashed	6,973.00 FS	*5,578.40 FS
50	1		*LED HEADLIGHT POWER MODULE - RH	Not Necessary	695.00 FS	*- FS
51	1		*LED HEADLIGHT CONTROL UNIT - RH	Not Necessary	657.00 FS	*- FS
52	2		*COMPENSATING PIECE	Not Necessary	73.00 FS	*- FS
53	1		*LED HEADLIGHT LIFT CYLINDER - RH	Not Necessary	184.00 FS	*- FS
54	1		*WASH WATER RESERVOIR	Deformed	128.00 FS	*102.40 FS
55	1		*CONNECTION PLATE - RH	Not Necessary	189.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT WHEEL HOUSING - RH	Not Necessary	52.00 FS	*- FS
57	1		*FRONT FENDER FILLER PANEL - RH	Not Necessary	219.00 FS	*- FS
58	1		*FRONT DOOR - RH	Distorted	2,048.00 FS	*1,638.40 FS
59	1		*FRONT OUTER DOOR SEAL - RH	Necessary	176.00 FS	*140.40 FS
60	1		*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
61	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
62	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
63	1		*DOOR ATTACHMENT PARTS	Not Necessary	462.00 FS	*- FS
64	1		*FRONT DOOR CATCH - RH	Not Necessary	92.00 FS	*- FS
65	1		*FRONT DOOR CATCH COVER - RH	Not Necessary	13.00 FS	*- FS
66	1		*FRONT DOOR HINGE HALF - RH UPPER	Bent	40.00 FS	*31.68 FS
67	1		*FRONT DOOR HINGE HALF - RH LOWER	Bent	39.00 FS	*30.80 FS
68	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR - RH	Not Necessary	242.00 FS	*- FS
69	1		*FRONT WINDOW REGULATOR MOTOR - RH	Not Necessary	228.00 FS	*- FS
70	1		*FRONT DOOR CONTROL UNIT - RH	Not Necessary	653.00 FS	*- FS
71	1		*DATE PLATE FOR TYRE PRESSURE	Necessary	33.00 FS	*27.36 FS
72	1		*CHASSIS DATA TAG	Not Necessary	406.00 FS	*- FS
73	1		*FRONT ALUMINIUM RIM - RH	Cut	563.00 FS	*450.00 FS
74	4		*RUBBER VALVE	Necessary	12.00 FS	*9.92 FS
75	1		*ASSEMBLY CARRIER	Bent	1,657.00 FS	*1,325.60 FS
76	1		*FRONT WISHBONE LINK - RH	Bent	476.00 FS	*380.40 FS
77	1		*FRONT SUSPENSION GUIDE - RH	Bent	834.00 FS	*667.20 FS
78	1		*FRONT GUIDE - RH UPPER	Bent	452.00 FS	*361.20 FS
79	1		*FRONT GUIDE - RH REAR UPPER	Bent	452.00 FS	*361.20 FS
80	1		*FRONT WHEEL BEARING - RH	Damaged	848.00 FS	*678.40 FS
81	1		*FRONT SWIVEL JOINT - RH	Bent	165.00 FS	*132.00 FS
82	1		*FRONT WHEEL HUB - RH	Damaged	433.00 FS	*346.00 FS
83	1		*FRONT WHEEL BEARING WITH ASSEMBLY - RH	Damaged	283.00 FS	*226.00 FS
84	1		*FRONT SUSPENSION FORKS - RH	Not Necessary	225.00 FS	*- FS
85	1		*FRONT DOOR CATCH COVER - RH	Not Necessary	13.00 FS	*- FS
86	1		*FRONT COUPLING ROD - RH	Bent	124.00 FS	*98.80 FS
87	1		*FRONT GAS SHOCK ABSORBER - RH	Not Necessary	260.00 FS	*- FS
88	1		*FRONT DRIVE SHAFT WITH CONSTANT - RH	Not Necessary	2,363.00 FS	*- FS
89	1		*FRONT STRUT MOUNTING - RH	Not Necessary	80.00 FS	*- FS
90	1		*FRONT STEERING GEAR	Damaged	5,761.00 FS	*4,608.80 FS
91	1		*FRONT TRACK ROD - RH	Bent	87.00 FS	*68.88 FS
92	1		*STEERING GEAR GREASE	Not Necessary	39.00 FS	*- FS
93	1		*FRONT TIE ROD END	Bent	169.00 FS	*135.20 FS
94	1		*REAR DOOR - RH	Distorted	1,928.00 FS	*1,542.40 FS
95	1		*REAR DOOR OUTER DOOR SEAL - RH	Necessary	176.00 FS	*140.40 FS
96	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
97	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
98	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
99	1		*SEALING STRIP	Not Necessary	14.00 FS	*- FS
100	1		*REAR DOOR CATCH - RH	Not Necessary	105.00 FS	*- FS
101	1		*REAR DOOR CATCH COVER - RH	Not Necessary	12.00 FS	*- FS
102	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	488.00 FS	*- FS
103	1		*REAR SIDE PANEL RH	Repair	2,787.00 FS	*- FS
104	1		*REAR WINDOW	Not Necessary	1,014.00 FS	*- FS
105	2		*PRIMER	Not Necessary	37.00 FS	*- FS
106	1		*REAR SIDE WINDOW - RH	Not Necessary	541.00 FS	*- FS
107	1		*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - RH	Not Necessary	265.00 FS	*- FS
108	1		*REAR WINDOW SLOT SEAL WITH TRIM STRIP - RH	Not Necessary	317.00 FS	*- FS
109	1		*REAR TRIM STRIPS FOR SIDE WINDOW	Not Necessary	426.00 FS	*- FS
110	1		*REAR FENDER LEDGE COVER - RH	Not Necessary	53.00 FS	*- FS
111	1		*REAR DOOR SEAL INNER - RH	Not Necessary	176.00 FS	*- FS
112	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
113	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
114	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
115	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*REAR W/S SEALANT	Not Necessary	200.00 FS	*- FS
117	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
118	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*- FS
119	1		*SUNDRIES	Necessary	1,000.00 FS	*201.36 FS
120	1		*FRONT TYRE - RH	Punctured	250.00 FS	*250.00 FS
121	1		*FRONT DOOR HINGE - RH INNER UPPER	Bent	31.44 FS	*31.44 FS
122	1		*FRONT DOOR HINGE - RH INNER LOWER	Bent	33.04 FS	*33.04 FS
123	1		*A-PILLAR PANEL - RH	Dented	1,877.60 FS	*1,877.60 FS
124	1		*FRONT ENTRANCE TRIM - RH	Necessary	87.20 FS	*87.20 FS
125	1		*BULB	Damaged	22.80 FS	*22.80 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	53,876.08	27,047.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT. (NPA)	New	0.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	New	800.00	0.00
3	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
4	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	New	1,000.00	0.00
5	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL. INSPECT FOR DAMAGES.	New	3,200.00	3,200.00
6	TO DISLODGE AND REINSTALL RHS A-PILLAR, RHS FRONT DOOR HARNESS, RHS REAR DOOR HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	1,400.00	560.00
7	TO SUSPEND ENGINE ASSY, TO DISMANTLE FRONT SUSPENSION ASSY. TO INSPECT DAMAGES AND RENEW ACCORDINGLY.	New	2,800.00	2,800.00
8	TO REMOVE AND TRANSFER REAR PARKING AID AN REAR LID KICK SENSOR. CHECK FUNCTION.	New	360.00	360.00
9	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS FOR FENDER RENEWAL.	New	600.00	0.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BETTER MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	0.00
11	TO REMOVE AND REINSTALL RHD FRONT SEAT, RHS REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,800.00	0.00
12	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND REWELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,800.00	1,000.00
13	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, ROOF CHANNEL, DRAIN CHANNEL AND END PANELLING. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	New	3,300.00	1,100.00
14	TO CARRY OUT DIAGNOSTIC CHECKS.	New	394.00	394.00
15	TO SETUP VEHICLE ON CAR O-LINER FOR REPAIR.	New	2,400.00	0.00
16	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS HEADLIGHT. RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. CUT OUT AND REWELD RHS FRONT FENDER TOP SUPPORT, A-PILLAR AND RHS SILL PANEL. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	10,500.00	5,000.00
17	TO RESPRAY FRONT BUMPER, BONNET, BONNET HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR, RHS REAR DOOR, RHS A-PILLAR. RHS SILL PANEL, DOOR HANDLES, DOOR HINGES AND WING MIRROR COVER. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT.	New	7,100.00	4,400.00
18	TO RENEW RHS FRONT RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
19	TO REMOVE MAIN WIRE HARNESS AND ALL INSTALLATIONS ON FIREWALL TO FACILITATE WHEEL HOUSE REPAIRS.	New	110.00	1,100.00
20	TO CUT AND REWELD FIREWALL TO FACILITATE WHEEL HOUSE PANEL REPAIRS.	New	3,000.00	1,500.00
21	TO INSULATE AND RESPRAY FIREWALL AND WHEEL HOUSE.	New	800.00	550.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
Gross Labour Cost (\$\$)			46,404.00	22,604.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >