

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1267/2018/GW
Date : 8/11/2018

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLT 8274 B**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Loh Boon Yiong
Address : 87 Jurong West Central 3
#11-48
Singapore 648343
Telephone : (HP) 96962615
Type of Claim : Third Party Claims
Policy No. : 2100507389-01
Vehicle No : **SDU 887 A**
Model Code : Audi A4 Sedan 1.41 TFSI S
Model / Year : Apr-18
Engine No : CVN 032575
Chassis No : WAUZZZF42GA111565
Mileage : 32803 KM
Date In : 4-Nov-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Nov-18
Place of Accident : Junction of Bishan St 14 and Bishan St 15

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N WAIVED ✓
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00 ?
3	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
4	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/ regas and to pressurise cooling system.	S/N \$ 1,000.00 ?
5	To remove and reinstall center console and dashboard assy for A- pillar renewal. Inspect for damages.	S/N \$ 3,200.00 X
6	To dislodge and reinstall rhs A-pillar, rhs front door harness, rhs rear door harness, multi-lock system and power window devices. Inspect for damages.	S/N \$ 1,400.00 560.
7	To suspend engine assy. To dismantle front suspension assy. To inspect damages and renew accordingly.	S/N \$ 2,800.00 ?
SUB-TOTAL LABOUR CHARGES - FRONT		: \$ <u><u>9,560.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
8	To setup vehicle on car-o-liner for repair.	S/N \$ 2,400.00 ?
1/2 9	To dismantle and renew front bumper, bonnet, rhs headlight. Rhs front fender, rhs front door and rhs rear door. Cut out and reweld rhs front fender top support, A-pillar and rhs sill panel. To renew front lock carrier and align to position. Re-organise crash management components. reinstall all parts removed.	\$ 10,500.00 3000. 60x \$500
10	To respray front bumper, bonnet, bonnet hinges, rhs front fender, rhs front fender top support, rhs front door, rhs rear door, rhs A-pillar. rhs sill panel, door handles, door hinges and wing mirror cover. To carry out joint sealant works and stone chip treatment.	\$ 7,100.00 3850.
11	To renew rhs front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00 ✓
TOTAL LABOUR CHARGES - FRONT		: \$ 29,840.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	\$ 1,849.00	✓
2	FRONT BUMPER FIXING PARTS <i>?</i>	\$ 245.00	?
3	FRONT BUMPER SECURING STRIP <i>?</i>	\$ 30.00	?
4	FRONT BUMPER GRILLE-CENTER <i>see in.</i>	\$ 171.00	x
5	FRONT BUMPER CLOSING ELEMENT <i>see in</i>	\$ 180.00	x.
6	FRONT BUMPER AIR GUIDE-RH <i>Engd</i>	\$ 73.00	✓
7	RADIATOR <i>see in</i>	\$ 1,524.00	x
8	FRONT BUMPER AIR GUIDE GRILLE-RH <i>missing</i>	\$ 319.00	✓
9	FRONT BUMPER GUIDE SECTION-RH <i>Engd</i>	\$ 32.00	✓
10	FOAM FILLER PIECE <i>see in.</i>	\$ 107.00	x
11	FRONT BUMPER CARRIER <i>see in</i>	\$ 702.00	x.
12	FRONT BUMPER COVER <i>see in</i>	\$ 109.00	x
13	SIGN " CAUTION " <i>2 not</i>	\$ 12.00	x
14	AIR CODITIONER STICKER <i>see</i>	\$ 7.00	x
15	FRONT FENDER-RH <i>Distorted</i>	\$ 665.00	✓
16	FRONT FENDER ATTACHEMENT PARTS-RH <i>?</i>	\$ 45.00	?
17	FRONT FENDER CLOSING ELEMENT-RH <i>?</i>	\$ 44.00	?
18	FRONT FENDER BRACKET-RH <i>Best</i>	\$ 31.00	✓
19	FRONT FENDER FOR DEFORMATION ELEMT-RH <i>see</i>	\$ 43.00	✓
20	FRONT FENDER RETAINING BRACKET-RH <i>Engd</i>	\$ 27.00	✓
SUB- SPARE PARTS CHARGES - FRONT		\$ 6,215.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER UPPER BRACKET-RH <i>Best</i>	\$	15.00 ✓
22	FRONT FENDER BRACE-RH <i>Best</i>	\$	103.00 ✓
23	FRONT FENDER CLOSING LEMENT-RH ?	\$	29.00 ?
24	FRONT WHEEL HOUSING LINER-RH <i>torn</i>	\$	209.00 ✓
25	WHEEL HOUSING ATTACHEMENT PARTS ?	\$	78.00 ?
26	FRONT WHEEL SPOILER-RH <i>torn</i>	\$	63.00 ✓
27	FRONT END PLATE-RH <i>Damaged</i>	\$	31.00 ✓
28	FRONT STONE CHIP GUARD-RH <i>new</i>	\$	44.00 ✓
29	FRONT FENDER LEDGE COVER-RH <i>3 new</i>	\$	27.00 ✓
30	FRONT FENDER LEDGE TOP COVER-RH	\$	20.00 ✓
31	BONNET <i>Distorted.</i>	\$	2,163.00 ✓
32	BONNET ATTACHEMENT PARTS ?	\$	105.00 ?
33	BONNET LID HINGE-LH/RH ?	2 \$	532.00 ?
34	BONNET STOP BUFFER <i>new</i>	\$	9.00 +
35	BONNET IMPACT EDGE PROTECTION-CENTER <i>3 new</i>	\$	24.00 ✓
36	BONNET IMPACT EDGE PROTECTION-LH/RH	2 \$	48.00 ✓
37	BONNET GAS FILLED STRUT	2 \$	209.00 +
38	BONNET STRIKER-LH/RH	2 \$	88.00 +
39	BONNET LID LOCK	2 \$	376.00 +
40	BONNET BOWDEN CABLE-CENTER	\$	50.00 +
SUB- SPARE PARTS CHARGES - FRONT		\$	4,223.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	BONNET RELEASE LEVER <i>not see</i>	\$	12.00 <i>x</i>
42	PLENUM CHAMBER COVER <i>not see</i>	\$	85.00 <i>x</i>
43	LOCK CARRIER BRACKET <i>not see</i>	\$	118.00 <i>x</i>
44	FRONT BUMPER SUPPORT-LH/RH ?	2 \$	48.00 ?
45	FANFARE - LOW TONE ?	\$	254.00 ?
46	SPRING SHACKLE-RH ?	\$	25.00 ?
47	LOCK CARRIER WITH MOUNTING ?	\$	891.00 ?
48	COOLANT CONCENTRATE 1.5 LTR ?	4 \$	133.00 ?
49	LED HEADLIGHT-RH <i>Smashed</i>	\$	6,973.00 ✓
50	LED HEADLIGHT POWER MODULE-RH <i>not see</i>	\$	695.00 <i>x</i>
51	LED HEADLIGHT CONTROL UNIT-RH <i>not see</i>	\$	657.00 <i>x</i>
52	COMPENSATING PIECE ?	2 \$	73.00 ?
53	LED HEADLIGHT LIFT CYLINDER-RH ?	\$	184.00 ?
54	WASH WATER RESERVOIR <i>behind</i>	\$	128.00 ✓
55	CONNECTION PLATE-RH ?	\$	189.00 ?
56	FRONT WHEEL HOUSING-RH ?	\$	52.00 ?
57	FRONT FENDER FILLER PANEL-RH ?	\$	219.00 ?
58	FRONT DOOR-RH <i>Distorted</i>	\$	2,048.00 ✓
59	FRONT OUTER DOOR SEAL-RH <i>see</i>	\$	176.00 ✓
60	BONDNG AGENT ?	\$	43.00 ?
SUB- SPARE PARTS CHARGES - FRONT		\$	13,003.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	CLEANING SOLUTION ?	\$	64.00 ?
62	APPLICATOR ?	\$	7.00 ?
63	DOOR ATTACHMENT PARTS ?	\$	462.00 ?
64	FRONT DOOR CATCH-RH new ?	\$	92.00 ?
65	FRONT DOOR CATCH COVER-RH ?	\$	13.00 ?
66	FRONT DOOR HINGE HALF-RH UPPER ?	\$	40.00 ?
67	FRONT DOOR HINGE HALF-RH LOWER ?	\$	39.00 ?
68	FRONT WINDOW REGULATOR WITHOUT MOTOR-RH new ?	\$	242.00 x
69	FRONT WINDOW REGULATOR MOTOR-RH ? new	\$	228.00 x
70	FRONT DOOR CONTROL UNIT-RH	\$	653.00 x
71	DATE PLATE FOR TRYR PRESSURE new	\$	33.00 ✓
72	CHASSIC DATA TAG ?	\$	406.00 ?
73	FRONT ALUMINIUM RIM-RH new	\$	563.00 ✓
74	RUBBER VALVE new	4 \$	12.00 x
75	ASSEMBLY CARRIER ?	\$	1,657.00 ?
76	FRONT WISHBONE LINK-RH ?	\$	476.00 ?
77	FRONT SUSPENSION GUIDE-RH ?	\$	834.00 ?
78	FRONT GUIDE-RH UPPER ?	\$	452.00 ?
79	FRONT GUIDE-RH REAR UPPER ?	\$	452.00 ?
80	FRONT WHEEL BEARING-RH ?	\$	848.00 ?
SUB SPARE PARTS CHARGES - FRONT		\$	<u>7,573.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	FRONT SWIVEL JOINT-RH ?	\$ 165.00	?
82	FRONT WHEEL HUB-RH ?	\$ 433.00	?
83	FRONT WHEEL BEARING WITH ASSEMBLY-RH ?	\$ 283.00	?
84	FRONT SUSPENSION FORKS-RH ?	\$ 225.00	?
85	FRONT DOOR CATCH COVER-RH ?	\$ 13.00	?
86	FRONT COUPLING ROD-RH ?	\$ 124.00	?
87	FRONT GAS SHOCK ABSORBER-RH ?	\$ 260.00	?
88	FRONT DRIVE SHAFT WITH CONSTANT-RH ?	\$ 2,363.00	?
89	FRONT STRUT MOUNTING-RH ?	\$ 80.00	?
90	FRONT STEERING GEAR ?	\$ 5,761.00	?
91	FRONT TRACK ROD-RH ?	\$ 87.00	?
92	STEERING GEAR GREASE ?	\$ 39.00	?
93	FRONT TIE ROD END ?	\$ 169.00	?
TOTAL SPARE PARTS CHARGES - FRONT :		\$ 41,016.00	
TOTAL LABOUR CHARGES - FRONT		\$ 29,840.00	
GRAND TOTAL - FRONT		\$ 70,856.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 887 A

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓
2	To renew rear windscreen and rhs 1/4 glass for fender renewal.	S/N \$ 600.00 ✗
3	To dislodge and reinstall rear wire harness for lights, better manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✗
4	To remove and reinstall rhd front seat, rhs rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,800.00 ✗
5	To dismantle rear bumper and rear lid. Cut out and reweld RHS rear fender. Re-organize crash management components. Reinstall all parts removed.	\$ 4,800.00 1000. ✓
6	To respray rear bumper, RHS rear fender, door entrances, roof channel, drain channel and end panelling. To carry out joint sealant work and stone chip treatment.	\$ 3,300.00 1100. ✓
7	To carry out diagnostic checks.	S/N \$ 394.00 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 12,654.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDU 887 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-RH <i>Distorted</i>	\$ 1,928.00	✓
2	REAR DOOR OUTER DOOR SEAL-RH <i>new</i>	\$ 176.00	✓
3	BONDING AGENT ?	\$ 43.00	?
4	CLEANING SOLUTION ?	\$ 64.00	?
5	APPLICATOR ?	\$ 7.00	?
6	SEALING STRIP ?	\$ 14.00	?
7	REAR DOOR CATCH -RH <i>{ new</i>	\$ 105.00	*
8	REAR DOOR CATCH COVER-RH <i>new</i>	\$ 12.00	*
9	REAR DOOR ATTACHMENT PARTS ?	\$ 488.00	?
10	REAR SIDE PANEL TRIM -RH <i>Regi</i>	\$ 2,787.00	*
11	REAR WINDOW <i>{ new new</i>	\$ 1,014.00	*
11	PRIMER	2 \$ 37.00	*
12	REAR SIDE WINDOW-RH <i>Not new</i>	\$ 541.00	*
13	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>not new</i>	\$ 265.00	*
14	REAR WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>not new</i>	\$ 317.00	*
15	REAR TRIM STRIPS FOR SIDE WINDOW <i>new</i>	\$ 426.00	*
16	REAR FENDER LEDGE COVER-RH <i>new</i>	\$ 53.00	*
17	REAR DOOR SEAL INNER-RH <i>new</i>	\$ 176.00	*
18	ACRYLIC SEALNT ?	S/N \$ 180.00	*
19	CAVITY WAX <i>{ new</i>	S/N \$ 140.00	*
20	STONE CHIP	S/N \$ 180.00	*
SUB-TOTAL SPARE PARTS - frt/rear		: \$ 8,953.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDU 887 A

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	METAL FILLER POWDER ?	S/N \$ 280.00	*
22	REAR W/S SEALANT	S/N \$ 200.00	*
23	1/4 GLASS SEALNT	S/N \$ 100.00	*
24	FRONT NO. PLATE	S/N \$ 25.00	*
25	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS CHARGES - FR/RR		:	\$ 51,574.00
TOTAL LABOUR CHARGES - FR/RR			\$ 42,494.00
GRAND TOTAL - FF/RR			\$ 94,068.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 12/11/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 18 Days. Inclusive of undercarriage
Not Inclusive of lock barriers.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant