

ASS. REC. BY:

REF: CS/FCL18020192 / Dgd/3n2

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

aws

Joanne Yong

of

FCL

Date/Time:

08/12/08 10:08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 9122U

Insured:

SHA 29777

at Workshop m/s

Teamwork

Tel:

6844 2475

of

53 Ubi Ave 1 #01-24

Policy No:

Claim No:

D1800-7968M FSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/12/08

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

08/12/08 11:04am

Person Contacted:

Damen

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 9122U - NA / ALG18020155 / ZL

DA: 04/12/08

SHA 29777 - CS / FCL17006751 / KH3V1

DA: 02/04/07

03/11/08 @ 2:57pm informed Joanne Yong, we are pending estimate from repairer.

14/5/09 @ 3:14pm revised to Joanne Yong by email.

* MV: 8DK (201); VJA: 55819; NV: 24181.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: SLU 9122U Yr Regn: Sept 2009
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Porsche Cayman S C.C. 3387
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 113972 T/Radio: Insured / Std / NI / NA
 Eng/No: 66802661
 C/No: W702229828U773697
 Gen. Cond: G / Fair / Poor / Burnt
 Steering: G / Inoper / Jammed / Leaked / Burnt or
 Brake: G / Inoper / Jammed / Leaked / Burnt or
 Modi: Nil / S / STD A/Rim or
 Tyre Size: F: 235/35 R19
 R: —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin
 Front Rear
 R/Bal: S mm R/Bal: S mm
 L/Bal: S mm L/Bal: S mm
 D.O.A. 04/11/2018 D.O.I. 08/11/2018
 Survey held at Teamwork Page Wbi
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Front
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
First report SMA 29777

Pending estimate

MV 8016
LTA 55K
NL 25K

RECEIVED 14 MAY 2019

14/05/19 Invoice 2/S 7600/- with 5 days grace (Red 10054-76, 57%)

Date/Time File Pass to? : Preli. Report
14/5/19 : Final Report
 Date/Time File Return to?

Days Of Repair: 5
 Resurvey No. of Trip: 2

TX15 = 105

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:	170 + 105
Transportation:	50
S + PE:	50 + 50
Shows:	60
Cost:	16/5/19
TOTAL:	485

Report Format: TP
 Lump Sum / I.B.F. (\$): 7600



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007968MFSH
Our Ref: CS/FCI18020192/Dqd3

Date: 14 May 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 9122U .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2018 at the premises of M/s TEAMWORK GARAGE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>17,654.76</u> .
Revised Estimate Amount	: S\$ <u>7,600.00 (Lump Sum)</u> .
“Check” Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the o/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date 07-11-2018 **Our Ref No.** D18007968MFSH

Accident Date 04-11-2018 **Claim Type.** Third Party

Insured Vehicle SHA2977T **Third Party Vehicle.** SLU9122U

Survey Location BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK

Contact Person. VIVI

Contact No. 68442475/ 0 **Fax No.** 68442474

Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop TEAMWORK GARAGE **Attention.** NIL
PTE LTD

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge JOANNEY

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 14 May 2019 3:14 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007968MFSH/1
Attachments: CSFC118020192Dqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLU 9122U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 November 2018 2:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joaneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007968MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SLU 9122U on 08/11/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 8 November 2018 11:06 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joaneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007968MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 November 2018 2:51 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007968MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SLU 9122U on 08/11/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 8 November 2018 11:06 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joaneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007968MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 8 November, 2018 10:08 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joaneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007968MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4924G
Vehicle Details	
Vehicle No.:	SLU9122U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	PORSCHE
Vehicle Model:	CAYMAN S SPORT
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	66802661
Chassis No.:	WPOZZZ98Z8U773697
Maximum Power Output:	223.0 kW (299 bhp)
Open Market Value:	\$108,471.00
Original Registration Date:	11 Sep 2009
First Registration Date:	11 Sep 2009
Transfer Count:	3
Actual ARF Paid:	\$108,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Sep 2019
PARF Rebate Amount:	\$54,235.00
Intended COE Rebate Details	
COE Expiry Date:	10 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,629.00
COE Rebate Amount:	\$1,584.00
Total Rebate Amount:	\$55,819.00

The information contained herein is correct as at 08 Nov 2018

OK



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park

Tel : 6844 2475
 Email : claims@teamworkgarage.com

DKK Auto Consultants hereto hereby
 the Repairer of the following:
 • To resurvey the car after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Written Evidence Basis"
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be approved
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Vehicle number	SLU9122U
Make / Model	PORSCHE CAYMAN
Chassis number	WPOZZZ9Z8U773697
Accident date	4/11/18
Reference	1811-09

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>Dented</i>	2944.10 7500.00 ✓
2	FRONT BUMPER RETAINER <i>o/s broken N/S NW</i>	125.20 250.40 ✓
1	FRONT BUMPER BRACKET <i>NW</i>	350.00 X
1	FRONT RH HEADLAMP <i>mounting broken</i>	3928.80 ✓
1	FRONT RH SIDE MARKER LAMP <i>SVL</i>	1020.00 X
1	FRONT RH BUMPER COVER <i>Lower crack / cut</i>	560.30 ✓
1	FRONT RH FOG LAMP <i>mounting crack</i>	730.10 ✓
1	FRONT RH FENDER <i>rep</i>	1260.00 X
1	FRONT RH FENDER INNER SHIELD <i>SVL</i>	415.00 X
	8288.50	16014.60
	Less 10% 5%	1601.46
	Subtotal	14413.14
	Balance C/F	14413.14
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	14413.14
1 SET	FRONT BUMPER CLIP <i>Nec</i>	120.00 30/-
1	FRONT RH FENDER INNER SHIELD <i>clips NW</i>	70.00 X
	Subtotal	190.00
	Balance C/F	14603.14
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	14603.14
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM <i>1330/-</i>	60.00 30/-
2	CHECK FRONT WHEEL ALIGNMENT	150.00 NW
3	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 NW
4	PANEL BEATING ON AFFECTED AREAS	800.00 700/-
4	SPARY PAINTING ON AFFECTED AREAS	800.00 600/-
	Subtotal	2310.00
	Grand total	16913.14

08/11/2018 @ 12:00pm
not Andrew 5 days.
4/3mm
 Ryan Lkk And
 8819.65 L/S 7600/-
 Supp 702.58



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
 3RD PARTY CLAIM ESTIMATION

FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Vehicle number	SLU9122U
Make / Model	PORSCHE CAYMAN
Chassis number	WPOZZZ9Z8U773697
Accident date	4/11/18
Reference	1811-09

Qty Particulars

Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT RH FOG LAMP COVER <i>out</i>	312.15 ✓
1	FRONT RH LOWER GRILLE <i>minty crack / deformed</i>	468.50 ✓
	10%	780.65
	Less 5%	39.03
	Subtotal	741.62
	Balance C/F	741.62

[Signature]

2KK And

[Signature]

780.65

10% 702.58

==



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18020192/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-05-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2977T	Veh. Inspected	SLU 9122U
Policy No.		Coverage (\$)	0.00
Claim No.	D18007968MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	08/11/2018
2. Vehicle Particulars & Condition			
Make & Model	PORSCHE CAYMAN S	c.c	3387
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WPOZZZ98Z8U773697	Colour	GREY
Odometer	113972	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/35 R19	MICHELIN	5 mm
L/H Front Tyre	235/35 R19	MICHELIN	5 mm
R/H Rear Tyre	235/35 R19	MICHELIN	5 mm
L/H Rear Tyre	235/35 R19	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/11/2018	Inspection Date	08/11/2018
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9122U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	7,500.00	2,944.10
2	FRONT BUMPER RETAINER	O/S BROKEN / N/S NOT NECESSARY	250.40	125.20
1	FRONT BUMPER BRACKET	NOT NECESSARY	350.00	-
1	FRONT RH HEADLAMP	MOUNTING BROKEN	3,928.80	3,928.80
1	FRONT RH SIDE MARKER LAMP	SERVICEABLE	1,020.00	-
1	FRONT RH BUMPER COVER	LOWER CRACKED / CUT	560.30	560.30
1	FRONT RH FOG LAMP	MOUNTING CRACKED	730.10	730.10
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	1,260.00	-
1	FRONT RH FENDER INNER SHIELD	SERVICEABLE	415.00	-
1	FRONT RH FOG LAMP COVER (ADDITIONAL)	CUT	312.15	312.15
1	FRONT RH LOWER GRILLE (ADDITIONAL)	MOUNTING CRACKED / DEFORMED	468.50	468.50
	LESS 10% DISCOUNT		-1,679.53	-906.92
			15,115.72	8,162.23
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	120.00	30.00
1	FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	70.00	-
			190.00	30.00
LABOUR				
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	CHECK FRONT WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	DIAGNOIS CHECK AND CLEAR FAULT CODE.	NOT NECESSARY	500.00	-
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		800.00	700.00
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	600.00
			2,310.00	1,330.00



GRAND TOTAL		17,615.72	9,522.23
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,600.00

Report Ref No. CS/FC118020192/Dqd3n2

MARKET VALUE: \$80,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$55,819.00=NETT VALUE: \$24,181.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.