

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

6841 2132
OIC = Poh Kin LKK Auto

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKS8019P
Chassis No : MRHRU1830FP000119
Model : HRV LX-SIN CVT YM 2015
Owner's Name : NG CHEE KIONG
Ins Policy No. : 18-MW004278-R03
Date of Accident : 6/11/2018

Document No. : SQT18004764 Page 1
Date : 7. Nov 2018
Customer No. : WZA006
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15Z71000122
Date | Time : 7. Nov 2018 2:32:00 PM
Surveyor Name :
Survey Date : DID : +65 6846 5673
HP : +65 8100 6306
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71570) OWNER: NG CHEE KIONG OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 06/11/2018@15.15PM SURVEYED BY: REF NO: CCA/ASM18020196/fb3 TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SJR14Y (TOYOTA/PINIC/BLUE)						
91505-TM8-003	CLIP,BUMPER <i>rec</i>	14	2.30	25	24.15	1.69	25.84
33100-T7S-T51	HEADLIGHT ASSY,R.	1	358.60	25	268.95	18.83	287.78
71101-T7J-H00ZZ	FACEFR.BUMPER <i>Deep cut</i>	1	466.20	25	349.65	24.48	374.13
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	24.60	25	18.45	1.29	19.74
71193-T7A-000	SPACERR.FR.BUMPER SIDE <i>3y</i>	1	10.40	25	7.80	0.55	8.35
60210-T8N-T20ZZ	PANEL COMP,R.FR.FENDER <i>2</i>	1	358.30	25	268.72	18.81	287.53
74107-T7M-H01	PROTECTORR.FR.WHEEL ARCH <i>groze</i>	1	150.60	25	112.95	7.91	120.86
	Sum Item				1050.67	73.56	1,124.23
BOSUN	SUNDRIES <i>rec</i>	1	40.00	20	40.00	2.80	42.80
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	120.00	100	120.00	8.40	128.40
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1120.00	150	1120.00	78.40	1198.40
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1350.00	900	1350.00	94.50	1444.50
	Sum Labor				2630.00	184.10	2,814.10

Survey By Mercus Hal
Date & Time 18/12/18
Excess _____
Status not affect
Signature Wahyudi. Supriatny.
3 dy.

Total Amount 3,680.67 257.66 3,938.33
Total (Inclusive of GST) **3,938.33**

LKK Auto Consultants hereby notify the Repairer that:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: