



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004941
INV Date 15/07/2020
Reference CC4/LPC18020208/Kka3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SJN 3096L
Insured Veh. SMA 446M
Claim No. 18/18/18/VP05/021101
Policy No. Z18VP05019276
Accident Date 04/11/2018
Inspection Date 08/11/2018

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD	Ref : CC4/LPC18020208/Kka3q2
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555	Date : 15-07-2020
	Code : LPC2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 446M	Veh. Inspected	SJN 3096L
Policy No.	Z18VP05019276	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021101	Excess (\$)	0.00
Assign From	GERALD	Assign Date	08/11/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1FAAC11Z0010325	Colour	METALLIC GREY
Odometer	74253	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	FALKEN	5 mm
L/H Front Tyre	185/60 R15	FALKEN	5 mm
R/H Rear Tyre	185/60 R15	FALKEN	4 mm
L/H Rear Tyre	185/60 R15	FALKEN	4 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
--	---

5. General Information

Accident Date	04/11/2018	Inspection Date	08/11/2018
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
--	-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3096L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	457.30	457.30
1	FRONT HEAD LAMP RHS	* CHECK	370.90	-
1	FRONT FOG LAMP COVER RHS	SERVICEABLE	91.00	-
1	FRONT BUMPER SIDE RETAINER RHS	SERVICEABLE	33.00	-
	LESS 10% DISCOUNT		-95.22	-45.73
			856.98	411.57
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIP (SN)	NECESSARY	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEAT THE ACCIDENT AREAS.		500.00	200.00
	TO SPRAY FRONT BUMPER .		250.00	200.00
	RUSH PROOFING.	NOT NECESSARY	120.00	-
	TO ADJUST HEAD LAMP AND CHECK WIRING.		180.00	15.00
	ALIGNMENT FRONT SUPPORT PANEL.	NOT NECESSARY	150.00	-
			1,200.00	415.00
	GRAND TOTAL		2,091.98	861.57
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$333.81 NETT)			861.57

Report Ref No. CC4/LPC18020208/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 3096L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 3096L

RE-INSPECTION

