

DING AUTO PTE LTD

Blk 10, #01-20
 Sin Ming Industrial Est. Sec C
 Singapore 575645
 Tel: 6452 1208
 Fax: 6452 0614

Vehicle: SJN3096L
Model: NISSAN LATIO
Chassis: JN1FAAC11Z0010325

NO	DESCRIPTION	QTY	NETT	DISC	PRICE	SURVEYORS MARKING
1	FRONT BUMPER	1	\$ 457.30	10%	\$ <i>Bu</i> 411.57	✓
2	FRONT HEAD LAMP RHS	1	\$ 370.90	10%	\$ 333.81	?
3	FRONT FOG LAMP COVER RHS	1	\$ 91.00	10%	\$ <i>su</i> 81.90	X
4	FRONT BUMPER SIDE RETAINER RHS	1	\$ 33.00	10%	\$ <i>su</i> 29.70	X
TOTAL:					\$ 856.98	

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	FRONT BUMPER CLIP	1	\$ <i>su</i> 35.00	✓
6		1		
7		1		
8		1		
9		1		
10		1	\$ 35.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	TO STRAIGHTEN AND PANLE BEAT THE ACCIDENT AREAS	\$ 500.00	<i>200</i>
2	TO SPRAY FRONT BUMPER	\$ 250.00	<i>200</i>
3	RUSH PROOFING	\$ <i>su</i> 120.00	X
4	TO ADJUST HEAD LAMP AND CHECK WIRING	\$ 180.00	<i>15h</i>
5	ALIGNMENT FRONT SUPPORT PANEL	\$ <i>su</i> 150.00	X
TOTAL:		\$ 1,200.00	

PARTS	\$ 856.98
LABOUR	\$ 1,200.00
SPECIAL NETT	\$ 35.00
TOTAL	\$ 2,091.98

Not Notified
11 May 8?

2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: