COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHC 3137J

MAKE

DATE 7/11/2018 11:27

China

Qty	Parts Description/ Labour	Type	Unit Price	An	ount
	Rear Fender Mudflap (RH)			\$	15.50
	SUB TOTAL			\$	15.50
	LESS 20%			\$	3.10
	DISCOUNTED TOTAL			\$	12.40
	Rear Bumper Advertisement Logo			\$	50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$	200.00
				\$	250.00
			1.00		
	Labour Charge				200
	Panel Beating-Repair Fender			\$	400.00
	Spray Painting Charge			\$	600.00
	Tuff Kote		h - h : .	\$	50.00
	Remove/Refix Reverse Sensor			\$	80,00
	TOTAL LABOUR			\$ 1	,130.00
	ESTIMATE TOTAL			0 1	202.40
	ESTIMATE TOTAL			\$ 1	,392.40
	1-1-1166		notify.		7
	Kalne ICKKy	LKK Auto	Consultants hence notify		1
	1 7/1/18 1200 hr 2 Pgs	the Repa	el of the reason painting		1
	1/1/1/1200 27	- To display	damageu parmer	y	1
	// 1/1/18 /2	· Parts pri	es are subject a "Without Prejuc	ice" basis	
	2 023	- No illons	modification	nd and	1
	21/	• Supplier	modification(s) is anowed rentary item(s) must be resurvey it to final approval from Insurance	e Compan	y
	L/s				1
	Us Alle Rose plate	Acknowle	dged by Repairer		4000
	Alle Report phit	Signatur Date:	e.		
		Dato			

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1