

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9602Z****AAD1811-027***Not Authored*  
*1/1/2018*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHB 9602Z**  
KL1LA69RJB122741  
CHEVROLET  
EPICA 2.0  
3.11.2018  
**EQ**

|    |   | PART                                    |    | LIST     |
|----|---|-----------------------------------------|----|----------|
| 1  | 1 | Front Fender LH                         | \$ | 837.60   |
| 2  | 1 | Front Fender Liner LH                   | \$ | 47.00    |
| 3  | 1 | Front Fender Inner Wheel House Panel LH | \$ | 1,437.00 |
| 4  | 1 | Front Bumper                            | \$ | 1,202.00 |
| 5  | 1 | Front Bumper Lower Absorber             | \$ | 180.00   |
| 6  | 1 | Front Bumper Reinforcement              | \$ | 356.00   |
| 7  | 1 | Front Bumper Retainer RH                | \$ | 102.00   |
| 8  | 1 | Front Bumper Retainer LH                | \$ | 102.00   |
| 9  | 1 | Front Bumper Lower Grille               | \$ | 78.00    |
| 10 | 1 | Front Bumper Lower Stiffener            | \$ | 134.37   |
| 11 | 1 | Front Bumper Bracket LH                 | \$ | 10.00    |
| 12 | 1 | Front Bumper Bracket RH                 | \$ | 10.00    |
| 13 | 1 | Bumper Fog Lamp Cover RH                | \$ | 32.40    |
| 14 | 1 | Bumper Fog Lamp Cover LH                | \$ | 32.40    |
| 15 | 1 | Front Support Panel Assy                | \$ | 1,222.32 |
| 16 | 1 | Headlamp RH                             | \$ | 816.00   |
| 17 | 1 | Headlamp LH                             | \$ | 816.00   |
| 18 | 1 | Windscreen Washer Tank - Filler Neck    | \$ | 4.80     |
| 19 | 1 | Windscreen Washer Tank                  | \$ | 62.00    |
| 20 | 1 | Windscreen Washer Tank Motor            | \$ | 51.00    |
| 21 | 1 | Washer Tank Hose                        | \$ | 21.00    |
| 22 | 1 | Radiator Assembly                       | \$ | 618.00   |
| 23 | 1 | Radiator upper hose                     | \$ | 30.00    |
| 24 | 1 | Radiator lower hose                     | \$ | 120.00   |
| 25 | 1 | Radiator Grille (Grille A-Rad)          | \$ | 367.00   |
| 26 | 1 | Radiator Grille Top Cover               | \$ | 45.02    |
| 27 | 1 | Fan Blade(A/C)                          | \$ | 536.00   |
| 28 | 1 | Fan Blade(Radiator)                     | \$ | 634.00   |
| 29 | 1 | Aircon Condenser                        | \$ | 600.00   |

X

**Trans-cab Auto Services Pte Ltd**

AAD1811-027

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9602Z

|    |   |                                        |    |             |
|----|---|----------------------------------------|----|-------------|
| 30 | 1 | Aircon hose - condenser to compressor  | \$ | SH 450.00 X |
| 31 | 1 | Aircon hose - compressor to evaporator | \$ | SH 624.00 X |
| 32 | 1 | Aircon hose - condenser to evaporator  | \$ | SH 580.00 X |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>9,836.31</b> |
| <b>10%</b>   | <b>\$</b> | <b>983.63</b>   |
|              | <b>\$</b> | <b>8,852.68</b> |

**Specical Nett**

|   |       |                                    |    |           |     |
|---|-------|------------------------------------|----|-----------|-----|
| 1 | 1 Set | Front Bumper Fastener Clip         | \$ | nn 24.00  | } X |
| 2 | 2     | Front Windscreen Sealant           | \$ | nn 100.00 |     |
| 3 | 1     | Front Windscreen Inner Sponge Seal | \$ | nn 100.00 |     |
| 4 | 1 Set | Radiator Grille Top Cover Clip     | \$ | nn 10.00  |     |
| 5 | 1 Set | Front licence plate with holder    | \$ | SH 192.00 |     |
| 6 | 1 Set | Radiator Grille clip               | \$ | nn 35.00  |     |
| 7 | 1 Set | Front Fender Liner clip RH         | \$ | nn 30.00  |     |
| 8 | 1 Set | Louver Cowl Top clip               | \$ | nn 30.00  |     |
| 9 | 2     | Bonnet stopper                     | \$ | SH 15.00  |     |

**TOTAL \$ 536.00****TOTAL PARTS \$ 9,388.68****LABOUR**

|                                                                                                                           |    |               |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------|
| To Check Electrical Lighting Concerned.                                                                                   | \$ | nn 170.00 X   |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | nn 3,000.00 X |
| Putty and spray painting of the affected portion.                                                                         | \$ | 3,000.00 200/ |
| To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.                                          | \$ | nn 440.00 X   |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                           | \$ | nn 380.00 X   |

**Trans-cab Auto Services Pte Ltd****AAD1811-027**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9602Z**

|                                                                                                 |    |             |
|-------------------------------------------------------------------------------------------------|----|-------------|
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | nn 380.00 X |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing.   | \$ | nn 380.00 X |
| To check steering geometry and computer wheel alignment                                         | \$ | nn 220.00 X |
| To transfer of tire, rim and on wheel balancing.                                                | \$ | nn 170.00 X |
| To replace, refix and top up coolant for radiator                                               | \$ | nn 170.00 X |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.                    | \$ | nn 380.00 X |
| To rust-proofing of the affected areas.                                                         | \$ | nn 170.00 X |
| To transfer of end panel fittings and conduct water seepage test.                               | \$ | nn 170.00 X |
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                          | \$ | nn 170.00 X |
| To transfer of boot fittings and conduct water seepage test.                                    | \$ | nn 170.00 X |
| To reinstall rear bumper parking sensor.                                                        | \$ | nn 170.00 X |

**TOTAL \$ 9,540.00****Over All Total \$ 18,928.68**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**(LUMP SUM) Repair Days****10-DAYS***1 day*