

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA7719P

DATE: 7. Nov. 2018

MAKE : HYUNDAI

MODEL : i40

DOA: 7. Nov. 2018

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	Rear Bumper ✓			\$553.00	
10	Rear Bumper Clips ✓		\$2.20	\$22.00	
1	Rear Bumper Sponge ?			\$103.50	
1	Rear Bumper Undercover ✓			\$228.00	
SUB TOTAL				\$906.50	
LESS 20%				\$181.30	
DISCOUNTED TOTAL				\$725.20	
1	Advertisement – Rear Bumper ✓			\$50.00	Nett
2	Advertisement – Rear Fenders RH/LH ✓		\$100.00	\$200.00	Nett
1	Rear Bumper Rubber Mat (mod type) ✓			\$50.00	Nett
				\$300.00	
Labour Charge					
Panel Beating				200 \$250.00	
Spray Painting Charge				200 \$250.00	
Remove/refix reverse sensor				70 \$100.00	
TOTAL LABOUR				\$600.00	
ESTIMATE TOTAL				\$1,625.20	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Larry Ng

Kalvin 16/11/18
7/11/18 12.20
2 Rys
45
After Repair