



# UCB Engineering Pte Ltd

GST Registration Number: 19-9501338-G

Business Reg. No. 199501338G

Our ref: PA6860A.Sky  
Your ref :

07 November 2018

Sky Island Transport & Trading Pte Ltd  
Blk 535 Bukit Panjang Ring Road  
#11-817  
Singapore 670535

QUOTATION  
without Prejudice

Dear Sir,

## COST OF REPAIR FOR PA 6860 A

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>PRICE</u> S\$
1 pc	LHS body – below structure with aluminium panel - <i>Buy ✓</i>	950.00
1 pc	Luggage compartment door panel - <i>repair</i>	850.00
1 pc	Sealant	35.00
	Labour charges for remove & replace the above damaged parts, checking alignment	<del>1,600.00</del> <i>600</i>
	To putty & spray painting onto affected areas	<del>1,100.00</del> <i>500</i>
	Logo artwork	<del>500.00</del> <i>300</i>
	<b>TOTAL</b>	<b>5,035.00</b>

(SGD: Five Thousand And Thirty-Five Only)

Price quoted above is subjected to 7% GST

Yours faithfully,  
Tan Tiong Chia

*Resale*  
*HP 90010068*  
*4 days*  
*4/3*  
*13/11/18 @ 1650*  
*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: