

ASS. REC. BY:

REF: 06/EN18020222/Kldm24 Special Instruction:

Surveyor: Kalvin

ASSIGNMENT (Office) ✓

From (Person): Yee Pei Li

of

ECRDate/Time: 08-11-2018 256pm

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SHC 6464U

Insured: _____

GBF 7120K

at Workshop m/s _____

Premier

Tel: _____

6544 6682

of _____

23 Chungi South Ave 2 # 03-02

Policy No: _____

Claim No: _____

GBF 7120K / RH/pl

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 08112018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 08-11-2018 304pm

Person Contacted: _____

GohVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6464 U - (C3 / CTL17000499 / F11h03 n2)DLA: 070117GBF 7120K - x09/11/18 @ 3.17pm revised to Polaris by email.

08/11/18

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

4 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6464^UYr Regn: 16 Mar 2015Type: M. Car / M. Cycle / Bus / Van / Lorry / T₀ / Prime Mover /

Truck / Trailer or

Make: KIA optimac.c. 1885Colour: SilverA/C: Ins~~ured~~ / Std / NI / NASp. Reading: 468627T/Radio: Ins~~ured~~ / Std / NI / NA

Eng/No: _____

C/No: KNA 6M414MF558850xGen. Cond: Good / Fair / Poor / BurntSteering: Inord~~er~~ / Jammed / Leaked / Burnt orBrake: Inord~~er~~ / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD Alm orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal. 7

mm

R/Bal. 7

mm

L/Bal. 7

mm

L/Bal. 7

mm

D.O.A. 8/11/18D.O.I. 8/11/18Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/11/18	Librand up \$420 / 4 hrs. (Red 62979.70, 42%) <u>SGT</u>
	<u>4s.</u>
	RECEIVED 26 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 9/11/18☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: TPLump Sum / I.B.I. (\$) 420

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBF 7120K/RH/pl

Date: 09th November 2018

Our Ref: CS/EG118020222/K1qb

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6464U


We thank you for the instruction on 08/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2018 at the premises of M/s PREMIER AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,179.70</u>
Revised Estimate Amount	: S\$ <u>4,680.50</u>
"Check" Items Amount	: S\$ <u>1,033.20</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

Kalvin Ang
Automotive Assessor

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 8 November, 2018 2:56 PM
To: 'admin-d@lkkauto.com'
Cc: SUR (sur@lkkauto.com)
Subject: OI : GBF7120K / TP : SHC6464C/LKK / DOA : 08/11/2018
Attachments: SHC6464C - SAS.pdf; SHC6464C - PRS FORM.pdf; Pre-inspection SHC6464C & GBF7120K on 08.11.18 (1.38 MB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PREMIER AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : 23 CHANGI SOUTH AVE 2
#03-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 9 November 2018 3:17 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; Rohaini Bte Hussain
Cc: SUR; assignments
Subject: RE: GBF7120K / TP : SHC6464C/LKK / DOA : 08/11/2018
Attachments: CSEGI18020222K1qb.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SHC 6464U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 8 November 2018 3:09 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: GBF7120K / TP : SHC6464C/LKK / DOA : 08/11/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 8 November, 2018 2:56 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>
Subject: OI : GBF7120K / TP : SHC6464C/LKK / DOA : 08/11/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PREMIER AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : 23 CHANGI SOUTH AVE 2
#03-02
SINGAPORE 486443

ERGO

Date: 08.11.2018
Our Reference: GBF 7120K/RH/pl
Your Reference: SHC 6464C

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /
incent.chua@premiertaxi.com

To: **PREMIER AUTOMOTIVE SERVICES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHC 6464C
Insured's Vehicle: GBF 7120K
Date Of Accident: 08.11.2018


We acknowledge receipt of your request for PRS on: 08.11.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us to date.
- ☒ Others: OFFICIER-IN-CHARGE - ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	16 Mar 2015 / 09:07:04	Receipt No.:	AACCK001-AX239-150316-000002
Asset Type:	Vehicle	Transaction Amount:	\$65,391.00
Asset ID:	SHC6464U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150316090704695850		

Vehicle No.:	SHC6464U
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	16 Mar 2015
Original Registration Date:	16 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588504
Engine No.:	D4FDEH313613
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,185.00
Minimum PARF Benefit:	\$8,495.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	16 Mar 2015 09:07:04
COE No.:	2015031601002241W
COE Expiry Date:	15 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	15 Mar 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6464 C

1 pc	Boot lid <i>Paint</i>	\$	1,119.00
1 pc	Boot lid lock <i>Paint</i>	\$	99.00
1 pc	Bootlid striker <i>X</i>	\$	21.00
1 pc	Bootlid emblem <i>new</i>	\$	27.00
1 pc	Bootlid CRDi <i>new</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X</i>	\$	96.00
1 pc	Boot lid lower garnish <i>X repair</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 <i>Paint</i>	\$	132.00
1 pc	End panel <i>X repair</i>	\$	250.00
1 pc	End panel garnish <i>X</i>	\$	74.00
1 pc	Rear n/s tail lamp <i>new</i>	\$	421.00
1 pc	Bootlid n/s reflector <i>new</i>	\$	350.00
1 pc	Rear bumper <i>Paint</i>	\$	696.00
1 pc	Rear bumper lower cover <i>new</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>new</i>	\$	58.00 <i>29</i>
1 pc	Rear bumper inner sponge <i>X</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>new</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$	36.00
1 pc	Rear bumper reflector n/s <i>new</i>	\$	46.00
		\$	4,813.00
Less 10%		\$	481.30
		\$	4,331.70

S/NETT

1 set	Rear bumper clips <i>new</i>	\$	48.00
1 set	End panel inner garnish clips <i>X</i>	\$	30.00
1 set	Bootlid lower garnish clips <i>X</i>	\$	60.00
1 set	Bootlid stickers <i>new</i>	\$	100.00
1 set	Reverse sensor <i>shaded</i>	\$	280.00 200
1 pc	Rear bumper top protector <i>new</i>	\$	80.00 50

8-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6464 C

Sundry	\$ 50.00 20
Towing Fee	\$ 50.00 x 1,
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 900.00 600
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel <i>Rear LH Fender</i>	\$ 800.00 720
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 50
	<u>\$ 7,179.70</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kalin (Kia)
8/11/18 1610 hr
1+3 Dps.*

*45
After Repair photo*






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18020222/K1qbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 03-12-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 7120K	Veh. Inspected	SHC 6464U	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBF7120K/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	08/11/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5588504	Colour	SILVER	
Odometer	468627	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MAXXIS	7 mm	
L/H Front Tyre	205/60 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/11/2018	Inspection Date	08/11/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6464U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	BENT	99.00	99.00
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGES @\$66.00	BENT	132.00	132.00
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	SERVICEABLE	74.00	-
1	REAR N/S TAILLAMP	CRACKED	421.00	421.00
1	BOOTLID N/S REFLECTOR	CRACKED	350.00	350.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @\$53.00	SERVICEABLE	106.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
1	REAR BUMPER REFLECTOR N/S	CRACKED	46.00	46.00
	LESS 10% DISCOUNT		-481.30	-376.10
			4,331.70	3,384.90
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/EGI18020222/K1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			648.00	418.00
	LABOUR			
	TOWING FEE.	NOT NECESSARY	50.00	-
	TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL.		900.00	600.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, REAR LH FENDER.		800.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			2,200.00	1,450.00
	GRAND TOTAL		7,179.70	5,252.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS/EG18020222/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.