

# FACSIMILE MESSAGE

DATE \_\_\_\_\_ TIME \_\_\_\_\_

TO LKK FAX NO \_\_\_\_\_

ATTN Mr Taufikh NO OF PAGES \_\_\_\_\_  
(INCLUSIVE OF THIS PAGE)

CC \_\_\_\_\_

ATTN \_\_\_\_\_ FAX NO. \_\_\_\_\_

FROM Kevin Leong FAX NO. \_\_\_\_\_

TEL NO. 91165600

If this fax is not received in order, please do call us. Thank you.

Dear Sirs,

Supplementary repair for BMW

BMW 116d

Vehicle Registration No.

SKB2132Z

Vehicle Chassis No.

V725533

Supplementary Parts to be replaced :	Qty	Price (Net)
LH WISHBONE	1	\$ 268.75
LH TENSION STRYT W/HYDRAULIC MOUNT	1	\$ 268.75
SPHERICAL COLLAR SCREW M12X1.25X45	5	\$ 38.50
WHEEL HUB WITH BEARING FRT	1	\$ 465.75
FRT LH CARRIER	1	\$ 461.15
HEX BOLT WITH WASHER M8X30	5	\$ 27.00
FRT GUIDE SUPPORT	1	\$ 237.80
FRT SPRING STRUT	1	\$ 496.65
LH TIE ROD	1	\$ 289.40
EXCH STEERING BOX ELECTR (ZF)	1	\$ 3,630.45
COMBINATION NUT M14X1.5	4	\$ 22.20
HEX NUT WITH FLANGE	1	\$ 2.35
ALLOY RIM 7.5JX17 STAR SPOKE 379	1	\$ 899.25
RIVET	4	\$ 1.80
Total :		\$ 7,109.80

br -  
br -  
rec -  
br -  
br -  
dec -  
br -  
br -  
br -  
br -  
br -  
rec -  
rec -  
MX  
rec -

<b>Supplementary Labour :</b>		
To remove and install front suspension for inspection and replace damaged parts.	1	\$ 1,128.00 ✓
To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.	1	\$ 752.00 ✓
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	1	\$ 451.00 ✓
Total :		\$ 2,331.00
Grand Total :		\$ <u>9,440.80</u>