

FASTECT AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

not Authorized
 when
 9/17 \$2881.94
 3 days
 8/11/18

VEHICLE NO: SLT 1206U

QTY	PARTICULAR (NETT ITEM)			
1 PCS	BOOTLID		n	\$688.20 x
1 PCS	BOOTLID REAR LOGO		11	\$64.50 x
1 PCS	BOOTLID 'SYLPHY' EMBLEM		11	\$82.80 x
1 PCS	BOOTLID REFLECTOR O/S	299.20	scr	\$385.20 /
1 PCS	BOOTLID WEATHERSTRIP		11	\$211.30 x
1 PCS	TAILLAMP O/S	388.10	scr	\$425.30 /
1 PCS	REAR BUMPER	107	scr	\$685.30 /
1 PCS	REAR BUMPER REFLECTOR O/S	65.00	102	\$121.00 /
1 PCS	REAR BUMPER SIDE HOLDER O/S	30.90	320	\$95.50 /
1 SET	REAR BUMPER CLIPS		scr	\$30.00 /
1 PCS	REAR BUMPER INNER SPONGE O/S	126.40	scr	\$195.00 /
1 PCS	REAR END PANEL		n	\$622.20 x
1 PCS	REAR FENDER O/S		n	\$866.30 x
1 SET	REAR REVERSE SENSOR		sltd	\$250.00 2005.N
				\$4,722.60
LABOUR CHARGES:				
	TO CHECK WIRING			\$50.00 20
	TO DISMANTLE & REFIX REVERSE SENSOR			\$80.00 50
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY			\$120.00 60
	TO SPRAY RUSF PROOFING		11	\$80.00 x
	TO DISMANTLE REFIX BOOTLID MECHANISM		11	\$80.00 x
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$800.00 450
	TO PUTTY & SPRAY PAINTING			\$1,500.00 800
			TOTAL	\$7,432.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-1446-60
 102
 1301.94
 S.N + 200.00
 labour + 1380.00
 2881.94