


REF:

MS16 / 003 / MSC18020228 / Uvb n2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: BNF 5587
 at Workshop m/s: ll.
 of _____
 Insured: Ym 6968D
 Policy No: 29090793MKF
 Claims No: 574963
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: BNF 5587 Yr Regn: Y15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: Perodua ALZA C.C. 1495
 Colour: Red A/C: Insured / Std / Nil / NA
 Sp. Reading: 95768 T/Radio: Insured / Std / Nil / NA
 Eng/No: G20B96E
 C/No: PM2M502400240118
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R15
 R: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: RM40k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Handool.
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 11.18 D.O.I. Shulis
 Survey held at _____
 Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & R.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/1/18 Email police report to Nyuk Aui
 29/1/18 45 \$ 13,000 confirm with Alan (Red 29,536, 696)
 31/12/18 Send preli revised via merimen

[Signature]
 31/12/2018

RECEIVED 02 JAN 2019

Date/Time. File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 10
 Resurvey No. of Trip: 2

1) _____
 2) 2/1 - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:
 Transportation: _____
 Photos _____
 Others _____

250
10
TOTAL
260

Report Format : merimen
 Lump Sum / I.B.I: (\$) 13,000/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 31 Dec 2018

Preliminary Advice

Insured Vehicle No	: YM6968D	Accident Date	: 01/11/2018
TP Vehicle No	: BNF5587	Assignment Date	: 31/12/2018
Make	: ADIVA AD1 200	Est. Duration of Repair	: 10.00
Date of Inspection	: 08/11/2018		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,536.00
Revised Amount	:S\$	13,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Dec 2018		31 Dec 2018 12:27 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N	
Main Claimant:	SITI AISHAH BINTI ABDUL KARIM, ID: G1372146M	
Vehicle Reg. No.:	BNF5587	Date of Loss: 01/11/2018 15:00 - :59
Claim Type:	TP / 574963	Policy/Cover Note No.: 29090793MKF (Third Party Only) Coverage: 01/09/2018 - 31/08/2019
Vehicle Reg. No. (Insured):	YM6968D	Policy No. (Claimant):
		Excess:
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 01/01/2019]	
Driver/Custodian (Insured):	ABDUL PATAR BIN YADI (), NRIC: S16767711, Tel: +6591991532	
Adj Asg. Remarks:	DIRECT SURVEY BY LKK. SURVEY DONE ON 8/11/2018	

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Low Yi Qian <yiqian_low@sg.msig-asia.com>
Sent: Monday, 31 December 2018 12:30 PM
To: Veron Chen (LKKAuto)
Cc: Elaine Ngu; Nabilah Rasol
Subject: RE: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/11/2018,BNF 5587 (TP VEHICLE), YM 6968D (OI VEHICLE) - Claim ref: 574963

Dear Veron

Merimen created. Claim ref: 574963

For your necessary action.

Thank you and have a great day ahead!

Best Regards
Low Yi Qian
Administrative Officer
Claims Services Department
Direct line +65 6594 2525 | Direct fax +65 6225 7402 | yiqian_low@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://www.facebook.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, 31 December, 2018 10:27 AM
To: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/11/2018,BNF 5587 (TP VEHICLE), YM 6968D (OI VEHICLE)

Dear Nyuk Pui,

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Friday, 9 November 2018 2:44 PM

To: 'Chhia Nyuk Pui' <NyukPui_Chhia@sg.msig-asia.com>

Cc: SUR <sur@lkkauto.com>; Accounts (LKKAuto) <account@lkkauto.com>; KKLau <kklau@lkkauto.com>

Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 1/11/2018, BNF 5587 (TP VEHICLE), YM 6968D (OI VEHICLE)

Dear Nyuk Pui,

Please be informed that we had inspected the vehicle BNF 5587 at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 8/11/2018

Enclosed herewith a copy of police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 9 November 2018 2:44 PM
To: 'Chhia Nyuk Pui'
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA:
1/11/2018,BNF 5587 (TP VEHICLE), YM 6968D (OI VEHICLE)
Attachments: POLICE REPORT.pdf

Dear Nyuk Pui,

Please be informed that we had inspected the vehicle BNF 5587 at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 8/11/2018

Enclosed herewith a copy of police report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN: **BNF5587**

No. Siri B **8293556**
eapVAdZS

870603105622
[MAL]

Nama Pemunya Berdaftar : **SITI AISHAH BINTI ABDUL KARIM**

Alamat : **NO 173 BATU 29 KAMPUNG JENDERAM ULU
43800 DENGKIL SELANGOR**

No. Enjin	: 020090E	B.D.M/B.G.K	: -
No. Casis	: PH2M502G002240118	B.T.T.	: -
Buatan	: PERODUA	Berat Kerb	: -
Nama Model	: ALZA - 1500 SE (AUTO)	B.T.M.	: -
Keupayaan Enjin	: 1495	B.G.1	: -
Bahan Bakar	: PETROL	B.G.2	: -
Warna	: MERAH	B.G.3	: -
Kelas Kegunaan	: PERSENDIRIAN-MOTOKAR INDIVIDU	B.G.4	: -
Jenis Badan	: MOTOKAR PELBAGAI UTILITI	B.G.5	: -
Tahun Dibuat	: 2015	B.G.6	: -
tarikh Pendaftaran	: 27/04/2015	B.G.7	: -
Status Pemunya	: PERSENDIRIAN	B.G.8	: -
Muatan Tempet		B.G.9	: -
Duduk	: 7	B.G.10	: -
Kadar Lesen		B.G.11	: -
Kenderaan Motor	: 6 bulan 12 bulan	B.G.12	: -
	: 45.00 90.00		

CERTIFIED TRUE COPY

Federal Customs Collection Station
Royal Malaysian Customs

Perakuan Pendaftaran ini dikeluarkan
oleh Pengerah JPJ Negeri JPJ BANGSA MAJU

Tandatangan Pemunya Berdaftar

UNTUK KEGUNAAN PEJABAT

1. PEMASANGAN TEMPATAN

2. HAK MILIK DITUNTUT OLEH : AMBANK (M) BERHAD NO SIRI : 020180201503

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikahendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butiran-butiran kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikahendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini ke pembeli. Anda dan pembeli dikahendaki mengisytiharkan dan mengesahkan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari tidak penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas urusan berkaitan dengan kenderaan sehingga pertukaran milikan disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini ke Pengerah JPJ dalam tempoh tujuh hari dari tarikh pelaksanaan.

Home / Used Cars / Perodua / Alza / Advance

Updated on: November 08, 2018

RM 543/month
RM 41,900

Perodua Alza 1.5 Advance MPV

Updated on: November 08, 2018

 Dealer  Selangor » Cheras »



Seller Information

 Dealer

 Selangor » Cheras

Key details

	Car type	Used Car
	Make	Perodua
	Model	Alza
	Variant	Advance
	Year	2015
	Engine Capacity	1495 cc
	Transmission	Automatic
	Seat Capacity	7
	Mileage	35 - 40K
	Colour	Silver

Seller's comments

Say Carlist.my for the best deal

!!!SALAM HORMAT & SEJAHTERA!!!

WELCOME TEST & VIEW OUR CAR !!!
PROMOSI MEGA SALES BULAN INI !!!
ALZA ADV PERFECT CONDITION DALAM MARKET !!!

~WE FREE 1 YEAR WARRANTY

Selling Price : Rm 41 ,900 only.

ALZA ADV FULL SPEC (A) PREMIUM
~ LUXURY & ECONOMIC PRACTICAL MPV.

Home / Used Cars / Perodua / Alza / SE

Updated on: November 08, 2018

RM 545/month
RM 42,000

2015 Perodua Alza 1.5 SE MPV

Updated on: November 08, 2018

Private Selangor » Shah Alam »



Seller Information

Private

Selangor » Shah Alam

Key details

	Car type	Used Car
	Make	Perodua
	Model	Alza
	Variant	SE
	Year	2015
	Engine Capacity	1495 cc
	Transmission	Automatic
	Seat Capacity	7
	Mileage	40 - 45K
	Colour	White

Seller's comments

Say Carlist.my for the best deal

- 1 Careful Lady Owner- Use car for work
- 100 % Like New Car
- 100% Original Paint
- 100% Accident Free
- Nice Plat Number
- Nice & Clean Interior
- 15" Sport Rim
- DVD+ Roof Monitor/CD/Radio Player
- Reverse/Front HD Camera
- Front & Rear Dash Camera
- ATTENTION: ONLY FOR SERIOUS BUYER



Head Office: SYARIKAT TAKAFUL MALAYSIA BERHAD (131040-K)
26th Floor, Annex Block, Menara Takaful Malaysia,
No. 4, Jalan Sultan Sulaiman, 50000 Kuala Lumpur, Malaysia
P.O. Box 11483, 50746 Kuala Lumpur

takaful-malaysia.com.my
1-300 8 TAKAFUL (825 2385)
F 603.2274 0237
E csa@takaful-malaysia.com.my



NO KOD KOMPUTER JPJ: 92
COVER NOTE
NO: **TMCA0818726**
JPJ STATUS: **ACCEPTED**
ISM STATUS: **000**
ISM ABI INDICATOR: Y

**BORANG PENGESAHAN SKIM TAKAFUL KENDERAAN BERINJIN
MOTOR TAKAFUL SCHEME CONFIRMATION SLIP**

PERATURAN CBC - Seksyen 25 Akta Takaful 1984:
Perlindungan Takaful tidak akan diberikan sehingga Sumbangan Takaful dijelaskan mengikut peraturan-peraturan yang dikeluarkan di bawah Seksyen ini. Sesiapa yang gagal mematuhi peraturan ini adalah melakukan suatu kesalahan dan jika bersabit kesalahan boleh didenda tidak lebih daripada RM5,000. Bayaran boleh dibuat menggunakan wang tunai, cek, kiriman atau wang pos, draf bank atau arahan bayaran kepada syarikat dan dipalangkan 'Akaun Pembayar Sahaja'.

CBC REGULATION - Section 25 of the Takaful Act 1984:
No cover can be granted until the Takaful contribution has been paid in accordance with the Regulations issued under the Section. Any person who fails to comply with this Section shall be guilty of an offence and shall on conviction be liable to a fine not exceeding RM5,000. All Takaful contribution may be paid by cash, cheque, money or postal order, bankers draft or cashiers order made payable to the company and crossed 'Account Payee Only'.

NAME / NAME : SITI AISHAH BINTI ABDUL
KARIM

ALAMAT / ADDRESS : NO 173 BATU 28 KAMPUNG
JENDERAM ULU
43800 DENGKIL SELANGOR

NO. KP / NO 870603-10-5522
DAFTAR
PERNIAGAAN / :
NRIC /
BUSINESS REG.
NO.

PEKERJAAN / OTHERS
PERNIAGAAN / :
OCCUPATION /
BUSINESS

TARIKH LAHIR / 03-06-1987
DATE OF BIRTH :

NO. TEL. / TEL.
NO. :

RUMAH
HOUSE

PEJABAT
OFFICE

TELEFON BIMBIT 0193561694
HANDPHONE

BAHAWASANYA Peserta yang namanya tercatat di atas telah bercadang untuk menyertai Skim Takaful Kendaraan Berinjin dan telah membayar Sumbangan Takaful sebanyak yang dinyatakan bagi kenderaan tersebut adalah dengan ini dipertanggungjawabkan mengikut syarat-syarat Sijil Takaful Kendaraan Berinjin bagi tempoh takaful seperti yang dinyatakan di bawah.
WHEREAS the Participant having proposed for the Motor Takaful Certificate cover, particulars all of which are stated in the Schedule below for the period stated herein.

JADUAL / SCHEDULE

*Akta Pengangkutan Jalanraya 1987 (Malaysia) Peraturan-peraturan Kendaraan Berinjin (Risiko ke atas Pihak Ketiga) 1950 (Malaysia), Peraturan-peraturan Kendaraan Berinjin (Risiko ke atas Pihak Ketiga dan Pampasan) Ordinan 1960 (No. 1 1960) (Republik Singapura), Peraturan-peraturan Kendaraan Berinjin (Risiko ke atas Pihak Ketiga dan Pampasan) 1960 (Republik Singapura), Insuran Kendaraan Berinjin (Risiko ke atas Pihak Ketiga) Enakmen 1950 (Brunei)
Road Transport Act, 1987 (Malaysia) The Motor Vehicles (Third Party Risks and Compensation) Rules 1950 (Malaysia), The Motor Vehicles (Third Party Risks And Compensation) Ordinance 1960 (No. 1 of 1960) (Republic of Singapore), The Motor Vehicles (Third Party Risks And Compensation) Rules 1960 (Republic of Singapore), The Motor Vehicles Insurance (Third Party Risks) Enactment 1950 (Brunei)

BUATAN / MODEL MAKE / MODEL	RUANG DUDUK / SEATING CAPACITY	TAHUN DIPERBUAT / YEAR OF MANUFACTURE	KEUPAYAAN PADU / CUBIC CAPACITY (CC)	NO. PENDAFTARAN / REGISTRATION NO.	NO. KAD PENDAFTARAN / VEHICLE REG. CARD NO.
PERODUA - PERODUA ALZA 1.5	7	2015	1495 CC	BNF5587	NIL
JANTINA / GENDER KORPORAT / CORPORATE	HAD PENGGUNAAN / LIMITATION AS TO USE	JENIS PERLINDUNGAN / TYPE OF COVER	NCD%	EKSES, RM / EXCESS, RM	NILAI PERLINDUNGAN / SUM COVERED
FEMALE	PRIVATE CAR PRIVATE USE (DRIVE TO WORK OR DAILY USE)	COMPREHENSIVE	38.33	0.00	RM 38000.00
LOKASI GARAJ / LOCATION OF GARAGE	Parking Lot - Covered			AKSES KECURIAN KENDERAAN RM/ EXCESS THEFT OF VEHICLE RM	
NO. CASIS / CHASSIS NO.	PM2M502G002240118			RM 0.00	
NO. ENJIN / ENGINE NO.	G20B96E				
PEGANGAN KEWANGAN / HP OWNERSHIP	NIL				
NAMA PEMANDU / NAMED DRIVERS	1) SITI AISHAH BINTI ABDUL KARIM 2) MAZLINA BINTI ABDUL KARIM			RM 800.00	
PERLINDUNGAN TAMBAHAN / OTHER BENEFITS	BREAKAGE OF GLASS IN W/SCREEN PASSENGER LIABILITY COVER NAMED DRIVERS				
TEMPOH TAKAFUL / PERIOD OF TAKAFUL	DARI / FROM	27/04/2018	PAGI/PETANG PADA / AM/PM ON	12:01 AM	HINGGA TENGAHMALAM / TO MIDNIGHT OF
					26/04/2019

Saya/Kami dengan ini mengesahkan bahawa Nota Perlindungan Takaful ini dikeluarkan mengikut peruntukan-peruntukan yang terkandung dalam Bahagian IV Akta Pengangkutan Jalanraya, 1987 (Malaysia) dan Kendaraan Berinjin (Risiko ke atas Pihak Ketiga dan Pampasan) Ordinan 1960 (Republik Singapura), Insuran Kendaraan Berinjin (Risiko ke atas Pihak Ketiga) Enakmen 1950 (Brunei).

SUMBANGAN : 955.42



SCHEDULE / JADUAL

MX1

CLASS OF CERTIFICATE JENIS SIJIL	: PRIVATE CAR	COVER TYPE JENIS PERLINDUNGAN	: MOTOR-COMPREHENSIVE
CERTIFICATE NO. NOMBOR SIJIL	: VPP-V1283754-03-AGT-18	AGENCY CODE KOD AGENSI	: 10-204-GCA03602
PARTICIPANT NAME NAMA PESERTA	: SITI AISHAH BINTI ABDUL KARIM	NRIC	: 870603-10-5522
ADDRESS ALAMAT	: NO 173 BATU 28 KAMPUNG JENDERAM ULU 43800 SELANGOR	COMPANY REG. NO. NO. PENDAFTARAN SYARIKAT	:
REPLACING CERT.NO. NOMBOR SIJIL ASAL	: TMCA0818726	REFERENCE NO. NOMBOR RUJUKAN	: gca03602
BUSINESS / OCCUPATION PERNIAGAAN / KEGUNAAN	: OTHERS		

ISSUED & SIGNED AT
DIKELUARKAN DAN
DITANDATANGANI DI

PERIOD OF TAKAFUL
TEMPOH PERLINDUNGAN

(BOTH DATE INCLUSIVE)
(TERMASUK KEDUA-DUA TARIKH)

DATE OF SIGNATURE OF
PROPOSAL & DECLARATION
FORM
TARIKH TANDATANGAN BORANG
CADANGAN & AKUAN
15/04/2018

a.) FROM
MULA

: 27/04/2018

TO
TAMAT

: 26/04/2019

b.) ANY SUBSEQUENT PERIOD FOR WHICH THE PARTICIPANT SHALL PAY AND THE COMPANY SHALL AGREE TO ACCEPT A RENEWAL CONTRIBUTION
MANA-MANA TEMPOH SELANJUTNYA DI MANA PESERTA MEMBAYAR DAN SYARIKAT BERSETUJU MENERIMA SUMBANGAN PEMBAHARUAN

DETAILS OF VEHICLE BUTIR KENDERAAN		THE CERTIFICATE'S CONTRIBUTION (RM) SUMBANGAN SIJIL (RM)		
REGISTRATION NO. NO. PENDAFTARAN	BNF5587	BASIC CONTRIBUTION SUMBANGAN ASAS		1,267.50
MAKE & MODEL BUATAN & MODEL	PERODUA ALZA 1.5			
CUBIC CAPACITY KEUPAYAAN PADU	1,495			
TONNAGE / KG TON / KG				
SEATING CAPACITY INCLUDING 7 DRIVER RUANG DUDUK TERMASUK PEMANDU				
YEAR OF MANUFACTURE TAHUN DI BUAT	2015	NCD ENTITLEMENT KELAYAKAN NCD	38.33 %	485.83
ENGINE NO. NO. ENJIN	G20B96E	ADDITIONAL COVERAGE PERLINDUNGAN TAMBAHAN		
CHASSIS NO. NO. CASIS	PM2M502G002240118	BREAKAGE OF GLASS IN W/SCREEN LEGAL LIABILITY TO PASSENGERS	800.00	120.00 53.75
SUM COVERED JUMLAH PERLINDUNGAN	RM 38,000			
EXCESS / AKSES	RM 0.00	SUB TOTAL / JUMLAH KECIL		955.42
USE OF VEHICLE KEGUNAAN KENDERAAN	PRIVATE CAR-PRIVATE USE	REBATE / REBAT		0.00
		GST / CUKAI BARANG dan PERKHIDMATAN	6.00%	57.33
		STAMP DUTY / DUTI SETEM		10.00
REPLACING COVER NOTE NO. NO. PENGGANTIAN / PEMBATALAN NOTA LINDUNG		TOTAL AMOUNT PAYABLE / JUMLAH PEMBAYARAN		1,022.75
PREVIOUS CERTIFICATE NO. NO. SIJIL TERDAHULU		ACT CONTRIBUTION SUMBANGAN AKTA		74.93



HIRE PURCHASE/LEASING COMPANY/EMPLOYER
SEWA BELI/SYARIKAT MENYEWA/MAJIKAN

NAMED DRIVERS
PEMANDU YANG DINAMAKAN

: SITI AISHAH BINTI ABDUL KARIM
MAZLINA BINTI ABDUL KARIM

SUBJECT TO FOLLOWING OPERATIVE ENDORSEMENTS ATTACHED
TERTAKLUK KEPADA ENDOSMEN-ENDOSMEN BERIKUT YANG DISERTAKAN

: C089, C100, C113

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE AND LIMITATIONS AS TO USE AS SPECIFIED IN THE CERTIFICATE OF TAKAFUL
ISSUED IN RELATION TO THIS SCHEDULE.
MANA-MANA ORANG YANG DIBENARKAN MEMANDU DAN HAD ATAS KEGUNAAN ADALAH TERMAKTUB DALAM SIJIL TAKAFUL YANG
DIKELUARKAN SEHUBUNGAN DENGAN JADUAL INI.

SUBJECT TO THE FOLLOWING WARRANTIES/CLAUSES/ENDORSEMENTS AS PRINTED HEREIN OR ATTACHED HERETO:
TERTAKLUK KEPADA WARANTI/KLAUSA/ENDOSMEN YANG DICETAK ATAU DILAMPIRKAN SEPERTI BERIKUT :

C089 COVER FOR WINDSCREENS, WINDOWS AND SUNROOF

C100 LEGAL LIABILITY TO PASSENGERS

C113 REFERENCE TO MOTOR VEHICLE MARKET VALUATION SYSTEM

IN WITNESS WHEREOF THIS CERTIFICATE HAS BEEN SIGNED ON BEHALF AND WITH THE AUTHORITY OF THE COMPANY.
BAHAWASANYA SIJIL INI TELAH DITANDATANGANI DENGAN KEBENARAN DAN BAGI PIHAK SYARIKAT.

DATE : 15/04/2018

TARIKH

SIGNED AT : IBU PEJABAT CORPORATE SALES

LOKASI

SYARIKAT TAKAFUL MALAYSIA BERHAD (131646-K)

AUTHORISED SIGNATORY
PENANDATANGAN YANG SAH



LESEN MEMANDU
DRIVING LICENCE



MALAYSIA

SITI AISHAH BINTI ABDUL KARIM



Wangsa / Nationality: MALAYSIA
No. Pendaftaran / Identity No: 870603105522

Kelas / Class: B2 D
Tempoh / Validity: 30/05/2017 - 03/06/2020

Kemast / Address: NO 173 BATU 28
KAMPUNG JENDERAM ULU

43800 DENGKIL
SELANGOR



JUJUK

17E4043E


- A. Kenderaan Berang (berat maksimum) 6750 tidak melebihi 450 kg
- A1. Kenderaan Berang (berat (cycle) melebihi 450 kg) tidak melebihi 1000 kg
- B. Kenderaan Berang (berat (cycle) melebihi 450 kg) tidak melebihi 2000 kg
- B1. Kenderaan Berang (berat (cycle) melebihi 450 kg) tidak melebihi 2000 kg
- B2. Kenderaan Berang (berat (cycle) melebihi 450 kg) tidak melebihi 2000 kg
- C. Kenderaan Tiga Roda
- C1. Kenderaan Tiga Roda (berat maksimum) 2000 kg
- C2. Kenderaan Tiga Roda (berat maksimum) 2000 kg
- D. Kenderaan Tiga Roda (berat maksimum) 2000 kg
- D1. Kenderaan Tiga Roda (berat maksimum) 2000 kg
- D2. Kenderaan Tiga Roda (berat maksimum) 2000 kg
- E. Kenderaan Berang (berat maksimum) 450 kg
- E1. Kenderaan Berang (berat maksimum) 450 kg
- E2. Kenderaan Berang (berat maksimum) 450 kg
- F. Kenderaan Berang (berat maksimum) 450 kg
- F1. Kenderaan Berang (berat maksimum) 450 kg
- F2. Kenderaan Berang (berat maksimum) 450 kg
- G. Kenderaan Berang (berat maksimum) 450 kg
- G1. Kenderaan Berang (berat maksimum) 450 kg
- G2. Kenderaan Berang (berat maksimum) 450 kg
- H. Kenderaan Berang (berat maksimum) 450 kg
- H1. Kenderaan Berang (berat maksimum) 450 kg
- H2. Kenderaan Berang (berat maksimum) 450 kg
- I. Kenderaan Berang (berat maksimum) 450 kg
- I1. Kenderaan Berang (berat maksimum) 450 kg
- I2. Kenderaan Berang (berat maksimum) 450 kg
- J. Kenderaan Berang (berat maksimum) 450 kg
- J1. Kenderaan Berang (berat maksimum) 450 kg
- J2. Kenderaan Berang (berat maksimum) 450 kg

209002 PQqEjUe

[Signature]



Ketua Pengarah Pengangkutan Jalan



CERTIFIED TRUE COPY

Federal Customs Collection Station
Royal Malaysian Customs

10

Visa/Visas



G 137246 M

The validity of the above immigration endorsement is extended to 13/12/18
 on the condition that the holder remains a dependent of an employee of Malaysia
 Immigration / Malaysia Federal Customs / MAJLIS Kawaja Tanah Selangor
 and is deployed at the Woodlands Train Checkpoint as such employee.

13/12/17

Date

661

Controller of Immigration

Singapore

* delete where appropriate.

CERTIFIED TRUE COPY
 Federal Customs Collection Station
 Royal Malaysian Customs



Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

Report No. T/20181101/2116

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/11/2018 19:11	Vide Report No.: F/20181101/0163	Station Diary No.: 65
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: SITI AISHAH BINTI ABDUL KARIM		Address: 26A PEPYS ROAD SINGAPORE 118453	
ID Type / ID No.: FIN NO / G1372146M		Contact No.: Home/Office: Mobile: 81424614	
Nationality: MALAYSIAN		Email:	
Sex: Female	Age: 31	Date of Birth: 03/06/1987	Type of Informant: Driver
Race: Malay		Language:	Institution / School Name:
Occupation: MALAYSIAN CUSTOM		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 01/11/2018 15:45	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY TOWARDS WOODLANDS Lamp Post Number: 165F			
Weather: Drizzling	Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BNF5587	Car				Slightly Damaged	0
SJW2797G	Car				Slightly Damaged	0
YM6968D	Lorry				Slightly Damaged	0
YP7950G	Lorry				Slightly Damaged	2



**SINGAPORE
POLICE FORCE**



T/20181101/2116

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

2 of 3

Report No. T/20181101/2116

CONTINUATION OF REPORT

Brief Details.

On 01/11/2018 at 1545hrs, I was driving my personal vehicle (BNF5587) along BKE(Woodlands) near to lamp post 165F. The traffic was heavily congested and it was still raining. I was driving slowly on the second lane and came to a complete stop. Out of the sudden I felt a hard impact from the rear of my vehicle causing me to hit onto the front vehicle. I then went out from my vehicle to make a check and saw YM6968D (last vehicle) had collided onto SJW2797G followed by my vehicle BNF5587 and YP7950G (first vehicle). No one was injured during the accident. Traffic police came to assist me and directed me to lodge a police report ref to incident F/20181101/0163 under TP IO Dylan (DID: 6547 6251).



**SINGAPORE
POLICE FORCE**



T/20181101/2116

3 of 3

Report No. T/20181101/2116

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J / Sgt 1 MUHAMMAD SHARIN BIN ROSLI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/11/2018 19:11
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARSITA BINTE BOHARI Contact No.: 65476219	Classification Of Case: <div style="text-align: right;">SN 127</div>

Authentication Stamp
NP168



Signature :

Singapore Police Force

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

not attached
 2/1/18
 4/5 @ 13.000
 10 day

VEHICLE NO:BNF 5587

QTY	PARTICULAR			
1 PCS	TAILGATE	750	Body	\$1,205.00 ✓
1 PCS	TAILGATE OUTER TOP GARNISH		11	\$450.00 X
1 PCS	TAILGATE REAR LOGO		11	\$50.00 X
1 PCS	TAILGATE 'ALZA' EMBLEM		11	\$52.00 X
1 PCS	TAILGATE INNER LOCK	155	D/S	\$245.00 ✓
1 PCS	TAILGATE INNER TRIM BOARD	266	Del/Torn	\$391.00 ✓
1 SET	TAILGATE INNER TRIM BOARD CLIPS		11	\$50.00 ✓
1 PCS	TAILGATE WEATHERSTRIP	180	11	\$299.00 ✓
2 PCS	TAILGATE DAMPERS @\$305.00		11	\$610.00 X
1 PCS	REAR WINDSCREEN MOULDING		11	\$110.00 ✓
1 PCS	REAR BUMPER	480	D.S	\$820.00 ✓
1 PCS	REAR BUMPER BEAM		11	\$299.00 X
2 PCS	REAR BUMPER REFLECTORS @\$85.00		CRA	\$170.00 ✓
1 SET	REAR BUMPER CLIPS		11	\$45.00 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$85.00	55 x 2 = 110	11	\$170.00 ✓
1 PCS	REAR END PANEL	580	Body	\$785.00 ✓
1 PCS	REAR END PANEL TOP GRANISH	95	Del/Torn	\$192.00 ✓
1 PCS	REAR FLOOR PANEL	780	crumpled/suc	\$1,120.00 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD		11	\$805.00 X
1 PCS	REAR FLOOR PANEL TOP TRAY	485	Del/Torn	\$699.00 ✓
2 PCS	TAILLAMPS @\$650.00	425 x 2 = 850	11	\$1,300.00 ✓
2 PCS	TAILLAMP LOWER GARNISHS @\$205.00	168 x 2 = 336	Del/Torn	\$410.00 ✓
1 PCS	REAR EXHAUST PIPE		11	\$485.00 X
2 PCS	REAR EXHAUST PIPE MOUNTINGS @\$60.00		11	\$120.00 X
2 PCS	REAR FENDERS @\$985.00		11	\$1,970.00 X
2 PCS	REAR FENDER INNER TRIMS @\$680.00	405 x 2 = 810	Del/CRA	\$1,360.00 ✓
1 PCS	REAR SPARE TYRE BRACKET		11	\$215.00 ✓
1 PCS	BONNET	685	11	\$1,105.00 ✓
2 PCS	BONNET HINGES @\$105.00	90 x 2 = 180	11	\$210.00 ✓
1 PCS	BONNET INSULATOR	148	Del/waph	\$320.00 ✓
1 SET	BONNET INSULATOR CLIPS		11	\$50.00 ✓
1 PCS	BONNET LOCK	95	11	\$145.00 ✓
1 PCS	FRONT GRILLE	188	11	\$325.00 ✓
1 PCS	FRONT BUMPER	495	D.S	\$825.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00		11	\$130.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	300	11	\$485.00 ✓
1 SET	FRONT BUMPER CLIPS		11	\$50.00 ✓
1 PCS	FRONT BUMPER TOW COVER		11	\$30.00 X
2 PCS	FRONT BUMPER FOG LAMPS @\$450.00		11	\$900.00 X

10%

2 PCS	FRONT FENDERS @\$605.00	2	\$1,210.00	X
2 PCS	FRONT FENDER INNERSHIELDS @\$185.00	2	\$370.00	12C
1 SET	FRONT FENDER INNERSHIELD CLIPS	1	\$50.00	X
2 PCS	HEADLAMPS @\$850.00	2	\$1,700.00	—
1 PCS	FRONT SUPPORT PANEL	1	\$915.00	—
2 PCS	FRONT CONDENSE SIDE GARNISHS @\$205.00	2	\$410.00	—
1 PCS	AIRCON CONDENSER	1	\$1,120.00	—
1 PCS	AIRCON SUCTION HOSE	1	\$311.00	X
1 PCS	AIRCON DISCHARGE HOSE	1	\$380.00	X
1 PCS	AIRCON LIQUID PIPE	1	\$195.00	X
1 PCS	RADIATOR	1	\$1,480.00	—
1 PCS	RADIATOR FAN ASSY	1	\$885.00	—
1 PCS	RADIATOR SPARE TANK	1	\$105.00	X
1 PCS	FRONT BRACE PANEL	1	\$110.00	—
1 PCS	FRONT GRILLE CHROME MOULDING	1	\$388.00	—
1 PCS	FRONT WIPER TANK	1	\$185.00	X
2 PCS	ENGINE MOUNTINGS @\$205.00	2	\$410.00	X
1 PCS	ALTERNATOR	1	\$1,800.00	X
1 PCS	COMPRESSOR	1	\$1,550.00	X
			\$32,576.00	
	S.NETT ITEM			
1 PCS	REAR WINDSCREEN SEALANT	1	\$50.00	40
1 PCS	REAR LICENCE PLATE	1	\$50.00	X
1 SET	REAR BUMPER REVERSE SENSOR	1	\$280.00	200
1 PCS	REAR END PANEL SEALANT	1	\$50.00	—
1 SET	REAR FLOOR PANEL INSULATOR	1	\$220.00	120
1 PCS	REAR BUMPER LOWER SKIRTING	1	\$880.00	500
1 PCS	FRONT BUMPER LOWER SKIRTING	1	\$880.00	500
1 PCS	FRONT LICENCE PLATE	1	\$50.00	14
	LABOUR CHRAGES:			
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING REVERSE SENSOR		\$80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM		\$100.00	60
	TO SPRAY RUST PROOFING		\$180.00	150
	TO REFILL AIR CON GAS		\$150.00	100
	TO DISMANTLE & REFIX REAR EXHAUST		\$100.00	60
	TO MOUNT VEHICLE ON CAR O-LINER		\$380.00	X
	TO DISMANTLE & REFIX PETROL TANK		\$100.00	60
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$180.00	80
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$3,000.00	200
	TO PUTTY & SPRAY PAINTING		\$3,000.00	1800
	TOTAL		\$42,536.00	

I, the undersigned, hereby notify the Repairer of the following:

- To be used for creative spray painting
- To disclose damaged parts during resurvey
- For all prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

6134

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18020228/UVB2

Date: 03/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29090793MKF
Claimant Vehicle No :	BNF5587	Insured Vehicle No :	YM6968D
Date of Loss:	01/11/2018	Nature of Claim:	TP
		Claim No:	574963

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	BNF5587	Engine No:	G20B96E
Make & Model:	PERODUA ALZA, 1.5 SE (A)	Chassis No:	PM2M502G002240118
Reg. Date:	27/04/2015 (Man. Year: 2015)	Odometer:	95768 km
Colour:	Red		
Engine Capacity:	1495 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	35,036.00	13,391.12	21,644.88	61.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	4,710.00	2,790.00	37.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,536.00	18,101.12	24,434.88	57.45
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	42,536.00	13,000.00	29,536.00	69.44
+ GST 7.00/7.00% (S\$)	2,977.52	910.00	2,067.52	69.44
Nett Amount (S\$)	45,513.52	13,910.00	31,603.52	69.44

INSPECTION

Date of Assignment:	31/12/2018		
Date Inspected:	08/11/2018 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883	
Estimated Period of Repair:	10.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: M1-MPV	PERODUA ALZA 1.5 SE (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for BNF5587)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,205.00 F	*750.00 FL
2	1		*TAILGATE OUTER TOP GARNISH	Not Necessary	450.00 F	*- FL
3	1		*TAILGATE REAR LOGO	Not Necessary	50.00 F	*- FL
4	1		*TAILGATE ALZA EMBLEM	Not Necessary	52.00 F	*- FL
5	1		*TAILGATE INNER LOCK	Dented/Jammed	245.00 F	*155.00 FL
6	1		*TAILGATE INNER TRIM BOARD	Deformed/Torn	391.00 F	*266.00 FL
7	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	299.00 F	*180.00 FL
9	2		*TAILGATE DAMPERS	Not Necessary	610.00 F	*- FL
10	1		*REAR WINDSCREEN MOULDING	Necessary	110.00 F	*110.00 FL
11	1		*REAR BUMPER	Distorted	820.00 F	*480.00 FL
12	1		*REAR BUMPER BEAM	Not fitted	299.00 F	*- FL
13	2		*REAR BUMPER REFLECTORS	Cracked	170.00 F	*170.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
15	2		*REAR BUMPER SIDE RETAINERS	Bent	170.00 F	*110.00 FL
16	1		*REAR END PANEL	Badly Dented	785.00 F	*580.00 FL
17	1		*REAR END PANEL TOP GARNISH	Deformed/Twisted	192.00 F	*95.00 FL
18	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,120.00 F	*780.00 FL
19	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	805.00 F	*- FL
20	1		*REAR FLOOR PANEL TOP TRAY	Deformed/Cracked	699.00 F	*485.00 FL
21	2		*TAILLAMPS	Cracked	1,300.00 F	*850.00 FL
22	2		*TAILLAMP LOWER GARNISHS	Deformed/Torn	410.00 F	*336.00 FL
23	1		*REAR EXHAUST PIPE	Repair	485.00 F	*- FL
24	2		*REAR EXHAUST PIPE MOUNTINGS	Not Necessary	120.00 F	*- FL
25	2		*REAR FENDERS	Repair	1,970.00 F	*- FL
26	2		*REAR FENDERS INNER TRIMS	Deformed/Cracked	1,360.00 F	*810.00 FL
27	1		*REAR SPARE TYRE BRACKET	Bent	215.00 F	*215.00 FL
28	1		*BONNET	Buckled	1,105.00 F	*685.00 FL
29	2		*BONNET HINGES	Bent	210.00 F	*180.00 FL
30	1		*BONNET INSULATOR	Deformed/Warped	320.00 F	*148.00 FL
31	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 F	*50.00 FL
32	1		*BONNET LOCK	Bent/Twisted	145.00 F	*95.00 FL
33	1		*FRONT GRILLE	Broken	325.00 F	*188.00 FL
34	1		*FRONT BUMPER	Distorted	825.00 F	*495.00 FL
35	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
36	1		*FRONT BUMPER REINFORCEMENT	Bent	485.00 F	*300.00 FL
37	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
38	1		*FRONT BUMPER TOW COVER	Not Necessary	30.00 F	*- FL
39	2		*FRONT BUMPER FOG LAMPS	Not Necessary	900.00 F	*- FL
40	2		*FRONT FENDERS	Repair	1,210.00 F	*- FL
41	1		*FRONT FENDER INNERSHIELDS	N/s Torn	370.00 F	*185.00 FL
42	1		*SET FRONT FENDER INNERSHIELD CLIPS	Not Necessary	50.00 F	*- FL
43	2		*HEADLAMPS	Cracked	1,700.00 F	*1,030.00 FL
44	1		*FRONT SUPPORT PANEL	Bent	915.00 F	*499.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*FRONT CONDENSE SIDE GARNISHS	Torn	410.00 F	*170.00 FL
46	1		*AIRCON CONDENSER	Bent/Punctured	1,120.00 F	*861.30 FL
47	1		*AIRCON SUCTION HOSE	Not Necessary	311.00 F	*- FL
48	1		*AIRCON DISCHARGE HOSE	Not Necessary	380.00 F	*- FL
49	1		*AIRCON LIQUID PIPE	Not Necessary	195.00 F	*- FL
50	1		*RADIATOR	Bent/Punctured	1,480.00 F	*899.50 FL
51	1		*RADIATOR FAN ASSY	Cracked/Jammed	885.00 F	*366.00 FL
52	1		*RADIATOR SPARE TANK	Not Necessary	105.00 F	*- FL
53	1		*FRONT BRACE PANEL	Bent	110.00 F	*110.00 FL
54	1		*FRONT GRILLE CHROME MOULDING	Cracked	388.00 F	*388.00 FL
55	1		*FRONT SIPER TANK	Not Necessary	185.00 F	*- FL
56	2		*ENGINE MOUNTINGS	Not Necessary	410.00 F	*- FL
57	1		*ALTERNATOR	Not Necessary	1,800.00 F	*- FL
58	1		*COMPRESSOR	Not Necessary	1,550.00 F	*- FL
59	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
60	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
61	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
62	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
63	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	220.00 FS	*120.00 FS
64	1		*REAR BUMPER LOWER SKIRTING	Broken	880.00 FS	*500.00 FS
65	1		*FRONT BUMPER LOWER SKIRTING	Deformed/Torn	880.00 FS	*500.00 FS
66	1		*FRONT LICENCE PLATE	Cracked	50.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,036.00	14,720.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,329.68
Total Parts (\$\$)	35,036.00	13,391.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	180.00	150.00
6	TO REFILL AIR CON GAS	New	150.00	100.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
10	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	180.00	80.00
11	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	3,000.00	2,200.00
12	TO PUTTY & SPRAY PAINTING	New	3,000.00	1,800.00
Gross Labour Cost (S\$)			7,500.00	4,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >