

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 233/JC/TC/HO/2018
DATE : 07-NOV-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MISS CHIANG HWEE YEN JEAN (ZHANG HUIYAN JEAN)
ADDRESS : 91 TAMPINES AVENUE 1
#08-38
S(528690)
TELEPHONE NO : 96377802

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : AXA 3RD PARTY DIRECT SETTLEMEN
VEHICLE NO : SKT3180H
MODEL CODE : TDWAREZE12VDAY381Z
MODEL/YEAR : NOTE 1.2L CVT DIG-S (I)
ENGINE NO : HR12079628B
CHASSIS NO : JN1TBAE12Z0981063
MILEAGE : 1 KM
DATE IN : 07/11/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 02/11/2018

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT3180H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NP1	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	60.00	X NN
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL @\$120.00/PANEL X 2 PANEL	240.00	X NN
3	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA @\$100.00/PANEL X 2 PANEL	200.00	X 100
5	ZZ/001	REMOVE/INSTALL REAR BUMPER, END PANEL, BACK DOOR AND AFFECTED PORTION. REPAIR LHR FENDER AND RHR FENDER	1000.00 250	X 625
6	ZZ/002	RESPRAY PAINT REAR BUMPER, END PANEL, TRUNK FLOOR PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	1750.00 200	X 600
7	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE THE REPAIR	240.00	X 60.
8	ZZ/004	TRANSFER BACK DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	/
9	ZZ/005	RENEW BACK DOOR WINDSCREEN GLASS	150.00	X /
10	ZZ/006	RENEW BACK DOOR WINDSCREEN GLASS SOLAR FILM	150.00	X /
11	ZZ/007	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	X /
12	ZZ/008	SEARCH FEE	2.00	X /
13	ZZ/009	TOWING AND RECOVERY CHARGES FOR DIRECT SETTLEMENT CLAIMS	80.00	X / NN
TOTAL LABOUR CHARGES			4027.00	1840

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKT3180H

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	CARPET-LUGGAGE FLOOR X	84903-3VA1A	411.20	
2	PLATE-LUGGAGE, REAR X	84992-3VA0A	63.50	
3	DRAFTER-AIR X	76804-2DZ0A	62.30	
4	LOCK ASSY-BACK DOOR X	90502-1HM1A	116.70	
5	WEATHER STRIP-BACK DOOR X	90830-3VA0A	64.90	
6	STAY ASSY-BACK DOOR, RH X	90450-3VA0A	182.50	
7	STAY ASSY-BACK DOOR, LH X	90451-3VA0A	182.50	
8	BUMPER-RUBBER, BACK DOOR @ \$8.40 EACH X2PCS X	90878-2LR0A	16.80	
9	FINISHER ASSY-BACK DOOR X	90810-3VA6A	243.90	
10	EMBLEM-REAR	90893-3VU0A	59.70	/
11	EMBLEM-REAR	90892-3VA0A	73.60	/
12	EMBLEM-REAR	90890-3VA0A	59.70	/
13	REAR W/SCREEN SEALANT / MC	SEALANT - 4		80.00 /
14	RUBBER-DUM / MC	G2716-89900	60.20	/
15	GLASS-BACK DOOR WINDSCREEN 8 / MC	90300-3VA0A	1240.00	/
16	DOOR ASSY-BACK / BUC	K010M-3VAMA	976.40	/
17	REAR BUMPER STAY @ \$86.60 EACH X2PCS X NN	H5212-1HMMA	173.20	
18	REAR BUMPER ENERGY ABSORBER ?	85090-3VA0A	111.90	
19	RH REAR BUMPER SIDE BRACKET ?	85220-3VA0C	47.10	
20	LH REAR BUMPER SIDE BRACKET ?	85221-3VA0C	47.10	
21	SENSOR-REVERSE ?	SENSOR		200.00
22	REAR BUMPER CLIP @ \$1.20 EACH X3PCS MC	01553-10501	3.60	/
23	REAR BUMPER FASCIA / DE	85022-3VA0H	414.00	/
24	REAR END PANEL ?	79100-3VA0A	552.80	
25	LAMP ASSY-REAR COMBI, LH ?	26555-3VA5B	293.70	

2886.8 280
20% 2309.44
4429.44

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SET1180H

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
SUB TOTAL		5457.20	0.00	280.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1091.44	0.00	0.00
GRAND TOTAL		4365.76	0.00	280.00
OVERALL TOTAL		4645.76		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKT3180H

TOTAL LABOUR CHARGES	4027.00
TOTAL SPARE PARTS CHARGES	4645.76
GRAND TOTAL	8672.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	:

Caro King - 82880282
2/2/19.
before paint photos.
5 Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: