

ASS. REC. BY:

REF: CS3/FCI18015889/R1qb-1 Special instruction:

Surveyor: Ramu ASSIGNMENT (Office)

From (Person): Bitheva of FCI Date/Time: 08/11/2018

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES OD RES EVA INV MV CS

To inspect Vehicle No: YN 8976L Insured: SHC 06317

at Workshop m/s: AAK Logistics Tel: 6677 6227

of: Blk 153 Blk Bafolk St-11 #03-292

Policy No: _____ Claim No: D18006353MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ (Client's Record) D.O.A. 21/08/2018

Insp: 4 penjam close

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 1:02pm 30/8/18 Person Contacted: pei juen Vehicle: LOOT

Date/Time	Action/Instruction (X) Estimate
	<u>YN 8976L - X</u>
	<u>SHC 06317 - CE4/ASM18008098/Dpb3 DOA: 25/4/18</u>
<u>31/8/18</u>	<u>Diminished</u>

26/9/18 @ 11:25am Ramu finalised at US \$4200, 7 days. Cred to 7367.36, 64%.

12/11/18 check with Celine, she said just follow the estimate amount for billing.

* use CS3/FCI18015889/R124d352 photographs.

RECEIVED 12 NOV 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18015889/R1z4d3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-08-2018



Code : FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 631T	Veh. Inspected	YN 8976L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006353MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	31/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/08/2018	Inspection Date	30/08/2018
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

MOTOR SURVEY ASSIGNMENT

Date	24-08-2018	Our Ref No. D18006353MFSH
Accident Date	21-08-2018	Claim Type. Third Party
Insured Vehicle	SHC0631T	Third Party Vehicle. YN8976L
Survey Location	Blk 153 Bt Batok St 11 #03-292	
Contact Person.	PEIJUAN	
Contact No.	66650190/ 66776227	Fax No. 65619509
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AAK LOGISTICS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Rasul (LKKAuto)

From: Peijuan <auto@aakls.com>
Sent: Wednesday, 26 September, 2018 11:25 AM
To: Rasul (LKKAuto)
Subject: RE: Finalize amount for YN8976L

Hi Rasul,

Ok close at \$4,200

Best regards,
Peijuan
AAK
4 Penjuru Close
Singapore 608574
Tel: 66776227

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, 26 September 2018 11:20 AM
To: Peijuan <auto@aakls.com>
Subject: RE: Finalize amount for YN8976L

Hi Pei juan,

Offer at 4200

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Peijuan [<mailto:auto@aakls.com>]
Sent: Wednesday, 26 September, 2018 10:55 AM
To: Rasul (LKKAuto)
Subject: RE: Finalize amount for YN8976L

Hi Rasul,

Give me a little more, \$4,500.00?

Best regards,
Peijuan
AAK
4 Penjuru Close
Singapore 608574

Tel: 66776227

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, 26 September 2018 10:29 AM
To: Peijuan <auto@aakls.com>
Subject: RE: Finalize amount for YN8976L

Hi Pei juan,

4800 is unacceptable

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Peijuan [<mailto:auto@aakls.com>]
Sent: Wednesday, 26 September, 2018 10:26 AM
To: Rasul (LKKAuto)
Subject: RE: Finalize amount for YN8976L

Hi Rasul,

I'm asking for \$4,800.00 / LS 7days

Best regards,

Peijuan

AAK

4 Penjuru Close

Singapore 608574

Tel: 66776227

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, 26 September 2018 10:07 AM
To: Peijuan <auto@aakls.com>
Subject: RE: Finalize amount for YN8976L

Hi Peijuan,

Kindly refer to attachment

Finalise amount is \$ 4,100.00 / 7 days lump sum

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Peijuan [<mailto:auto@aakls.com>]

Sent: Wednesday, 19 September, 2018 3:03 PM

To: Rasul (LKKAuto)

Subject: Finalize amount for YN8976L

Hi Rasul,

Kindly refer to attached supplementary item and finalize amount with me.

Best regards,

Peijuan

AAK

4 Penjuru Close

Singapore 608574

Tel: 66776227

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


ACCIDENT STATEMENT

Date Of Report	23/08/2018 09:55
Date Of Accident	21/08/2018 18:15
Exact Location Of Accident	EAST COAST PARK CARPARK D1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN8976L
Insured/Policyholder	
Name Of Registered Owner	AAK LOGISTICS SERVICES PTE LTD
Co Reg No	201325787M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66650190
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21ER3SDEB (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCX/P1954824
Cover Note Number	
Driver	
Name of Driver	JUMAT BIN RAHIM
NRIC No	S7639378H
Date Of Birth	26/11/1976
Occupation	OUTDOOR
Date Of Driving Pass	25/03/2014
Driving Experience	4 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82311401
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/8/18 10:47am

Reporting Centre Personnel's Signature
Name: Pu Huan
NRIC/FIN No.: S92265922



AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153
 Tel: (65) 6665 0190 Fax: (65) 6561 9509
 E-mail: admin@aakls.com
 Company Registration No.: 201325787M
 GST Reg. No.: 201325787M

Quotation

TO: **MS FIRST CAPITAL INSURANCE LIMITED**
 36, Robinson Road, #16-01
 City House
 Singapore 068877

DATE: 29-Aug-18
 TERMS: 30 Days
 PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (\$)	
Accident Repair of YN8976L (CANTER FEB21)					
DOA: 21/08/2018 @ EAST COAST PARK CARPARK D1 INVOLVING SHC631T					
1	BUMPER ASSY,FRONT	1	\$929.76	\$ 929.76	
2	STAY,FR BUMPER,RH	1	\$186.95	\$ 186.95	
3	COVER,FR BMPR CORNER,RH	1	\$325.54	\$ 325.54	
4	WEATHERSTRIP,WINDSHIELD	1	\$477.20	\$ 477.20	
5	PANEL, CAB FR CORNER -RH	1	\$482.75	\$ 482.75	
6	SEAL, CORNER PANEL -RH	1	\$35.07	\$ 35.07	
7	PILLAR,FR RH	1	\$1,289.49	\$ 1,289.49	
8	STEP, FR SIDE,RH	1	\$572.80	\$ 572.80	
9	PANEL ASSY,FR DOOR,RH	1	\$1,391.59	\$ 1,391.59	
10	HINGE,FR DOOR 02TD DOM DX	1	(\$154.89)	\$ 309.78	
11	GARNISH,AIR OUTLET	1	\$46.30	\$ 46.30	
12	REGULATOR ASSY,F/DR PWR WD	1	\$1,254.47	\$ 1,254.47	
13	LATCH,F/DR POWER	1	\$639.41	\$ 639.41	
14	HEADLAMP ASSY,RH	1	\$461.45	\$ 461.45	
15	BEZEL,HEADLAMP	1	\$13.83	\$ 13.83	
16	RIVET,FOG LAMP	1	\$2.48	\$ 2.48	
17	SIGNAL LAMP ASSY -RH	1	\$245.15	\$ 245.15	
18	GARNISH,HEADLAMP,RH	1	\$211.96	\$ 211.96	
19	SCUFF PLATE, FR -RH	1	\$143.69	\$ 143.69	
				\$9,019.67	
LABOUR					
1	TO REMOVE AND INSTALL FRONT WINDSCREEN TO FACILITATE REPAIR			\$300.00	
2	TO PANEL BEAT/REPAIRRHS BODY			\$500.00	
3	TO DISMANTLE/REPLACE ABOVE MENTIONED PARTS			\$1,000.00	
4	SPRAY PAINTING			\$600.00	
E & O. E.				SUB-TOTAL	\$11,419.67
SGD: TWELVE THOUSAND TWO HUNDRED NINETEEN AND CENTS FIVE ONLY.				7% GST	\$799.38
				TOTAL	\$12,219.05

4721.45
 2596
 3541.08

ZIP
 1600
 900/1000
 800
 XCH su

Note: Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

AAK LOGISTICS SERVICES PTE LTD



Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

RASUL
 HP 90010068
 7 days
 4S
 30/08/18 @ 1800
 Regy after repair

1156336

AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@akls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

MS FIRST CAPITAL INSURANCE LIMITED
 36, Robinson Road, #16-01
 City House
 Singapore 068877

Quotation

DATE: 19-Sep-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (\$)
Accident Repair of YN8976L (SUPPLEMENTARY)				
DOA : 21/08/2018 @ EAST COAST PARK CARPARK D1 INVOLVING SHC63IT				
1	RH INNER STEP GARNISH	1	SCA / \$143.69	\$ 143.69
<p> P - 3541.08 Suppl - 107.76 L - 1600.00 <hr/> T - 5248.84 20% 4199.07 <hr/> 415 - 4200 </p>		<p> 143.69 25% 107.76 <hr/> 7 days </p>		
E. & O. E.			SUB-TOTAL	\$143.69
SGD: ONE HUNDRED FIFTY-THREE AND CENTS SEVENTY-FIVE ONLY.			7% GST	\$10.06
			TOTAL	\$153.75

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd.".

AAK LOGISTICS SERVICES PTE LTD



Authorised Signature

AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

MS FIRST CAPITAL INSURANCE LIMITED
36, Robinson Road, #16-01
City House
Singapore 068877

*Resurvey
on
31/08/18
Paul*

Quotation

DATE: 29-Aug-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (\$)
Accident Repair of YN8976L (CANTER FEB21)				
DOA : 21/08/2018 @ EAST COAST PARK CARPARK D1 INVOLVING SHC631T				
1	BUMPER ASSY,FRONT	1	\$929.76	\$ 929.76
2	STAY,FR BUMPER,RH	1	\$186.95	\$ 186.95
3	COVER,FR BMPR CORNER,RH	1	\$325.54	\$ 325.54
4	WEATHERSTRIP,WINDSHIELD	1	\$477.20	\$ 477.20
5	PANEL, CAB FR CORNER -RH	1	\$482.75	\$ 482.75
6	SEAL, CORNER PANEL -RH	1	\$35.07	\$ 35.07
7	PILLAR,FR RH	1	\$1,289.49	\$ 1,289.49
8	STEP, FR SIDE,RH	1	\$572.80	\$ 572.80
9	PANEL ASSY,FR DOOR,RH	1	\$1,391.59	\$ 1,391.59
10	HINGE,FR DOOR 02TD DOM DX	1	\$154.89	\$ 309.78
11	GARNISH,AIR OUTLET	1	\$46.30	\$ 46.30
12	REGULATOR ASSY,F/DR PWR WD,	1	\$1,254.47	\$ 1,254.47
13	LATCH,F/DR POWER	1	\$639.41	\$ 639.41
14	HEADLAMP ASSY,RH	1	\$461.45	\$ 461.45
15	BEZEL,HEADLAMP	1	\$13.83	\$ 13.83
16	RIVET,FOG LAMP	1	\$2.48	\$ 2.48
17	SIGNAL LAMP ASSY -RH	1	\$245.15	\$ 245.15
18	GARNISH,HEADLAMP,RH	1	\$211.96	\$ 211.96
19	SCUFF PLATE, FR -RH	1	\$143.69	\$ 143.69
				\$9,019.67
LABOUR				
1	TO REMOVE AND INSTALL FRONT WINDSCREEN TO FACILITATE REPAIR			\$ 300.00
2	TO PANEL BEAT/REPAIRRHS BODY			\$ 500.00
3	TO DISMANTLE/REPLACE ABOVE MENTIONED PARTS			\$ 1,000.00
4	SPRAY PAINTING			\$ 600.00
E. & O. E.				
SUB-TOTAL				\$11,419.67
7% GST				\$799.38
TOTAL				\$12,219.05
SGD: TWELVE THOUSAND TWO HUNDRED NINETEEN AND CENTS FIVE ONLY.				

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

AAK LOGISTICS SERVICES PTE LTD

Authorised Signature



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

*RASUL
HP 90010068
7 days
4S
30/08/18 @ 1800
Resy after repair*




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FC118015889/R1z4d3s2 Date: 05-10-2018	
Code: FCI2			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 631T	Veh. Inspected	YN 8976L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006353MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	30/08/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI CANTER FEB21	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	FEB21EA10279	Colour	YELLOW
Odometer	131252 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	WEST LAKE	7 mm
L/H Front Tyre	195 R15C	WEST LAKE	7 mm
R/H Rear Tyre	195 R15C (D)	WEST LAKE	7/7 mm
L/H Rear Tyre	195 R15C (D)	WEST LAKE	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
5. General Information			
Accident Date	21/08/2018	Inspect Date / Time	30/08/2018 (05:43 PM)
Survey held at	AAK LOGISTICS - BLK 153 BKT BATOK ST 11 #03-292		
Repairer	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/FC118015889/R1z4d3s2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS3/FCI18015889/R1qbe2-1	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-11-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 631T	Veh. Inspected	YN 8976L
Policy No.		Coverage (\$)	0.00
Claim No.	D18006353MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	08/11/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI CANTER FEB21ER3SDEB	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	FEB21EA10279	Colour	YELLOW
Odometer	131252	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	WEST LAKE	7 mm
L/H Front Tyre	195 R15C	WEST LAKE	7 mm
R/H Rear Tyre	195 R15C (D)	WEST LAKE	7/7 mm
L/H Rear Tyre	195 R15C (D)	WEST LAKE	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/08/2018	Inspection Date	30/08/2018
Survey held at	AAK LOGISTICS SERVICES PL 153 BUKIT BATOK STREET 11 #03-292 SINGAPORE 650153		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 8976L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER ASSY FRONT	BENT	929.76	929.76
1	STAY,FR BUMPER RH	SERVICEABLE	186.95	-
1	COVER,FR BUMPER CORNER,RH	MISSING	325.54	325.54
1	WEATHERSTRIP,WINDSHIELD	SERVICEABLE	477.20	-
1	PANEL,CAB FR CORNER-RH	CUT	482.75	482.75
1	SEAL,CORNER PANEL-RH	SERVICEABLE	35.07	-
1	PILLAR,FR RH	TO REPAIR SEE LABOUR	1,289.49	-
1	STEP,FR SIDE,RH	SCRATCHED	572.80	572.80
1	PANEL ASSY,FR DOOR,RH	BENT	1,391.59	1,391.59
2	HINGE,FR DOOR Q2TD DOM DX	O/S BENT / N/S SERVICEABLE	309.78	154.89
1	GARNISH,AIR OUTLET	SERVICEABLE	46.30	-
1	REGULATOR ASSY,F/DR PWR WD	SERVICEABLE	1,254.47	-
1	LATCH,F/DR POWER	SERVICEABLE	639.41	-
1	HEADLAMP ASSY,RH	BROKEN	461.45	461.45
1	BEZEL,HEADLAMP	MISSING	13.83	13.83
1	RIVET,FOG LAMP	SERVICEABLE	2.48	-
1	SIGNAL LAMP ASSY-RH	BROKEN	245.15	245.15
1	GARNISH,HEADLAMP,RH	SERVICEABLE	211.96	-
1	SCUFF PLATE,FR-RH	CRACKED	143.69	143.69
1	RH INNER STEP GARNISH (ADDITIONAL)	SCRATCHED	143.69	143.69
	LESS 25% DISCOUNT		-	-1,216.29
			9,163.36	3,648.85
<u>LABOUR</u>				
	TO REMOVE AND INSTALL FRONT WINDSCREEN TO FACILITATE REPAIR.	NOT NECESSARY	300.00	-
	TO DISMANTLE/REPLACE ABOVE MENTIONED PARTS.INCLUSIVE OF THE REPAIR OF PILLAR,FR RH. }		1,000.00	1,000.00
	TO PANEL BEAT/REPAIR RHS BODY. }		500.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		600.00	600.00
			2,400.00	1,600.00
	GRAND TOTAL		11,563.36	5,248.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS3/FC118015889/R1qbe2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.