

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJL 2704H

Vehicle Model : TOYOTA COROLLA ALTIS

Chassis Number : MR053REH104537713

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	710.00 X SVL
2	BOOT LID INSULATION	1	451.60 X SVL
3	BOOT LID INSULATION CLIPS	20	100.00 X SVL
4	BOOT LID LOCK	1	357.00 X SVL
5	BOOT LID WEATHERSTRIP	1	178.50 X SVL
6	BOOT LID LAMP (LH & RH)	2	583.36 X SVL
7	BOOT LID "TOYOTA" LOGO	1	90.00 X SVL
8	BOOT LID "COROLLA ALTIS" EMBLEM	1	96.00 X SVL
9	BOOT LID CENTER CHROME MOULDING	1	224.65 X SVL
10	REAR BUMPER RETAINER (LH & RH)	2	196.00 $\frac{2}{3}$ / CRK
11	REAR BUMPER	1	486.50 / CRK
12	REAR BUMPER REINFORCEMENT	1	386.60 $\frac{2}{3}$ / DEF
13	REAR BUMPER CLIPS	10	50.00 $\frac{2}{3}$ / NEC
14	REAR BUMPER REFLECTOR (LH & RH)	2	114.00 X SVL
15	TAIL LAMP (LH & RH)	2	773.00 $\frac{2}{3}$ X LH SVL RH CRK
16	END PANEL	1	649.20 $\frac{2}{3}$ / DD
17	END PANEL UPPER GARNISH	1	202.70 $\frac{2}{3}$ X SVL
18	SPARE TYRE BOARD	1	532.00 $\frac{2}{3}$ X SVL
19	FENDER INNER TRIM (RH)	1	521.70 X SVL
20	FENDER INNER TRIM RH CLIPS	20	100.00 X SVL
			\$ 6802.81
Discount Less 25%			1700.70
List Prices Total			\$ 5,102.11

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR - inform Naz.	1 SET	\$ 350.00 X SVL / SVL
2	REAR NUMBER PLATE WITH HOLDER	1 SET	\$ 60.00 X SVL / NN
Special Nett Total			\$ 410.00
Spare Part's Total Price			\$ 5512.11

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJL 2704H
Vehicle Model : TOYOTA COROLLA ALTIS
Chassis Number : MR053REH104537713

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR BOOT FLOOR PANELS, TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1800.00 300 600
2	TO SPRAY PAINTING ON: BOOT LID (INNER & OUTER), REAR BUMPER, REAR END PANEL & BOOT FLOOR PANEL.	\$ 1500.00 300 600
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 100.00 20
4	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO NEW BOOT LID & TEST FUNCTION	\$ 100.00 X MN
5	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$ 120.00 ? 50
6	TO RESET & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	\$ 180.00 30
7	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 50.00 ? 30

NA2 LKK
8/14/18
L/S
4 1/2 DAYS

CHECK ITEMS PHOTOS
AFTER REPAIR PHOTOS

LKK Auto Consultants here by	Labour Total	\$ 3850.00
the Repairer of the following:	Parts & Labour Total	\$ 9362.11
<ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 		
Acknowledged by Repairer		
Signature:		
Date:		