



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 08.11.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2343G HONDA SHUTTLE HYBRID (2017)

To Supply

1) 1pc	Front bumper <i>DE</i>	\$	1,350.00
2) 1set	Front bumper clip <i>re</i>	\$	30.00
3) 1pc	Front bumper left side retainer <i>re</i>	\$	35.00
4) 1pc	Front bumper reinforcement ?	\$	520.90
5) 1pc	Front bumper lower grille ?	\$	140.00
6) 1pc	Left head lamp <i>scr</i>	\$	1,050.00
7) 1pc	Left head lamp lower bracket ?	\$	38.00
Sub total parts		\$	3,163.90
Less: 20% discount		\$	(632.78)
		\$	2,531.12

L/charges

1) To tuff kote.	\$	30 50.00 <i>50</i>
2) To focus left head lamp.	\$	30.00
3) To remove front bumper & left head lamp. Knock / repair radiator top panel. Replace the above parts. Align & adjust front bonnet & left front fender.	\$	400.00 300

4) To putty, respray painting front bumper & radiator top panel. To polish.

\$ 300.00

Sub total L/charges	\$ 780.00
Estimated Grand Total	\$ 3,311.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul

Hp 90010068

3 days

P/P

08/11/18 @ 1700

Resury after -
54 paint