

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: WONG KHIO KONG
 INSURER: ERGO INSURANCE PTE LTD
 POLICY NO: DMPC175021852
 REFERENCE: TP CLAIM
 DATE OF ACCIDENT: 29/10/2018

TPAXA.
 Asher

REPAIR ESTIMATE

Est. No. : E18110001
 Date : 07/11/2018
 Vehicle Num. : SDY8830P
 Make/Model : Ford ,S-Max trend 5DR
 Chassis/Eng# : WF0SXXGBWS9P76669
 Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper <i>Repair</i>	1.00	590.00	590.00 X
2	Rear Bumper Reinforcement	1.00	1,095.00	1,095.00 X
3	Rear Bumper Holder	1.00	120.00	120.00 X
4	Rear Bumper Side Retainer	2.00	114.00	228.00 X
5	Rear Bumper Centre Parking Sensor <i>He nee</i>	2.00	148.00	296.00 X
6	Tailgate <i>Dented</i>	1.00	3,853.00	3,853.00 2880
7	Tailgate Garnish <i>cracked.</i>	1.00	260.00	260.00 ✓
8	Tailgate Logo Emblem	1.00	138.00	138.00 ✓
9	Tailgate "S-Max" Emblem <i>new</i>	1.00	194.00	194.00 ✓
10	Tailgate Lamp <i>cracked.</i>	2.00	340.00	680.00 ✓
11	Tailgate Opening Switch <i>He nee</i>	1.00	170.00	170.00 X
12	Tailgate Inner Lock <i>Damaged.</i>	1.00	280.00	280.00 ✓
13	Rear End Panel	1.00	550.00	550.00 X
14	Rear End Panel Top Garnish <i>new</i>	1.00	250.00	250.00 X
15	Rear Windscreen Wiper Motor <i>Damaged</i>	1.00	720.00	720.00 ✓
16	Tailgate Outer Cover <i>Behind</i>	1.00	873.00	873.00 ✓

Amt S\$ 10,297.00
 Discount (20.00%) S\$ 999.99
 Subtotal S\$ 8,237.60

Section: LABOUR

17	TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS	1.00	980.00	980.00 400
18	TO PUTTY & SPRAY PAINTING ON ACCIDENT DAMAGED PORTION	1.00	720.00	720.00 400

800

Continue on next page...

bizSAFE₃



JOO HAK KEE AUTO PTE LTD
 裕合记汽车私人有限公司
 SINCE 1986

REPAIR ESTIMATE

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: WONG KHIO KONG
 INSURER: ERGO INSURANCE PTE LTD
 POLICY NO: DMPC175021852
 REFERENCE: TP CLAIM
 DATE OF ACCIDENT: 29/10/2018

Est. No. : E18110001
 Date : 07/11/2018
 Vehicle Num. : SDY8830P
 Make/Model : Ford ,S-Max trend 5DR
 Chassis/Eng# : WF0SXXGBWS9P76669
 Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
				Amt S\$ 1,700.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 1,700.00

*Addin hiny
 H/S 08/11/18.*

04 days.

total: 5620

2/s: A.H.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

[Handwritten signature]



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal	S\$ 8,237.60
LABOUR Subtotal	S\$ 1,700.00
Total	S\$ 9,937.60

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701 TEL: 6743 1913 FAX: 6743 5234 CO/GST REG NO: 201300082W
 BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702 EMAIL: admin@jhk.com.sg WEBSITE: www.jhk.com.sg

bizSAFE₃