

AXA Insured's Veh No : SHF768S
 Date of Accident : 05 November 2018

Mr Pay Kim Swee

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to confirmation

TAN LIN MOTOR PTE LTD
 51 Defu Lane 10 Singapore 539216
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn No: M2-8922054-2

Acknowledged by Repairer
 Signature: _____
 Date: 05 November 2018

not Allowed make survey
 1/5 @ 3150
 8/11/18
 the photo attached
 Hdy.

confirm with Marcus
 08-11-2018 @ 10:15hr

Estimate To Repair SH3142L - Hyundai Elantra 1.6GLS
 Chassis No : KMHDH41CMEU128979

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	side mirror RH <i>500</i>	\$ 471.00
02	1 pc	rear door RH <i>n</i>	\$ 1,228.00
03	1 pc	rear fender RH <i>no/survey</i>	\$ 1,748.00
04	1 pc	rear fender inner trim RH <i>shield RH Tom</i>	\$ 175.00
05	1 pc	rear fender air vent RH	\$ 29.00
06	1 pc	rear windscreen moulding <i>88-10</i>	\$ 180.00
07	1 pc	rear wheel hub cap <i>cut</i>	\$ 115.00
08	1 pc	rear wheel rim <i>11</i>	\$ 260.00
09	1 pc	rear mudflap RH <i>good</i>	\$ 27.00
10	1 pc	rear bumper <i>Tom</i>	\$ 459.00
11	2 ps	rear bumper side retainer @ \$26.00 <i>2/13/18</i>	\$ 52.00
12	8 ps	rear bumper clip @ \$4.30 <i>all</i>	\$ 34.40
13	1 pc	rear lamp RH <i>scd</i>	\$ 362.00
		Less 20% <i>50%</i>	\$ 5,140.40
			\$ 1,028.08
			\$ 4,112.32
<u>SPECIAL NETT ITEMS</u>			
14	1 pc	rear windscreen sealant <i>neu</i>	\$ 60.00
15	1 pc	rear tyre RH <i>11</i>	\$ 180.00
			\$ 240.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass.	\$ 120.00
02		To check electrical lighting concerned.	\$ 30.00
03		To check steering geometry and computer wheel alignment.	\$ 11 80.00
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 80.00
05		To transfer of door fittings and perform water seepage test.	\$ 11 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
07		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 1,990.00
		Total	\$ 6,342.32

P- 3505.50
50%
1752.75
S-NY 40.00
10hr 1380
 TOTAL *3172.75*