



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR WANG HONGJUAN
BLK 410 WOODLANDS ST 41
#08-91 (S) 730410

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SHB 7625 X (AXA)
OUR REF : TP 5959
VEHICLE NO : SJD 2414 L
MAKE/MODEL : Mit Lancer CY2
DATE OF ACCIDENT : 25.07.18

SURVEY BY

DATE : 10.11.18

1 PC REAR BUMPER		S\$	669.00	✓ CER
1 PC FRONT BUMPER SIDE RETAINER R/H			23.00	?
1 PC REAR FENDER R/H			738.00	✓ DEF
3 PCS REAR WINDSCREEN GLASS MOULDING	55.00		165.00	✓ NEC
		S\$	1,595.00	
	LESS 20%		319.00	
		S\$	1,276.00	
2 PCS REAR WINDSCREEN GLASS SEALN	40.00	S\$	80.00	S/NETT ✓ NF
TO REMOVE AND REFIX CUSHION SEATS		S\$	80.00	✓ NF 60
TO REMOVE AND REFIX REAR WINDSCREEN GLASS			140.00	✓ 120
TO CHECK WIRING FUNCTION			20.00	✓ NEC
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL			50.00	✓ NEC
LABOUR CHARGES			600.00	✓ 500
TO PUTTY AND SPRAY PAINTING CHARGES			600.00	✓ 400
		S\$	2,846.00	

SIN DOLLARS: TWO THOUSAND EIGHT HUNDRED AND FORTY-SIX DOLLARS ONLY.

YOUR FAITHFUL CONSULTANT

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation

CYS AUTOMOBILE SERVICES PTE LTD

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12
NAZ LICK 11/11/18

L/S

5 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO