



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/11/2018

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB102A
Case Reference Number	BUS/10/18/1045
Registration Date	29/07/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Chong Kuek Kheong
Type of Accident	Head to Rear
Accident Date and Time	27/10/2018 2:40 PM
Accident Reported Date and Time	27/10/2018 5:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	right front portion damaged
Prepared Date and Time	01/11/2018 12:20 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$111.82	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,787.82	\$0.00
Lump Sum Total	\$1,800.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	01/11/2018 12:23 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 01/11/2018

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	795
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$616.00	528
Total Spray Painting & Panel Beating	\$616.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009700	VE		LAMP,BLINKER:FRONT, LEFT,FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	/ CRK
Total					\$155.30		\$139.77		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NA2 LKK
1/27/18
LIS
2 DAYS
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The 3 party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: