

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1261/2018/GW
Date : 8-Nov-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chua Tze Hon
Address : 22 Lorong Puntong
#17-03
Singapore 576439
Telephone : HP +65 9853571
Type of Claim : Own Damage Claim
Policy No. : 2100510350-01
Vehicle No : **SLQ 848 P**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : Jun-17
Engine No : CVK 036553
Chassis No : WAUZZZF54HA037527
Mileage : 19767 KM
Date In : 5-Nov-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Nov-18
Place of Accident : Junction of Havelock and Eu Tong Seng road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLQ 848 P.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To dislodge and reinstall rear parking aid and rear lid kick sensor check function.	S/N \$ 360.00	✓
2	To remove and transfer lhs front and rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00	✓
3	To dismantle rear bumper, lhs front door, lhs rear and lhs sill panel trim. To repair rear bumper and lhs rear fender. To inspect lhs B-pillar for further damages. To renew lhs front door, lhs rear door and lhs sill panel trim. Re-organize crash management components. reinstall all parts removed.	\$ 4,200.00 2000.	✓
4	To respray rear bumper, lhs front door, lhs rear door, lhs sill panel trim, door handles, hinges and lhs rear fender.	\$ 4,400.00 2475.	✓
5	To renew lhs rear rim and carry out wheel alignment.	\$ 280.00	✓
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,992.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 848 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR -LH <i>Distorted.</i>	\$ 2,692.00	✓
2	FRONT OUTER DOOR SEAL-LH <i>new</i>	\$ 192.00	✓
3	BONDING AGENT ?	\$ 43.00	?
4	CLEANING SOLUTION ?	\$ 64.00	?
5	APPLICATOR ?	\$ 7.00	?
6	FRONT DOOR CATCH-LH <i>new</i>	\$ 105.00	X
7	FRONT DOOR CATCH COVER-LH <i>new</i>	\$ 13.00	X
8	FRONT DOOR TRIM-LH <i>new</i>	\$ 138.00	X
9	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH <i>new</i>	\$ 309.00	X.
10	FRONT DOOR HANDLE TRIM-LH <i>new</i>	\$ 48.00	X
11	FRONT DOOR MOUNTING BAR-LH	\$ 143.00	X
12	REAR DOOR-LH <i>Distorted</i>	\$ 2,692.00	✓
13	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 192.00	✓
14	BONDING AGENT ?	\$ 43.00	?
15	CLEANING SOLUTION ?	\$ 64.00	?
16	APPLICATOR ?	\$ 7.00	?
17	REAR DOOR CATCH-LH ?	\$ 105.00	?
18	REAR DOOR COVER CATCH-LH ?	\$ 12.00	?
19	REAR DOOR HINGE HALF-LH ?	\$ 40.00	?
20	REAR DOOR HINGE HALF LOWER-LH ?	\$ 65.00	?
SUB - TOTAL SPARE PARTS		\$ 6,974.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLQ 848 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR DOOR HINGES HALVES UPPER-LH ?	\$ 40.00	?
22	REAR DOOR HINGE HALVES LOWER-LH ?	\$ 40.00	?
23	REAR DOOR SEAL ,INNER-LH <i>new</i>	\$ 511.00	X.
24	REAR WINDOW REGULATOR WITHOUT MOTOR-LH <i>new</i>	\$ 309.00	X
25	REAR WINDOW REGULATOR MOTOR-LH <i>new</i>	\$ 228.00	X.
26	EDGE PROTECTION-LH ?	\$ 134.00	?
27	MOLDING-ROOF <i>new</i>	\$ 543.00	X
28	REAR WINDOW SLOT SEAL WITH TRIMS STRIP -LH <i>3 new</i>	\$ 317.00	X
29	REAR WINDOW SLOT SEAL WITH TRIM STRIP CHROME-LH <i>new</i>	\$ 345.00	X.
30	SIDE MEMBER TRIM - <i>Replaced</i>	\$ 723.00	✓
31	SIDE MEMBER TRIM ATTACHMENT PARTS ?	\$ 111.00	?
32	ADHESIVE TAPE <i>new</i>	\$ 182.00	✓
33	REAR RIM-LH <i>new</i>	\$ 934.00	✓
34	RUBBER VALVE <i>new</i>	4 \$ 12.00	X.
35	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 11,903.00
TOTAL LABOUR CHARGES		:	\$ 9,992.00
GRAND TOTAL		:	<u>\$ 21,895.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 08/11/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized, 08 by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant